

Optimization of Machining Processes

1



Prof. S. S. Pande

Mechanical Engineering Department
Indian Institute of Technology, Bombay

1

Outline

- Product-Process Optimization criteria
- Machining Process Optimization Objective
 - To *Maximize* Productivity
 - To *Minimize* Cost
 - To *Maximize* Profit rate
- Selection of Optimum Process Parameters

2

Product-Process Optimization Perspective

Product Design Optimization

- Material Selection – Function related
- Shape design Constraints : Size, Stress, Thermal
- Product Quality - Dimensions, Tolerances

Production Process Optimization

- Optimum Plant Layout
 - Product Flow in shop
- Supply Chain ; Inventory management
- Production Unit Operation
 - Selection of Optimum Process Parameters (Local optimization)

3

Criteria for Process Optimization

Aim

To select Optimum Process Parameters

Criteria

- *Maximize* Productivity
 - Minimum Production time / job
- *Minimize* Cost per piece
- *Maximize* Profit rate

4

Formulating Objective Function

Nomenclature

N_b = No of parts produced in the batch

N_t = No of Tools used for N_b

t_s = Setup time per job

t_m = Machining time per job

t_{ct} = Tool changing time per tool

N = Spindle speed

V = cutting Speed (m/min)

f = feed rate (mm/rev)

5

Calculation of Production Time

Production time for batch of N_b parts

$$T = N_b \cdot t_s + N_b \cdot t_m + N_t \cdot t_{ct}$$

Production Time per piece t_p

$$t_p = \frac{T}{N_b} = t_s + t_m + \frac{N_t}{N_b} \cdot t_{ct}$$

Where,

t_s = Setup time per job

t_m = Machining time per job

t_{ct} = Tool changing time per tool

6

Calculating Setup Time t_s

Set up time is the *Non Cutting* (Idle) time.

It comprises of

- Set up of machine / Tool / Fixtures
- Loading/ Unloading of job
- Approach of tool to job at start
- Tool return to the start of cut

7

Optimization of Turning Process

Single Pass, Single Tool, Constant feed Operation

Cutting Speed $V = \frac{\pi DN}{1000}$ (m/min)

Job dimensions D, L in mm

Spindle speed N in RPM

Feed f in mm/rev

Machining time per job

$$t_m = \frac{L}{N \cdot f} \text{ min}$$

$$= \frac{\pi DL}{1000 V f}$$

$$t_m = \frac{K}{V} \text{ K is the Constant}$$

8

Calculating Tools used

Taylor's Tool Life Equation

$$VT^n = C$$

$$\text{Tool Life } T = \frac{C}{V^n}$$

Cutting Speed V in m/min; Tool Life T in min

N_t tools are used for producing N_b jobs

$$N_t \cdot T = N_b \cdot t_m$$

Substituting

$$\frac{N_t}{N_b} = \frac{t_m}{T} = \frac{KV^{n-1}}{C}$$

9

Formulating Objective Function - t_p

Time per piece t_p

$$t_p = t_s + \frac{K}{V} + \frac{KV^{\frac{1}{n}-1}}{C^{1/n}} \cdot t_{ct}$$

To maximise Productivity


Minimize t_p

$$\frac{dt_p}{dv} = 0$$

t_p varies as a function of V

10

Production time t_p vs V



11

Optimum Parameters for minimum t_p

For minimum t_p

Tool Life t_p is

$$t_p = \left(\frac{1}{n} - 1\right) t_{ct}$$

Cutting Speed V_p

$$V_p = \frac{C}{T_p^n}$$

12

Optimizing Cost per piece C_p

C_p includes M and C_t

M = Machine Hour Rate (Rs/min)

M includes

- Price of the machine
- Amortization period
- Labor Rate
- Cost of land, power
- Overheads

C_t = Cost of one tool / insert edge

13

Objective Function C_p

Cost of producing N_b parts in the batch

C_b = Setup + Machining + Tool cost

$$= M \cdot N_b \cdot t_s + M \cdot N_b \cdot t_m + N_t \cdot C_t + N_t \cdot t_{ct} \cdot M$$

$$\text{Cost per piece } C_p = \frac{C_b}{N_b}$$

$$C_p = M \cdot t_s + M \cdot t_m + \frac{N_t}{N_b} \cdot C_t + \frac{N_t}{N_b} \cdot t_{ct} \cdot M$$

$$C_p = M \cdot t_s + M \cdot t_m + M \frac{N_t}{N_b} \left[t_{ct} + \frac{C_t}{M} \right]$$

14

Formulating Objective Function C_p

Substituting

$$t_m = \frac{K}{V} ; \frac{N_t}{N_b} = \frac{KV^{\frac{1}{n}-1}}{C^{\frac{1}{n}}}$$

Objective Function C_p


$$C_p = M \cdot t_s + M \cdot \frac{K}{V} + M \frac{KV^{\frac{1}{n}-1}}{C^{\frac{1}{n}}} \left[t_{ct} + \frac{C_t}{M} \right]$$

To minimize Cost C_p

$$\frac{dC_p}{dv} = 0$$

15

Cost per piece C_p vs V



16

Optimum Parameter for minimum C_p

For minimum C_p ,

Optimum Tool Life T_c

$$T_c = \left(\frac{1}{n} - 1 \right) \left[t_{ct} + \frac{C_t}{M} \right]$$

Optimum Cutting Speed V_c

$$V_c = \frac{C}{T_c^n}$$


It is seen that

$$T_c > T_p$$

$$\text{So } V_c < V_p$$

17

Hi – Efficiency Range



$V_c - V_p$ – high E Range

18

Calculation of Tool Cost C_t

Regrindable tools

N_g = No of grinds

C_g = Cost of grinding per regrind

$$C_t = \frac{N_g \times C_g + \text{Tool Cost}}{N_g + 1}$$

Throw away Carbide insert

C_i = cost of insert

N_e = No of cutting edges provided

$$C_t = \frac{C_i}{N_e}$$

For a square insert;

$N_e = 4$ (positive rake on insert)

$= 8$ (Zero rake on insert)

19

Constraints in Optimization

On the *Unconstrained* Optimization, the following constraints apply

- Maximum Speed, Feed provided on machine
- Steps in Speed, Feed (or Stepless speed drive)
- Permissible Surface Finish
- Maximum Cutting Force, Power
- Shop Practices

20

Two Factor Optimization

Objective Function

t_p or $C_p = f(V, f)$

Extended Taylor's Tool Life equation

$$T V^{n_1} f^{n_2} = C^1$$

Optimization Technique

- Unconstrained
- Constrained

21