

**Design & Technology**  
**AQA GCSE**

# **How materials are cut shaped and formed to a tolerance**

## **Materials required for questions**

---

- Pencil
- Rubber
- Calculator

## **Instructions**

---

- Use black ink or ball-point pen
- Try answer all questions
- Use the space provided to answer questions
- Calculators can be used if necessary
- For the multiple choice questions, circle your answer

## **Advice**

---

- Marks for each question are in brackets
- Read each question fully
- Try to answer every question
- Don't spend too much time on one question

**Good luck!**

**Q1.** What is a tolerance in manufacturing?

- A**      The colour of a finished product
- B**      The acceptable range between minimum and maximum measurements
- C**      The type of material used

**Q2.** Why are tolerances important in mass production?

- A**      They make every product unique
- B**      They ensure parts fit together correctly and maintain quality standards
- C**      They reduce the need for measurements

**Q3.** If a dimension is given as  $50\text{mm} \pm 0.5\text{mm}$ , what is the maximum acceptable size?

- A**      49mm
- B**      51mm
- C**      50.5mm

**Q4.** Which tool is most suitable for checking tolerances precisely?

- A**      A ruler
- B**      A saw
- C**      A vernier caliper

**Q5.** Explain how tolerances are used to control quality when making a prototype. Give two examples of how incorrect tolerances could cause problems. **(4 marks)**

---

---

---

---

## Answers

Q1. B

Q2. B

Q3. C

Q4. C

Q5.

### Example Answer (4 marks):

1. **Purpose of tolerances (1 mark):** Tolerances define the allowable variation in measurements to ensure parts fit and function correctly.
2. **Quality control (1 mark):** During prototyping, tolerances help identify errors early, reducing waste and ensuring consistency.
3. **Problem 1 (1 mark):** If a drilled hole is **too small** (below minimum tolerance), a bolt won't fit, making assembly impossible.
4. **Problem 2 (1 mark):** If a component is **too large** (above maximum tolerance), it might not fit into other parts, causing structural weakness.