

# CURRENT STATE OF HARDWARE DEBUGGING AND HINTS ON SIMULATION DISCREPANCIES


Hendrik Borras

Supervisor: Michael Schmelling

# HARDWARE DEBUGGING: CURRENT STATE

- Board repaired as far as feasible during the last week
- Smoke tested the HV circuit (e.g. bias on the pin-diodes)
  - No problems up to 60 V (breakdown voltage)
- Setup for measuring the amplification chain

# HARDWARE DEBUGGING: REPAIRS



- ✓
- Resistor was switched out by the workshop
- ✗
- At the red arrow: Accident while repairing; trace was pulled out
- At the blue arrow: Unclear where the short is on the board; further investigation needed

µTelescope: Schematics for pin-diodes;  
Important parts are highlighted in red


# HARDWARE DEBUGGING: CURRENT DETECTOR CAPACITY

Readout: Row/Column	Column 1	Column 2	Column 3	Column 4
Row 1	Full	Full	Full	Half (upper)
Row 2	Full	Full	Full	Half (upper)
Row 3	Half (lower)	Half (lower)	Half (lower)	None
Row 4	Full	Full	Full	Half (upper)

- Table explanation:
  - Full: Sensor correctly wired after repair on both sides
  - Half: Only the sensor on one side is available (no coincidence)
  - None: No working diode in this space
- Design detector area:  $1,44 \text{ cm}^2$
- Available detector area (full detection):  $0,81 \text{ cm}^2$

# HARDWARE DEBUGGING: FURTHER TEST SETUP

- Measurements of the amplification chain
  - Setup a lighttight box
  - Soldering of pins onto the amplifier in and outputs
- Radiation source in the lab
  - Would reduce the time one has to wait for a cosmic, by a large factor
  - The energy of the particles is exactly known
  - Got the OK from Jim
  - Got first information from Ralf Lackner
  - Waiting for response from Ralf



Box with light tight cloth for measurements;  
PSUs in the background



# SIMULATIONS

- Numerical detector acceptance calculation from Michael
  - Reduced calculation need down to one integral
  - Shows the same results as the MC from Michael
  - Currently working on implementing this model into Hendriks numerical simulation
- So far the discrepancy seems to be a systematical error between the two simulations