



# PicoVNA®


## Vector Network Analyzers

### System Z0 Conversion Guide

# 1 System Z<sub>0</sub> conversion

The **System Z<sub>0</sub> Conversion** facility allows measurements, which are always taken in 50 Ω, to be converted to another impedance that you select. This feature can be useful, for example, for measuring 75 Ω devices. The value of Z<sub>0</sub> entered must be real (purely resistive) and must be within the range of 10 Ω to 200 Ω. Whenever this facility is selected, an indicator is displayed on the top right corner of the graphics display as shown in the second figure below. **Note** that when requested, impedance conversion will be performed on the **live measurement** and any stored **memory trace**.

There are two possible ways of using the **System Z<sub>0</sub> Conversion** facility. For example, 75 Ω devices can be measured using the techniques illustrated below.



Impedance matching pads can be used to measure a connectorized device. Use external matching pads and calibrate with a 75 Ω calibration kit.

A discrete device mounted on a 50 Ω test jig is simpler to measure. Calibrate with a 50 Ω calibration kit, use de-embedding to remove the test jig and allow mathematical conversion to 75 Ω impedance.

## Possible techniques for measuring 75 Ω devices


The steps necessary for each of the two techniques illustrated in the figure above are as follows:

### 75 Ω device with connectors

- Connect **50 Ω to 75 Ω impedance matching networks** (e.g. matching pads) at the ends of the cables connected to ports 1 and 2.
- In the **Enhancement** window, check the **Convert System Z<sub>0</sub>** box
- Check **External Z<sub>0</sub> match** to indicate external matching networks in use
- Enter **75** in the **Convert System Z<sub>0</sub>** value box and click **Apply**
- Proceed to calibrate using a **75 Ω calibration kit**
- Connect the DUT and **start the measurement**

### 75 Ω device mounted on 50 Ω test jig

- In the **Enhancement** window, uncheck the **Convert System Z<sub>0</sub>** box
- Calibrate at the ends of the test cables using a 50 Ω calibration kit
- Apply de-embedding to remove test jig effects. See Calibration kit for some suggestions.
- In the **Enhancement** window, check the **Convert System Z<sub>0</sub>** box
- Uncheck the **External Z<sub>0</sub> match** box (in this case mathematical impedance conversion is done by the software)
- Enter 75 in the **Convert System Z<sub>0</sub> value** box and click **Apply**
- Connect the DUT and start the measurement



**Note:** S-parameters are interrelated, so, when using the Z<sub>0</sub> conversion facility (and no external impedance matching networks) without a full set of S-parameters available (e.g. only an S<sub>11</sub> calibration) the program will assume values for the unavailable parameters as shown in the following table. A warning will be displayed in such cases.

S <sub>11</sub>	S <sub>12</sub>	S <sub>21</sub>	S <sub>22</sub>
10 <sup>-6</sup> , j0.0	10 <sup>-6</sup> , j0.0	10 <sup>-6</sup> , j0.0	10 <sup>-6</sup> , j0.0

Values assumed for parameters not available during Z<sub>0</sub> conversion

**UK headquarters:**

Pico Technology  
James House  
Colmworth Business Park  
St. Neots  
Cambridgeshire  
PE19 8YP  
United Kingdom

Tel: +44 (0) 1480 396 395

[sales@picotech.com](mailto:sales@picotech.com)  
[support@picotech.com](mailto:support@picotech.com)

[www.picotech.com](http://www.picotech.com)

**North America office:**

Pico Technology  
320 N Glenwood Blvd  
Tyler  
TX 75702  
United States

Tel: +1 800 591 2796

[sales@picotech.com](mailto:sales@picotech.com)  
[support@picotech.com](mailto:support@picotech.com)

**Asia-Pacific office:**

Pico Technology  
Room 2252, 22/F, Centro  
568 Hengfeng Road  
Zhabei District  
Shanghai 200070  
PR China

Tel: +86 21 2226-5152

[pico.asia-pacific@picotech.com](mailto:pico.asia-pacific@picotech.com)