

## ASSIGNMENT- 4

### CODE AND CONNECTION IN WOKWI FOR THE ULTRASONIC SENSORS

#### CODE:

```
#include <stdio.h>
#include <stdbool.h>
#include <freertos/FreeRTOS.h>
#include <freertos/task.h>
#include <esp_err.h>

#include "ultrasonic.h"

#define ECHO_GPIO 12
#define TRIGGER_GPIO 13
#define MAX_DISTANCE_CM 500 // Maximum of 5 meters

void ultrasonic_test(void *pvParameters)
{
    float distance;

    ultrasonic_sensor_t sensor = {
        .trigger_pin = TRIGGER_GPIO,
        .echo_pin = ECHO_GPIO
    };

    ultrasonic_init(&sensor);

    while (true) {
        esp_err_t res = ultrasonic_measure(&sensor, MAX_DISTANCE_CM,
&distance);

        if (res == ESP_OK) {
            printf("Distance: %0.04f m\n", distance);
        } // Print error
        else {
            printf("Error %d: ", res);
        }
    }
}
```

```

        switch (res) {
            case ESP_ERR_ULTRASONIC_PING:
                printf("Cannot ping (device is in invalid state)\n");
                break;
            case ESP_ERR_ULTRASONIC_PING_TIMEOUT:
                printf("Ping timeout (no device found)\n");
                break;
            case ESP_ERR_ULTRASONIC_ECHO_TIMEOUT:
                printf("Echo timeout (i.e. distance too big)\n");
                break;
            default:
                printf("%s\n", esp_err_to_name(res));
        }
    }

    vTaskDelay(pdMS_TO_TICKS(500));
}

void app_main()
{
    xTaskCreate(ultrasonic_test, "ultrasonic_test", configMINIMAL_STACK_SIZE
* 3, NULL, 5, NULL);
}

```