

ROLL: 1705045

Iftekhar Hakim Kaowsar

Flaws:

1. It is 8086 microprocessor, not 8088, but here A8-A15 shown. They should be AD8-AD15. Moreover, for AD8-A15, one more 74LS373 latch for demultiplexing and one more 74LS245 latch for bidirectional buffering, and 74LS244 will not be needed to connect for this part.

No other flaws.