


Name : Sofiyan Ahmad Chaudhry
 Roll NO : 08 PRN NO : 50641920181162511002
 Semester : 07 Branch : Mechanical Engineering
 Subject : Manufacturing process III

Assignment 3: To develop a manual part program of a given component on a CNC lathe using Stock removal cycle.

Part Drawing :



Absolute Co-ordinate System (G90)

Absolute point(p)	X	Z
0	0	0
1	10	0
2	10	-20
3	30	-20
4	30	-40

part program
01010

N10	G90	G96	G21 ;
N20	M03	M07 ;	
N30	T0101	S500	F0.8 ;
N40	G00	X0	Z0 ;
N50	G71	U1	R1 ;
N60	G71	P70 Q100 U0.5 W0.5 F0.8	
N70	G01	X10 ;	
N80	G01	Z-20 ;	
N90	G01	X-30 ;	
N100	G01	Z-40	
N110	G70	P70 Q100 ;	
N120	G00	X50 Z100 ;	
N130	M05	M09 ;	
N140	M03 ;		

Explanation:

01010	-	Program Name
G90	-	Absolute programme System
G96	-	Constant Surface cutting Speed
G21	-	Metric conversion System (in mm)
M03	-	Spindle on (clockwise direction)
M07	-	Coolant on (Mist Type)
T0101	-	Tool 01 and offset no.01

- S500 - Spindle Speed
- F0.8 - feed rate
- G00 - Rapid Traverse
- X0.20 - origin of part
- G71 - Stock Removal Cycle (lanned cycle)
- U - Depth of cut
- R - Retract value
- P - Starting block
- Q - Ending block
- U - Material left for finishing
- W - Material left for finishing ^{x-axis} 2-axis
- F - overrid feed rate btw P and Q.
- G01 - linear interpolation
- G70 - finishing cycle
- M05 - Spindle off
- M01 - coolant off
- M030 - Reset the program