


Name Sufiyan Ahmad Chaudhry  
Roll No: 06 PRN NO: 50641920181162511002  
Semester: 7 Branch: Mechanical Engineering  
Subject: Manufacturing process II

Assignment 6: To develop a manual part program of given component on CNC Milling Machine using pocket Milling cycle.



## Absolute coordinate System;

Point	x-axis	y-axis
0	0	0
1	25	0
2	15	25
3	15	25
4	-15	25
5	-25	15
6	-25	-15
7	-15	-25
8	15	-25
9	25	-15

Such Program.

0 1 0 0 0 5

No 10	G00	G54	G90	X0 Y0 F100
No 20	G01	G91	Z-0.1	F100;
No 30	G01	G90	X25	Y0;
No 40	G01	X25	Y15	
No 50	G03	X15	Y25	R10;
No 60	G01	X-15	Y25	;
No 70	G02	X-25	Y15	R10;
No 80	G01	X-25	Y-15	;
No 90	G03	X-15	Y-25	R10;



N100	G101	X15	Y-25 ;
N110	G102	X25-0	Y-15 R10 ;
N120	G01	X25	Y5 ;
N130	G01	X0	Y5 ;
N140	G01	Y0	
N150	M99		

### Explanation

M06 - Tool Selection

T01 - Tool 01

M03 - Spindle on (clockwise direction)

S1000 - Spindle Speed

G00 - Rapid Traverse

G54 - Setting Work of offset

(G54 is used in sub program)

G90 - Absolute Coordinate

X0 Y0 - Centre of work piece

F500 - Feed

G43 - Height data is set in Tool

G43 H01 → Tool length compensation <sup>or offset</sup>

H01 → Height data is set in Tool or

Z50 → 50mm gap between tool and work <sup>offset</sup> piece

Z1 → linear interpolation

F100 → Feed is 100

M08 → Coolant on

G150 → General pocket Milling cycle <sup>on</sup>

C41 → cutter radius compensation

an (because tool path is clockwise).

p10005 - calling sub-program 10005

G0-1 - Depth of cut

X0 Y0 - work part zero

Z-5 - Total dept -5 (because started with Z1)

R1 - Retraction

T6 - Incremental cut on y axis  
(creates cavity in y-direction)

K0.05 - finishing allowance

D01 - Tool diameter data is  
set in D offset.

G40 - cutter radius compensation off.

M03 - coolant off

M05 - Spindle off

M30 - Reset the program.