

Product: RTL8811A/RTL8821A USB Software Package - Linux Driver
Version: v5.2.6.2_23547.20170814_COEX20170206-6760

Release History:

| | |
|--|---|
| v4.2.0_6952.20130315 | 1. First release. |
| v4.2.0_7054.20130328 | 1. Fix LED behavior |
| v4.2.2_7502.20130517 | 1. Support 11AC for STA. |
| v4.2.3_8123.20130705 | 1. Update PHY parameters to improve throughput. |
| v4.2.4_9533.20131209 | 1. Update Phy Parameter for IOT issue 2. MP Driver - Packet Tx function 3. Fix memory leakage issue 4. Fix crash issue when change_band_update_ie() is called for 2.4G->5G 5. Security-TKIP - Prevent starvation caused by log of rtw_tkip_decrypt() when binstallGrpkey == _FALSE 6. avoid crash issue when quickly insert/remove driver 7. If AP support 802.11r, that will be send deauth with reason code 2 to STA. We will loop in connecting. 8. Improve P2P connection successful rate & IOT issue for P2P connection 9. IOT issue on concurrent mode 10. Support Linux kernel 3.10 |
| v4.3.0_10674.20140321 | 1. To fix data rate issue of AP mode 2. To fix transmission power issue 3. To update PHY setting when driver switches wireless band 4. To fix DHCP issue 5. To fix race condition issue |
| v4.3.14_13455.20150212_BT COEX20150128-51 | 1. This driver can support 8811AU and 8821AU 2. Support BT coexist 3. Support Adaptivity 4. Support efuse and mac address can read from file 5. Support Sniffer feature 6. Support Linux kernel 3.16.0 7. Fix some 802.11 logo issue. 8. Fix WPS issue |
| v4.3.19_15408.20151102_B TCOEX20150921-58 | 1. Support Linux kernel 4.0 2. Support Android 5.0 3. Update BT coexist (v58) 4. Update Adaptivity (v8.6) 5. Update PID,VID list 6. Support ifconfig modify WiFi MAC 7. Fix wpa_supplicant disconnect ignore issue 8. Fix UDP packet lose issue 9. Fix P2P listen state setting listen channel issue |
| v4.3.19.1_16074.20151222_ BT COEX20150921-58 | 1. Support Linux kernel 4.1 2. Fix Adaptivity IPS issue 3. Enhance RF setting |

| | |
|--|---|
| v4.3.19.2_16962.20160225_BT COEX20150921-58 | <ol style="list-style-type: none"> 1. Fix Adaptivity scan issue 2. Support Driver switch antenna band feature for one antenna module |
| v4.3.19.3_17177.20160325_BT COEX20150921-58 | <ol style="list-style-type: none"> 1. Support rtkm 2. Fix some scan results issue |
| v4.3.19.4_17413.20160414_BT COEX20150921-58 | <ol style="list-style-type: none"> 1. Fix MP mode IQK issue |
| v4.3.19.5_17672.20160506_BT COEX20150921-58 | <ol style="list-style-type: none"> 1. Fix adaptivity issue when DIG change IGI |
| v5.2.6_21981.20170407_COEX 20170206-6760 | <ol style="list-style-type: none"> 1. Support 1 antenna BT coexist 2. Support TDLS 3. Support 8821au 1 antenna setting 4. Support Android 7.0 5. Support NAPI GRO 6. Update BT coexist 7. Update PID,VID list 8. Fix SoftAP mode some IOT TP issue 9. Fix writing-efuse may cause card-loss issue. |
| v5.2.6.1_22092.20170503_COEX 20170206-6760 | <ol style="list-style-type: none"> 1. Update adaptivity for new ETSI spec. (CE-RED) |
| v5.2.6.2_23547.20170814_COEX 20170206-6760 | <ol style="list-style-type: none"> 1. Support Linux Kernel 4.11 2. Fix softap issue 3. Fix enable MP mode warning message |

Description:

Realtek provides the solution for WLAN in hardware and software. The software package could be adopted for Realtek RTL8811A/RTL8821A USB WLAN series hardware on Linux based platforms.

Software Version:

RTL8811A/RTL8821A USB Linux Driver Version: v5.2.6.2_23547.20170814_COEX20170206-6760

Hardware Supported:

- RTL8811AU
- RTL8821AU

Platform Supported:

- Linux (kernel 2.6.18 ~ 4.11)
- Android 1.6 ~ 2.3, 4.0 ~ 7.0

CPU supported:

- x86
- ARM
- MIPS