

YETS Maintenance Update

January 19, 2023

Peter Camporeale, Jacky Li
On behalf of TileCal maintenance team



Interventions

1. LBC 24

Problem: Trips on MB side; Harting connector pins were burned (pin 33) and had been soldered improperly

Intervention: Replaced the Harting connector, burnt wire, and LVPS damaged

Status: Drawer closed and ready for DVS tests

2. LBC 55

Problem: Towers 1-3 dead in L1Calo; confirmed with MobiDick Adder test (no signal from these towers)

Intervention: Extracted drawer and repaired broken (loose/cut) wires on the trigger cables.

Status: Drawer closed; tested with MobiDick after insertion of drawer

Interventions

3. LBA 33

Problem: Trips on MB side

Intervention: Tested drawer with external power supply and MobiDick from USA15; Passed all digital tests

Status: Drawer closed and ready for DVS tests; MB trip seen on 19.01 at 12:17

4. LBA 35

Problem: Trips on the HV side of the module

Intervention: Checked all HV pins and found that the 5V wire was not well soldered. All pins were crimped.

Status: Drawer closed and ready for DVS tests

Interventions

5. LBA 48

Problem: Per Filipe's suggestion, HV wires in Harting connector needed to be checked

Intervention: Opened drawer and saw no visible damage; Pins were crimped for good measure; Cooling problem was observed after intervention but then solved

Status: Drawer closed

6. LBA 29

Problem: Modules in Loop 11 started to overheat

Intervention: Cooling water flow was increased

Status: All modules in Loop 11 are running (with exception of LBA 30 which was previously excluded as a suspicious module with a leak)

Interventions

7. LBC 64

Problem: Cooling investigation due to possible leak

Intervention: Internal part of HV side of drawer had already been excluded from the cooling loop

Status: Drawer closed

8. EBA 07, LBA 30, LBA 45, LBA 58, LBC 38, EBC 30

Problem: Possible leak

Intervention: Excluded from cooling loops. Only EBA 07 shows a temperature increase on internal HV_OPTO board compared to its neighbors

Status: Ongoing cooling investigation, LVPS will not be started there

Maintenance Team 16.1-19.1

Irakli


Stan

Nugzar



Jacky

Peter


Appendix



LBC 24: Burnt
Harting connector
and wire



EBA07 HV_Opto-ext "7 deg higher"
than in neighbor EBA08, EBA06



EBA07

Monitored temperature HV_Opto-ext in EBA07
Jumped Up in 2022 by ~ 1 degree
Compare to 2021

