

## **Statistical Quality Control (SQC)**

**Statistical Quality Control (SQC)** is a statistical method for finding whether the variation in the quality of the product is due to random causes or assignable causes.

**Process Control** means control of the quality of the goods while they are in the process of production.

**Control Chart** is a graphical device mainly used for the study and control of the manufacturing process.

There are **two types** of control charts namely,

1. Control charts of variables (Mean and range charts).
2. Control charts of attributes (p-chart and c-chart).

**Variables** are the quality characteristics of a product that are measurable. E.g., diameter of a hole in bored drilling machine.

**Attributes** are the quality of the characteristics of a product that are not measurable. E.g., presence of defective items in a sample.

### **Control charts for Attributes**

p-chart - proportion of defectives

np-chart - number of defects

c- chart - number of defects in a unit

### **Construction of $\bar{x}$ -chart**

The following values must be computed for drawing an  $\bar{x}$  chart:

- (i) The mean of each sample, i.e.,  $\bar{x}_1, \bar{x}_2, \bar{x}_3$ , etc., are obtained using  $\bar{x} = \frac{\sum x}{n}$  where  $n$  is the number of items in the sample (or sample size).
- (ii) The mean of the sample means  $\bar{\bar{x}}$  is obtained by  $\bar{\bar{x}} = \frac{\sum \bar{x}}{\text{number of samples}}$
- (iii) The control limits are set at  $UCL = \bar{\bar{x}} + 3 \frac{\sigma}{\sqrt{n}}$  (or)  $UCL = \bar{\bar{x}} + A_2 \bar{R}$  and  $LCL = \bar{\bar{x}} - 3 \frac{\sigma}{\sqrt{n}}$  or  $LCL = \bar{\bar{x}} - A_2 \bar{R}$  where  $\sigma$  is the standard deviation and  $\bar{R}$  is a biased estimator of  $\sigma$  found by  $\bar{R} = \frac{\sum R}{n}$  and  $R$  is the sample range. The value of  $A_2$  can be obtained from the table in the appendix.

### Construction of R-chart

The general procedure for constructing the R chart is similar to that of  $\bar{x}$  chart. The steps are:

- (i) The range of each sample,  $R$  is determined.
- (ii) The mean of the sample ranger,  $\bar{R}$  is calculated.
- (iii) The total control limits are found as

$$UCL = \bar{R} + 3\sigma_R$$

$$\text{and } LCL = \bar{R} - 3\sigma_R$$

where  $\sigma_R$  is the standard error of the range. However, in practice, it is convenient to compute UCL and LCL by using the values of  $D_4$  and  $D_3$  provided as

$$UCL = D_4 \bar{R} \text{ and } LCL = D_3 \bar{R}.$$

### Construction of p-chart

This chart gives best results when the sample size is large. The steps in constructing the chart are:

- (i) The average fraction defective  $\bar{p}$  is computed by dividing the number of defectives by the total number of units inspected.
- (ii) The central line is drawn with value  $\bar{p}$ .
- (iii) UCL and LCL are determined using

$$UCL = \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}} \text{ and } LCL = \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$$

It is to be noted that, if  $p$  is small, substitution in the formula for LCL might yield a negative number. When this occurs, it is customary to assume the LCL to be equal to zero.

### Construction of np-chart

Instead of plotting the fraction defective in a sample of size  $n$ , the number of defectives can be plotted directly. Such a chart is called control chart for number of defectives or np chart. To obtain this chart, the central line as well as control limits of  $p$  chart are multiplied by  $n$ . Therefore, we get,

$$\text{Central line} = n\bar{p}$$

$$UCL = n\bar{p} + 3\sqrt{n\bar{p}(1-\bar{p})} \text{ and } LCL = n\bar{p} - 3\sqrt{n\bar{p}(1-\bar{p})}$$

### Construction of c-chart

There are situations where it is necessary to control the number of defects in a unit of product, rather than the fraction defective or the number of defectives. For example, controlling the number of defects per hundred meters of cloth, number of air bubbles in a piece of glass, etc. Such situations are described by the Poisson distribution.

Let  $C$  represents the number of defects counted in one unit of cloth and  $\bar{c}$  represent the mean of the defects counted in several such units of cloth.

Central line =  $\bar{c}$ ,  $UCL = \bar{c} + 3\sqrt{\bar{c}}$  and  $LCL = \bar{c} - 3\sqrt{\bar{c}}$

---