



AANDERAA
INSTRUMENTS

5852 Bergen, Norway. Tel. +47 55 10 99 00

Test and Calibration Sheet

Pressure Sensor 3815A ☐
Pressure Sensor 3815B ☐
Pressure Sensor 3815C ☐
Pressure Sensor 3815D ☒
Pressure Sensor 3815E ☐
Serial No: 826

1. Visual and Mechanical Checks:

- 1.01 Treads
- 1.02 Swagelok cone
- 1.03 O-ring grooves
- 1.04 Components correctly inserted
- 1.05 Soldering quality
- 1.06 O-rings

Before casting

☒
☒
☒
☒
☒

After casting

☒
☒
☒
☒
☒

2. Performance test:

2.01. Typical raw data reading in air for range: 0 - 700 kPa: (155-175)

0 - 3500 kPa: (30-60)

0 - 7000 kPa: (20-50)

0 - 20 MPa: (10-40)

0 - 60 MPa: (10-40)

.....
.....
.....
29.....
.....

2.02 Typical raw data reading at full range (Typical reading: 950-1010)

2.03 Maximum temperature drift over the range -5 to +40 °C (max: ±2 LSB)

1009.....
.....

Date: 7/8-2003 Sign: Helge Solhveit

3. Calibration:

This sensor is calibrated against a Budenberg dead weight tester. Sensor accuracy better than ±0.25% of range. This is an absolute pressure sensor. Pressure range:

0 - 700 kPa (0 - 101.5 psi)

0 - 3500 kPa (0 - 507.6 psi)

0 - 7000 kPa (0 - 1015.2 psi)

0 - 20 MPa (0 - 2901.0 psi)

0 - 60 MPa (0 - 8702.0 psi)

☐
☐
☐
☒
☐

Pressure, Bar MPa	<u>0,101</u>	<u>5,107</u>	<u>10,113</u>	<u>15,120</u>	<u>20,126</u>
Raw data reading (N)	<u>32</u>	<u>278</u>	<u>524</u>	<u>768</u>	<u>1011</u>

Calibration formula: Pressure (^{MPa}Bar) = A + BN + CN² + DN³

Calculated coefficients:

A: -5.444E-01

B: 2.025E-02

C: 1.950E-07

D: 0

Installation:

Special care should be taken when installing the sensor to prevent damage to the O-rings. If necessary, grease the O-rings. Coat the threads near the Top End-Plate after installation with TECTYL 506 to prevent crevice corrosion.

Date: 26/8-2003 Sign: Roar Sagmes



AANDERAA
INSTRUMENTS

5852 Bergen, Norway.Tel. +47 55 10 99 00

Test and Calibration Sheet

Pressure Sensor 3815A ☐
Pressure Sensor 3815B ☐
Pressure Sensor 3815C ☐
Pressure Sensor 3815D ☒
Pressure Sensor 3815E ☐
Serial No: 827

1. Visual and Mechanical Checks:

- 1.01 Treads
- 1.02 Swagelok cone
- 1.03 O-ring grooves
- 1.04 Components correctly inserted
- 1.05 Soldering quality
- 1.06 O-rings

Before casting

☒
☒
☒
☒
☒

After casting

☒
☒

☒

2. Performance test:

2.01. Typical raw data reading in air for range: 0 - 700 kPa: (155-175)

0 - 3500 kPa: (30-60)

0 - 7000 kPa: (20-50)

0 - 20 MPa: (10-40)

0 - 60 MPa: (10-40)

.....☐
.....☐
.....☐
.....34.....☒
.....☐

2.02 Typical raw data reading at full range (Typical reading: 950-1010)

2.03 Maximum temperature drift over the range -5 to +40 °C (max: ±2 LSB)

.....1005.....
.....1.....

Date: 27/8-2003 Sign: Helge Solhveit

3. Calibration:

This sensor is calibrated against a Budenberg dead weight tester. Sensor accuracy better than ±0.25% of range. This is an absolute pressure sensor. Pressure range:

0 - 700 kPa (0 - 101.5 psi)

0 - 3500 kPa (0 - 507.6 psi)

0 - 7000 kPa (0 - 1015.2 psi)

0 - 20 MPa (0 - 2901.0 psi)

0 - 60 MPa (0 - 8702.0 psi)

☐
☐
☐
☒
☐

Pressure, Bar MPa	<u>0,101</u>	<u>5,108</u>	<u>10,114</u>	<u>15,120</u>	<u>20,126</u>
Raw data reading (N)	<u>37</u>	<u>281</u>	<u>524</u>	<u>767</u>	<u>1007</u>

Calibration formula: Pressure (^{MPa}Bar) = A + BN + CN² + DN³

Calculated coefficients:

A: -6,518E-01

B: 2,043E-02

C: 2,003E-07

D: 0

Installation:

Special care should be taken when installing the sensor to prevent damage to the O-rings. If necessary, grease the O-rings. Coat the threads near the Top End-Plate after installation with TECTYL 506 to prevent crevice corrosion.

Date: 1/9-2003 Sign: Pau Argemes



AANDERAA
INSTRUMENTS

5852 Bergen, Norway. Tel. +47 55 10 99 00

Test and Calibration Sheet

Pressure Sensor 3815A ☐
Pressure Sensor 3815B ☒
Pressure Sensor 3815C ☐
Pressure Sensor 3815D ☐
Pressure Sensor 3815E ☐
Serial No: 598

1. Visual and Mechanical Checks:

- 1.01 Treads
- 1.02 Swagefok cone
- 1.03 O-ring grooves
- 1.04 Components correctly inserted
- 1.05 Soldering quality
- 1.06 O-rings

Before casting



After casting



2. Performance test:

2.01. Typical raw data reading in air for range: 0 - 700 kPa: (155-175)

0 - 3500 kPa: (30-60)

0 - 7000 kPa: (20-50)

0 - 20 MPa: (10-40)

0 - 60 MPa: (10-40)

32
1006
1

2.02 Typical raw data reading at full range (Typical reading: 950-1010)

2.03 Maximum temperature drift over the range -5 to +40 °C (max: ±2 LSB)

Date: 21/8-2003 Sign: Helge Soltveit

3. Calibration:

This sensor is calibrated against a Budenberg dead weight tester. Sensor accuracy better than ±0.25% of range. This is an absolute pressure sensor. Pressure range:

- 0 - 700 kPa (0 - 101.5 psi)
- 0 - 3500 kPa (0 - 507.6 psi)
- 0 - 7000 kPa (0 - 1015.2 psi)
- 0 - 20 MPa (0 - 2901.0 psi)
- 0 - 60 MPa (0 - 8702.0 psi)



Pressure, Bar	kPa	100,7	801,6	1702,7	2503,7	3404,9
Raw data reading (N)		35	237	496	724	980

Calibration formula: Pressure (Bar) = $A + BN + CN^2 + DN^3$

Calculated coefficients:

- A: -2.015E+01
- B: 3.456E+00
- C: 4.032E-05
- D: 0

Installation:

Special care should be taken when installing the sensor to prevent damage to the O-rings. If necessary, grease the O-rings. Coat the threads near the Top End-Plate after installation with TECTYL 506 to prevent crevice corrosion.

Date: 26/8-2003 Sign: Rana Dagmar



AANDERAA
INSTRUMENTS

5852 Bergen, Norway. Tel. +47 55 10 99 00

Test and Calibration Sheet

Pressure Sensor 3815A ☐
Pressure Sensor 3815B ☒
Pressure Sensor 3815C ☐
Pressure Sensor 3815D ☐
Pressure Sensor 3815E ☐
Serial No: 597...

1. Visual and Mechanical Checks:

- 1.01 Treads
- 1.02 Swagelok cone
- 1.03 O-ring grooves
- 1.04 Components correctly inserted
- 1.05 Soldering quality
- 1.06 O-rings

Before casting



After casting



2. Performance test:

2.01. Typical raw data reading in air for range: 0 - 700 kPa: (155-175)

0 - 3500 kPa: (30-60)

0 - 7000 kPa: (20-50)

0 - 20 MPa: (10-40)

0 - 60 MPa: (10-40)

31
1002
1

2.02 Typical raw data reading at full range (Typical reading: 950-1010)

2.03 Maximum temperature drift over the range -5 to +40 °C (max: ±2 LSB)

Date: 21/8-2003 Sign: Helge Solhveit

3. Calibration:

This sensor is calibrated against a Budenberg dead weight tester. Sensor accuracy better than ±0.25% of range. This is an absolute pressure sensor. Pressure range:

- 0 - 700 kPa (0 - 101.5 psi)
- 0 - 3500 kPa (0 - 507.6 psi)
- 0 - 7000 kPa (0 - 1015.2 psi)
- 0 - 20 MPa (0 - 2901.0 psi)
- 0 - 60 MPa (0 - 8702.0 psi)



Pressure, Bar	100,7	801,6	1702,7	2503,7	3404,9
Raw data reading (N)	34	235	493	722	976

Calibration formula: Pressure (Bar) = A + BN + CN² + DN³

Calculated coefficients:

A: -1.613E+01

B: 3.464E+00

C: 4.079E-05

D: 0

Installation:

Special care should be taken when installing the sensor to prevent damage to the O-rings. If necessary, grease the O-rings. Coat the threads near the Top End-Plate after installation with TECTYL 506 to prevent crevice corrosion.

Date: 26/8-2003 Sign: Ron Dagmar