



GE Energy

## Functional Testing Specification

Parts & Repair Services  
Louisville, KY

LOU-GEF-SPPC1

### Test Procedure for SPPC1 Printed Circuit Board for a 1050HL Control

**DOCUMENT REVISION STATUS:** Determined by the last entry in the "REV" and "DATE" column

REV.	DESCRIPTION	SIGNATURE	REV. DATE
A	Initial release	R. Diercks	01/21/2011
B			
C			

© COPYRIGHT GENERAL ELECTRIC COMPANY

Hard copies are uncontrolled and are for reference only.

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

<b>PREPARED BY</b> Rick Diercks	<b>REVIEWED BY</b>	<b>REVIEWED BY</b>	<b>QUALITY APPROVAL</b> <i>Charlie Wade</i>
<b>DATE</b> 01/21/2011	<b>DATE</b>	<b>DATE</b>	<b>DATE</b> 1/24/2011

<p><b>LOU-GEF-SPPC1 REV. A</b></p>	<p><b>g</b></p> <p><b>GE Energy</b> Parts &amp; Repair Services Louisville, KY</p>	<p><b>Page 2 of 6</b></p>
--	--	---------------------------

Functional test procedure for 1050HL SPPC1 44A294562-G01 Printed Circuit Board

## 1. SCOPE

1.1 The instructions apply to all SPPC1 boards in test.

## 2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

## 3. APPLICABLE DOCUMENTS

3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.

- 3.1.1 **GEK-25345 1050HLX Blue Book Manual**
- 3.1.2 **GEK-84815 Test instructions**
- 3.1.3 **GEK-25346 Board Diagrams for 1050HLX boards.**
- 3.1.4 **44C704931 SPPC1.1 Elementary**

## 4. ENGINEERING REQUIREMENTS

### 4.1 Description

4.1.1 The 1050 Control is a solid-state, integrated circuit controller/processor system using LSI circuits for data processing and control. The static logic circuits are arranged on modular, plug in, printed circuit boards, clearly identified by type. The circuit boards are mounted with functional grouping. In addition, a board identification number marks each rack slot.

### 4.2 Equipment Cleaning

4.2.1 Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to site specific SRA's for cleaning guidelines.

### 4.3 Equipment Inspection

4.3.1 Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:

- 4.3.1.1 Wires broken or cracked
- 4.3.1.2 Terminal strips / connectors broken or cracked
- 4.3.1.3 Loose wires
- 4.3.1.4 Components visually damaged
- 4.3.1.5 Capacitors leaking
- 4.3.1.6 Solder joints damaged or cold
- 4.3.1.7 Circuit board burned or de-laminated
- 4.3.1.8 Printed wire runs burned or damaged

## 5. EQUIPMENT REQUIRED

- 5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1	GE 1050HLX # H188669	Control with axis cart # H188770

## 6. TESTING

### 6.1 Purpose

- 6.1.1 To describe the procedure for testing the circuitry of the SPPC1 board using the 1050HLX simulator. Diagnostic Composed of 10 Sub-tests 00-09.
- 6.1.2 The SPPC1 Board is the 1050HIL Spindle Control/Axis board for all HL Control. Board has RAM Memory, ALU Functions, and Wave-shaper generation and interrupts. Monitors Spindle RPM Counter/Timing and Resolver angular position.

### 6.2 TESTING PROCESS

#### 6.3 Diagnostic Procedure

- 6.3.1 First make should PROM3 Diagnostic Board is in Rack Slot 14 and connect Axis/Spindle cables to PWM Cart. X Cable to X, Spindle to Y, and Z to Z
- 6.3.2 Remove the test SPPC1 board from slot 24 and insert the board to be tested.
- 6.3.3 Special Mode Switch should be on (UP).
- 6.3.4 Press "ON".
- 6.3.5 Monitor should display Diagnostic Page, remove all tests except Spindle Test. (tested can be removed by moving cursor up or down to highlight test to be removed press "Shift" and "Delete".
- 6.3.6 AC Spindle BRD 99 test should be left, Press "Cycle Start" to start testing Tests 1-09 run test for @ 1 hour. \*\*\* If board fails refer to GEK-84814 in 1050HLX Blue Book GEK-25345. If board passes continue test.
- 6.3.7 Depress "Shift" and "Clear" to stop test.
- 6.3.8 Test Spindle Operator-Aided Test
- 6.3.9 Remove AC Spindle BRD 99 Test (Shift and Delete).
- 6.3.10 Test Sub-Test 01 Spindle RPM Test

<p>LOU-GEF-SPPC1 REV. A</p>	<p><b>g</b></p> <p><b>GE Energy</b> Parts &amp; Repair Services Louisville, KY</p>	<p>Page 4 of 6</p>
---------------------------------	--	--------------------

- 6.3.11** To test Press “**SPCL 1**” display in bottom left corner INSERT NO? Enter in “**06**” depress “**enter**” Subtest NO? Enter in “**01**” depress “**enter**” Repeat test? Enter “**N**”. \*\*\* Refer to Diagnostic GEK-84814 page 42 for help.
- 6.3.12** Manually run the spindle to track the spindle RPM you can see count on Monitor under operator-aided display.
- 6.3.13** Depress “**Shift**” and “**Clear**” to stop test and Delete Sub-Test 01 (Sift and Delete)
- 6.3.14** Test Sub-Test 02 Spindle Resolver Test.
- 6.3.15** To test Press “**SPCL 1**” display in bottom left corner INSERT NO? Enter in “**06**” depress “**enter**” Subtest NO? Enter in “**02**” depress “**enter**” Repeat test? Enter “**N**”. \*\*\* Refer to Diagnostic GEK-84814 page 42 for help.
- 6.3.16** Manually run the spindle to track the spindle resolver angular position you can see count on Monitor under operator-aided display a smooth count rate from 0-999 in proportion to the amount of the spindle.
- 6.3.17** Depress Shift and Clear to stop test.
- 6.3.18** If Board passed all test continual to Part Program Test. **Turn Off Control.**

<p><b>LOU-GEF-SPPC1 REV. A</b></p>	<p><b>g</b></p> <p><b>GE Energy</b> Parts &amp; Repair Services Louisville, KY</p>	<p><b>Page 5 of 6</b></p>
--	--	---------------------------

#### **6.4 Part Program Test**

**6.4.1** Remove PROM3 Diagnostic Board Slot 14 and place in PROM3 Exec Board.

**6.4.2** Turn on Control

MSD must be stored in memory, Depress “**P3**” – MSD Editing Mode. Check to see if MSD is in memory if not enter it in.

##### **MSD Program**

```

00 0050 0054
01 0100 1000
02 0000 0000
03 1500 2525
04 2929 3131
05 1010 5066
06 0000 0000
07 0000 0000
08 1725 0000
09 2000 2500
10 0000 0000
11 0500 1500
12 1725 0000
13 0000 0000
14 0000 0000
15 0000 0000
29 0000 0000

```

**6.4.3** Turn Control Off, Switch Special Mode (UP).

**6.4.4** Turn Control on

**6.4.5** GOTO to Data then go to memory location 01 and add the following:

X at 01 enter 00.00

Z at 01 enter 00.00

**6.4.6** Enter in PART PROGRAM

**6.4.7** Depress “**PRGRAM**” Then “**SUB PG ←**” then “**Page down**”, then  
“**Curser down**” enter program name (like Test) depress “**enter**” then  
“**SUB PG →**” Enter in Program.

```

N10:  G94
N20:  G90
N30:  G01      X2 Z2 F25 M03 S500
N40:      X-2 Z-2 F50 M03 S1000
N50:      X0 Z0 F75 M03 S1500
N60:  G04      X10
N70:  G01      X2 Z2 F25 M04 S500
N80:      X-2 Z-2 F50 M04 S1000
N90:      X0 Z0 F75 M04 S1500
N100: G04      X10
N110: G25 P1 30 P2 100 P3 50 to 100 cycles
N120: M30

```

**6.4.8** Turn **off** Control

**6.4.9** Turn Control **on**

**6.4.10** Depress “**PRGRM**”

**6.4.11** Depress “**SUB PG ←**”

**6.4.12** Depress “**Enter**” to select program

**6.4.13** Depress “**SUB PG →**” (program should be displayed)

**6.4.14** Depress “**POSN**”

**6.4.15** Turn on AXIS Cart and enable XYZ (Y will be the Spindle)

**6.4.16** Depress “**AUTO**” then “**CYCLE START**”

**6.4.17** Part Program will run as many cycles that you entered in Program Block

**N110**

**6.4.18** After Cycles are complete Disable X Y Z Axis and turn off Axis Cart

**6.4.19** Turn Off Control and remove SPPC1 Board

**6.5 \*\*\*TEST COMPLETE \*\*\***

## **7. REFERENCE:**

**7.1** None at this time.