

**g**

GE Energy Services

**Functional Testing Specification**

*Inspection and Repair Services  
Louisville, KY*

**LOU-Woodward-5421146**


**Test Procedure for a Woodward Governor 5421-146-B**

**DOCUMENT REVISION STATUS:** Determined by the last entry in the "REV" and "DATE" column

REV.	DESCRIPTION	SIGNATURE	REV. DATE
A	Initial release	Paul Kelley	3/16/2004
B			
C			

© COPYRIGHT GENERAL ELECTRIC COMPANY

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

<b>PREPARED BY</b> Paul Kelley	<b>REVIEWED BY</b>	<b>REVIEWED BY</b>	<b>QUALITY APPROVAL</b> 
<b>DATE</b> 3/16/2004	<b>DATE</b>	<b>DATE</b>	<b>DATE</b> 3/17/04

## Functional test procedure for a 5421-146-B

### 1. SCOPE

1.1 This is a functional testing procedure for a Blade Driver Amplifier Card.

### 2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

### 3. APPLICABLE DOCUMENTS

3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.

3.1.1

### 4. ENGINEERING REQUIREMENTS

#### 4.1 Equipment Cleaning

4.1.1 Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.

#### 4.2 Equipment Inspection

4.2.1 Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:

4.2.1.1 Wires broken or cracked

4.2.1.2 Terminal strips / connectors broken or cracked

4.2.1.3 Loose wires

4.2.1.4 Components visually damaged

4.2.1.5 Capacitors leaking

4.2.1.6 Solder joints damaged or cold


4.2.1.7 Circuit board burned or de-laminated

4.2.1.8 Printed wire runs burned or damaged

### 5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
4		Fluke 85 DMM (or Equivalent)
1		+ and – 30 V DC Supply
2		0 to 15 V DC Supply

LOU-Woodward-5421146 REV. A	 <b>GE Energy Services</b> <i>Inspection and Repair Services</i> Louisville, KY	Page 3 of 6
--------------------------------	---	-------------


## 6. TESTING PROCESS

### 6.1 Setup

- 6.1.1** Hook up as shown in the diagram below in Fig.1 . You can use 3 meters as the diagram shows or use 1 meter and switch the meter common to the proper point as indicated.

### 6.2 Testing Procedure

- 6.2.1** With PS1 and PS2 at 0 V apply + - 15 V power to the board.
- 6.2.2** With meter 1 verify +12 V on TP24.
- 6.2.3** With meter 1 verify – 12 V on TP10.
- 6.2.4** Turn R1, R3, R5, R7 fully CW.
- 6.2.5** Turn R9, R13, R14, R15 fully CCW.
- 6.2.6** With meter 1 verify 0 V on TP6.
- 6.2.7** Short TP6 to ground.
- 6.2.8** Short pin 48 (TP1) to ground.
- 6.2.9** With meter 1 adjust R2 to obtain 0 V on TP2.
- 6.2.10** Remove short from TP6.
- 6.2.11** With meter 1 adjust R5 for 6.13 V on TP6.
- 6.2.12** With meter 2 adjust R1 for 0.00 V on TP2.
- 6.2.13** With meter 3 verify .80 V + - .02 V across 200 ohm resistor (between pins 71 and 72).
- 6.2.14** Remove short on pin 48 (TP1).
- 6.2.15** With PS 1 input –10.00 V to pin 48 (TP1).
- 6.2.16** With meter 2 verify 10 V + - .1 V on TP2.
- 6.2.17** With meter 2 adjust R1 for 10.00 V on TP2.
- 6.2.18** With meter 3 verify 4 V + - .03 V across 200 ohm resistor (between pins 71 and 72).
- 6.2.19** Remove PS1 volts applied to pin 48 (TP1).
- 6.2.20** Connect pin 48 (TP1) to PS1 ground.
- 6.2.21** With meter 1 adjust R6 for 0.00 V on TP7.
- 6.2.22** Connect TP7 to PS1 ground.
- 6.2.23** With meter 1 adjust R4 for 0.00 V on TP5.
- 6.2.24** Connect TP20 and TP16 to PS1 ground.

LOU-Woodward-5421146 REV. A	 <b>GE Energy Services</b> <i>Inspection and Repair Services</i> Louisville, KY	Page 4 of 6
--------------------------------	---	-------------


- 6.2.25** Connect TP11 to TP25.
- 6.2.26** Adjust R11 for 0.000 V on TP25.
- 6.2.27** Remove TP20 and TP16 from ground.
- 6.2.28** Remove pin 48 (TP1) from ground.
- 6.2.29** With PS1 input –5.0 V to pin 48 (TP1).
- 6.2.30** With meter 1 adjust R3 for 3.60 V on TP5.
- 6.2.31** Remove TP7 from ground.
- 6.2.32** With meter 1 adjust R6 for 5.00 V on TP7.
- 6.2.33** With meter 1 verify -3.4 V on TP5.
- 6.2.34** With meter 4 verify +16.9 V + - .3 V on pin 21 and –16.9 V + - .3 V on pin 24.
- 6.2.35** Set PS2 to 1.00 V.
- 6.2.36** With meter 1 verify 8.23 V + - .1 V on TP15.
- 6.2.37** With meter 4 verify +16.9 V + - .3 V on pin 5 and –16.9 V + - .3 V on pin 8.
- 6.2.38** With meter 1 verify .98 V + - .02 V on TP20.
- 6.2.39** With meter 4 verify +16.9 V + - .3 V on pin 13 and –16.9 V + - .3 V on pin 16.
- 6.2.40** With meter 1 verify 8.23 V + - .1 V on TP16.
- 6.2.41** Remove the PS1 1.00 V applied to pins 11 (TP9), 3 (TP19) and 19 (TP3) and connect these 3 pins to ground.
- 6.2.42** With meter 1 adjust R10 for 0.00 V on TP12.
- 6.2.43** Connect TP12 to PS1 ground.
- 6.2.44** With meter 1 verify 0 V on TP16.
- 6.2.45** Connect TP16 to PS1 ground.
- 6.2.46** With meter 1 adjust R8 for 0.00 v on TP23.
- 6.2.47** Remove grounds from TP12 and TP16 from ground.
- 6.2.48** With meter 1 adjust R10 for 8.23 V on TP12.
- 6.2.49** With meter 2 adjust R7 for 0.00 V on TP23.
- 6.2.50** With meter 3 verify .80 V across the 200 ohm resistor (between pins 67 and 68).
- 6.2.51** Remove ground from pins 11 (TP9), 3 (TP19) and 19 (TP3) and connect back to PS2.
- 6.2.52** Set PS2 voltage (approx - .83 V) to get 10.0 V on TP23 with meter 2.
- 6.2.53** With meter 3 verify 4 volts across 200 ohm resistor (between pins 67 and 68).
- 6.2.54** Using meter 1 verify 10.13 V + - .2 V on TP25.
- 6.2.55** Using meter 1 verify 10.13 V + - .2 V on TP21.

LOU-Woodward-5421146 REV. A	<b>g</b>  <b>GE Energy Services</b> <i>Inspection and Repair Services</i> <i>Louisville, KY</i>	Page 5 of 6
--------------------------------	---	-------------

- 6.2.56 Verify good contact closure between pins 42 and 41.
- 6.2.57 Connect pin 43 to PS1 ground
- 6.2.58 Verify good contact closure between pins 41 and 40.
- 6.2.59 With meter 1 verify 13.46 V + .2 V on TP21.
- 6.2.60 Remove the pin 43 to ground connection.
- 6.2.61 With meter 1 adjust R6 for 0.00 V on TP21.
- 6.2.62 With meter 1 adjust R15 for 0.80 V on TP21.
- 6.2.63 With meter 1 adjust R14 for 1.50 V on TP21.
- 6.2.64 With scope 1 adjust R13 for a 4 V PtoP signal on TP26.
- 6.2.65 Adjust R12 for 9.0 HZ on TP26.
- 6.2.66 Replace the jumper between TP25 and TP11 with a 100K resistor.
- 6.2.67 With meter 1 adjust R6 for –6.06 volts on TP7.
- 6.2.68 With a scope 1 adjust R6 for a centered signal on TP21.
- 6.2.69 Verify the signal is approx 6 V PtoP.
- 6.2.70 Verify a good contact closure between pins 35 and 36.
- 6.2.71 Verify a good contact closure between pins 33 and 32.
- 6.2.72 Connect pin 37 to pin 39.
- 6.2.73 Verify a good contact closure between pins 35 and 34
- 6.2.74 Verify a good contact closure between pins 33 and the junction of C20-R37.
- 6.2.75 Remove the pin 37 to 39 connection.
- 6.2.76 With meter 1 verify + 15 V on pin 38.
- 6.2.77 Verify a < .5 ohm connection between pins 29 and 27.
- 6.2.78 Verify a < .5 ohm connection between pins 27 and 44, 46, 52, 61, 62, 63, 64.
- 6.2.79 Verify a < .5 ohm connection between pins 17 and 18.
- 6.2.80 Verify a < .5 ohm connection between pins 69 and 70.
- 6.2.81 Verify a < .5 ohm connection between pins 55 and 56.
- 6.2.82 Verify a < .5 ohm connection between pins 1 and 2.
- 6.2.83 Verify a < .5 ohm connection between pins 9 and 10.
- 6.2.84 Verify a < .5 ohm connection between pins 30 and 31.
- 6.2.85 Verify a < .5 ohm connection between pins 65 and 66.
- 6.2.86 With meter 1 verify + 15 V on pin 45, 55, 56.
- 6.2.87 With meter 1 verify + 12 V on pin 47.
- 6.2.88 With meter 1 verify – 12 V on pin 49.
- 6.2.89 With meter 1 verify – 15 V on pin 50.

**6.3 \*\*\*TEST COMPLETE \*\*\***

**7. Drawings:**



**Fig. 1**