

g GE Canada

Electronic Products Repair

Test Instructions for

0621L0112 G001

Device Number

Six pulse non reversing speed current control card

Description of Device

Originated By: Dennis Cully
Typed Name

Date: June 8, 2005
mm/dd/yy

Approved By: Dennis Cully
Signature

Approval Date: June 8, 2005
mm/dd/yy

TEST INSTRUCTIONS

PREVIOUS REVISION SHEET

0621L0112 G001

Device Number

Six pulse non reversing speed current control card

Description of Device

[illegible]

TEST INSTRUCTIONS

g

Location: Book or file File

Six pulse non reversing speed current control card
0621L0112 G001
Date: June 8, 2005

Pg.: 3/13

1. PURPOSE:

- a. Static and dynamic test procedures for Six pulse non reversing speed current control card 0621L0112 G001

2. ELEMENTARY:

- a. S & C Data Book 1190 Section 112 drawing number 0238A2965

3. EQUIPMENT:

- a. Stationary Super card Test box - TL #00363 or equivalent. [SP3000/3100 Test Dive](#)
- b. Oscilloscope [TEK 460A H192009](#)
- c. Multi meter HP [or Fluke](#) - or equivalent.
- d. Interface DII card 0621L0110 – 113. [TL # 00913](#)
- e. Resistor 2.7M.
- f. Resistor 100K Ω . $\frac{1}{2}$ W.
- g. Power Supply –
- h. 115/21 VACCT isolation transformer TL# 847-TM002

4. SET UP:

- a. Connect

- i. 0° to cp031
- ii. 60° to cp033
- iii. 120° to cp035
- iv. 180° to cp032
- v. 240° to cp034
- vi. 300° to cp036
- vii. ACOM to cp037
- viii. \emptyset 1 acct. f1 to cp051
- ix. \emptyset 1 acct. f2 to cp052
- x. \emptyset 2 acct. f1 to cp053
- xi. \emptyset 2 acct. f2 to cp054
- xii. \emptyset 3 acct. f1 to cp055
- xiii. \emptyset 3 acct. f2 to cp056
- xiv. P1fg to cp001
- xv. P1fc to cp002
- xvi. P2fg to cp003
- xvii. P2fc to cp004
- xviii. P3fg to cp005
- xix. P3fc to cp006
- xx. N1fg to cp007
- xxi. N1fc to cp008

TEST INSTRUCTIONS

gg

Location: Book or file File

Six pulse non reversing speed current control card
0621L0112 G001
Date: June 8, 2005

Pg.: 4/13

- xxii. N2fg to cp009
- xxiii. N2fc to cp010
- xxiv. N3fg to cp011
- xxv. N3fc to cp012
- b. Insert interface card for 0621L0112 G001 into cr. 2.
- c. Check switch positions.
 - i. Switch 1 out.
 - ii. Switch 2 out.
 - iii. Switch 3 out.
 - iv. Switch 4 in.
 - v. Switch 5 out.
 - vi. Switch 6 out.
 - vii. Switch 7 out.
 - viii. Switch 8 out.
 - ix. Set IEC switch to 3000
- d. Set all unsealed potentiometers CCW.
- e. Set both M1 and M2 field potentiometers CCW.

5. PROCEDURE:

- a. Static Tests
 - i. Apply 3-phase AC power with CB1 up.
 - ii. DC. Power
 - 1. + 15 VDC \pm 1.5 VDC between 1TB35 (+) and 1TB37 (-) < 300 MV ripple P / P.
 - 2. - 15 VDC \pm 1.5 VDC between 1TB39 (-) and 1TB37 (+) < 300 MV ripple P / P.
 - 3. + 10 VDC \pm 500 MV between 1TB36 (+) and 1TB37 (-) < 30 MV ripple P / P.
 - 4. - 10 VDC \pm 500 MV between 1TB38 (-) and 1TB37 (+) < 30 MV ripple P / P.
 - 5. + 5 VDC \pm 300 MV between cp110 (+) and 1TB37 (-) < 30 MV ripple P / P.
 - iii. AC. Input Power (Drawing 0238A2965 pg. 10)
 - 1. Apply 3-phase AC power with CB1 up.
 - 2. With oscilloscope observe inputs of 28 to 34 VAC P / P. (Use Ø1 and Ø2 in differential mode to compare the other positions).
 - a. Cp031 is 0°
 - b. Cp032 is 180°
 - c. Cp033 is 60°
 - d. Cp034 is 240°
 - e. Cp035 is 120°
 - f. Cp036 is 300°
- g. Observe phase shift inputs of 22 to 26 VAC. P / P. (Use Ø1 and Ø2 in differential mode to compare the other positions).
 - i. Cp112 is 30°

TEST INSTRUCTIONS

gg

Location: Book or file File

Six pulse non reversing speed current control card
0621L0112 G001
Date: June 8, 2005

Pg.: 5/13

- ii. Cp113 is 210°
- iii. Cp114 is 90°
- iv. Cp115 is 270°
- v. Cp116 is 150°
- vi. Cp117 is 330°
- iv. Phase Rotation Circuit (Drawing 0238A2965 pg. 9)
 - 1. With the 3-phase AC power applied in the correct sequence L180 should be illuminated.
 - 2. Reverse 0° and 180°
 - a. L180 goes out when one lead is off
 - b. L100 illuminates.
 - 3. Replace 0° and 180°
 - a. L180 is illuminated and L100 stays illuminated until PB100 is pressed and released.
- v. Reset (Drawing 0238A2965 pg. 8)
 - 1. Set the suicide switch to static
 - 2. Depress PB100.
 - 3. IEC relay picks up.
 - 4. Release PB100.
 - a. IEC relay drops out
 - b. Cp106 is $+ 250 \text{ MVDC} \pm 100 \text{ MV}$.
 - c. L100 is extinguished.
- vi. Phase Loss and Relay Driver (Drawing 0238A2965 pg. 8 and 9)
 - 1. Remove 0° from cp031.
 - a. IEC relay picks up
 - b. Cp106 goes to $-15 \text{ VDC} \pm 100 \text{ MV}$.
 - c. L100 illuminates.
 - 2. Replace 0° to cp031
 - 3. Depress and release PB100.
 - a. Relay drops out
 - b. Cp106 goes to $+ 250 \text{ MVDC} \pm 100 \text{ MV}$.
 - c. L100 extinguishes.
 - 4. Repeat with 120° on cp035.
 - 5. Repeat with 240° on cp034.
- vii. Ramp Circuit
 - 1. Zero
 - a. Place suicide to static.
 - b. Adjust R1 & R2 CW
 - c. Disconnect cp071 from cp099.
 - d. Connect a $2.7 \text{ M}\Omega$ resistor between 1TB3 and 1TB4.
 - e. Connect cp99 to ground.
 - f. Adjust output on 1TB4 to $0 \text{ VDC} \pm 10 \text{ MV}$ with R19.
 - g. Reconnect all changes.
 - 2. Positive Ramp and Suicide (Maximum Ramp Rate)
 - a. Apply $+ 10 \text{ VDC}$ to 1TB1 with switch 5 out and R10 CW.

TEST INSTRUCTIONS

gg

Location: Book or file File

Six pulse non reversing speed current control card
0621L0112 G001
Date: June 8, 2005

Pg.: 6/13

- b. Set suicide switch to off (middle) to disconnect 1TB5 from 1TB37 (ACOM.)
- c. Ensure that the voltage on cp071 or 1TB6 is < -10 VDC (R1)
- d. Set suicide switch to static to connect 1TB5 to 1TB37 (ACOM.)
- e. Ensure that the voltage on 1TB4 ramps to $+10$ VDC ± 400 MV in 500 milliseconds ± 15 milliseconds.
- f. Set suicide switch to off to disconnect 1TB5 from 1TB37 (ACOM.)
- g. Output on 1TB4 should snap to 0 VDC ± 10 MV.
- 3. Negative Ramp and Suicide (Maximum Ramp Rate)
 - a. Apply -10 VDC to 1TB1 with switch 5 in and R10 CW.
 - b. Set suicide switch to off (middle) to disconnect 1TB5 from 1TB37 (ACOM.)
 - c. Ensure that the voltage on cp071 is $> +10$ VDC.
 - d. Set suicide switch to static to connect 1TB5 to 1TB37 (ACOM.)
 - e. Ensure that the voltage on 1TB4 ramps to -10 VDC ± 400 MV in 500 milliseconds ± 15 milliseconds.
 - f. Set suicide switch to off (middle) to disconnect 1TB5 from 1TB37 (ACOM.)
 - g. Output on 1TB4 should snap to 0 VDC ± 10 MV.
- 4. Minimum Ramp Rate
 - a. Set R1 and R2 CCW.
 - b. Apply $+10$ VDC to 1TB1 with switch 5 out and R10 CW.
 - c. Set suicide switch to static to connect 1TB5 to 1TB37 (ACOM.)
 - d. Ensure that the voltage on 1TB4 ramps to $+10$ VDC ± 400 MV in 9 seconds ± 2 seconds.
 - e. Set suicide switch to off to disconnect 1TB5 from 1TB37 (ACOM.)
 - f. Output on 1TB4 should snap to 0 VDC ± 10 MV.
 - g. Apply -10 VDC to 1TB1 with switch 5 in.
 - h. Set suicide switch to static to connect 1TB5 to 1TB37 (ACOM.)
 - i. Ensure that the voltage on 1TB4 ramps to -10 VDC ± 400 MV in 9 seconds ± 2 seconds.
 - j. Set suicide switch to off to disconnect 1TB5 from 1TB37 (ACOM.)
 - k. Output on 1TB4 should snap to 0 VDC ± 10 MV.
- viii. Auxiliary op. / amp.
 - 1. IC 44
 - a. Connect 1TB25 to 1TB37 (ACOM.).
 - b. Output on 1TB26 should be 0 V ± 40 MV.
 - c. Connect 1TB1 to 1TB25
 - d. Apply $+10$ VDC with R10 CW, switch 5 out and switch 1 out.
 - e. Output on 1TB26 should be -10 VDC ± 240 MV.
 - f. Apply -10 VDC with R10 CW and switch 5 in.
 - g. Output on 1TB26 should be $+10$ VDC ± 240 MV.
 - h. Return R10 CCW.
 - 2. IC 45
 - a. Output on 1TB28 should be 0 V ± 40 MV (Plus the offset of IC 44).

TEST INSTRUCTIONS

gg

Location: Book or file File

Six pulse non reversing speed current control card
0621L0112 G001
Date: June 8, 2005

Pg.: 7/13

- b. Apply + 10 VDC with R10 CW and switch 5 out.
- c. Output on 1TB28 should be + 10 VDC \pm 500 MV.
- d. Apply - 10 VDC with switch 5 in.
- e. Output on 1TB28 should be - 10 VDC \pm 500 MV.
- f. Disconnect 1TB1 to 1TB25.
- ix. Speed Regulator Amplifier (Drawing 0238A2965 pg. 2)
 - 1. Zero IC 40
 - a. Ensure that the voltage on 1TB18 is - 10 VDC \pm 500 MV
 - b. Ensure that the voltage on 1TB19 is + 10 VDC \pm 500 MV.
 - c. Adjust R3 and R7 CW
 - d. Adjust R4 to R6 CCW.
 - e. Set suicide to static to connect 1TB21 to 1TB37 (ACOM.)
 - f. Put a 2.7M Ω resistor between 1TB8 and 1TB16.
 - g. Remove 1TB07.
 - h. Apply 0 VDC to 1TB9 with switch 2 out and R10 CCW.
 - i. Adjust voltage on 1TB16 to 0 VDC \pm 10 MV with R15.
 - j. Remove a 2.7M Ω resistor from 1TB8 and 1TB16.
 - k. Reconnect 1TB07.
 - 2. Current Limit
 - a. Adjust R10 to apply + 10 VDC to 1TB9 with switch 5 out, switch 2 out and R5 CCW.
 - b. Set suicide switch to static which will connect 1TB21 to 1TB37 (ACOM.)
 - c. Output on 1TB16 should be - 500 MVDC \pm 100 MV.
 - d. Adjust R5 CW
 - e. Output on 1TB16 should increase to -10.85 VDC \pm 800 MV.
 - f. Set suicide switch to off (middle) which will disconnect 1TB21 from 1TB37 (ACOM.)
 - g. Apply - 10 VDC to 1TB9 with switch 5 in, switch 2 out and R6 CCW.
 - h. Set suicide switch to static which will connect 1TB21 to 1TB37 (ACOM.)
 - i. Output on 1TB16 should be 500 MVDC \pm 100 MV.
 - j. Adjust R6 CW
 - k. Output on 1TB16 should increase to + 10.85 VDC \pm 800 MV.
 - l. Set suicide switch to off which will disconnect 1TB21 from 1TB37 (ACOM.)
 - 3. Maximum Speed Potentiometer Response
 - a. Apply + 10 VDC to 1TB9 with switch 2 & 5 out, R03 CCW, R5 & R6 CW.
 - b. Jumper 1TB8 to 1TB16
 - c. Set suicide switch to static which will connect 1TB21 to 1TB37 (ACOM.)
 - d. Output on 1TB16 should be - 9 VDC \pm 500 MV.
 - e. Adjust R3 CW
 - f. Output on 1TB16 should increase to -11 VDC \pm 1 V (Max Speed)
 - g. Set 1TB14 to -10 VDC with R7.
 - h. The voltage on 1TB 15 should be + 10 VDC \pm 40 MV.
 - i. Apply - 10 VDC to 1TB9 with switch 5 in, switch 2 out and R3 CCW.
 - j. Output on 1TB16 should be + 9 VDC \pm 500 MV.

TEST INSTRUCTIONS

69

Location: Book or file File

Six pulse non reversing speed current control card
0621L0112 G001
Date: June 8, 2005

Pg.: 8/13

- k. Adjust R3 CW.
- l. Output on 1TB16 should increase to $+ 11 \text{ VDC} \pm 1 \text{ V}$ (Max Speed.)
- m. Observe $+ 10 \text{ VDC}$ on 1TB14.
- n. The voltage on 1TB 15 should be $- 10 \text{ VDC} \pm 40 \text{ MV}$.
- o. Return R5 and R6 CCW.
- p. Remove 1TB8 from 1TB16.
- q. Set suicide switch to off (middle).
- 4. Current Regulator Amplifier (Drawing 0238A2965 pg. 3)
 - a. Zero
 - i. Put a $2.7\text{M}\Omega$ resistor between 1TB13 and 1TB34.
 - ii. Set switch 3 & 5 out and R10 CCW.
 - iii. Remove both 1TB12 and the jumper on CP77 – CP78.
 - iv. Connect cp120 to cp121, cp122 to cp123, cp126 to cp127, cp079 to cp080, and cp73 to cp74.
 - v. Set suicide switch to static to connect 1TB20 to 1TB37 (ACOM).
 - vi. Adjust output of 1TB34 to $0 \text{ VDC} \pm 10 \text{ MV}$ with R016. Adjust R16 in small increments. Allow oscillations to die down then continue to adjust R16.
 - b. Functionality
 - i. Remove a $2.7\text{M}\Omega$ resistor
 - ii. Connect a $100\text{K}\Omega$ resistor from 1TB23 to 1TB34.
 - iii. Turn R12 and R13 CCW.
 - iv. Remove jumper from CP73-CP74.
 - v. Connect 1TB44 to 1TB1 with switch 3 & 5 out and R10 CCW.
 - vi. Apply $+ 1 \text{ VDC}$ to 1TB44 with R10 CW.
 - vii. Set suicide switch to static to connect 1TB20 to 1TB37 (ACOM.)
 - viii. Output on 1TB34 should be -0.5 VDC (D176) and 1TB23 should be $\approx 0\text{VDC} \pm 100\text{MV}$.
 - ix. Apply $- 1 \text{ VDC}$ to 1TB44 with switch 5 in and R10 CW.
 - x. Output on 1TB34 should be $> + 10 \text{ VDC}$
 - xi. Output on 1TB23 should be $0\text{VDC} \pm 100 \text{ MV}$.
 - xii. Lower the voltage on 1TB44 until the output is $+ 10 \text{ VDC}$
 - xiii. The voltage on 1TB23 should be $0 \text{ VDC} \pm 10 \text{ MV}$.
 - xiv. Set suicide switch to off to disconnect 1TB20 from 1TB37 (ACOM.)
 - xv. Ensure that 1TB34 snaps to $0 \text{ VDC} \pm 10 \text{ MV}$.
 - xvi. Remove a $100\text{K}\Omega$ resistor from 1TB23 to 1TB34.
 - xvii. Replace the jumper from CP73 to CP74 and CP77 to CP78.
 - xviii. Reconnect 1TB12.
- x. Auxiliary Functions (Drawing 0238A2965 pg. 4)
 - 1. Ensure that the voltage on cp129 is $+ 10 \text{ VDC} \pm 500 \text{ MV}$.
 - 2. Ensure that the voltage on cp131 is $- 10 \text{ VDC} \pm 500 \text{ MV}$.
 - 3. Turn R17 and R18 CCW.
 - 4. Connect cp130 to cp131.
 - 5. Connect 1TB24 to 0 VDC with switch 5 out and R9 CCW.

TEST INSTRUCTIONS

gg

Location: Book or file File

Six pulse non reversing speed current control card
0621L0112 G001
Date: June 8, 2005

Pg.: 9/13

6. Voltage on cp030 should be $0 \text{ VDC} \pm 55 \text{ MV}$.
7. Voltage on cp040 should be $0 \text{ VDC} \pm 60 \text{ MV}$.
8. Voltage on cp041 should be $0 \text{ VDC} \pm 80 \text{ MV}$.
9. Adjust R18 CW.
10. Cp041 should be $- 2.1 \text{ VDC} \pm 800 \text{ MV}$.
11. Adjust R17 CW.
12. Cp041 should be $- 10.5 \text{ VDC} \pm 1.8 \text{ V}$.
13. Connect cp131 to cp132
14. Turn R18 CW
15. Turn R17 CCW.
16. Jumper 1TB1 to 1TB24
17. Turn R10 CW to apply $+ 10 \text{ VDC}$ to 1TB24 with switch 5 out.
18. Output on cp040 should be $0 \text{ VDC} \pm 2.2 \text{ V}$.
19. Disconnect 1TB1 from 1TB24.
20. Set R18 CCW.
21. Move jumper from CP131-132 to CP129-132
22. Output on cp040 should be $0 \text{ VDC} \pm 3.3 \text{ VDC}$.
23. Put a jumper between cp029 and cp030
24. Output of CP40 should be $- 2.2 \text{ VDC} \pm 320 \text{ MV}$ when R18 CW.
25. Turn R17 CW.
26. Voltage on cp041 should be $+ 10.5 \text{ VDC} \pm 1.8 \text{ V}$.
27. Return R10 CCW.
28. Disconnect CP29 from CP30
29. Disconnect CP129 from CP132
30. Set switch 5 in.
31. Connect cp042 to 1TB1.
32. Slowly turn R10 CW until the voltage between 1TB43 and 1TB39 becomes 0VDC (voltage at CP42 is about $- 1.5 \text{ VDC}$).
33. Connect a 24-volt relay coil to 1TB43 (+) and 1TB39 (-).
34. Turn R10 CCW.
35. Output between 1TB43 and 1TB39 should be $+ 25 \text{ VDC} \pm 3 \text{ V}$.
36. Return R10 CCW.
37. Remove jumper from cp042 and 1TB1.

xi. Stall Function

1. Jumper cp043 to 1TB1
2. Apply $+ 1 \text{ VDC}$ with R10 CW to $+ 1 \text{ VDC}$.
3. Output on cp044 should be $- 10 \text{ VDC} \pm 200 \text{ MV}$.
4. Remove jumper from 1TB1 from CP43.
5. Connect 1TB1 to 1TB41.
6. Voltage on cp044 should be $- 1 \text{ VDC} \pm 40 \text{ MV}$
7. Readjust R10 to attain $+ 1 \text{ VDC}$ at 1TB1-1TB41 due to load of the potentiometer within interface card.
8. Repeat the above procedure for 1TB42 and the result should be the same.

TEST INSTRUCTIONS

gg

Location: Book or file File

Six pulse non reversing speed current control card
0621L0112 G001
Date: June 8, 2005

Pg.: 10/13

9. Remove the jumper from 1TB42
10. Turn R10 CCW.
- xii. Current Feedback (Drawing 0238A2965 pg. 5)
 1. Forward
 - a. Apply 10 VAC with an isolation transformer (TL # 847 - TM002) between the following:
 - i. Cp051 and cp052
 - ii. Cp053 and cp054
 - iii. Cp055 and cp056.
 - b. Measure + 8.3 VDC \pm 200 MV on 1TB42 for each set of "a"
 - c. Voltage on 1TB22 should + 8.3 VDC \pm 280 MV.
 2. Reverse
 - a. N / A
- xiii. Lockout
 1. Forward
 - a. Voltage on CP98 should be – 6.9 VDC \pm 500 MV.
 - b. Connect the power supply between 1TB42 (+) and 1TB37 (-ACOM)
 - c. Increase the voltage on 1TB42 until the IEC trips at + 10 VDC \pm 1.2 VDC
 2. Reverse
 - a. N/A
- xiv. Gate Pulse Generator (Drawing 0238A2965 pg. 6 and 7)
 1. Forward
 - a. Remove jumper from cp079 and cp080.
 - b. Set suicide switch to static to connect 1TB20 to 1TB37 (ACOM.)
 - c. Jumper 1TB1 to 1TB34.
 - d. Turn R10 CCW & put switch 5 out to apply 0 VDC on 1TB34.
 - e. Output on the following should be + 15 VDC \pm 1.5 V.
 - i. Cp085
 - ii. Cp086
 - iii. Cp087
 - iv. Cp088
 - v. Cp089
 - vi. Cp090
 - f. Apply + 8 VDC to 1TB34 with R10 CW.
 - g. Measure pulses with oscilloscope (comparing channel 1 on 0° with channel 2) on cp085 (P1), cp086 (P2), cp086 (P3), cp088 (N1), cp089 (N2) and cp090 (N3). Each pulse width should be 375 μ seconds \pm 100 μ seconds.
 - i. P1 occurs at 120° @ 5.5ms
 - ii. P2 occurs at 240° @ 11ms
 - iii. P3 occurs at 0°

TEST INSTRUCTIONS

gg

Location: Book or file File

Six pulse non reversing speed current control card
0621L0112 G001
Date: June 8, 2005

Pg.: 11/13

iv. N1 occurs at 300° @ 13.8ms

v. N2 occurs at 60° @ 2.8ms

vi. N3 occurs at 180° @ 8.35ms

h. Disconnect 1TB1 from 1TB34

i. Connect 1TB34 to 1TB35.

j. Pulses should appear as above, but at the following positions with the same pulse width.

i. P1 occurs at 60° @ 2.8ms

ii. P2 occurs at 180° @ 8.35ms

iii. P3 occurs at 300° @ 13.8ms

iv. N1 occurs at 240° @ 11ms

v. N2 occurs at 0°

vi. N3 occurs at 120° @ 5.5ms

k. Retard limit:

i. N / A

l. Disconnect 1TB34 from 1TB35.

m. Disconnect 3-phase power with CB1 down.

n. Reattach CP79 to CP80.

o. Seal R15, R16 and R19.

2. Reverse

a. N / A

b. Dynamic Tests

i. Setup

1. Switch 1 out.
2. Switch 2 in.
3. Switch 3 in.
4. Suicide switch to dynamic
5. Switch 5 in.
6. Switch 6 in.
7. Switch 7 in.
8. Switch 8 in.
9. Select switch to 6p
10. IEC switch to 3000
11. PS switch to N. C.
12. ϕ L switch to N. C.
13. VFBK switch to N. C.
14. M1 FLD to internal.
15. Suicide switch to dynamic.
16. R1-3, R7, R10 CW
17. R4, R11 Middle
18. R5, R6, R9 CCW
19. R12 & R13 1/8 Back from CW
20. Turn M2 field potentiometer CCW

TEST INSTRUCTIONS

gg

Location: Book or file File

Six pulse non reversing speed current control card
0621L0112 G001
Date: June 8, 2005

Pg.: 12/13

21. M1 field potentiometer to 40%.
22. FEX switch to INT-M2
23. KS-M2 Bridge
24. KS-M1 Load
- ii. AC. Input Power
 1. Put oscilloscope leads on current (1TB22).
 2. Apply 3-phase power with CB1 up.
- iii. Current Limit
 1. Forward
 - a. Put suicide switch to dynamic.
 - b. Turn M1 field potentiometer CW to 40%.
 - c. M2 field potentiometer CCW.
 - d. Press Start.
 - e. Voltage on 1TB22 should be $+ 500 \text{ MVDC} \pm 500 \text{ MV}$.
 - f. Increase voltage on 1TB22 to $+ 7.5 \text{ VDC}$ by slowly rotating R6 CW.
 - g. M2.armature ampere meter should read $+ 10 \text{ ADC} \pm 1 \text{ A}$.
 - h. Put suicide switch to off.
 2. Reverse
 - a. N / A
- iv. Drive Power
 1. Set R10 CCW
 2. M2 to 100%
 3. Set suicide switch to dynamic.
 4. Slowly turn R10 CW until M2 armature volts = 180 VDC (equal to - 10 VDC on 1TB1)
 5. Turn R3 CCW to vary the motor speed.

6. UPGRADES:

- a. Since we are not sure of the latest revision status let's use REV. 5.
- b. Ensure that all components circled in the schematics are the correct values. (R190, C215 and R035 from pg. 001; R038 from pg. 002; R065 from pg. 003; C150, C151 and C152 from pg. 004; R253, R254 and Z100 from pg. 008; C180, R183 and R185 from pg. 009; R210 and R211 from pg. 010; R220 to R225 from pg. 011).
- c. **REFERENCE RAMP**

TEST INSTRUCTIONS

g

Location: Book or file File

Six pulse non reversing speed current control card
0621L0112 G001
Date: June 8, 2005

Pg.: 13/13

- | | | | |
|-------------------------------|----------------|----------------|----------------|
| | i. R35 | 1K | 0177A1001 P049 |
| | ii. R190 | 47 | 0177A1001 P017 |
| | iii. C215 | 0.047 μ F | 0177A1049 P021 |
| d. SPEED REGULATOR | | | |
| | i. R38 | 1K | 0177A1001 P049 |
| e. CURRENT REGULATOR | | | |
| | i. R65 | 1K | 0177A1001 P049 |
| f. AUXILLARY FUNCTIONS | | | |
| | i. C150 | 0.0047 μ F | 0177A1049 P009 |
| | ii. C151, C152 | 0.1 μ F | 0177A1283 P016 |
| g. IEC | | | |
| | i. Z100 | 1N961B, 10V | 0177A1090 P008 |
| h. PHASS LOSS | | | |
| | i. C180 | 2.2 μ F | 0177A1270 P035 |
| | ii. R183, R185 | 47K | 0177A1001 P089 |
| i. POWER SUPPLY | | | |
| | i. R210, R211 | 47 | 0177A1001 P017 |
| j. SNUBBERS | | | |
| | i. R220-225 | 40 | 0177A1030 P015 |
7. END.