

g

GE Industrial Systems

Functional Testing Specification

*Renewal Services
Louisville, KY*

LOU-GED-IC3650MISC


Test Procedure for Miscellaneous IC3650 cards

DOCUMENT REVISION STATUS: Determined by the last entry in the "REV" and "DATE" column

REV.	DESCRIPTION	SIGNATURE	REV. DATE
A	Initial release	D.Laemmle	9/18/02
B			
C			

© COPYRIGHT GENERAL ELECTRIC COMPANY

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

PREPARED BY D. Laemmle	REVIEWED BY	REVIEWED BY	QUALITY APPROVAL 
DATE 09/18/02	DATE	DATE	DATE 10/16/02

Functional test procedure for a Card

1. SCOPE

1.1 This is a functional testing procedure for a Card.

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.

3.1.1 **259A2101 – Test Instruction for IC3655A117**

3.1.2 **PGEI-1430 – LodTrak Calibration Instructions**

4. ENGINEERING REQUIREMENTS

4.1 Equipment Cleaning

4.1.1 Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.

4.2 Equipment Inspection

4.2.1 Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:

4.2.1.1 Wires broken or cracked

4.2.1.2 Terminal strips / connectors broken or cracked

4.2.1.3 Loose wires

4.2.1.4 Components visually damaged

4.2.1.5 Capacitors leaking

4.2.1.6 Solder joints damaged or cold

4.2.1.7 Circuit board burned or de-laminated

4.2.1.8 Printed wire runs burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		Fluke 85 DMM (or Equivalent)
1		LodTrak Calibration Box

<p>LOU-GED-IC3650MISC REV. A</p>	<p>g</p> <p><i>GE Industrial Systems</i> Renewal Services Louisville, KY</p>	<p>Page 3 of 16</p>
--------------------------------------	---	---------------------

6. TESTING PROCESS

6.1 Setup

6.1.1

 **Note:**

6.2 IC3650SODB

6.2.1 .

6.3 IC3650SODC

6.3.1

6.4 IC3650SPUA

6.4.1

6.5 IC3650SRDG

6.5.1

6.6 IC3655A117

6.6.1

6.7 IC3655A137

6.7.1

6.8 ***TEST COMPLETE ***

7. NOTES

9-18-02; 9:03AM; GE INDSYS

GEARTY LIMITED

502 493 0640

1/ 13

CONT. CN SHEET. 2

SH. NO. 1

TITLE

Instructions for LōdTrak Card Calibration Using the
Portable Calibration Box

FIRST MADE FOR

PGEI-1430

GENERAL OPERATING PROCEDURE

The portable calibration box is intended for calibrating the Overload, Overload/
Overtemperature, Unbalance and Ground Fault functions of a LōdTrak motor protection
relay. A circuit card containing electronic components is installed in the
box and should remain there permanently. On no account should any of the sealed
trim potentiometers of this card be adjusted. Space is provided for a relay
driver card and a function card, to be provided by the LōdTrak relay under test.
Cards are withdrawn from the relay and also from the calibration box using the
card puller provided. IT IS IMPORTANT THAT POWER BE REMOVED FROM THE RELAY
BEFORE CARDS ARE REMOVED. A SWITCH MARKED "CARD POWER" IS PROVIDED ON THE
CALIBRATION BOX. THIS SWITCH SHOULD ALWAYS BE IN THE OFF POSITION WHEN CARDS
ARE EITHER BEING INSERTED OR WITHDRAWN.

Prior to using the calibration box it should be connected to a standard 115V
60Hz supply, the main power switch turned on and the equipment allowed to warm
up for approximately 10 minutes.

Operation of the equipment for calibrating individual card functions is described
in the following pages. After individual card calibration all cards should be
replaced in the CORRECT relay base, care being taken to ensure that they are
properly seated. A functional test should be done on the complete relay as
follows.

Push the test button of each function card in turn and check that the trip and
alarm relays pick up and that all latching relays latch after the button has
been released. Check also that the appropriate annunciator lamps light and

REVISION

PRINTS

DRAWN BY

D. R. BOOTHMAN

CHECKED BY

P. ERNST

ENGINEERING LAB

PGEI-1430

9-18-02; 9:03AM; GE INDSYS

1502 493 0640

3/ 13

PGEI-1430

Instructions for LodTrak Card Calibration Using the
Portable Calibration Box

FIRST MADE FOR

that the trip lamps latch. (Note there is some delay in operation of the test function of the unbalance card, the trip signal produced by other cards should be immediate.)

A. Overload Card (IC3650S0DB1)

1. Set controls as follows

- "UNBALANCE" switch - "F.L. AMPS"
- "UNBALANCE" potentiometer - CCW
- "CURRENT INPUT" - Both CCW
- "OVERLOAD OVERTEMPERATURE" - "F.L. AMPS"
- "FUNCTION" - "OVERLOAD"

~~Turn both trim potentiometers of overload card, R36 and R37, fully counterclockwise (Service Factor).~~
~~Turn "TRIP LEVEL" adjustment on card to 100%.~~

^{C-13}
Clip orange jumper lead to CEF lead nearest to card front (first scrape off transparent varnish to ensure good contact). Now insert both overload and relay driver cards in their appropriate slots, using sufficient force to ensure good contact in the sockets. Insert jumper lead plug into socket marked "JUMPER".
~~Turn both trim pots of overload card, R36 & R37, fully CCW (about 15 turns)~~
Turn card power switch to "ON".

2. Adjust "CURRENT INPUT" controls until digital meter displays the desired ^{3.0} ~~desired~~ trip current (Between 2.0 and 5.0 amps). Turn "OVERLOAD/OVERTEMPERATURE" switch to "ADJUST F.L." then push "FAST CAL" button on card and hold while turning "RUN" trim potentiometer clockwise. When a trip is indicated, back off R37 CCW until relay released then very slowly turn CW again until relay just trips. (Further rotation than is necessary to just cause the relay to trip will result in the relay being set at too low a value)

REVISION

BY

R. BOOTHMAN

CHECKED BY

P. ERNST

ENGINEERING LAB

PETERBOROUGH

PGEI-1430

PLANT

CONT. ON SHEET. 3

SER. NO. 2

PRINTS TO

9-18-02; 9:03AM; GE INDSYS

1502 493 0640

4/ 13

PGEI-1430

Instructions for LdTrak Card Calibration Using the
Portable Calibration Box

FIRST MADE FOR

7807

GE# 4447C
Poc 14

Ken Stafford

3. Turn "OVERLOAD/OVERTEMPERATURE" switch to "L.R. AMPS" and adjust "CURRENT INPUT" controls until digital meter displays the desired locked rotor current.
(Between 12 and 30 amps if locked rotor current is six times full load current)
Turn "OVERLOAD/OVERTEMPERATURE" switch to "ADJUST L.R." then adjust "STALL" trimpot CW until the digital display reads the value given by table 1, below,
for the desired maximum stall time. (This operation will approximately set the desired stall time).

TABLE 1

TIME (sec)	METER READING	TIME (sec)	METER READING	TIME (sec)	METER READING
5	226	10	116	20	062
5.5	206	11	106	21	058
6	190	12	098	22	056
6.5	176	13	090	23	054
7	164	14	084	24	052
7.5	152	15	080	25	050
8	144	16	074	26	048
8.5	136	17	070	28	046
9	128	18	068	30	042
9.5	122	19	064	49.8	019

4. Turn "OVERLOAD/OVERTEMPERATURE" switch to "TIME". Press and hold down the yellow "TIME" button. Card will now experience a simulated locked rotor and after trip will display the time taken to trip. Releasing the button resets

BY

BOOTHMAN

CHECKED BY

P. ERNST

ENGINEERING LAB

PETERSBOROUGH

PLANT

PGEI-1430

CONT. ON SHEET. 4 SH. NO. 3

PRINTED TO

9-18-02; 9:03AM;GE INDSYS

1502 493 0640 # 5/ 13

PGEI-1430

Portable Calibration Box

FIRST MADE FOR

the circuit and, after a wait of ten seconds, the button may be depressed again to repeat the test. If the time taken to trip is too long turn R36 CW a little and repeat the test. If the time is too short turn R36 CCW. Repeat until the time to trip is within acceptable limits.

5. Turn card power switch to "OFF". Remove cards and jumper from Overload card.

REVISION

PRINTS TO

BOOTHMAN

CHECKED BY
P. ERNST

ENGINEERING LAB
PETERBOROUGH

PLANT

PGEI-1430

CONT. ON SHEET. 5

SH. NO. 4

9-18-02; 9:03AM; GE

INDSYS

1502 493 0640

6/ 13

Instructions for Locirak Card Calibration Using the

Portable Calibration Box

FIRST MADE FOR

PGEI-1430

TP 7-19
2-34
1-27
6-27

meter 20101 9.1042 set for 0 13800 14.05 set for 6.5V

CHECK WIRES TEST JACKS TO PINS

B. OVERLOAD/OVERTEMPERATURE CARD (IC365 SODC)

1. Set controls as follows

- "UNBALANCE" switch - "F.L. AMPS"
- "UNBALANCE" potentiometer - CCW
- "CURRENT INPUT" - Both CCW
- "OVERLOAD/OVERTEMPERATURE" - "F.L. AMPS"
- "FUNCTION" - "OVERLOAD/OVERTEMPERATURE"

Pencil
INSERT
NOMIN.
Settings
DO

Insert both Overload/Overtemperature and relay driver cards in their appropriate slots and apply sufficient force to ensure good contact in their sockets.

Rotate "ALARM", "TRIP", "RUN" and "STALL" trimpots fully CW (approximately 15 turns). TURN CARD POWER SWITCH TO "ON". Check meter at 400 & 150°

SODC1 RTD-10.6 14.2

2. (OMIT IF NO ALARM FUNCTION IS REQUIRED). Check wiring to test jacks

Set "RTD RESISTANCE" decade switch the resistance equivalent to the desired Alarm temperature.

Example:

E.g. 120°C
SODC1 - 10 Ω Copper
SODC2 - 120 Ω Nickel (GE or Edison #7)
SODC3 - 100 Ω Platinum

R.T.D. Resistance
Switch Setting

013.7 219.3 9
220.2 276.5
146.3
4.1 on p. 16 of 64H-4449

For other types or temperatures refer to published resistance tables. Turn "ALARM" pot CCW until alarm lamp lights. Turn CW until lamp goes out then slowly CCW again until lamp just lights again.

3. Set "RTD RESISTANCE" decade switch for the resistance equivalent to the desired trip temperature

These cal. should be on customers order request if new or if it calibrated

BY
L. BOOTHMAN

CHECKED BY
P. ERNST

ENGINEERING LAB
PETERBOROUGH

PGEI-
CONT.

9-18-02; 9:03AM; GE INDSYS

1502 493 0640

7/ 13

PGEI-1430

INSTRUCTIONS FOR LOGIRAK Card Calibration Using the
Portable Calibration Box

FIRST MADE FOR

135-14,25

Example:

E.g. 130°C

Switch Setting

SODC1 - 10 Ω Copper
SODC2 - 120 Ω Nickel (GE or Edison #7)
SODC3 - 100 Ω Platinum

014.0-228.92
~~120.0~~ 225.1
~~100.0~~ 150.2

For other types or temperatures refer to the published resistance tables

Turn "TRIP" pot CCW until trip lamp lights. Turn CW until lamp goes out then slowly
CCW again until lamp just lights up again.

4. Set "RTD RESISTANCE" decade switch for the resistance equivalent to 40°C

Switch Setting

SODC1 - 10 Ω Copper
SODC2 - 120 Ω Nickel
SODC3 - 100 Ω Platinum

010.6
~~120.0~~ 152.3
~~100.0~~ 115.4

Adjust "CURRENT INPUT" controls until digital meter displays the desired full
load current, (between 2.0 and 5.0 amps). Turn "OVERLOAD/OVERTEMPERATURE"
switch to "ADJUST F.L." and rotate "RUN" trim potentiometer on card until
display reads 05.0. whatever customer request for F.L. current

5. Turn "OVERLOAD/OVERTEMPERATURE" switch to "L.R. AMPS". Adjust "CURRENT
INPUT" controls until digital meter displays the desired locked rotor current
(between 12 and 30 amps if locked rotor current is six times full load current)

Turn "OVERLOAD/OVERTEMPERATURE" switch to "ADJUST L.R." and turn "STALL" pot
on card until meter displays the number from the chart below for the desired
maximum stall time. 155 sec ON CALIB req. - see time chart next page
(This operation will approximately set the desired stall-
time). The number shown is for 10- Ω Cu RTD. It will vary from
these values for the Ni & Pt RTD's.

13.7 - 14.1

BY BOOTHMAN	CHECKED BY P. ERNST	ENGINEERING LAB PETERBOROUGH	PGEI-1430 CONT. ON SHEET, 7	PRINTS TO SH. NO. 6
----------------	------------------------	---------------------------------	--------------------------------	------------------------

9-18-02; 9:03AM; GE INDSYS

COMPANY LIMITED

1502 493 0640

8 / 13

CONT. ON SHEET. 8

GEI-1430

TITLE

Instructions for LedTrak Card Calibration Using the
Portable Calibration Box

FIRST MADE FOR

1250

	RTD TRIP TEMP		TIME (sec)	RTD TRIP TEMP		TIME (sec)	RTD TRIP TEMP	
	130°C	155°C		130°C	155°C		130°C	155°C
	999	1247	10	522	651	20	284	355
	913	1138	11	479	597	21	273	340
	840	1048	12	443	552	22	263	328
	779	972	13	412	514	23	253	316
	727	906	14	386	481	24	245	305
	681	849	15	363	453	25	237	296
	641	800	16	343	428	26	230	287
	606	756	17	326	407	27	223	278
	575	717	18	311	387	28	217	271
	547	682	19	297	370	30	206	257

9-18-02; 9:03AM; GE INDSYS

1502 493 0640

9/ 13

6. Turn "OVERLOAD/OVERTEMPERATURE" switch to time. Wait ten seconds then push and hold yellow "TIME" button. Card will experience a simulated locked rotor and after the trip the meter will display the time taken to trip. ^{Time} Releasing the button resets the circuit card and timer and, after a wait of ten seconds, the button may be depressed again to repeat the test. If the time taken is too short then rotate the stall pot CW a little and repeat the test. If the time is too long rotate the pot CCW. Repeat until the time to trip is within acceptable limits.

7. Turn card power switch to "OFF". Remove cards.

DRAWN BY.

D. R. BOOTHMAN

CHECKED BY

P. ERNST

ENGINEERING LAB

PETERBOROUGH

PGI-1450

CONT. ON NEXT C

Make sure the RTD setting is 400C for
Timing calibration. Too low setting causes
an increase in time. Too high setting
causes a decrease in time -

Pin
T P 1 - 21
T P 1 - 22
T P 2 - 34
T P 7 - 18

9-18-02; 9:03AM; GE INDSYS

1502 493 0640

10/ 13

PGEI-1430

Portable Calibration Box

FIRST MADE FOR

P7 Namplate.

C. PHASE UNBALANCE CARD (IC3650SPUA-2)

1. Set controls as follows

"UNBALANCE" switch - "UNBAL"

"UNBALANCE" potentiometer - CCW

"CURRENT INPUT" - Both CCW

"OVERLOAD/OVERTEMPERATURE" - "F.L. AMPS" #4

"FUNCTION" - "UNBALANCE"

Remove Jumper T3-T4 from unbalance card, set "TRIP LEV" adjustment on card to desired trip level (scale is marked 10%, 20% and 30%, pot is infinitely adjustable within this range). Note that CCW rotation is toward 30% & CCW is toward 10%. Now insert both unbalance and relay driver cards in their appropriate slots and apply sufficient force to ensure good contact in their sockets. Rotate both trimpots fully CW (approximately 15 turns). Turn card power switch to "ON".

2. Adjust "CURRENT INPUT" controls until digital meter displays the desired full load current. Check that "UNBALANCE" potentiometer is indeed fully CCW then rotate CW until digital meter displays the reduced value of current equivalent to the unbalance level required for ultimate trip of the relay.

(FROM 2.0 AMP)

(e.g. if full load current = 5 amps.

and unbalance to trip = 10% then meter should read 90% of 5 amps = 4.5 amps)

Now rotate the trim pot (R85) on unbalance card (the trimpot on the left) CCW till trip lamp lights. Turn CW until lamp goes out then slowly CCW again until lamp just lights. Note that if the "UNBALANCE" potentiometer is now checked off fully CCW, then slowly CW again, the alarm lamp will light first at

1 OBSERVE Use

3.3 710%
#1. FLA X 90% = 4.5
#2. Y - FLA = DIFF
#3. DIFF X 67% = 3.03
#4. 2 - FLA = TRIP AT 67%
#5. FLA X 1.5 = 7.5
2.97 (UNBAL)
3.03
ALARM

USING UNBAL POT (TRIP)

USING POT (TRIP)

REVIE

ALARM

67%

3.03

67%

4.5

DRAWN BY
D. R. EOTHMAN

CHECKED BY
P. ERNST

ENGINEERING LAB
PETERBOROUGH

PGEI-1430

PLANT CONT. ON SHEET 9 - SH. NO. 3

9-18-02; 9:03AM; GE INDSYS

1502 493 0640

11/ 13

-1430

Instructions for LodTrak Card Calibration Using the
Portable Calibration Box

FIRST MADE FOR

37 of the trip value if

the alarm function is included) then the trip lamp will light at the level
of unbalance just calibrated. Now turn the "UNBALANCE" potentiometer fully

CCW.

ADD Jumper Ck. T3 to T4

task 7 time Delay

CCW 2.031

Turn "UNBALANCE" switch to "1.5 x F.L." then adjust "CURRENT INPUT" controls
until digital meter reads a value 1.5 times the full load current.

~~UNBALANCE switch to "1.5 x F.L."~~ then rotate clamp trimpot (R82, the trimpot on
the right) slowly CCW until the reading on the digital meter just starts to
decrease. Meter will be inclined to "bounce" some. Look for a steady decrease
R82 is turned and then come back to where it just begins.

Turn card power switch to "OFF". Remove cards and replace T3-T4 jumper on
balance card.

Turn power off. Put jumper back to

Timing
After setting R82

Go back check trip set unbalance switch to
unbalance

5.25
NOV. 1982

REVISIONS

BOOTHMAN

CHECKED BY
P. ERNST

ENGINEERING LAB
PETERBOROUGH

PGEI-1430

PRINTS TO

9-18-02; 9:03AM; GE INDSYS

1502 493 0640
CONT. ON SHEET. F

12/ 13

TITLE

Instructions for LcdTrak Card Calibration Using the
Portable Calibration Box

FIRST MADE FOR

GROUND FAULT CARD (IC3650SGDB1/2)

Set controls as follows

- "UNBALANCE" switch - "F.L. AMPS"
- "UNBALANCE" potentiometer - CCW
- "CURRENT INPUT" - Both CCW
- "OVERLOAD/OVERTEMPERATURE" - "F.L. AMPS"
- "FUNCTION" - "GROUND"

Toggle sw to 1 if trip is
over. 1 Turn POT CW. Then set
DIGITAL Read out for ? with
current input controls. Then
Turn POT CW UNTIL Trip goes
out then CCW till out. Then turn current input
CCW + Then CW ALARM should come on
at 67% of trip reading & trip
should come on at whatever
digital was set at for trip

Push TEST TRIP button to
see if both lights come on.

REVISIONS

Set the (range switch) for the desired ground trip level range and turn the
ground fault level potentiometer fully CW. Insert the ground and relay driver
cards in their appropriate slots using sufficient force to ensure good contact
in the card sockets. Turn card power switch to "ON".

Adjust "CURRENT INPUT" controls until digital meter displays the desired
ground fault current to trip. Now turn the trip level adjustment on the card
slowly CCW until the trip lamp lights. Back off the "CURRENT INPUT" control
fully CCW then slowly increase again. Firstly the alarm lamp will light at
about 67% of the current required to trip (if the alarm function is included),
then the trip lamp will light at the level for which the card was calibrated.

Turn card power switch to "OFF". Remove cards.

PRINTS TO

EN BY

CHECKED BY

ENGINEERING LAB

PGE1-1430

9-18-02; 9:03AM; GE INDSYS

1502 493 0640

13/ 13

TABLE 1 (Cont'd)
STALL SETTINGS USE FOR 3 ϕ OVERLOAD CARD

9	064	18	034	30	021
9.5	061	19	032		

TABLE 2
STANDARD RTD'S USED WITH LODTRAK
(Resistance in Ohms)

Super

TEMPERATURE °C	10 OHM COPPER	100 OHM PLATINUM	CGE 100 OHM NICKEL	CGE OR EDISON 120 OHM NICKEL
0	9.04	100.00	100.00	120.00
10	9.42	103.96	105.97	127.17
20	9.81	107.92	112.10	134.52
30	10.19	111.86	118.38	142.06
40	10.58	115.78	124.83	149.79
50	10.97	119.70	131.45	157.74
60	11.35	123.60	138.25	165.90
70	11.74	127.50	145.21	174.25
80	12.12	131.38	152.37	182.84
90	12.51	135.25	159.67	191.64
100	12.90	139.11	167.20	200.64
110	13.28	142.95	174.87	209.85
120	13.67	146.79	182.74	219.29
130	14.06	150.61	190.80	228.96
140	14.44	154.42	199.04	238.85
150	14.83	158.22	207.46	248.95
160	15.22	162.01	216.08	259.30
170	15.61	165.79	224.92	269.31
180	16.00	169.55	233.97	280.77
190	16.39	173.30		291.96
200	16.78	177.04		303.46

LOU–GED-IC3650MISC REV. A	 GE Industrial Systems <i>Renewal Services Louisville, KY</i>	Page 16 of 16
--------------------------------------	---	----------------------

8. Oscilloscope Verification Examples:

Fig. 1

Fig. 2