



GE Energy

## Functional Testing Specification

*Parts & Repair Operations  
Louisville, KY*

**LOU-GEF-IC600CB5xx**

### Test Procedure for a Series Six Communications Control card

**DOCUMENT REVISION STATUS:** Determined by the last entry in the "REV" and "DATE" column

REV.	DESCRIPTION	SIGNATURE	REV. DATE
A	Initial release	Cristyn Edlin	2/4/2010
B			
C			

© COPYRIGHT GENERAL ELECTRIC COMPANY

Hard copies are uncontrolled and are for reference only.

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

<b>PREPARED BY</b> Cristyn Edlin	<b>REVIEWED BY</b>	<b>REVIEWED BY</b>	<b>QUALITY APPROVAL</b> Charlie Wade
<b>DATE</b> 2/4/2010	<b>DATE</b>	<b>DATE</b>	<b>DATE</b> 2/9/2010

LOU-GEF-IC600CB5xx REV. A	g  <b>GE Energy</b> <i>Parts &amp; Repair Operations</i> <i>Louisville, KY</i>	Page 2 of 5
------------------------------	--	-------------

## 1. SCOPE

- 1.1 This is a functional testing procedure for a Series Six CCM card. This procedure encompasses all of the following models. IC600CB514, IC600CB516, IC600CB517, IC600CB536 and IC600CB537

## 2. STANDARDS OF QUALITY

- 2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

## 3. APPLICABLE DOCUMENTS

- 3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
- 3.1.1

## 4. ENGINEERING REQUIREMENTS

- 4.1 Equipment Cleaning
- 4.1.1 Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- 4.2 Equipment Inspection
- 4.2.1 Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
- 4.2.1.1 Wires: broken, cracked, or loosely connected
- 4.2.1.2 Terminal strips / connectors: broken or cracked
- 4.2.1.3 Components: visually damaged
- 4.2.1.4 Capacitors: bloated or leaking
- 4.2.1.5 Solder joints: damaged or cold
- 4.2.1.6 Circuit board: burned or de-laminated
- 4.2.1.7 Printed wire runs / Traces: burned or damaged

## 5. EQUIPMENT REQUIRED

- 5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		Series Six CPU-1 <u>Local</u> Rack
1		Series Six Work-Master computer
1		Series Six Operator Interface Terminal

## 6. Testing

### 6.1 Setup

**6.1.1** Ensure that the power to the CPU-1 LOCAL rack is off.

**6.1.2** On the CCM card, there are 3 sets of dipswitches, which are labeled SW1, 9 and 17. Chart 1 illustrates the positions to which these dipswitches are to be set.

<b>X=Opened, L =Closed</b>								
<b>SW1</b>	L	L	L	L	L	L	L	L
<b>SW9</b>	L	L	L	L	L	L	L	L
<b>SW17</b>	L	X	X	X				

**Chart 1**

**6.4.1** There are 12 sets of jumpers, which are labeled T2, T4, T6, T8 and JP1-8. Charts 2 and 3 illustrate the positions to which these jumpers are to be set.

<b>T2</b>	<b>T4</b>	<b>T6</b>	<b>T8</b>
<b>2-3</b>	<b>2-3</b>	<b>2-3</b>	<b>1-2</b>

**Chart 2**

<b>JP1</b>	<b>JP2</b>	<b>JP3</b>	<b>JP4</b>	<b>JP5</b>	<b>JP6</b>	<b>JP7</b>	<b>JP8</b>
<b>1-2</b>	<b>1-2</b>	<b>1-2</b>	<b>1-2</b>	<b>1-2</b>	<b>2-3</b>	<b>1-2</b>	<b>1-2</b>

**Chart 3**

**6.4.2** In the C: prompt of the Work-Master, type "2" and press enter.

**6.4.3** Follow the instructions of the Work-Master until you get to the "Basic-Master 6" supervisor menu

### 6.2 Test Process

**6.2.1** After ensuring dipswitch and jumper settings are set in accordance with section 6, insert the card into slot 7.

**6.2.2** Connect the communications cable labeled "Top" to port 1 (the top port) of the card.


**6.2.3** Connect the communications cable labeled "Bottom" to port 2 (the bottom port) of the card.

**6.2.4** Turn on the power to the CPU-1 LOCAL rack.

**6.2.5** Allow the card approximately 5-10 seconds to perform the "self-test" function.

**6.2.6** Press "F6" to enter the Load/Store/Verify screen.

**6.2.7** Press "F5" to enter the clear function.

<b>LOU-GEF-IC600CB5xx REV. A</b>	  <b>GE Energy</b> <i>Parts &amp; Repair Operations</i> <i>Louisville, KY</i>	<b>Page 4 of 5</b>
--------------------------------------	--	--------------------

- 6.2.8** Press “Y” to clear the memory of the ASCII/BASIC card. Once the memory is cleared, “Memory cleared” should show up in the bottom left corner of the screen.
- 6.2.9** Press “F1” to enter the load function.
- 6.2.10** Type “C:\ABM\1” and press enter. It should take approximately 1 minute for the ABM program 1 to load. Once program 1 is loaded, the Work-Master should beep.
- 6.2.11** After the beep, press the escape key to enter the supervisor menu.
- 6.2.12** Press “F2” to enter the “Smart Terminal” screen.
- 6.2.13** Press “F2” again to run program 1. Program 1 should begin drawing screens on the Operator Interface Terminal. This should take approximately 2 minutes. It will then be recommended by the Operator Interface Terminal to clear the memory then load and run the “C:\ABM\2” file.
- 6.2.14** Press the escape key to enter the supervisor menu.
- 6.2.15** Press “F6” to enter the Load/Store/Verify screen.
- 6.2.16** Press “F5” to enter the clear function.
- 6.2.17** Press “Y” to clear the memory of the ASCII/BASIC card. Once the memory is cleared, “Memory cleared” should show up in the bottom left corner of the screen.
- 6.2.18** Press “F1” to enter the load function.
- 6.2.19** Type “C:\ABM\2” and press enter. It should take approximately 1 minute for program 2 to load. Once program 2 is loaded, the Work-Master should beep.
- 6.2.20** After the beep, press the escape key to enter the supervisor menu.
- 6.2.21** Press “F2” to enter the “Smart Terminal” screen.
- 6.2.22** Press “F2” again to run program 2.
- 6.2.23** Identify the orange “F” keys on the Operator Interface Terminal.
- 6.2.24** Press “F” key 2 of the OIT to see the CCM data page.

<p><b>LOU-GEF-IC600CB5xx</b> <b>REV. A</b></p>	<p><b>g</b></p> <p><b>GE Energy</b> <i>Parts &amp; Repair Operations</i> <i>Louisville, KY</i></p>	<p><b>Page 5 of 5</b></p>
--	--	---------------------------

**6.2.25** Ensure that both ports A and B are having “good conversations” and no “bad conversations” or “header retries”.

**6.2.26** Let card run for at least one hour with good conversations.

**6.2.27** Press the escape key to enter the supervisor menu.

**6.2.28** Press “F6” to enter the Load/Store/Verify screen.

**6.2.29** Press “F5” to enter the clear function.

**6.2.30** Press “Y” to clear the memory of the ASCII/BASIC card.

**6.2.31** Turn off the power to the CPU-1 LOCAL rack.

**6.2.32** **\*\*\*TEST COMPLETE\*\*\***

## **7. Notes**

**7.1** None at this time

## **8. Attachments**

**8.1** None at this time