



GE Energy

## Functional Testing Specification

*Parts & Repair Services  
Louisville, KY*

**LOU-GED-DS3800NRXA**

### Test Procedure for a DS3800NRXA

**DOCUMENT REVISION STATUS:** Determined by the last entry in the "REV" and "DATE" column

REV.	DESCRIPTION	SIGNATURE	REV. DATE
A	Initial release	John Wychulis	9/4/2008
B	Added note to step 6.2.1	Steve Pharris	10/28/08
C	Improve clarity, page 3	S Pharris	4/3/2009

© COPYRIGHT GENERAL ELECTRIC COMPANY

Hard copies are uncontrolled and are for reference only.

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

<b>PREPARED BY</b> John Wychulis	<b>REVIEWED BY</b> Steve Pharris	<b>REVIEWED BY</b>	<b>QUALITY APPROVAL</b> Charlie Wade
<b>DATE</b> 9/4/2008	<b>DATE</b> 10/28/2008	<b>DATE</b>	<b>DATE</b> 10/28/2008

LOU-GED-DS3800NRXA REV. C	g  <i>GE Energy</i> <i>Parts &amp; Repair Services</i> <i>Louisville, KY</i>	Page 2 of 4
------------------------------	--	-------------

## 1. SCOPE

1.1 This is a functional testing procedure for a Card.

## 2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

## 3. APPLICABLE DOCUMENTS

3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.

## 4. ENGINEERING REQUIREMENTS

### 4.1 Equipment Cleaning

4.1.1 Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.

### 4.2 Equipment Inspection

4.2.1 Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:

- 4.2.1.1 Wires - broken, cracked, or loosely connected
- 4.2.1.2 Terminal strips / connectors - broken or cracked
- 4.2.1.3 Components - visually damaged
- 4.2.1.4 Capacitors - bloated or leaking
- 4.2.1.5 Solder joints - damaged or cold
- 4.2.1.6 Circuit board - burned or de-laminated
- 4.2.1.7 Printed wire runs / Traces - burned or damaged

## 5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		Fluke 87 DMM (or Equivalent)
2		Variable DC power supplies
1		Signal Generator
1		Current Source

<p><b>LOU-GED-DS3800NRXA</b> <b>REV. C</b></p>	<p><b>g</b></p> <p><b>GE Energy</b> <i>Parts &amp; Repair Services</i> <i>Louisville, KY</i></p>	<p><b>Page 3 of 4</b></p>
--	--	---------------------------

## 6. TESTING PROCESS

### 6.1 Power Supply Test

- 6.1.1 Put 12V at JEXT-8(+) JEXT-7(-).
- 6.1.2 Verify 11.4 V across C20.
- 6.1.3 Verify TP7(+) TP4(-) is 5V.
- 6.1.4 Verify TP9(+) TP4(-) is 12V.
- 6.1.5 Verify TP8(+) TP4(-) is -12V.
- 6.1.6 LED CR4 is on.
- 6.1.7 Adjust R102 until TP1(+) TP4(-) is -8V.
- 6.1.8 Connect power supply #2 JEXT-10(+) JEXT -9(-).
- 6.1.9 Increase supply until CR5 turns on (AC Power on)
- 6.1.10 Connect voltmeter across C19, should be 9VDC +/- .25V
- 6.1.11 Decrease supply until CR5 is off.
- 6.1.12 Verify 8V across C19 +/- .25V.
- 6.1.13 Disconnect variable supply #2 and set to 12VDC then connect to JEXT-12(+) JEXT-10(-).
- 6.1.14 Repeat steps 6.1.3 thru 6.1.6 plus CR5 should be on.
- 6.1.15 Disconnect variable supply and reconnect 12VDC to JEXT-9(+) JEXT-12(-).
- 6.1.16 Repeat steps 6.1.3 thru 6.1.6 plus CR5 should be on.
- 6.1.17 Verify Voltage at TP10(+) TP4(-) is 10.5VDC

### 6.2 Signal Conditioning and Driver Test

- 6.2.1 Connect Load across TBI-1(+) TBI-2(-).
  - 6.2.1.1 Load is 2 1N5624 diodes and a 1-Ohm 10W resistor in series.
- 6.2.2 Apply 10VDC to JEXT 9 (+) & JEXT10(-)
- 6.2.3 Apply a 300Hz 5Vp-p square wave to JEXT-2(+) JEXT-1(-).
- 6.2.4 Verify waveform is 4Vp-p at 3.3ms at TP5.
- 6.2.5 Verify waveform is 1Vp-p at 3.3ms at load between diode and resistor.
- 6.2.6 Disconnect 10V from JEXT-9 & JEXT-12. CR5 is off and verify load resistor waveform drops to .6V at 3.3ms

### 6.3 Current Limit Test

- 6.3.1 Jumper at 6.5 current limit.
- 6.3.2 Connect current source from TBI-2(+) and TBI-3(-)
- 6.3.3 Increase to 6.5A. Voltage at TP6 should be zero (0V).
- 6.3.4 Switch current source off.

<p><b>LOU-GED-DS3800NRXA REV. C</b></p>	<p><b>g</b></p> <p><b>GE Energy</b> Parts &amp; Repair Services Louisville, KY</p>	<p><b>Page 4 of 4</b></p>
---	--	---------------------------

#### 6.4 Field Heating

- 6.4.1 Adjust R101 full CCW.
- 6.4.2 Apply -10V to TP3(-) TP4(+).
- 6.4.3 TP2 should be -5.1V
- 6.4.4 Disconnect -10V and adjust R101 CW
- 6.4.5 Apply 5V TP3(+) and TP4(-)
- 6.4.6 TP2 is >5.1V
- 6.4.7 Adjust R101 until TP2 is 5.1V
- 6.4.8 Apply -5V to JEXT-3(-) and TP4(+)
- 6.4.9 Use TP4 for common and measure JEXT-4=0 and JEXT-5=.6
- 6.4.10 Apply 12VDC to JEXT-10(+) and JEXT-9(-)
- 6.4.11 Verify CR5 LED is on.
- 6.4.12 Output at JEXT-5(+) and TP4(-) is -5V.
- 6.4.13 JEXT-4(+) and TP4(-) is 4.6V.
- 6.4.14 Disconnect -5V from JEXT3(-) and TP4(+).
- 6.4.15 Apply -8V to TP3(+) and TP4(-)
- 6.4.16 Should read JEXT-5(+) and TP4(-) = -6.2V

#### 6.5 **\*\*\*TEST COMPLETE\*\*\***

#### 7. **NOTES**

- 7.1 None noted at this time

#### 8. **ATTACHMENTS**

- 8.1 None at this time