

g

GE Energy

Functional Testing Specification

*Parts & Repair Services
Louisville, KY*

LOU-GED-DS200GSIAG1C

Test Procedure for a

DOCUMENT REVISION STATUS: Determined by the last entry in the "REV" and "DATE" column

REV.	DESCRIPTION	SIGNATURE	REV. DATE
A	Initial release	Jimmy Morgan	11-27-2017
B			
C			

© COPYRIGHT GENERAL ELECTRIC COMPANY

Hard copies are uncontrolled and are for reference only.

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

PREPARED BY Jimmy Morgan	REVIEWED BY	REVIEWED BY	QUALITY APPROVAL L. Groves
DATE 11/27/2017	DATE	DATE	DATE 11/27/2017

LOU- REV. A	g GE Energy <i>Parts & Repair Services</i> <i>Louisville, KY</i>	Page 2 of 5
----------------	--	-------------

1. SCOPE

1.1 This is a functional testing procedure for a Card.

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.

3.1.1 Check board's electronic folder for more information

4. ENGINEERING REQUIREMENTS

4.1 Equipment Cleaning

4.1.1 Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to site specific SRA's for cleaning guidelines.

4.2 Equipment Inspection

4.2.1 Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:

4.2.1.1 Wires - broken, cracked, or loosely connected

4.2.1.2 Terminal strips / connectors - broken or cracked

4.2.1.3 Components - visually damaged

4.2.1.4 Capacitors - bloated or leaking

4.2.1.5 Solder joints - damaged or cold

4.2.1.6 Circuit board - burned or de-laminated

4.2.1.7 Printed wire runs / Traces - burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		Fluke 87 DMM (or Equivalent)
1		Oscilloscope
1		+5vdc, -15vdc, +15vdc Power Supplies (Tenma power supply)
1		GSIAG1A test rig (including 2PL power cable)

<p>LOU- REV. A</p>	<p>g</p> <p>GE Energy Parts & Repair Services Louisville, KY</p>	<p>Page 3 of 5</p>
------------------------	--	--------------------

6. Modifications/Upgrades

6.1 None

7. Testing Process

7.1 Setup

- 7.1.1 Tie all Power supply commons together for this test and use this point for all input and output references unless otherwise specified.
- 7.1.2 Set power supply to output +15vdc and -15vdc
- 7.1.3 Mount Card under test on GSIAG1A test rig.
- 7.1.4 Connect 2PL power cable to 2PL connector on card.
- 7.1.5 Connect power cable wire marked "P5" to +5vdc power supply. (2PL-5)
- 7.1.6 Connect power cable wire marked "P15" to +15vdc power supply. (2PL-3)
- 7.1.7 Connect power cable wire marked "N15" to -15vdc power supply. (2PL-2)
- 7.1.8 Connect power cable wire marked "DCOM" to common of supply. (2PL-4)
- 7.1.9 Connect cable marked TP67.
- 7.1.10 Connect cable marked 1PLS-31.



Note: This test does not verify operation of the processor (U3).

Recommend replacement of U3 processor every time.

7.2 Testing Procedure

- 7.2.1 Turn power supply on and verify the following voltages on card.
 - 7.2.1.1 P5 TP60 5vdc +/- 2%
 - 7.2.1.2 P15 TP62 15vdc +/-2%
 - 7.2.1.3 N15 TP63 -15Vdc +/- 2%
 - 7.2.1.4 DCOM TP67 0v
- 7.2.2 Microprocessor Self-test.
 - 7.2.2.1 Led 1 should be pulsing to signal a fault. Press the reset button for 1-2 sec. The led should go out.
- 7.2.3 Connect a jumper from GSPL-32 to TP60.
- 7.2.4 Connect a jumper from GSPL-31 to TP67.
- 7.2.5 Connect Oscilloscope negative to TP67.
- 7.2.6 Connect Oscilloscope positive to U20 pin 11 (R52).
- 7.2.7 Turn power supply on.
- 7.2.8 Press the reset button (for 1-2 seconds).

<p>LOU- REV. A</p>	<p>g</p> <p>GE Energy Parts & Repair Services Louisville, KY</p>	<p>Page 4 of 5</p>
-------------------------------	--	---------------------------

7.2.9 Verify the Oscilloscope measures a 500Khz square wave +/-10Khz.

7.2.10 Turn power supply off.

7.2.11 Move jumper from TP60 to TP67.

7.2.12 Turn power supply on and press the reset button (for 1-2 seconds).

7.2.13 Verify Oscilloscope measures 0Khz output +/- 1Khz.

7.2.14 Turn power supply off.

7.2.15 Remove jumpers.

7.2.16 Connect jumper from TP60 to GSPL-37

7.2.17 Connect jumper from TP67 to GSPL-36

7.2.18 Move Oscilloscope probe to U18 pin 11 (R45).

7.2.19 Turn on power supply, press the reset button (for 1-2 seconds).

7.2.20 Verify the Oscilloscope measures a 500Khz square wave +/- 10Khz

7.2.21 Turn power supply off.

7.2.22 Move jumper from TP60 to TP67

7.2.23 Turn power supply on and press the reset button (for 1-2 seconds).

7.2.24 Verify Oscilloscope measures 0Khz output +/- 1Khz.

7.2.25 Turn power supply off.

7.2.26 Disconnect all jumpers (leave power cables connected).

7.2.27 Connect a jumper from TP73 to TP60.

7.2.28 Connect Oscilloscope to U34 pin 11 (R140)

7.2.29 Press the reset button (for 1-2 seconds).

7.2.30 Verify the Oscilloscope measures a 500Khz square wave +/- 10Khz.

7.2.31 Turn power supply off.

7.2.32 Move jumper from TP60 to TP67.

7.2.33 Press the reset button (for 1-2 seconds).

7.2.34 Verify the Oscilloscope measures 0Khz output +/- 1Khz.

7.2.35 Turn power supply off.

7.3 Post Testing Burn-in Required ☐ Yes ☒ No



Note: All MARK I, II, & III Turbine related cards require a post testing burn-in of 100 hours.

7.4 *TEST COMPLETE *****

LOU- REV. A	gg	GE Energy <i>Parts & Repair Services</i> <i>Louisville, KY</i>	Page 5 of 5
------------------------	-----------	---	--------------------

8. Notes

8.1 None at this time?

9. Attachments

9.1 None at this time?