



GE Energy

## Functional Testing Specification

*Parts & Repair Services  
Louisville, KY*

**LOU-GED-IC3600CCCC1**

### Test Procedure for a Relay Driver Card

**DOCUMENT REVISION STATUS:** Determined by the last entry in the "REV" and "DATE" column

REV.	DESCRIPTION	SIGNATURE	REV. DATE
A	Initial release	G. Chandler	4/28/2010
B			
C			

© COPYRIGHT GENERAL ELECTRIC COMPANY

Hard copies are uncontrolled and are for reference only.

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

<b>PREPARED BY</b> G. Chandler	<b>REVIEWED BY</b>	<b>REVIEWED BY</b>	<b>QUALITY APPROVAL</b> Charlie Wade
<b>DATE</b> 4/28/2010	<b>DATE</b>	<b>DATE</b>	<b>DATE</b> 4/28/210

LOU-GED-IC3600CCCC1 REV. A	g  <b>GE Energy</b> Parts & Repair Services Louisville, KY	Page 2 of 5
-------------------------------	--	-------------

## 1. SCOPE

1.1 This is a functional testing procedure for a Card.

## 2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

## 3. APPLICABLE DOCUMENTS

3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.

3.1.1 Check board's electronic folder for more information

## 4. ENGINEERING REQUIREMENTS

### 4.1 Equipment Cleaning

4.1.1 Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to site specific SRA's for cleaning guidelines.

### 4.2 Equipment Inspection

4.2.1 Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:

4.2.1.1 Wires - broken, cracked, or loosely connected

4.2.1.2 Terminal strips / connectors - broken or cracked

4.2.1.3 Components - visually damaged

4.2.1.4 Capacitors - bloated or leaking

4.2.1.5 Solder joints - damaged or cold

4.2.1.6 Circuit board - burned or de-laminated

4.2.1.7 Printed wire runs / Traces - burned or damaged

## 5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		Fluke 87 DMM (or Equivalent)
1		Current Meter
2		20-30 VDC Power Supplies
1		Fluke 5500
1		50V Power Supply

## 6. TESTING PROCESS

### 6.1 Setup

- 6.1.1 Connect Pin-28 to 5.3VDC
- 6.1.2 Connect Pin-51 to Common (DCOM)
- 6.1.3 Connect a current meter, negative side to Pin-12 and the positive side of meter to an adjustable 19VDC power supply.
- 6.1.4 Connect PCOM (Pin-22) to the adjustable 19VDC source ground. Connect PCOM (Pin-22) to DCOM (Pin-51) or ground to ground on the power supplies.
- 6.1.5 Set the current meter to measure m-amps.
- Special Note: This circuit is 50m Amps MAX, do not go over 50m Amps.**
- 6.1.6 Set the adjustable 19VDC source to zero volts.

### 6.2 Testing Procedure

- 6.2.1 Power on the 5.3VDC supply.
- 6.2.2 Power on the adjustable power supply.
- 6.2.3 Adjust the voltage from zero to +15VDC. The current meter should remain at zero current.
- 6.2.4 Adjust supply back to 10VDC.
- 6.2.5 Momentarily touch Pin-44 to ground, this should latch on the current relay driver and you should read 25mA. As the adjustable source is increased the current will increase.

Adjustable Voltage Level	Current reading
0VDC	0 mA
5VDC	13mA
10VDC	25mA
15VDC	39mA
19VDC	49mA

**DO NOT GO OVER 50m Amps**

- 6.2.6 Time Delay A (Pin-28): Touch Pin-47 to 5.3VDC, this will unlatch the above circuit and current will drop to 0mA.
- 6.2.7 Touch Pin-45 to ground, this will latch the relay driver circuit once again.
- 6.2.8 Power Down.
- 6.2.9 Connect a 5K pull-up resistor from Pin-37 to 5.3VDC.
- 6.2.10 Connect a -50V supply to Pin-30. Positive side of supply to ACOM (Pin-50 or P2).

<p><b>LOU-GED-IC3600CCCC1 REV. A</b></p>	<p><b>g</b></p> <p><b>GE Energy</b> Parts &amp; Repair Services Louisville, KY</p>	<p><b>Page 4 of 5</b></p>
--	--	---------------------------

**6.2.11** Connect a voltmeter to DCOM (Pin-37).

**6.2.12** Power up the supplies (+5.3VDC, -50VDC, and 10VDC Adjustable).

**6.2.13** Pin-37 should read zero volts & current should be at 0 Amps.

Special note: Pin-47 can be used to reset this circuit.

**6.2.14** Momentarily touch Pin-44 to ground, latch on (SET)

**6.2.14.1** Voltmeter on Pin-37 shall be 5.3VDC

**6.2.14.2** Current Meter shall read 25m Amps

**6.2.15** Momentarily touch Pin-47 to 5.3VDC, latch off (RESET)

**6.2.15.1** Voltmeter on Pin-37 shall be 0VDC

**6.2.15.2** Current Meter shall read 0m Amps

**6.2.16** Momentarily touch Pin-45 to ground, latch on (SET)

**6.2.16.1** Voltmeter on Pin-37 shall be 5.3VDC

**6.2.16.2** Current Meter shall read 25m Amps

**6.2.17** Momentarily touch Pin-47 to 5.3VDC, latch off (RESET)

**6.2.17.1** Voltmeter on Pin-37 shall be 0VDC

**6.2.17.2** Current Meter shall read 0m Amps

**6.2.18** Turn pots R25 & R30 fully CCW

**6.2.19** Connect the 5500 to Pin-15 & Pin-16.

**6.2.20** Set to 60Hz sine wave, amplitude set to .1V RMS.

**6.2.21** Connect Pin-44 to ground and adjust the variable DC supply until output current is 40m Amps at Pin-12.

**6.2.22** Monitor Pin-48 & Pin-49 with a DMM.

**6.2.23** With .1V signal applied to Pin-15 & Pin-16, Pin-48 should be logic HIGH and Pin-49 should be logic LOW.

**6.2.24** Begin increasing the amplitude of the signal applied to Pin-15 & Pin 16 until the voltage at Pin-48 begins to drop.

**6.2.25** The voltage on the Fluke 5500 should be approx 8V RMS.

**6.2.26** Reset the Fluke 5500 to .1V

<p><b>LOU-GED-IC3600CCCC1 REV. A</b></p>	<p><b>g</b></p> <p><b>GE Energy</b> Parts &amp; Repair Services Louisville, KY</p>	<p><b>Page 5 of 5</b></p>
--	--	---------------------------

#### **6.2.27**

**6.2.28** Turn Pot R25 fully CW.

**6.2.29** Again increase the amplitude of the Fluke 5500 until the DC volts at Pin-48 begins to drop. The voltage on the Fluke 5500 should be approx 21VDC.

**6.2.30** Continue to increase the amplitude of the Fluke 5500 until the voltage at pin-48 is 0VDC.

**6.2.31** The voltage at Pin-49 should be 5.3VDC.

**6.2.32** Reset the Fluke 5500 to .1V

**6.2.33** Turn Pot R30 fully CW.

**6.2.34** Again increase the amplitude of the Fluke5500A until the DC volts at Pin-46 begins to drop. The voltage on the Fluke 5500A should be approx 21VDC.

**6.2.35** Continue to increase the amplitude of the Fluke 5500A until the voltage at pin-46 is 0VDC.

**6.2.36** The voltage at Pin-47 should be 5.3VDC.

**6.2.37** Voltage should begin to drop on Pin-46 at 8V RMS on the Fluke 5500 and 18V RMS with R30 in CW position.

**6.2.38** Set the Fluke 5500 for 10V RMS.

**6.2.39** Measure the DC volts at Pin-13. It should measure approx 9.8VDC. Pin-14 should measure approx 10.2VDC

**6.2.40** Adjust the amplitude of Fluke 5500 until the current meter connect to Pin-12 = 20m Amps

**6.2.41** Move the input from the Fluke 5500 from Pin15 & Pin-16 to Pin 17 & Pin-18.

**6.2.42** Current should measure 20m Amps again.

**6.2.43** Move the input from the Fluke 5500 from Pin17 & Pin-18 to Pin 19 & Pin-20.

**6.2.44** Current should measure 20m Amps again.

**6.2.45** Power down and remove all connections from the unit under test.

**6.2.46** Apply +20VDC in series with a mA meter & 1.5K ohm resistor to Pin-13. Common of the supply to Pin-14.

**6.2.47** Current meter should measure less then 2m Amps.

**6.2.48** Reverse polarity on current meter, should measure 0m Amps

#### **6.3 \*\*\*TEST COMPLETE\*\*\***

### **7. NOTES**

**7.1** None at this time.

### **8. ATTACHMENTS**

**8.1** None at this time.