



ABB EPIS

Functional Testing Specification

Parts & Repair Services
Louisville, KY

LOU-GED-44C331863G02

Test Procedure for a GENERREX Relay card 44C331863-G02 card.

DOCUMENT REVISION STATUS: Determined by the last entry in the "REV" and "DATE" column

REV.	DESCRIPTION	SIGNATURE	REV. DATE
A	Initial release for -G02 versions only. G01 can be adapted later to this procedure.	J. Francis	09/05/2018

© COPYRIGHT ABB

Hard copies are uncontrolled and are for reference only.

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF ABB COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF ABB COMPANY.

PREPARED BY J. Francis	REVIEWED BY	REVIEWED BY	QUALITY APPROVAL L. Groves
DATE 09/05/2018	DATE	DATE	DATE 9/5/2018

LOU-GED-44C331863G02 Rev A	<div data-bbox="545 195 699 249" data-label="Image"> </div> <div data-bbox="730 268 980 344" data-label="Text"> <p>ABB EPIS Parts & Repair Services Louisville, KY</p> </div>	Page 2 of 10
-------------------------------	--	--------------

1. SCOPE

1.1 This is a functional testing procedure for a GENERREX Relay Card 44C331863-G02 card.

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.

3.1.1 Check board's electronic folder for more information.

4. ENGINEERING REQUIREMENTS

4.1 Equipment Cleaning

4.1.1 Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to site specific SRA's for cleaning guidelines.

4.2 Equipment Inspection

4.2.1 Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:

4.2.1.1 Wires - broken, cracked, or loosely connected

4.2.1.2 Terminal strips / connectors - broken or cracked

4.2.1.3 Components - visually damaged

4.2.1.4 Capacitors - bloated or leaking

4.2.1.5 Solder joints - damaged or cold

4.2.1.6 Circuit board - burned or de-laminated

4.2.1.7 Printed wire runs / Traces - burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
2	*	Fluke 87 DMM (or Equivalent)
2	*	Tenma Dual Power Supplies
1	*	44C Patch board

6. TESTING PROCESS

6.1 Testing Procedure

- 6.1.1 Insert Unit Under Test (UUT) into 44C Patch board.
- 6.1.2 Adjust F1P pot fully CCW.
- 6.1.3 Adjust F2P pot fully CCW.
- 6.1.4 Remove Fuses F1F and F2F.
- 6.1.5 Connect jumper F1S to terminals 1 to 2.
- 6.1.6 Connect jumper F2S to terminals 1 to 2.
- 6.1.7 Connect jumper F3S to terminals 2 to 3.
- 6.1.8 Connect jumper F4S to terminals 2 to 3.
- 6.1.9 Static connection checks

From:	To:	Results:
Pin 11	Pin 13	w/F1P fully CCW – 1060 to 1200 Ohms
Pin 11	Pin 13	w/F1P fully CW – 300 to 330 Ohms
Pin 11	Pin 15	w/F2P fully CW – 385 to 427 Ohms
Pin 13	Pin 15	w/F2P fully CW – 90 to 92 Ohms
Pin 9	Pin 28	Open
Pin 7	Pin 17	Open
Pin 19 (Positive lead)	Pin 22 (Neg Lead)	180 to 220 Ohms (FAR coil resistance)
Pin 19 (Neg lead)	Pin 22 (Positive lead)	180 to 220 Ohms (FAR coil resistance)
F2D Anode	F2D Cathode	Not Shorted
F3D Anode	F3D Cathode	Not Shorted

6.1.10 Visually check the following Components for correct values

- 6.1.10.1 Capacitors F1C and F2C are .33 uF
- 6.1.10.2 Resistors F10R and F11R are 150 Ohms.

6.1.11 Setup – Do not apply power at this time.

- 6.1.11.1 Connect 28 VDC Lamps to the following connections:

- 6.1.11.1.1 Pin 18 to Pin 28
- 6.1.11.1.2 Pin 20 to Pin 28
- 6.1.11.1.3 Pin 26 to Pin 28
- 6.1.11.1.4 Pin 27 to Pin 28

- 6.1.11.2 Connect jumper from Pin 21 to Pin 7.

- 6.1.11.3 Connect +24 VDC positive output to Pin 7 and 24 VDC return to Pin 9.

6.1.12 Testing

<p>LOU-GED-44C331863G02 Rev A</p>	<p>ABB</p> <p>ABB EPIS <i>Parts & Repair Services</i> <i>Louisville, KY</i></p>	<p>Page 4 of 10</p>
---	---	----------------------------

6.1.12.1 Apply Power to UUT.

6.1.12.1.1 Lamp connected to Pin 27 should light.

6.1.12.1.2 Lamp connected to Pin 20 should light.

6.1.12.1.3 "OUTPUT OFF" LED on front of UUT should light.

6.1.12.2 Press "OUTPUT ON" button on front of UUT. Lights should not change. Release button.

6.1.12.3 Connect Pin 17 to Pin 23.

6.1.12.4 Press "OUTPUT ON" button on front of UUT. Lights should not change. Release button.

6.1.12.5 Connect Pin 24 to Pin 25.

6.1.12.6 Press "OUTPUT ON" button on front of UUT.

6.1.12.6.1 "OUTPUT OFF" LED on front of UUT and lamp connected to Pin 27 should go out as long as button is pressed.

6.1.12.6.2 "OUTPUT ON" LED on front of UUT and lamp connected to Pin 26 should light as long as button is pressed.

6.1.12.7 Connect Pin 19 to Pin 10.

6.1.12.8 Connect Pin 22 to Pin 24.

6.1.12.8.1 Lamp connected to Pin 20 should go out.

6.1.12.8.2 Lamp connected to Pin 18 should light.

6.1.12.9 Press and release "OUTPUT ON" button of front of UUT. UUT should latch in this condition.

6.1.12.9.1 "OUTPUT OFF" LED on front of UUT and lamp connected to Pin 27 should go out.

6.1.12.9.2 "OUTPUT ON" LED on front of UUT and lamp connected to Pin 26 should light.

6.1.12.9.3 Press and release "OUTPUT OFF" button on front of UUT. Conditions listed in steps 6.1.12.9.1 and 6.1.12.9.3 should reverse.

6.1.12.9.4 Press and release "OUTPUT ON" button on front of UUT. Conditions listed in steps 6.1.12.9.1 and 6.1.12.9.3 should resume.

6.1.12.10 Disconnect Pin 17. "OUTPUT ON" LED should be off.

6.1.12.11 Connect Pin 17. "OUTPUT ON" LED should be off.

6.1.12.12 Disconnect Pin 24. "OUTPUT ON" LED should be off.

6.1.12.13 Connect Pin 24. "OUTPUT ON" LED should be off.

<p>LOU-GED-44C331863G02 Rev A</p>	<p>ABB</p> <p>ABB EPIS <i>Parts & Repair Services</i> <i>Louisville, KY</i></p>	<p>Page 5 of 10</p>
---	---	----------------------------

6.1.12.14 Press and release “OUTPUT ON” button on front of UUT.

6.1.12.14.1 “OUTPUT ON” LED should light.

6.1.12.15 Adjust F1p pot fully CCW.

6.1.12.15.1 Check resistance between Pin 11 to Pin 15 is between 950 to 1150 Ohms.

6.1.12.15.2 Check resistance between Pin 11 to Pin 13 is between 1050 to 1150 Ohms.

6.1.12.15.3 Check resistance between Pin 15 to Pin 13 is between 90 to 110 Ohms.

6.1.12.16 Connect adjustable power supply, set for 0 VDC, from Pin 11 and connect return to Pin 13.

6.1.12.17 Connect DMM, set to measure DC Volts, positive lead to Pin 15 and negative lead to Pin 13.

6.1.12.18 Slowly increase input on Pin 11 to +10 VDC ± 0.003 , making sure the “OUTPUT” meter on front of UUT tracks and follows input visually, within 3%.

6.1.12.19 With +10 VDC input connected to Pin 11, adjust F1P pot to read +1.00 VDC ± 0.03 VDC on meter connected to Pin 15.

6.1.12.20 Repeat steps 6.1.12.18 and 6.1.12.19 using negative voltages.

6.1.12.21 Adjust input on Pin 11 to +1.00 VDC.

6.1.12.22 Verify meter connected to Pin 15 reads +0.1 ± 0.003 VDC.

6.1.12.23 Adjust input on Pin 11 to -1.00 VDC.

6.1.12.24 Verify meter connected to Pin 15 reads -0.1 ± 0.003 VDC.

6.1.12.25 Press “OUTPUT OFF” button on front of UUT.

6.1.12.25.1 “OUTPUT OFF” LED should light.

6.1.12.25.2 Meter connected to Pin 15 should read 0 VDC.

6.1.12.26 Press “OUTPUT ON” button on front of UUT.

6.1.12.26.1 “OUTPUT ON” LED should light.

6.1.12.26.2 Meter connected to Pin 15 should read -0.1 ± 0.003 VDC.

6.1.12.27 Remove all power and connections.

6.2 *TEST COMPLETE*****


7. NOTES

7.1 Schematic Diagram 8.1 for setup reference.

7.2 Original test in 8.2 for testing reference.

8. ATTACHMENTS

8.1



REV NO.		TITLE		2 7 7 A 3 7 9 4	
2 7 7 A 3 7 9 4		Test Specifications		CONT ON SHEET 2 SH NO. 1	
CONT ON SHEET 2 SH NO. 1		FIRST MADE FOR 44C331863-G01 & G02			
<p>STANDING INSTRUCTIONS</p> <p>FOR RELAY</p> <p>RELAY PRINTED CIRCUIT BOARD</p> <p>FOR</p> <p>POWER SYSTEM STABILIZER</p>				REVISIONS	
<p>Distribution Copies:</p> <p>1 QC Eng.</p> <p>1 QC Test</p> <p>1 Eng.</p>				<p>3EL1</p> <p>4QA3</p> <p>1RA2</p> <p>4EK1</p> <p>DL13</p>	
<p>MADE BY RK Gerlitz 781109</p> <p>ISSUED 11-20-78</p>		<p>APPROVALS</p> <p><i>J.R. Person</i></p> <p>11/5/78</p>		<p>Drive Systems</p> <p>Salem, Va. USA</p>	
				<p>DIV OR DEPT. 2 7 7 A 3 7 9 4</p> <p>LOCATION CONT ON SHEET 2 SH NO. 1</p> <p>CODE IDENT NO.</p>	

FF-803 WF (11-77)
PRINTED IN U.S.A.

8.2

GENERAL ELECTRIC

REV NO.	TITLE		2 7 7 A 3 7 9 4																			
2 7 7 A 3 7 9 4	Test Specifications		CONT ON SHEET	SH NO. 2																		
CONT ON SHEET 3	SH NO. 2	FIRST MADE FOR 44C331863-G01 & G02																				
				REVISIONS																		
<p>I. Test Equipment Required</p> <p>A. Printed Circuit Board test setup 44C931365</p> <p>B. Adaptor Cable - Amp. Mod. II 30 pin.</p> <p>C. Adaptor Cable - Power Supplies</p> <p>D. Oscilloscope - Tektronix model 7403N or equivalent</p> <p>E. Patchboard PB-3.</p> <p>F. Drawings 44C306569 Elementary for G01 ③ 44C309094 " for G02 44C331863 Assembly 44C931365 Test Fixture</p>																						
<p>II. Connections</p> <p>A. Connect the Amp Mod II adaptor cable to "PL-1" on the Universal Tester (U.T.)</p> <p>B. Connect the Power Supply adapter cable to "PL-3" on the U.T. and to Power Supplies per lead markings.</p> <p>C. Insert patchboard PB-3 into carrier of U. T. and close.</p> <p>D. Connect a digital voltmeter to "BJ-1" and another to "BJ-2." (Red + and Black -).</p>																						
<p>III. Resistance Check</p> <p>Adjust 1P completely CCW. Remove F1F and F2F fuse. Connect Jumper 1S to Ter. 1-2 and Jumper 2S to Ter. 1-2, 3S to Ter. 2-3 and 4S to Ter. 2-3.</p> <p>① Adjust 2P completely CCW.</p> <p>Measure the following resistance:</p> <table border="1"> <thead> <tr> <th>Pin</th> <th>To</th> <th>Pin</th> <th>LP</th> <th>Resistance (Ohms)</th> <th>③ G02 only</th> </tr> </thead> <tbody> <tr> <td>11</td> <td></td> <td>13</td> <td>CCW</td> <td>1060 to 1200</td> <td>2060 to 2200</td> </tr> <tr> <td>11</td> <td></td> <td>13</td> <td>CW</td> <td>254 to 282</td> <td></td> </tr> </tbody> </table>				Pin	To	Pin	LP	Resistance (Ohms)	③ G02 only	11		13	CCW	1060 to 1200	2060 to 2200	11		13	CW	254 to 282		<p>3EL1</p> <p>4QA3</p> <p>1RA2</p> <p>4EK1</p> <p>DL13</p>
Pin	To	Pin	LP	Resistance (Ohms)	③ G02 only																	
11		13	CCW	1060 to 1200	2060 to 2200																	
11		13	CW	254 to 282																		
MADE BY RK Gerlitz 781109		APPROVALS J. R. P. 11/15/78		PRINTS TO																		
ISSUED 11-20-78		Drive Systems																				
		Salem, Va. USA																				
		LOCATION																				
		CONT ON SHEET 3																				
		SH NO. 2																				

FF-803 WF (11-77)
PRINTED IN USA.

REV. NO.		TITLE		2 7 7 A 3 7 9 4	
2 7 7 A 3 7 9 4		Test Specifications		CONT ON SHEET 4 SH NO. 3	
CONT ON SHEET 4 SH NO. 3		FIRST MADE FOR 44C331863-G01 & G02		REVISED	
11	15	2P CW	327/1A/368	385 to 427	②
13	15	2P CW	11447/1A/3443/12	90 to 92 *	
9	28			Inf. (X 100 scale)	
7	17			Inf. (X 100 scale)	
19 (+)	22 (-)			55-100 (X100 scale)	
19 (-)	22 (+)			180-220	
④ * If out of limits remove F3S and F4S and check each component individually. Reinsert fuses.				F5R = 95 to 105	
				F2P = 900 to 1100	
				Reinstall F3S and F4S	
IV. SETUP					
A. Turn all switches to OFF or NORMAL on both the UT and UPS.					
B. Install Dialco 28 volt 40 MA Lamps ③ "L18" in "L18", "L20", "L26" and "L27".					
C. Turn all D. C. power supplies to zero, then all varacs to zero on the UPS.					
D. Apply power to test stand.					
E. Install board to be tested into adaptor.					
V. Electrical Test					
A. Close "SW-1", "SW-18", "SW-20", "SW-26", "SW-34", depress "LPB-1" and increase PS-1 to 24 ±0.5 VDC at "BJ-1". Output Off light (④) shall be energized on PCB.					
② Note: Should it become necessary to remove all power from PC board, open "SW-1".					
B. Close "SW-21". "Light 20" shall energize. Close "SW-27". "Light 27" should energize.					
C. Depress Output On PB. No change in lights. Release Output On PB.					
D. Close "SW-17" then depress Output On PB. Again no change in lights. Release Output On PB.					
E. Close "SW-24". Then depress Output On PB. Output Off and light 27 shall deenergize and Output On and light 26 shall energize. Release Output On PB and Output On and light 26 deenergize and Output Off and light 27 energize.					
MADE BY		APPROVALS		DIV OR DEPT.	
RK Gerlitz 781109		J. K. Parnell		Drive Systems	
ISSUED 11-20-78		11/15/78		Salem, Va. USA	
				2 7 7 A 3 7 9 4	
				CONT ON SHEET 4 SH NO. 3	
				CODE IDENT NO.	

REV NO.		TITLE		2 7 7 A 3 7 9 4																																												
2 7 7 A 3 7 9 4		Test Specifications		CONT ON SHEET FL SH NO. 4																																												
CONT ON SHEET FL SH NO. 4		FIRST MADE FOR 44C331863-G01 & G02																																														
				REVISIONS																																												
<p>F. Close SW-22. Light 20 shall deenergize and light 18 shall energize.</p> <p>G. Depress and release Output on PB. Output Off and light 27 shall deenergize and Output On and light 26 shall be energized.</p> <p>H. Perform the following SW function and insure PCB will transfer from Output On to Output Off to Output On.</p> <table border="1"> <thead> <tr> <th>SW</th> <th>Open</th> <th>Closed</th> <th>Depress & Release</th> <th>Output</th> </tr> </thead> <tbody> <tr> <td>17</td> <td></td> <td>17</td> <td></td> <td>"OFF"</td> </tr> <tr> <td></td> <td></td> <td></td> <td>Output ON</td> <td>"OFF"</td> </tr> <tr> <td>24</td> <td></td> <td>24</td> <td></td> <td>"ON"</td> </tr> <tr> <td></td> <td></td> <td></td> <td>Output ON</td> <td>"OFF"</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td>"OFF"</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td>"ON"</td> </tr> </tbody> </table> <p>I. Adjust 1P completely CCW. Measure the following resistance.</p> <table border="1"> <thead> <tr> <th>Pin to Pin</th> <th>Resistance (Ohms)</th> </tr> </thead> <tbody> <tr> <td>11 15</td> <td>950 to 1150</td> </tr> <tr> <td>11 13</td> <td>1015 to 1150</td> </tr> <tr> <td>15 13</td> <td>90 to 110</td> </tr> </tbody> </table> <p>Remove Ohmmeter</p> <p>J. Connect an oscilloscope across 2D (or 20) then across 3D (or 1G) and check voltage delay time when Output Off PB is depressed. (Note the ground side of the oscilloscope can be connected to pin 28). TC = 25m sec. Verify F1C and F2C are .33 mfd. F1OR and F1LR are 150 ohm. -10-0+10</p> <p>K. Place "RS-1" to position on 1, close "SW-11" and slowly increase PS-4 to 10 volts at "BJ-2". Note that 110-110 voltmeter tracks BJ-2 voltage in a positive direction within 3%. Return PS-4 to Zero.</p> <p>L. Place "SW-11" down and repeat step K this time the voltage shall track in a negative direction. Return PS-4 to Zero.</p> <p>M. Open SW-1 then return remaining switches to OFF or Normal. Return power supplies to zero.</p> <p>① N. Measure forward resistance of F2D and F3D. Each shall be 7 to 80 ohms.</p>				SW	Open	Closed	Depress & Release	Output	17		17		"OFF"				Output ON	"OFF"	24		24		"ON"				Output ON	"OFF"					"OFF"					"ON"	Pin to Pin	Resistance (Ohms)	11 15	950 to 1150	11 13	1015 to 1150	15 13	90 to 110	<p>3EL1</p> <p>4QA3</p> <p>1RA2</p> <p>4EK1</p> <p>DL13</p> <p>PRINTS TO</p>	
SW	Open	Closed	Depress & Release	Output																																												
17		17		"OFF"																																												
			Output ON	"OFF"																																												
24		24		"ON"																																												
			Output ON	"OFF"																																												
				"OFF"																																												
				"ON"																																												
Pin to Pin	Resistance (Ohms)																																															
11 15	950 to 1150																																															
11 13	1015 to 1150																																															
15 13	90 to 110																																															
MADE BY RK Gerlitz 781109		APPROVALS <i>J.R. P...</i> 11/15/78		Drive Systems DIV OR DEPT. 2 7 7 A 3 7 9 4																																												
ISSUED 11-20-78		Salem, Va. USA LOCATION		CONT ON SHEET FL SH NO. 4																																												

FF-803 WF (11-77) PRINTED IN U.S.A.