

ENGINEERING MANUFACTURING INSTRUCTIONS — No. 5764



SUBJECT

CARD TESTING

SECTION— 551

PART— 1&3

PAGE— 1

CONT'D on PG.— 2

CAN-GEB-0621L0551-A

1. PURPOSE


Testing of: INPUT BRIDGE (DC TACH) 621L551G1

2. ELEMENTARY

S&C Data Bk 1190 sect 551 Dwg 266A9872

3. EQUIPMENT

- a) PN15VDC Reg Power Supply
15VDC Variable Power Supply
- b) Multimeter John Fluke 8300 or equiv.
- c) Resistor 1 M ohm 1% 177A1017P17
- d) Resistor 10K 1% 177A1015 P 023
- e) Resistor 620 2W 0.1% 177A1015 P 023

4. SET-UP5. TESTS

a) Power Supply

- 1) Apply PN15VDC
- 2) Adjust R9 for +10V \pm 0.1V at P10V
- 3) Adjust R10 for -10V \pm 0.1V at N10V

CP13

CP14

LET WARM UP
FEW MINS

b) Switch operation

- 1) Connect CP21 to CP22 and measure the voltage at CP17 for the following conditions.

Prepared By

H. Keyzers

Section and Unit

IC 910

Date Issued

30 Aug 78

Supersedes Issue Dated

New

Type Names

Prod. Engineering J.T. Strong

Manuf. Eng. J. Leanos

Quality Control H. Marksfield

Engr's Lab.

Signatures

A.C. Strong

S. Leanos

H. Marksfield

SIGNATURES PREPARED AS SHOWN

ENGINEERING MANUFACTURING INSTRUCTIONS — No. 5764



SUBJECT

CARD TESTING

SECTION— 551

PART— 1 & 3

PAGE— 2

CONT'D on PG.—

SET +E-10V

CONNECT	PB1	RB	ITB13	ITB16	CP 17
CP 16	DOWN	CW	OPEN	OPEN	+ 5.48
CP 14	DOWN				-5V
CP 15 TO:	UP				0V
				0V	-5V
CP 13				OPEN	0V
CP 12			0V		+5V
TO:			0V		-5V
CP 11	UP	CCW	0V		0V

2) Measure voltage at TB-11 for

	TB-10	TB-12	R7	R6	TB-11
i)	OPEN	OPEN	CW	CCW	0
ii)	0 VOLTS	OPEN	CCW	CCW	0
iii)	OPEN	0 VOLTS	CCW	CW	-0.75V
iv)	OPEN	OPEN	CCW	CW	0
c) Tach input	OPEN	OPEN	CW	CCW	+0.75V

- 1) Connect 1 M ohm 1% resistor in place of R31.
- 2) With R1 CW and TB-1 connected to 0V
Adjust R3 for 0V + 1 mV at CP3
- 3) Similarly adjust R4 for 0V + 1mV at TB2.
- 4) Apply +1V to TB-1
- 5) With R1 CW CP3 should be -5.5V ± .55V and TB-2
should be +5.5V ± 0.55.
- 6) With R1 CCW CP3 should be -0.5V ± .2V and TB-2
should be +0.5V ± .2V.

(Rev input for same results)

d) Tach Amp

- 1) Connect CP2 to CP3. Connect 10K 1% resistor in place of R80.
- 2) Apply approx 1V to TB-1 and adjust R1 until CP3 is -5.0V.
- 3) Voltage at CP5 should then be +5.0 ± .1V (Rev input + check)
- 4) Connect ammeter between TB-6 and 0V
- 5) With CP5 at 5V current should be 1 mA for R5 CW
and 0.33 mA for R5 CCW $900 \mu A$
- 6) Connect ammeter between TB-4 and 0V
- 7) Current should be 1mA for R2 CW and -0.33 mA for R2 CCW

Prepared By H. Keyzers	Section and Unit IC 910	Type Names Prod. Engineering J.T. Strong	Signatures J.T. Strong
Date Issued 30 Aug 78	Supersedes Issue Dated New	Manuf. Eng. J. Leanos	J. Leanos
SIGNATURES REQUIRED AS SHOWN		Quality Control H. Marksfield	H. Marksfield
		Eng'n. Lab	

ENGINEERING MANUFACTURING INSTRUCTIONS — No. 5764



SUBJECT

CARD TESTING

 SECTION— 551
 PART— 1&3
 PAGE— 3
 CONT'D on PG.— F
e) Absolute value op-amp and relay driver **connect TB2 to TB5**

- 1) Connect 620 ohm resistor between TB-8 and 0V **orig'g TB5**
- 2) Connect CP5 to CP6
- 3) Adjust voltage at TB-1 to 0V
- 4) Voltage at TB-8 should be $P15 \approx 12V + 12.7V$
- 5) Increase voltage at TB-1 until TB-8 is 0V **(1/P on 12V+)**
- 6) Voltage at CP6 should be $> +1V.9V$
- 7) Decrease voltage at TB-1 to 0V and TB-8 should go to $P15V$ again $\approx 12V$

~~8) Decrease voltage at TB-1 until TB-8 is 0V~~
~~9) Voltage at CP6 should be $> +1V.9V$~~

f) Reference Clamp

INTERACT

- 1) Connect TB-21 & TB-22 to 0V
- 2) Adjust R11 for $0V + .1 mV$ at CP19
- 3) Adjust R12 for $0V + .1 mV$ at CP23 **Repeat 2+3 till $0 \pm .1 mV$**
- 4) Connect TB-22 to $-10.000V$. Leave TB-21 at 0V
- 5) Note: In the following test it is imperative that that same meter is used on the same scale and the same input lead configuration.
 - a) Connect DVM(+) of meter to TB-18(0V)
 - b) " DVM(-) " " " TB-22
 - c) Note this reading $-10V$
 - d) Connect DVM(+) of meter to TB-18(0V)
 - e) " DVM(-) " " " CP-19
 - f) Adjust R13 to read $10.000V (+ 1mV)$ **ADJ TO READ AS C**
 - g) Connect DVM(+) of meter to CP23
 - h) " DVM(-) " " " TB18(0V)
 - i) Adjust R14 to read $0V + 1mV$

g) Measure resistance from:

CP20 to CP23	@ 10K ohm	
CP20 " TB20	@ 15K	RH1 CW
CP20 " TB20	@ 65K	RH1 CCW
CP20 " CP18	@ 165K	RH1 CCW

6. SEALING

The following pots are to be sealed
 R3, R4, R9, R10, R11, R12, R13, R14

Prepared By H. Keyzers	Section and Unit IC 910	Type Names Prod. Engineering JT Strong	Signatures J. Stevenson
Date Issued 30 Aug 78	Supersedes Issue Dated New	Manuf. Eng. J. Legros	S. Legros 10/2/78
SIGNATURES REQUIRED AS SHOWN		Quality Control H. Marksfield	