

# ABB

## Functional Testing Specification

**ABB**  
Parts & Repair Services  
Louisville, KY

LOU-GED-DS3800HPTP

### Test Procedure for a Card that goes on a PEG Module

**DOCUMENT REVISION STATUS:** Determined by the last entry in the "REV" and "DATE" column

REV.	DESCRIPTION	SIGNATURE	REV. DATE
A	Initial release	R. Johnson	3/30/2009
B	Correct some typos	S. Cash	5/18/2009
C	Comment in 6.2.3.1.1	J. Hardin	9/14/2009
D	Rewrite of procedure to accommodate new test fixture	S. Pharris	11/01/10
E	Added steps 6.2.1.12 & 6.2.1.14	S. Cash	9/5/2017
F.	Added steps 6.1.2 & 6.3.1	D. Bush	10/18/2017
G.	Inserted additional step at 6.2.1.6	D. Bush	1/2/2020

**PREPARED BY**  
Roger Johnson

**REVIEWED BY**  
Scott Cash

**REVIEWED BY**  
D. Bush

**QUALITY APPROVAL**  
*Charlie Wade*

**DATE**  
3/30/2009

**DATE**  
5/18/2009

**DATE**  
1/2/2020

**DATE**  
3/30/2009

**Functional test procedure for a DS3800HPTP Card**

**1. SCOPE**

1.1 This is a functional testing procedure for a DS3800HPTP Card.

**2. STANDARDS OF QUALITY**

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

**3. APPLICABLE DOCUMENTS**

3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.

3.1.1 See electronic folder for more information

**4. ENGINEERING REQUIREMENTS**

**4.1 Equipment Cleaning**

4.1.1 Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.

**4.2 Equipment Inspection**

4.2.1 Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:

4.2.1.1 Wires broken or cracked

4.2.1.2 Terminal strips / connectors broken or cracked

4.2.1.3 Loose wires

4.2.1.4 Components visually damaged

4.2.1.5 Capacitors leaking

4.2.1.6 Solder joints damaged or cold

4.2.1.7 Circuit board burned or de-laminated

4.2.1.8 Printed wire runs burned or damaged

**5. EQUIPMENT REQUIRED**

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

<b>Qty</b>	<b>Reference #</b>	<b>Description</b>
2		Fluke 87 DMM (or Equivalent)
1	H188955	PEG Test Station
1		O-Scope
1		AC Current Probe
1		Function Generator

## **6. TESTING PROCESS**

### **6.1 Setup**

**6.1.1** Install card in test fixture and make all connections.

**6.1.2** Remove jumper wire from TP6 to TP9.

### **6.2 Testing Procedure**

#### **6.2.1 Power On**

**6.2.1.1** Apply power to the unit by setting switch to "ON W/FAN" position.

**6.2.1.2** Adjust Variac for 120VAC +/- 1% between green jacks on top of fixture labeled 120VAC with reference to ACOM (black jack in middle).

**6.2.1.3** Verify IMOK LED CR52 and Firing LED CR51 are ON.

**6.2.1.4** With DMM across JD1 to JD2 should read short.

**6.2.1.5** Verify the voltages listed below using the jacks on the top of the fixture.

TP7	+10V
TP4	+15V
TP6	-15V

**6.2.1.6** After verifying above voltages, plug meter back in +10v(TP7), open test fixture drawer and adjust the AMTRAK SCR firing box both full on and full off. The +10v on TP7 should not vary more than .1 Vdc. (Note for repairs: If this step fails change U3 on main circuit board.)

**6.2.1.7** Verify steady firing pulses on O-Scope with approx 9.5 Amps amplitude.  
(Depending on the scope you are using you may have to measure the current as a peak to peak voltage. It will read approx 9.5V)

**6.2.1.8** Verify red and black jumpers on front of fixture are connected red to red and black to black.

**6.2.1.9** Set SW1 "UP" to turn on auxiliary power supply

**6.2.1.10** Using DMM verify 12VDC at jacks on front of fixture

**6.2.1.11** Set SW2 "UP"

**6.2.1.12** Push Black push button. IMOK LED should go OFF.

**6.2.1.13** Push Black push button again and verify JA-6 jack goes zero volts.

**6.2.1.14** Set SW2 "DOWN" and press Red push button. The IMOK will be OFF.

**6.2.1.15** Push Red push button again and verify JA-6 jack goes zero volts.

**6.2.1.16** Adjust the voltage to 7V on the red and black jacks.

**6.2.1.17** Connect the red test jack to the black test jack so as to form an X.

**6.2.1.18** Press Red push button JD1 to JD2 should open briefly.

**6.2.1.19** CR50 0V Fire LED should come ON and stay ON when button is released.  
(CR50 must latch, if it does not there is a problem with the card.)

**6.2.1.20** Push SW1 (on unit next to CR50).

**6.2.1.21** CR50 0V Fire LED should turn OFF.

**6.2.1.22** Set SW2 "UP"

**6.2.1.23** Press Black Button JD1 to JD2 should open briefly

**6.2.1.24** CR50 0V Fire LED should come ON and stay ON when button is released.

**6.2.1.25** Push SW1 (on unit next to CR50).

**6.2.1.26** CR50 0V Fire LED should turn OFF.

**6.2.1.27** Set SW1 "DOWN" to remove auxiliary power .

**6.2.1.28** Power down entire fixture for ten seconds then reapply power by setting  
switch back to "ON W/FAN" position.

**6.2.1.29** Allow unit to run for a minimum of one hour then re-verify pulse amplitude.

**6.3 \*\*\*TEST COMPLETE \*\*\***

**6.3.1** Reconnect jumper wire from TP6 to TP9.

**6.4**

**7. Notes**

**7.1** None at the time.

**8. Attachment**

**8.1** Picture of Test Fixture

**LOU-GED-DS3800HPTP  
REV. G**

**ABB**  
*Parts & Repair Services  
Louisville, KY*

**Page 5 of 5**

