

# Error Codes Directory

## All Robots



The information contained herein is the property of Universal Robots A/S and shall not be reproduced in whole or in part without prior written approval of Universal Robots A/S. The information herein is subject to change without notice and should not be construed as a commitment by Universal Robots A/S. This document is periodically reviewed and revised.

Universal Robots A/S assumes no responsibility for any errors or omissions in this document.

Copyright © 2009-2025 by Universal Robots A/S.

The Universal Robots logo is a registered trademark of Universal Robots A/S.



# Contents

<b>1. Introduction</b>	<b>12</b>
1.1. C0 No error	12
1.2. C1 Outbuffer overflow	12
1.3. C2 Inbuffer overflow	12
1.4. C3 Processor overloaded	12
1.5. C4 Communication issue	12
1.6. C5 Heavy processor load warning	19
1.7. C10 Controller communication issue	19
1.8. C11 Bad CRC	19
1.9. C12 Unknown message error	19
1.10. C14 Debug message	19
1.11. C17 Communication error between Safety Control Board and Motherboard	19
1.12. C25 Motor Encoder index missing	20
1.13. C26 Motor Encoder index drift detected	20
1.14. C27 Calibration data is invalid or does not exist, selftest is needed!	20
1.15. C29 Online Calibration data checksum failed	20
1.16. C30 Master received data from too many joints	20
1.17. C31 Caught wrong message (not from master)	20
1.18. C32 Flash write verify failed	21
1.19. C33 Calibration flash checksum failed	21
1.20. C34 Program flash checksum failed	21
1.21. C35 Joint ID is undefined	21
1.22. C36 Illegal bootloader command	21
1.23. C37 Inbuffer parse error	21
1.24. C38 Online RAM test failed	21
1.25. C39 Logic and Temporal Monitoring Fault	22
1.26. C40 AD-Converter hit high limit joint	23
1.27. C41 RC Oscillator Trim register hit high limit	23
1.28. C42 RC Oscillator Trim register hit low limit	23
1.29. C43 Change in invariant memory detected	23
1.30. C44 CRC check failure on primary bus	23
1.31. C45 AD-Converter error	24
1.32. C46 Loose gearbox or bad encoder mounting	24
1.33. C47 AD-Converter hit low limit	24
1.34. C49 RS485 receive warning	24
1.35. C50 Robot powerup issue	24



1.36. C51 CRC check failure on secondary bus .....	26
1.37. C53 IO overcurrent detected .....	27
1.38. C55 Safety system error .....	27
1.39. C56 Overvoltage shutdown .....	29
1.40. C57 Brake release failure .....	29
1.41. C58 Motor encoder not calibrated .....	29
1.42. C59 Overcurrent shutdown .....	29
1.43. C60 Energy surplus shutdown .....	29
1.44. C61 Idle power consumption to high .....	30
1.45. C62 Thermal issue .....	30
1.46. C63 Motor test failed in step {unsigned}. ....	30
1.47. C65 PSU voltage to high .....	30
1.48. C68 SPI error .....	30
1.49. C70 Close to gearbox shear limit .....	31
1.50. C71 Startup check error .....	31
1.51. C72 Power Supply Unit failure .....	33
1.52. C73 Brake test failed during selftest, check brakepin .....	33
1.53. C74 Joint encoder warning .....	33
1.54. C75 Joint encoder error .....	34
1.55. C76 Joint encoder communication CRC issue .....	34
1.56. C77 Sudden position change detected on the joint-encoder .....	35
1.57. C78 Large sudden position change detected on the joint-encoder .....	35
1.58. C85 Motor encoder error .....	35
1.59. C100 Robot changed mode .....	35
1.60. C101 Real Robot Connected .....	35
1.61. C102 Real Robot not connected - Simulating Robot .....	35
1.62. C103 Communication issue .....	35
1.63. C104 Error=Empty command sent to robot .....	36
1.64. C111 Something is pulling the robot .....	36
1.65. C115 Unknown robot type .....	36
1.66. C116 Realtime part warning .....	36
1.67. C117 Restart SCB failed .....	36
1.68. C150 Position close to joint limits .....	36
1.69. C151 Tool orientation close to limits .....	37
1.70. C152 Position close to safety plane limits .....	37
1.71. C153 Position deviates from path .....	37
1.72. C154 Position in singularity .....	37
1.73. C155 Robot cannot maintain its position, check if payload is correct .....	38

1.74. C156 Wrong payload or mounting detected, or something is pushing the robot when entering Freedrive mode .....	38
1.75. C157 Collision detected by joint .....	38
1.76. C158 Collision detected by joint .....	39
1.77. C159 Position deviates from path .....	40
1.78. C160 The robot was powered off last time due to a joint position disagreement .....	40
1.79. C161 Large movement of the robot detected while it was powered off. The joints were moved while it was powered off, or the encoders do not function .....	41
1.80. C162 The protective stop was likely caused by incorrectly specified payload mass and/or center of gravity. ....	41
1.81. C171 Issue with blends .....	41
1.82. C172 Illegal control mode .....	42
1.83. C173 Robot motion causes too high joint torques .....	42
1.84. C174 Robot motion causes too high jump in joint torques .....	43
1.85. C184 Joint self test not received by controller .....	44
1.86. C187 Temperature sensor test failed .....	44
1.87. C190 Joint failed during selftest .....	44
1.88. C191 Safety system violation .....	44
1.89. C192 Safety system fault .....	46
1.90. C193 One of the nodes is in fault mode .....	49
1.91. C194 One of the nodes is not booted or not present .....	51
1.92. C195 Conveyor speed too high .....	52
1.93. C196 MoveP speed too high .....	52
1.94. C197 Blend overlap warning .....	52
1.95. C200 Safety Control Board hardware error .....	52
1.96. C201 Setup of Safety Control Board failed .....	56
1.97. C202 SCE configuration was illegal, after applying tolerances .....	56
1.98. C203 PolyScope detected a mismatch between the shown and (to be) applied safety parameters .....	56
1.99. C204 Path sanity check failed .....	57
1.100. C205 Target speed does not match target position .....	57
1.101. C206 Sanity check failed .....	57
1.102. C207 Fieldbus input disconnected .....	58
1.103. C208 Debug Assertion failed .....	58
1.104. C209 A protective stop was triggered (for test purposes only) .....	58
1.105. C210 Socket is read-only when the robot is in local (Teach pendant) control .....	58
1.106. C211 Operational mode changed .....	58
1.107. C212 Name conflict in loaded program .....	58
1.108. C213 No Kinematic Calibration found (calibration.conf file is either corrupt or missing) ....	59
1.109. C214 Kinematic Calibration for the robot does not match the joint(s) .....	59



1.110. C215 Kinematic Calibration does not match the robot .....	59
1.111. C216 The offset of the joint has changed .....	59
1.112. C217 White space detected at the beginning of a string token at line {unsigned} .....	60
1.113. C218 A thread used a lot of time .....	60
1.114. C219 Change in offset is too high .....	60
1.115. C220 Kinematic Calibration .....	60
1.116. C221 GUI Communication .....	61
1.117. C257 An unexpected message was received (header {hex}) .....	61
1.118. C258 Message contains invalid payload, data {unsigned} .....	61
1.119. C259 Filesystem-related issue .....	61
1.120. C260 Brake Release - old procedure .....	64
1.121. C261 Temperature Sensor .....	66
1.122. C262 Communication .....	66
1.123. C263 Motor Encoder .....	68
1.124. C264 Task Manager .....	69
1.125. C265 Joint Encoder .....	70
1.126. C266 Self-test .....	73
1.127. C267 Bootloader error .....	76
1.128. C268 Special Command .....	77
1.129. C269 Transceiver - deprecated .....	77
1.130. C270 Self-test SYNC .....	85
1.131. C271 Low level real-time thread .....	86
1.132. C272 Missing calibration .....	86
1.133. C273 Cross monitoring .....	86
1.134. C274 Control box fan error .....	94
1.135. C275 Brake Pin .....	94
1.136. C276 Uart .....	95
1.137. C277 Memory .....	95
1.138. C278 Servo .....	96
1.139. C279 Flash .....	97
1.140. C280 Real-time error .....	98
1.141. C281 Robot State Machine .....	98
1.142. C282 SysTick .....	99
1.143. C283 Safety system .....	100
1.144. C284 Brake Release .....	110
1.145. C285 Joint Keep-Alive System .....	111
1.146. C286 Motor Controller .....	112
1.147. C287 Saved files .....	113
1.148. C288 IO control .....	113



1.149. C289 Tool Connector .....	113
1.150. C290 I2C .....	114
1.151. C291 EEPROM .....	115
1.152. C292 Online RAM test .....	115
1.153. C293 Exception .....	116
1.154. C294 ADC .....	117
1.155. C295 PCB .....	117
1.156. C296 Start up check .....	118
1.157. C297 Joint validation .....	120
1.158. C298 Hand protection .....	122
1.159. C299 Tool communication .....	122
1.160. C300 Safety message .....	123
1.161. C301 Safety message monitor .....	124
1.162. C302 Tool Configuration .....	125
1.163. C303 System status .....	125
1.164. C304 Self monitoring .....	126
1.165. C305 Robot Power Control .....	127
1.166. C306 Joint .....	128
1.167. C307 Data B: {data} .....	129
1.168. C308 Data A: {data} .....	129
1.169. C309 Keep-Alive System .....	129
1.170. C311 Delay Callback .....	130
1.171. C312 Data validation .....	130
1.172. C313 App version .....	131
1.173. C314 SPI IO .....	131
1.174. C315 Watchdog .....	132
1.175. C316 MCU .....	133
1.176. C317 Failure injection .....	134
1.177. C318 Stack monitor .....	134
1.178. C319 Filesys Diagnostic Tool .....	135
1.179. C320 REDnet BLVDS .....	135
1.180. C321 REDnet RS485 .....	141
1.181. C322 Switch .....	146
1.182. C323 SCB Endpoint .....	146
1.183. C324 TP UART .....	147
1.184. C325 SPI uA .....	147
1.185. C326 SPI uB .....	148
1.186. C327 PCIe .....	149
1.187. C328 Transceiver miscellaneous .....	149



1.188. C329 AXI STREAM .....	150
1.189. C330 IMMI IO .....	150
1.190. C331 Friction model .....	151
1.191. C332 Servo configuration .....	151
1.192. C333 File message .....	151
1.193. C334 Robot deviated from constrained axes while in Constrained Freedrive. ....	152
1.194. C336 Hardware configuration manager .....	152
1.195. C337 Control parameters .....	152
1.196. C338 PROFIsafe .....	153
1.197. C339 Cross communication .....	154
1.198. C340 Energy Monitoring .....	154
1.199. C400 Elbow position close to safety plane limits .....	154
1.200. C401 Exceeding user safety settings for stopping time .....	154
1.201. C402 Exceeding user safety settings for stopping distance .....	155
1.202. C403 Danger of clamping between the Robot's lower arm and tool .....	155
1.203. C404 Unexpected behavior .....	155
1.204. C450 Force-Torque sensor .....	155
1.205. C499 Motorencoder calibration .....	156
1.206. C500 Self-test step .....	156
1.207. C501 PC Selftest message .....	157
1.208. C502 Additional information .....	158
1.209. C503 Limit Violation - ADC calibration .....	158
1.210. C504 Limit Violation - Commutation offset calibration .....	159
1.211. C505 Limit Violation - Brake test .....	159
1.212. C506 Limit Violation - Zero torque offset calibration .....	159
1.213. C507 Limit Violation - Joint Calibration .....	160
1.214. C508 Deviation - Joint Calibration .....	160
1.215. C509 Limit Violation - Cogging calibration .....	160
1.216. C510 Limit Violation - Temperature .....	161
1.217. C511 Limit Violation - Joint encoder calibration .....	161
1.218. C512 Limit Violation - Motor encoder calibration .....	161
1.219. C513 Motor encoder statistics .....	161
1.220. C514 Limit Violation - RLS Encoder Signal Quality .....	162
1.221. C515 Limit Violation - Motor Parameters .....	162
1.222. C516 Selftest disagreement .....	162
1.223. C517 Limit Violation - Vibration Measurement .....	162
1.224. C518 Joint Selftest Data Message .....	163
1.225. C519 Limit Violation - Hardware Information .....	163
1.226. C520 Limit Violation - Commutation Offset Correction .....	163

1.227. C522 Limit Violation - Kinematic Error Calibration .....	163
1.228. C710 ROM Test .....	164
1.229. C720 LVD (low voltage detection) .....	164
1.230. C740 Hardware monitoring .....	164
1.231. C900 Debug message data: {data} .....	166



# 1. Introduction

Error codes are used in the robot error messages, Date Log, saved error reports and URScript Programming Language.

If the software prompts an error, immediately press emergency stop, write down the conditions that led to the error, find the corresponding error codes on the log screen, and contact your supplier.

The abbreviations in this document mean the following:

- On the Safety Control Board: Processor A = A uP = SafetySys1
- On the Safety Control Board: Processor B = B uP = SafetySys2
- PSU = Power Supply
- PC = Controller
- LVD = Low Voltage Detected

## 1.1. C0 No error

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.2. C1 Outbuffer overflow

### **C1A1 Buffer of stored warnings overflowed**

### **C1A2 Outbuffer to RS485 overflowed (problem with Controller message)**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.3. C2 Inbuffer overflow

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.4. C3 Processor overloaded

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.5. C4 Communication issue

### **C4A1 Lost communication with Controller**

#### EXPLANATION

Communication was lost between the Safety Control Board and the Motherboard

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check Ethernet cable between Safety Control Board and Motherboard, check that a script or UR+ software is not overloading the communication between the Safety Control Board and Motherboard, (B) Conduct a complete rebooting sequence, (C) Update the software

## **C4A2 Lost communication with Safety Control Board A uP**

### **SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check TCP/IP connection between Motherboard and Safety Control Board, (B) Conduct a complete rebooting sequence, (C) Exchange Safety Control Board

## **C4A3 Communication with Safety Control Board B uP lost**

### **SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check TCP/IP connection between Motherboard and Safety Control Board, (B) Conduct a complete rebooting sequence, (C) Exchange Safety Control Board

## **C4A4 Communication with primary Teach Pendant uP lost**

### **SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check RS485-12V connection between Motherboard and Teach Pendant, (B) Conduct a complete rebooting sequence, (C) Exchange Teach Pendant

## **C4A5 Communication with secondary Teach Pendant uP lost**

### **SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check RS485-12V connection between Motherboard and Teach Pendant, (B) Conduct a complete rebooting sequence, (C) Exchange Teach Pendant

## **C4A6 Communication with primary EUROMAP67 uP lost**

### **SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check Euromap67 connection between Motherboard and Teach Pendant, (B) Conduct a complete rebooting sequence, (C) Exchange Teach Pendant

## **C4A7 Communication with secondary EUROMAP67 uP lost**

### **SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check Euromap67 connection between Motherboard and Teach Pendant, (B) Conduct a complete rebooting sequence, (C) Exchange Teach Pendant

## **C4A8 Primary EUROMAP67 uP present, but euromap67 is disabled**

### **EXPLANATION**

Incorrect safety configuration

### **SUGGESTION**

Try the following actions to see which resolves the issue: (A) Update the miscellaneous settings in the Safety Configuration, (B) Conduct a complete rebooting sequence

## **C4A9 Secondary EUROMAP67 uP present, but euromap67 is disabled**

### **EXPLANATION**

Incorrect safety configuration

### **SUGGESTION**

Try the following actions to see which resolves the issue: (A) Update the miscellaneous settings in the Safety Configuration, (B) Conduct a complete rebooting sequence

## **C4A10 Primary Teach Pendant present, but Teach Pendant safety is disabled**

### **EXPLANATION**

Incorrect safety configuration

### **SUGGESTION**

Try the following actions to see which resolves the issue: (A) Update the miscellaneous settings in the Safety Configuration, (B) Conduct a complete rebooting sequence

## **C4A11 Secondary Teach Pendant uP present, Teach Pendant safety is disabled**

**EXPLANATION**

Incorrect safety configuration

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Update the miscellaneous settings in the Safety Configuration, (B) Conduct a complete rebooting sequence

**C4A12 Communication with joint 0 lost****EXPLANATION**

More than 1 package lost

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A13 Communication with joint 1 lost****EXPLANATION**

More than 1 package lost

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A14 Communication with joint 2 lost****EXPLANATION**

More than 1 package lost

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A15 Communication with joint 3 lost****EXPLANATION**

More than 1 package lost

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A16 Communication with joint 4 lost****EXPLANATION**

More than 1 package lost

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly (B) Conduct a complete rebooting sequence

**C4A17 Communication with joint 5 lost****EXPLANATION**

More than 1 package lost

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A18 Communication with tool lost****EXPLANATION**

More than 1 package lost

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly (B) Conduct a complete rebooting sequence

**C4A65 Lost package from Primary Teach Pendant****EXPLANATION**

1 package lost

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A66 Lost package from Secondary Teach Pendant****EXPLANATION**

1 package lost

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A67 Lost package from Primary Euromap67****EXPLANATION**

1 package lost

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A68 Lost package from Secondary Euromap67****EXPLANATION**

1 package lost

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A69 Lost package from Secondary Masterboard****EXPLANATION**

1 package lost

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A70 Lost package from joint 0****EXPLANATION**

Serial communication problem with one or more joints

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A71 Lost package from joint 1****EXPLANATION**

Serial communication problem with one or more joints

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A72 Lost package from joint 2****EXPLANATION**

Serial communication problem with one or more joints

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A73 Lost package from joint 3****EXPLANATION**

Serial communication problem with one or more joints

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A74 Lost package from joint 4****EXPLANATION**

Serial communication problem with one or more joints

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A75 Lost package from joint 5****EXPLANATION**

Serial communication problem with one or more joints

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A76 Lost package from tool****EXPLANATION**

Serial communication problem with one or more joints

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A77 Lost package from uPA to joints****EXPLANATION**

1 package lost

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A78 Lost package from uPA to teach pendant****EXPLANATION**

1 package lost



**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A79 Lost package from uPA to uPB****EXPLANATION**

1 package lost

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A80 Lost package from uPB****EXPLANATION**

1 package lost

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A81 Packet counter disagreement in packet from Primary Screen****EXPLANATION**

Safety processor 1 in Teach Pendant has a packet disagreement

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A82 Packet counter disagreement in packet from Secondary Screen****EXPLANATION**

Safety processor 2 in Teach Pendant has a packet disagreement

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A83 Packet counter disagreement in packet from Primary Euromap67****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A84 Packet counter disagreement in packet from Secondary Euromap67****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A85 Packet counter disagreement in packet from Safety Control Board B****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A86 Packet counter disagreement in packet from joint 0****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A87 Packet counter disagreement in packet from joint 1**

**SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A88 Packet counter disagreement in packet from joint 2****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A89 Packet counter disagreement in packet from joint 3****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A90 Packet counter disagreement in packet from joint 4****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A91 Packet counter disagreement in packet from joint 5****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A92 Packet counter disagreement in packet from tool****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A93 Packet counter disagreement in packet from processor A to joints****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A94 Packet counter disagreement in packet from processor A to B****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A95 Packet counter disagreement in packet from processor A to Teach Pendant and EUROMAP****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

**C4A100 Communication lost due to Packet counter disagreements****SUGGESTION**

If this happens often, try the following actions to see which resolves the issue: (A) Verify the communication cables are connected properly, (B) Conduct a complete rebooting sequence

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.6. C5 Heavy processor load warning

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.7. C10 Controller communication issue

### **C10A1 Lost packet from Controller**

#### **C10A101 Controller packet received too early**

#### **C10A102 Packet counter does not match**

#### **C10A103 Controller is sending packets too often**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.8. C11 Bad CRC

### EXPLANATION

Serial communication problem with joint

### SUGGESTION

Check black 2-wire connectors and wires in joints

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.9. C12 Unknown message error

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.10. C14 Debug message

### **C14A1 {float}**

### **C14A2 {signed}**

### **C14A3 {unsigned}**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.11. C17 Communication error between Safety Control Board and Motherboard

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check Ethernet connection between circuit boards, (B) Conduct a complete rebooting sequence, (C) Update the software

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.



## 1.12. C25 Motor Encoder index missing

### EXPLANATION

Joint mechanical problem, reader head skipped an index mark. Joint needs repair or replacement.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.13. C26 Motor Encoder index drift detected

### EXPLANATION

Joint mechanical problem, reader head cannot detect index marks. Joint needs repair or replacement.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.14. C27 Calibration data is invalid or does not exist, selftest is needed!

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice, replace joint

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.15. C29 Online Calibration data checksum failed

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice, replace joint

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.16. C30 Master received data from too many joints

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.17. C31 Caught wrong message (not from master)

### EXPLANATION

Serial communication problem with joint

### SUGGESTION

Check black 2-wire connectors and wires on joints

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.18. C32 Flash write verify failed

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.19. C33 Calibration flash checksum failed

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.20. C34 Program flash checksum failed

### SUGGESTION

Update Firmware

**C34A0 Program flash checksum failed during bootloading**

**C34A1 Program flash checksum failed at runtime**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.21. C35 Joint ID is undefined

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.22. C36 Illegal bootloader command

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.23. C37 Inbuffer parse error

### EXPLANATION

Serial communication problem with joint

### SUGGESTION

Check black 2-wire connectors and wires on joints

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.24. C38 Online RAM test failed

### SUGGESTION

Check the log file for what item is reporting this error. Replace the reporting item

**C38A1 Data-bus test failed**

**C38A2 Address-bus stuck-high test failed**

**C38A3 Address-bus stuck-low test failed**

**C38A4 Address-bus shorted test failed**



## C38A5 Memory-cell test failed

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.25. C39 Logic and Temporal Monitoring Fault

### C39A1 Max current deviation failure

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice, replace joint

### C39A2 Max joint-encoder speed exceeded

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice, replace joint

### C39A3 Max motor-encoder speed exceeded

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice, replace joint

### C39A4 Illegal state change in joint detected

### C39A5 A timing issue occurred during startup.

#### EXPLANATION

Too fast state change in joint detected

#### SUGGESTION

Conduct a complete rebooting sequence

### C39A6 5V regulator voltage too low

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice, replace joint

### C39A7 5V regulator voltage too high

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice, replace joint

### C39A100 Watchpoint fault: ADC task timeout

### C39A101 Watchpoint fault: Motor-Control task timeout

### C39A102 Watchpoint fault: Motor-encoder task timeout

### C39A103 Watchpoint fault: Joint-encoder task timeout

### C39A104 Watchpoint fault: Communication task timeout

### C39A105 Watchpoint fault: RAM-test task timeout

### C39A106 Watchpoint fault: CalVal-test task timeout

### C39A107 Watchpoint fault: ROM-test task timeout

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.26. C40 AD-Converter hit high limit joint

### EXPLANATION

EMC issue external or electronics internal

### SUGGESTION

Check grounding and shielding for EMC problems

---

If you unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.27. C41 RC Oscillator Trim register hit high limit

---

If you unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.28. C42 RC Oscillator Trim register hit low limit

---

If you unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.29. C43 Change in invariant memory detected

### **C43A1 Current sensor gain**

---

If you unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.30. C44 CRC check failure on primary bus

### EXPLANATION

Serial communication problem with joint or secondary bus node

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check black 2-wire connectors and wires in joints, (B) Conduct a complete rebooting sequence. (C) If this happens more than twice, contact your local service provider for assistance.

### **C44A0 Base**

### **C44A1 Shoulder**

### **C44A2 Elbow**

### **C44A3 Wrist 1**

### **C44A4 Wrist 2**

### **C44A5 Wrist 3**

### **C44A6 Tool**

### **C44A80 CRC Check failure on primary bus.**

### EXPLANATION

Most likely an interference on the communication bus.

---

If you unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.



## 1.31. C45 AD-Converter error

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.32. C46 Loose gearbox or bad encoder mounting

### EXPLANATION

Mechanical problem in gear related to encoder mounting

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice, replace joint

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.33. C47 AD-Converter hit low limit

### EXPLANATION

EMC issue external or electronics internal

### SUGGESTION

Check grounding and shielding for EMC problems

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.34. C49 RS485 receive warning

### **C49A200 Secondary RS485 bus is down**

### EXPLANATION

Bus for: Teach Pendant, Processor A and Processor B on SCB

### SUGGESTION

Check TCP/IP-12V cable to Teach Pendant

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.35. C50 Robot powerup issue

### EXPLANATION

Electrical error Control Box

### SUGGESTION

Remove all external connections to I/O-interface of Safety Control Board. Check for short circuit

### **C50A1 Voltage detected at 24V rail before startup**

### **C50A2 Voltage present at unpowered robot**

### **C50A5 Powersupply voltage too low**

### SUGGESTION

Check 48 V cable between power supply and SCB

### **C50A6 Powersupply voltage too high**



**C50A11 Voltage not detected at 24V rail after startup****C50A15 Warning, waiting for SafetySYS2****C50A16 The Teach Pendant does not respond****EXPLANATION**

Loose wire or incorrect safety configuration

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check the Teach Pendant cable and connections, (B) Check the settings in the miscellaneous tab in the Safety menu

**C50A17 The Euromap67 interface does not respond****EXPLANATION**

Loose wire or incorrect safety configuration

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check the Euromap67 cable and connections, (B) Check the settings in the miscellaneous tab in the Safety menu

**C50A18 Warning, waiting for SafetySYS1****EXPLANATION**

SafetySYS1 = Processor A on Safety Control Board

**C50A19 Warning, Waiting for a valid "euromap67 activated" status bit from secondary Safety Control Board****C50A20 5V, 3V3 or ADC error (5V too high)****C50A21 5V, 3V3 or ADC error (5V too low)****C50A22 Robot current sensor reading too high****C50A23 Robot current sensor reading too low****C50A24 48V not present (Check internal connection)****C50A25 Robot voltage present at 48V PSU powereup****C50A26 Voltage present on unpowered 48V power supply****C50A27 12V, 3V3 or ADC error (12V too high)****C50A28 12V, 3V3 or ADC error (12V too low)****C50A29 Analog I/O error (-12V too high)****C50A30 Analog I/O error (-12V too low)****C50A31 The other safetySYS do not initialize****C50A40 Wrong voltage from PSU1****C50A41 Wrong voltage from PSU2****C50A42 Voltage will not disappear from PSU****C50A43 Warning, waiting for CB2 type answer from primary processor****C50A50 Processor A 3.3V supply voltage out of bounds****C50A51 Robot voltage below threshold****C50A52 Robot voltage above threshold****C50A53 58V generator deviation error**



**C50A54 5V regulator too low**

**C50A55 5V regulator too high**

**C50A56 -4V generator too low**

**C50A57 -4V generator too high**

**C50A80 Last CPU reset caused by Low-Power-Reset**

**C50A81 Last CPU reset caused by Window-Watchdog-Reset**

**C50A82 Last CPU reset caused by Independent-Watchdog-Reset**

**C50A83 Last CPU reset caused by Software-Reset**

EXPLANATION

The safety control board was reset on explicit request.

SUGGESTION

**C50A84 Last CPU reset caused by External-Pin-Reset**

**C50A85 Last CPU reset caused by Brown-Out-Reset**

**C50A99 Wrong software on PCB**

**C50A100 Cable not connected**

SUGGESTION

Check cable and connections between robot and Control Box

**C50A101 Short circuit in robot detected or wrong robot connected to Control Box**

SUGGESTION

Check robot type. Look for short circuit in cable and in Robot Arm

**C50A102 Voltage rising too slowly**

**C50A103 Voltage failed to reach acceptable level**

**C50A104 The IMMI module does not respond**

EXPLANATION

Missing IMMI module, hardware failure or incorrect safety configuration

SUGGESTION

Try the following actions to see which resolves the issue: (A) Check the IMMI module and connections, (B) Check the settings in the Hardware tab in the Safety section of the installation

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.36. C51 CRC check failure on secondary bus

**C51A0 Processor B**

**C51A1 Primary screen processor**

EXPLANATION

CRC check failure on safety processor 1 in Teach Pendant

**C51A2 Secondary screen processor**

EXPLANATION

CRC check failure on safety processor 2 in Teach Pendant

**C51A3 Primary E67**

## C51A4 Secondary E67

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

### 1.37. C53 IO overcurrent detected

#### EXPLANATION

Safety Control Board error

#### SUGGESTION

Remove all external connections to I/O-interface of Safety Control Board. Check for short circuit

**C53A1 , max is 800mA**

**C53A2 , max is 600mA**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

### 1.38. C55 Safety system error

#### EXPLANATION

Safety system malfunction

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check Motherboard, Safety Control Board, Screenboard, Current distributor (Euromap, if installed), (B) Check safety devices and cables/connections to these devices, (C) Conduct a complete rebooting sequence

#### **C55A23 Safety relay error (minus connection)**

##### EXPLANATION

Current distributor error

##### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check cable from Safety Control Board to Current distributor or 48V Power supply and Current distributor for issues, (B) Conduct a complete rebooting sequence

#### **C55A24 Safety relay error (plus connection)**

##### EXPLANATION

Current distributor error

##### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check cable from Safety Control Board to Current distributor or 48V Power supply and Current distributor for issues, (B) Conduct a complete rebooting sequence

#### **C55A33 Safety relay error (a relay is stuck)**

##### EXPLANATION

Current distributor error

##### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check cable from Safety Control Board to Current distributor or 48V Power supply and Current distributor for issues (B) Conduct a complete rebooting sequence

#### **C55A34 Safety relay error (relays are not on)**

**EXPLANATION**

Current distributor error

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check cable from Safety Control Board to Current distributor or 48V Power supply and Current distributor for issues (B) Conduct a complete rebooting sequence

**C55A50 Voltage present at unpowered robot****EXPLANATION**

Safety Control Board hardware fault

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C55A51 Voltage will not disappear from robot****EXPLANATION**

Safety Control Board hardware fault

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C55A52 5V, 3V3 or ADC error (5V too low)****EXPLANATION**

Safety Control Board hardware fault

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C55A53 5V, 3V3 or ADC error (5V too high)****EXPLANATION**

Safety Control Board hardware fault

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C55A90 Bootloader error, robot voltage too low or current too high****C55A91 Bootloader error, robot voltage too high****C55A100 Safety violation****C55A101 Safety Channel Error In Safety Control Board****C55A102 Safety Channel Error In Screen****C55A103 Safety Channel Error In Euromap67 Interface****C55A109 Received fault message from Controller****C55A110 Safety State is changing too often****C55A111 On/Off State is changing too often****C55A112 Robot current sensors readings differ****C55A120 Robot current is too high while emergency stopped****C55A121 Robot current is too high while safeguard stopped**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.39. C56 Overvoltage shutdown

### EXPLANATION

Voltage exceeded 55V

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check Energy Eaters cable and connections, (B) Check Energy, (C) Replace Energy Eater

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.40. C57 Brake release failure

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check Brake, solenoid, (B) Check TCP configuration, payload, and mounting settings

**C57A1 Joint did not move or motor encoder is not functioning**

**C57A2 Large movement detected during brake release**

**C57A3 Robot was not able to brake release, see log for details**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.41. C58 Motor encoder not calibrated

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.42. C59 Overcurrent shutdown

### EXPLANATION

Overcurrent in joint. Argument = Current in Amps

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check for short circuit, (B) Conduct a complete rebooting sequence, (C) If this happens more than twice, replace joint

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.43. C60 Energy surplus shutdown

### EXPLANATION

The power supply is sending energy to the energy eater

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Ensure supply is not delivering more than 48V, (B) Contact support

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.



## 1.44. C61 Idle power consumption to high

### EXPLANATION

The system is drawing more power than expected while idle

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check Energy Eaters cable and connections, (B) Check Energy Eater, (C) Replace Energy Eater

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.45. C62 Thermal issue

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check nothing is hindering free movement of the joints, (B) Check TCP configuration, payload, and mounting settings

**C62A1 Joint temperature: High (80(C)**

**C62A3 Warning: Static load too high**

**C62A11 Joint temperature: Shut down (85(C)**

**C62A13 Shutdown: Static load too high**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.46. C63 Motor test failed in step {unsigned}.

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.47. C65 PSU voltage to high

### EXPLANATION

The power supply output voltage is above 49V

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Ensure supply is not delivering more than 48V, (B) Contact support

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.48. C68 SPI error

### EXPLANATION

Joint: Absolut encoder on joint communication error

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check for short circuit, (B) Conduct a complete rebooting sequence, (C) If this happens several times in a row, replace joint

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.49. C70 Close to gearbox shear limit

### EXPLANATION

Acceleration / deceleration too high. Mechanical problem in gear related to encoder mounting

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Reduce acceleration in user program, (B) Conduct a complete rebooting sequence, (C) If this happens several times in a row, replace joint

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.50. C71 Startup check error

### **C71A0 Hardware is size0, wrong firmware at the joint**

#### SUGGESTION

Update firmware

### **C71A1 Hardware is size1, wrong firmware at the joint**

#### SUGGESTION

Update firmware

### **C71A2 Hardware is size2, wrong firmware at the joint**

#### SUGGESTION

Update firmware

### **C71A3 Hardware is size3, wrong firmware at the joint**

#### SUGGESTION

Update firmware

### **C71A4 Hardware is size4, wrong firmware at the joint**

#### SUGGESTION

Update firmware

### **C71A5 Invalid hardware revision**

### **C71A6 ADC calibration failed**

### **C71A7 Unknown error result**

#### EXPLANATION

The motor wires are damaged, bad connection in screw terminals or defect PCB

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check joint for damaged or loose connections, (B) Replace the joint

### **C71A8 Motor short circuit to ground or H-bridge problems**

#### EXPLANATION

The motor wires are damaged, bad connection in screw terminals or defect PCB

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check joint for damaged or loose connections, (B) Replace the joint

### **C71A9 Motor indication signal does not work**



**EXPLANATION**

The motor wires are damaged, bad connection in screw terminals or defect PCB

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check joint for damaged or loose connections, (B) Replace the joint

**C71A10 Phase 1 is unconnected or not working****EXPLANATION**

The motor wires are damaged, bad connection in screw terminals or defect PCB

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check joint for damaged or loose connections, (B) Replace the joint

**C71A11 Phase 2 is unconnected or not working****EXPLANATION**

The motor wires are damaged, bad connection in screw terminals or defect PCB

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check joint for damaged or loose connections, (B) Replace the joint

**C71A12 Phase 3 or multiple phases is unconnected or not working****EXPLANATION**

The wire is (1) damaged or (2) has been disconnected from the PCB (not likely) or (3) defect PCB

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check joint for damaged or loose connections, (B) Replace the joint

**C71A50 Current sensor test failed****EXPLANATION**

Sensor reported wrong current when probed

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check joint for damaged or loose connections, (B) Replace the joint

**C71A51 Current sensor test failed****EXPLANATION**

Sensor reported wrong current when probed

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check joint for damaged or loose connections, (B) Replace the joint

**C71A52 Current sensor test failed****EXPLANATION**

Sensors reported different currents when probed

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check joint for damaged or loose connections, (B) Replace the joint

**C71A101 Wrong firmware on RLS encoder**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.



## 1.51. C72 Power Supply Unit failure

### **C72A1 0 PSUs are active**

#### EXPLANATION

PSU was not able to deliver 48V

#### SUGGESTION

Check power connection between power supply and Safety Control Board

### **C72A2 1 PSU active, but we expect 2 (UR10)**

#### EXPLANATION

PSU was not able to deliver 48V or UR10 flash card in UR5 robot

#### SUGGESTION

Check power connection between power supply and Safety Control Board and check that the flash card and robot match

### **C72A3 2 PSUs active, but we expect 1 (UR5)**

#### EXPLANATION

UR5 flash card in UR10 robot

#### SUGGESTION

Check that the flash card and robot match

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.52. C73 Brake test failed during selftest, check brakepin

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.53. C74 Joint encoder warning

#### EXPLANATION

Magnetic encoder error (absolute encoder). Argument = sum of C74 errors

### **C74A1 Invalid decode: Readhead misalignment, ring damaged or external magnetic field present.**

#### SUGGESTION

Check grounding and shielding for EMC problems

### **C74A2 Speed reading is not valid**

### **C74A4 System error=malfunction or inconsistent calibration detected**

### **C74A8 Supply voltage is out of range**

### **C74A16 Temperature is out of range**

### **C74A32 Signal lost =Misaligned readhead or damaged ring**

### **C74A64 Signal low =Too far from magnetic ring**

### **C74A128 Signal saturation =Too close to magnetic ring**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.



## 1.54. C75 Joint encoder error

### EXPLANATION

Magnetic encoder error (absolute encoder). Argument = sum of C75 errors

**C75A1 Invalid decode: Readhead misalignment, ring damaged or external magnetic field present.**

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check grounding and shielding for EMC problems, (C) If this happens more than twice, replace joint

**C75A2 Speed reading is not valid**

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice, replace joint

**C75A4 System error=malfunction or inconsistent calibration detected**

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice, replace joint

**C75A8 Supply voltage is out of range**

**C75A16 Temperature is out of range**

**C75A32 Signal lost =Misaligned readhead or damaged ring**

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check grounding and shielding for EMC problems, (C) If this happens more than twice, replace joint

**C75A64 Signal low =Too far from magnetic ring**

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check grounding and shielding for EMC problems, (C) If this happens more than twice, replace joint

**C75A128 Signal saturation =Too close to magnetic ring**

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check grounding and shielding for EMC problems, (C) If this happens more than twice, replace joint

**C75A200 Position from joint encoder does not change while motor is running**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.55. C76 Joint encoder communication CRC issue

### EXPLANATION

Error between sensor and joint circuit

### SUGGESTION

Check connections or very heavy electrical noise

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.56. C77 Sudden position change detected on the joint-encoder

### EXPLANATION

The position reading from the encoder was different than expected.

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.57. C78 Large sudden position change detected on the joint-encoder

### EXPLANATION

The position reading from the encoder was severely different than expected, the latest measurement was discarded. The argument relates to the size of the position change.

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.58. C85 Motor encoder error

### **C85A200 Position from motor encoder does not change while motor is running**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.59. C100 Robot changed mode

### EXPLANATION

Status warning, general modus change

### SUGGESTION

Check preceding errors in log history

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.60. C101 Real Robot Connected

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.61. C102 Real Robot not connected – Simulating Robot

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.62. C103 Communication issue

### **C103A1 Connection to Safety Control Board lost**

### EXPLANATION

PC did not receive 3 packets in a row



SUGGESTION

Try the following actions to see which resolves the issue: (A) Check that the Ethernet cable between Motherboard and Safety Control Board is connected, (B) Conduct a complete rebooting sequence

**C103A2 Package lost from Safety Control Board**

**C103A3 Ethernet connection initialization with Safety Control Board failed**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.63. C104 Error=Empty command sent to robot

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.64. C111 Something is pulling the robot

SUGGESTION

Check TCP configuration, payload, and mounting settings

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.65. C115 Unknown robot type

EXPLANATION

The robot type specified in the configuration is unknown

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.66. C116 Realtime part warning

EXPLANATION

Possible CPU-overload due to structure of user program

SUGGESTION

Restructure user program

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.67. C117 Restart SCB failed

EXPLANATION

The Safety Control Board couldn't be rebooted from the controller.

SUGGESTION

Conduct a complete rebooting sequence

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.68. C150 Position close to joint limits

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.69. C151 Tool orientation close to limits

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.70. C152 Position close to safety plane limits

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.71. C153 Position deviates from path

**C153A0 Base. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

### SUGGESTION

Check payload, center of gravity and acceleration settings.

**C153A1 Shoulder. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

### SUGGESTION

Check payload, center of gravity and acceleration settings.

**C153A2 Elbow. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

### SUGGESTION

Check payload, center of gravity and acceleration settings.

**C153A3 Wrist 1. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

### SUGGESTION

Check payload, center of gravity and acceleration settings.

**C153A4 Wrist 2. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

### SUGGESTION

Check payload, center of gravity and acceleration settings.

**C153A5 Wrist 3. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

### SUGGESTION

Check payload, center of gravity and acceleration settings.

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.72. C154 Position in singularity

### EXPLANATION

Robot can not move linear near a singularity

### SUGGESTION

Use MoveJ or change the motion



If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.73. C155 Robot cannot maintain its position, check if payload is correct

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.74. C156 Wrong payload or mounting detected, or something is pushing the robot when entering Freedrive mode

### EXPLANATION

The robot may move unexpected due to wrong settings

### SUGGESTION

Verify that the TCP configuration and mounting in the used installation is correct

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.75. C157 Collision detected by joint

**C157A0 Base. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

### SUGGESTION

Make sure no objects are in the path of the robot and resume the program.

**C157A1 Shoulder. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

### SUGGESTION

Make sure no objects are in the path of the robot and resume the program.

**C157A2 Elbow. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

### SUGGESTION

Make sure no objects are in the path of the robot and resume the program.

**C157A3 Wrist 1. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

### SUGGESTION

Make sure no objects are in the path of the robot and resume the program.

**C157A4 Wrist 2. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

### SUGGESTION

Make sure no objects are in the path of the robot and resume the program.

**C157A5 Wrist 3. Check payload, center of gravity and acceleration settings. Log screen may contain additional information.**

#### SUGGESTION

Make sure no objects are in the path of the robot and resume the program.

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.76. C158 Collision detected by joint

**C158A0 Base. The user specified payload is 0kg, please make sure this is correct.**

#### EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

#### SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

**C158A1 Shoulder. The user specified payload is 0kg, please make sure this is correct.**

#### EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

#### SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

**C158A2 Elbow. The user specified payload is 0kg, please make sure this is correct.**

#### EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

#### SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

**C158A3 Wrist 1. The user specified payload is 0kg, please make sure this is correct.**

#### EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

#### SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

**C158A4 Wrist 2. The user specified payload is 0kg, please make sure this is correct.**

#### EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

#### SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

**C158A5 Wrist 3. The user specified payload is 0kg, please make sure this is correct.**

#### EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

#### SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.





## 1.77. C159 Position deviates from path

**C159A0 Base. The user specified payload is 0kg, please make sure this is correct.**

EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

**C159A1 Shoulder. The user specified payload is 0kg, please make sure this is correct.**

EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

**C159A2 Elbow. The user specified payload is 0kg, please make sure this is correct.**

EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

**C159A3 Wrist 1. The user specified payload is 0kg, please make sure this is correct.**

EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

**C159A4 Wrist 2. The user specified payload is 0kg, please make sure this is correct.**

EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

**C159A5 Wrist 3. The user specified payload is 0kg, please make sure this is correct.**

EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

SUGGESTION

Make sure the specified payload mass and center of gravity are correctly specified.

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.78. C160 The robot was powered off last time due to a joint position disagreement



#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Verify that the robot position in the 3D graphics matches the real robot to ensure the encoders function before releasing the brakes. Stand back and monitor the robot performing its first program cycle as expected, (B) If the position is not correct, the robot must be repaired. In this case, tap Power Off Robot, (C) If the position is correct, please tick the check box below the 3D graphics and click Robot Position Verified

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

1.79. C161 Large movement of the robot detected while it was powered off. The joints were moved while it was powered off, or the encoders do not function

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Verify that the robot position in the 3D graphics matches the real robot to ensure the encoders function before releasing the brakes. Stand back and monitor the robot performing its first program cycle as expected, (B) If the position is not correct, the robot must be repaired. In this case, tap Power Off Robot, (C) If the position is correct, please tick the check box below the 3D graphics and click Robot Position Verified

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

1.80. C162 The protective stop was likely caused by incorrectly specified payload mass and/or center of gravity.

#### EXPLANATION

Specifying an incorrect payload mass and/or center of gravity may cause poor robot performance and/or protective stops.

#### SUGGESTION

Make sure the specified payload mass and center of gravity are correct.

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

1.81. C171 Issue with blends

#### **C171A0 A MoveC-Waypoint were skipped due to a blend.**

#### EXPLANATION

The value for the blend radius is too large compared to the distance between the Waypoints.

#### SUGGESTION

Decrease the blend radius or choose Waypoints that are further apart.

#### **C171A1 Blend radius too small in a MoveC**

#### SUGGESTION

Increase blend in MoveC

#### **C171A3 A ServoC-Waypoint were skipped due to a blend.**

**EXPLANATION**

The value for the blend radius is too large compared to the distance between the Waypoints.

**SUGGESTION**

Decrease the blend radius or choose Waypoints that are further apart.

**C171A4 Overlapping Blends in a MoveJ, a Waypoint was skipped****SUGGESTION**

Decrease the blend radius or choose Waypoints that are further apart.

**C171A5 Overlapping Blends in a MoveJ, a Waypoint was skipped****SUGGESTION**

Decrease the blend radius or choose Waypoints that are further apart.

**C171A6 Overlapping Blends in a MoveJ, a Waypoint was skipped****SUGGESTION**

Decrease the blend radius or choose Waypoints that are further apart.

**C171A7 Overlapping Blends in a MoveJ, a Waypoint was skipped****SUGGESTION**

Decrease the blend radius or choose Waypoints that are further apart.

**C171A9 A MoveP-Waypoint were skipped due to a blend.****EXPLANATION**

The value for the blend radius is too large compared to the distance between the Waypoints.

**SUGGESTION**

Decrease the blend radius or choose Waypoints that are further apart.

**C171A10 Blend radius too small error in a MoveP****C171A11 Overlapping Blends in a MoveL, a Waypoint was skipped****SUGGESTION**

Decrease the blend radius or choose Waypoints that are further apart.

**C171A12 Overlapping Blends in a MoveL, a Waypoint was skipped****SUGGESTION**

Decrease the blend radius or choose Waypoints that are further apart.

**C171A13 Overlapping Blends in a MoveL, a Waypoint was skipped****SUGGESTION**

Decrease the blend radius or choose Waypoints that are further apart.

**C171A14 Overlapping Blends in a MoveL, a Waypoint was skipped****SUGGESTION**

Decrease the blend radius or choose Waypoints that are further apart.

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.82. C172 Illegal control mode

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.83. C173 Robot motion causes too high joint torques

**EXPLANATION**

Exceeding joint torque ranges may damage robot hardware

**SUGGESTION**

Reduce accelerations in the robot motions around where the error was discovered. You can use the script command "pause\_on\_error\_code()" to make the robot stop when this warning occurs, to identify which motion causes the warning

**C173A0 Base.**

**C173A1 Shoulder.**

**C173A2 Elbow.**

**C173A3 Wrist 1.**

**C173A4 Wrist 2.**

**C173A5 Wrist 3.**

**C173A6 Base.** Problem identified when executing program line {unsigned}.

**C173A7 Shoulder.** Problem identified when executing program line {unsigned}.

**C173A8 Elbow.** Problem identified when executing program line {unsigned}.

**C173A9 Wrist 1.** Problem identified when executing program line {unsigned}.

**C173A10 Wrist 2.** Problem identified when executing program line {unsigned}.

**C173A11 Wrist 3.** Problem identified when executing program line {unsigned}.

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.84. C174 Robot motion causes too high jump in joint torques

**EXPLANATION**

High jumps in joint torque ranges may damage robot hardware. This can be caused by sudden big changes in acceleration in the target trajectory

**SUGGESTION**

Use blends or reduce accelerations in the robot motions around where the error was discovered. You can use the script command "pause\_on\_error\_code()" to make the robot stop when this warning occurs, to identify which motion causes the warning

**C174A0 Base.**

**C174A1 Shoulder.**

**C174A2 Elbow.**

**C174A3 Wrist 1.**

**C174A4 Wrist 2.**

**C174A5 Wrist 3.**

**C174A6 Base.** Problem identified when executing program line {unsigned}.

**C174A7 Shoulder.** Problem identified when executing program line {unsigned}.

**C174A8 Elbow.** Problem identified when executing program line {unsigned}.

**C174A9 Wrist 1.** Problem identified when executing program line {unsigned}.



**C174A10 Wrist 2. Problem identified when executing program line {unsigned}.**

**C174A11 Wrist 3. Problem identified when executing program line {unsigned}.**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

1.85. C184 Joint self test not received by controller

**C185A1 START\_NORMAL\_OPERATION is not allowed on selftest firmware**

**C185A2 GOTO\_BACKDRIVE\_COMMAND is not allowed on selftest firmware**

**C186A1 joint\_mode == JOINT\_RUNNING\_MODE is not allowed on selftest firmware**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

1.86. C187 Temperature sensor test failed

**C187A1 Starting temperature were lower than expected**

**C187A2 Starting temperature were higher than expected**

**C187A3 Temperature increased less than expected during warm up**

**C187A4 Temperature increased more than expected during warm up**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

1.87. C190 Joint failed during selftest

**C190A0 Motor encoder index mark not found**

**C190A1 Phases not mounted correctly**

**C190A2 Motor encoder counting the wrong way**

**C190A3 Joint encoder counting the wrong way**

**C190A4 No movement detected while trying to move the motor**

**C190A11 Temperature alignment did not warm up to 45 degrees C within 30 minutes**

**C190A12 Temperature alignment did not cool down to 45 degrees C within 60 minutes**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

1.88. C191 Safety system violation

**C191A1 Joint position limit violated**

**C191A2 Joint speed limit violated**

**C191A3 TCP speed limit violated**

**C191A4 TCP position limit violated**

**C191A5 TCP orientation limit violated**

**C191A6 Power limit violated**

**C191A7 Joint torque window violated****C191A8 Joint torque window too large****C191A9 Reduced mode output violation****C191A10 Safeguard stop output violation****C191A11 Emergency stop output violation****C191A12 Momentum limit violation****C191A13 Robot moving output violation****C191A14 Robot is not braking in stop mode****EXPLANATION**

During the braking process, the safety system monitors if the robot brakes as expected. If this is not the case, this error is generated

**SUGGESTION**

Check TCP configuration, payload, and mounting settings

**C191A15 Robot is moving in stop mode****EXPLANATION**

When the robot is stopped due to a safety violation or a safeguard stop, the safety system generates this error, if the robot moves while in this mode

**SUGGESTION**

(A) Check if the robot is physically pushed while safeguard stopped, (B) Check TCP configuration, payload, and mounting settings

**C191A16 Robot did not stop in time****C191A17 Received a null vector for TCP orientation****C191A18 Robot not stopping output violation****C191A19 Invalid safety IO configuration****C191A20 Configuration information or limit sets not received****C191A21 The other safety processor detected a violation****C191A22 Received unknown command from Controller****C191A23 Invalid setup of safety limits****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check Firmware/update firmware, (B) Conduct a complete rebooting sequence

**C191A24 Reduced Mode Output set, while it should not be****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check Firmware/update firmware, (B) Conduct a complete rebooting sequence

**C191A25 Reduced Mode Output not set, while it should be****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check Firmware/update firmware, (B) Conduct a complete rebooting sequence

**C191A26 Not Reduced Mode Output set, while it should not be**

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check Firmware/update firmware, (B) Conduct a complete rebooting sequence

**C191A27 Not Reduced Mode Output not set, while it should be****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check Firmware/update firmware, (B) Conduct a complete rebooting sequence

**C191A28 Robot Emergency Stop exceeded maximum stop time****EXPLANATION**

Too high payload

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check that max payload of the robot has not been exceeded, (B) Check TCP configuration, payload, and mounting settings

**C191A29 System Emergency Stop exceeded maximum stop time****EXPLANATION**

Too high payload

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check that max payload of the robot has not been exceeded, (B) Check TCP configuration, payload, and mounting settings

**C191A30 Safeguard Stop exceeded maximum stop time****EXPLANATION**

Too high payload

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check that max payload of the robot has not been exceeded, (B) Check TCP configuration, payload, and mounting settings

**C191A31 Operation mode switch is present while the three position switch is missing****C191A32 Joint speed limit violated - Base****C191A33 Joint speed limit violated - Shoulder****C191A34 Joint speed limit violated - Elbow****C191A35 Joint speed limit violated - Wrist 1****C191A36 Joint speed limit violated - Wrist 2****C191A37 Joint speed limit violated - Wrist 3**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.89. C192 Safety system fault

**C192A1 Robot still powered in emergency stop****EXPLANATION**

When the emergency stop is active, the Robot Arm powers off. The controller is responsible for sending the power off command. This error is generated if the safety system detects that the Robot Arm still has power

**C192A2 Robot emergency stop disagreement**

**EXPLANATION**

E-stop in teach pendant or in robot E-stop circuit problem

**SUGGESTION**

Check safety devices and cables/connections to these devices.

**C192A3 System emergency stop disagreement****EXPLANATION**

System E-stop circuit problem

**SUGGESTION**

Check safety devices and cables/connections to these devices.

**C192A4 Safeguard stop disagreement****EXPLANATION**

Safeguard circuit problem

**SUGGESTION**

Check safety devices and cables/connections to these devices.

**C192A5 Euromap safeguard stop disagreement****EXPLANATION**

Euromap circuit problem

**SUGGESTION**

Check cables from Safety Control Board to Euromap and to external machine

**C192A6 Joint position disagreement****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check TCP configuration, payload and mounting settings, (B) Check that safety settings respected

**C192A7 Joint speed disagreement****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check TCP configuration, payload and mounting settings, (B) Check that safety settings respected

**C192A8 Joint torque disagreement****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check TCP configuration, payload and mounting settings, (B) Check that safety settings respected

**C192A9 TCP speed disagreement****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check TCP configuration, payload and mounting settings, (B) Check that safety settings respected

**C192A10 TCP position disagreement****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check TCP configuration, payload and mounting settings, (B) Check that safety settings respected

**C192A11 TCP orientation disagreement****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check TCP configuration, payload and mounting settings, (B) Check that safety settings respected

**C192A12 Power disagreement**





EXPLANATION

Power calculation: uP-A and uP-B disagreement

**C192A13 Joint torque window disagreement**

**C192A14 Reduced mode input disagreement**

EXPLANATION

Safety I/O uP-A and uP-B disagreement

SUGGESTION

Check safety devices and cables/connections to these devices

**C192A15 Reduced mode output disagreement**

EXPLANATION

Safety I/O uP-A and uP-B disagreement

SUGGESTION

Check safety devices and cables/connections to these devices

**C192A16 Safety output failed**

EXPLANATION

The safety output did not reach the correct value in the expected time

SUGGESTION

Check for short circuit on I/O or for wrong connection to output.

**C192A17 Safeguard stop output disagreement**

EXPLANATION

Safety I/O uP-A and uP-B disagreement

SUGGESTION

Check safety devices and cables/connections to these devices

**C192A18 The other safety processor is in fault**

**C192A19 Emergency stop output disagreement**

EXPLANATION

Safety I/O uP-A and uP-B disagreement

SUGGESTION

Check safety devices and cables/connections to these devices

**C192A20 SPI output error detected**

EXPLANATION

Powersupply for the I/O is not detected

SUGGESTION

Check if the connection to the internal power supply is correct. If an external power supply is being used, check if it is powered on and at the correct voltage.

**C192A21 Momentum disagreement**

**C192A22 Robot moving output disagreement**

SUGGESTION

Check safety devices and cables/connections to these devices

**C192A23 Wrong processor ID**

**C192A24 Wrong processor revision**

**C192A25 Potential brownout detected**



**EXPLANATION**

Voltage drop on Safety Control Board or defect Safety Control Board

**C192A26 Emergency stop output disagreement****SUGGESTION**

Check safety devices and cables/connections to these devices

**C192A27 Safeguard stop output disagreement****SUGGESTION**

Check safety devices and cables/connections to these devices

**C192A28 Robot not stopping output disagreement****SUGGESTION**

Check safety devices and cables/connections to these devices

**C192A29 Safeguard reset input disagreement****SUGGESTION**

Check safety devices and cables/connections to these devices

**C192A30 Safety processor booted up in fault mode****C192A31 Reduced Mode Output disagreement****SUGGESTION**

Check safety devices and cables/connections to these devices

**C192A32 Not Reduced Mode Output disagreement****SUGGESTION**

Check safety devices and cables/connections to these devices

**C192A33 A timing issue occurred during startup. Please restart to proceed****EXPLANATION**

Checksum disagreement between safety processors uA and uB

**C192A34 User safety config checksum disagreement between uA and GUI****C192A35 Robot config checksum disagreement between uA and GUI****C192A36 Online RAM test failed****C192A37 Not all safety related functionalities are running****C192A38 Package too short for CRC calculation****C192A39 Three position switch input disagreement****C192A40 Operation mode switch input disagreement**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.90. C193 One of the nodes is in fault mode

**C193A0 Base Joint****SUGGESTION**

Try the following actions to see which resolves the issue: (A) See previous error, (B) Update the firmware on the joint, (C) Conduct a complete rebooting sequence

**C193A1 Shoulder Joint**

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) See previous error, (B) Update the firmware on the joint, (C) Conduct a complete rebooting sequence

**C193A2 Elbow Joint****SUGGESTION**

Try the following actions to see which resolves the issue: (A) See previous error, (B) Update the firmware on the joint, (C) Conduct a complete rebooting sequence

**C193A3 Wrist 1 Joint****SUGGESTION**

Try the following actions to see which resolves the issue: (A) See previous error, (B) Update the firmware on the joint, (C) Conduct a complete rebooting sequence

**C193A4 Wrist 2 Joint****SUGGESTION**

Try the following actions to see which resolves the issue: (A) See previous error, (B) Update the firmware on the joint, (C) Conduct a complete rebooting sequence

**C193A5 Wrist 3 Joint****SUGGESTION**

Try the following actions to see which resolves the issue: (A) See previous error, (B) Update the firmware on the joint, (C) Conduct a complete rebooting sequence

**C193A6 Tool****SUGGESTION**

Try the following actions to see which resolves the issue: (A) See previous error, (B) Conduct a complete rebooting sequence

**C193A7 Screen 1****EXPLANATION**

Safety Control Board has detected an error on Safety processor 1 in Teach pendant

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) See previous error, (B) Conduct a complete rebooting sequence

**C193A8 Screen 2****EXPLANATION**

Safety Control Board has detected an error on Safety processor 2 in Teach pendant

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) See previous error, (B) Conduct a complete rebooting sequence

**C193A9 Euromap 1****SUGGESTION**

Try the following actions to see which resolves the issue: (A) See previous error, (B) Conduct a complete rebooting sequence

**C193A10 Euromap 2****SUGGESTION**

Try the following actions to see which resolves the issue: (A) See previous error, (B) Conduct a complete rebooting sequence

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.91. C194 One of the nodes is not booted or not present

### **C194A0 Base Joint**

### **C194A1 Shoulder Joint**

### **C194A2 Elbow Joint**

### **C194A3 Wrist 1 Joint**

### **C194A4 Wrist 2 Joint**

### **C194A5 Wrist 3 Joint**

### **C194A6 Tool**

### **C194A7 Screen 1**

#### EXPLANATION

Safety Control Board has detected an error on Safety processor 1 in Teach pendant

### **C194A8 Screen 2**

#### EXPLANATION

Safety Control Board has detected an error on Safety processor 2 in Teach pendant

### **C194A9 Euromap 1**

### **C194A10 Euromap 2**

### **C194A128 Base not ready while brake release requested**

#### EXPLANATION

Must be at least in IDLE mode when the brake release is requested

#### SUGGESTION

Check for loose communication cable

### **C194A129 Shoulder not ready while brake release requested**

#### EXPLANATION

Must be at least in IDLE mode when the brake release is requested

#### SUGGESTION

Check for loose communication cable

### **C194A130 Elbow not ready while brake release requested**

#### EXPLANATION

Must be at least in IDLE mode when the brake release is requested

#### SUGGESTION

Check for loose communication cable

### **C194A131 Wrist 1 not ready while brake release requested**

#### EXPLANATION

Must be at least in IDLE mode when the brake release is requested

#### SUGGESTION

Check for loose communication cable

### **C194A132 Wrist 2 not ready while brake release requested**

#### EXPLANATION

Must be at least in IDLE mode when the brake release is requested



SUGGESTION

Check for loose communication cable

**C194A133 Wrist 3 not ready while brake release requested**

EXPLANATION

Must be at least in IDLE mode when the brake release is requested

SUGGESTION

Check for loose communication cable

**C194A134 Tool not ready while brake release requested**

EXPLANATION

Must be at least in IDLE mode when the brake release is requested

SUGGESTION

Check for loose communication cable

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.92. C195 Conveyor speed too high

EXPLANATION

Conveyor speed higher than robot is able to run

SUGGESTION

Make sure that conveyor tracking is set up correctly

**C195A1 for joint speed safety limit**

**C195A2 for TCP speed safety limit**

**C195A3 for momentum safety limit**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.93. C196 MoveP speed too high

EXPLANATION

Too high speed in relation to blend radius

SUGGESTION

Reduce speed or increase blend radius in user program

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.94. C197 Blend overlap warning

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.95. C200 Safety Control Board hardware error

**C200A1 Hardware ID is wrong**

EXPLANATION

Safety Control Board: uP-A has detected an error: Wrong Safety Control Board

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A2 MCU type is wrong****EXPLANATION**

Safety Control Board: uP-A has detected an error

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A3 Part ID is wrong****EXPLANATION**

Safety Control Board: uP-A has detected an error

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A4 RAM test failed****EXPLANATION**

Safety Control Board: uP-A has detected an error

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A5 Register test failed****EXPLANATION**

Safety Control Board: uP-A has detected an error

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A6 pRom Crc test failed****EXPLANATION**

Safety Control Board: uP-A has detected an error: firmware error

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A7 Watchdog reset the processor****EXPLANATION**

Safety Control Board: uP-A has detected an error

**C200A8 OVG signal test not passed****EXPLANATION**

Safety Control Board: uP-A has detected an error: over voltage generator

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A9 3V3A power good pin is low**

**EXPLANATION**

Safety Control Board: uP-A has detected an error

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A10 3V3B power good pin is low****EXPLANATION**

Safety Control Board: uP-A has detected an error

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A11 5V power good is low****EXPLANATION**

Safety Control Board: uP-A has detected an error

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A12 3V3 voltage too low****EXPLANATION**

Safety Control Board: uP-A has detected an error

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A13 3v3 voltage too high****EXPLANATION**

Safety Control Board: uP-A has detected an error

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) If this happens more than twice in a row, replace Safety Control Board

**C200A14 48V input is too low****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check 48 V Power supply, current distributor, energy eater and Safety Control Board for issues

**C200A15 48V input is too high****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check 48 V Power supply, current distributor, energy eater and Safety Control Board for issues

**C200A16 24V IO short circuited****EXPLANATION**

Too high current

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Disconnect external I/O connections and check external power supply if connected

**C200A17 PC current is too high**

#### EXPLANATION

Motherboard takes too high current

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check cable between Safety Control Board and Motherboard and check all connections to Motherboard. Also check for short circuit

### **C200A18 Robot voltage is too low**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for short circuit in Robot Arm, (C) Check 48 V Power supply, current distributor, energy eater and Safety Control Board for issues

### **C200A19 Robot voltage is too high**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check 48 V Power supply, current distributor, energy eater and Safety Control Board for issues

### **C200A20 24V IO voltage is too low**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Disconnect I/O, check external power supply if connected and check Safety Control Board for issues

### **C200A21 12V voltage is too high**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check 12 V Power supply, cables and Safety Control Board for issues

### **C200A22 12V voltage is too low**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check 12 V Power supply, cables and Safety Control Board for issues

### **C200A23 It took too long to stabilize 24V**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check 24 V and Safety Control Board for issues

### **C200A24 It took too long to stabilize 24V IO**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check 24 V and Safety Control Board for issues

### **C200A25 24V voltage is too high**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check external 24 V and Safety Control Board for issues, (B) Conduct a complete rebooting sequence, (C) If this happens more than twice in a row, replace Safety Control Board.

### **C200A26 24V IO voltage is too high**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Disconnect I/O's, (B) Conduct a complete rebooting sequence, (C) Check external 24 V and Safety Control Board for issues





If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.96. C201 Setup of Safety Control Board failed

### C201A0 Setup of Safety Control Board failed

#### EXPLANATION

No data was received from the Safety Control Board at initialization or invalid safety parameters have been received

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check that the ethernet cable between Motherboard and Safety Control Board is connected and verify that the setup of the Safety Configuration is valid.

### C201A1 SCB uA is not responding

#### EXPLANATION

No data or invalid data was received from the Safety Control Board uA at initialization

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check that the ethernet cable between Motherboard and Safety Control Board is connected and verify that the setup of the Safety Configuration is valid.

### C201A2 SCB uB is not responding

#### EXPLANATION

No data or invalid data was received from the Safety Control Board uB at initialization

#### SUGGESTION

Conduct a complete rebooting sequence.

### C201A3 SCB is not responding

#### EXPLANATION

No data or invalid was received from Safety Control Board when requested for configuration parameters

#### SUGGESTION

Conduct a complete rebooting sequence.

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.97. C202 SCE configuration was illegal, after applying tolerances

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.98. C203 PolyScope detected a mismatch between the shown and (to be) applied safety parameters

#### EXPLANATION

PolyScope continuously verifies that the shown safety parameters are equal to the running parameters



**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check that the software version is the same or newer than the firmware on the Safety Control Board, (B) Reload the installation, (C) Conduct a complete rebooting sequence

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.99. C204 Path sanity check failed

**C204A1 Sudden change in target position****C204A2 Inconsistency between target position and speed****C204A3 Sudden stop****EXPLANATION**

The program contains motions that are not ramped correctly down

**SUGGESTION**

To abort a motion, use "stopj" or "stopl" script commands to generate a smooth deceleration before using "wait". Avoid aborting motions between Waypoints with blend

**C204A4 Robot has not stopped in the allowed reaction and braking time****C204A5 Robot program resulted in invalid setpoint****C204A6 Blending failed and resulted in an invalid setpoint****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Try changing the blend radius, (B) Contact your local Universal Robots technical support

**C204A7 Robot approaching singularity - Acceleration threshold failed**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.100. C205 Target speed does not match target position

**C205A0 Inconsistency between target position and speed**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.101. C206 Sanity check failed

**C206A0 Target joint speed does not match target joint position change - Base****C206A1 Target joint speed does not match target joint position change - Shoulder****C206A2 Target joint speed does not match target joint position change - Elbow****C206A3 Target joint speed does not match target joint position change - Wrist 1****C206A4 Target joint speed does not match target joint position change - Wrist 2****C206A5 Target joint speed does not match target joint position change - Wrist 3**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.



## 1.102. C207 Fieldbus input disconnected

### SUGGESTION

Check fieldbus connections (RTDE, ModBus, EtherNet/IP and Profinet) or disable the fieldbus in the installation. Check RTDE watchdog feature. Check if a URCap is using this feature.

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.103. C208 Debug Assertion failed

### EXPLANATION

An assert was executed. Notice: The functionality is exclusively used for testing purposes.

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.104. C209 A protective stop was triggered (for test purposes only)

### EXPLANATION

A protective stop was triggered. Notice: The functionality is exclusively used for testing purposes.

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.105. C210 Socket is read-only when the robot is in local (Teach pendant) control

### SUGGESTION

Set the robot in remote control in PolyScope to enable receiving scripts in the controller

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.106. C211 Operational mode changed

**C211A0 Disabled**

**C211A1 Automatic**

**C211A2 Manual**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.107. C212 Name conflict in loaded program

**C212A1 {unsigned} name conflict(s) occurred between feature names and program variables**

### EXPLANATION

Some feature names and program variables share the same name, which may cause confusion.

### SUGGESTION

Rename the program variables.

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.108. C213 No Kinematic Calibration found (calibration.conf file is either corrupt or missing)

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.109. C214 Kinematic Calibration for the robot does not match the joint(s)

### EXPLANATION

The calibration checksum stored in the calibration.conf does not match the values from the joint(s)

### SUGGESTION

If moving a program from a different robot to this one, recalibrate the second robot to improve accuracy

**C214A1 The Kinematic Calibration checksum does not match the Base checksum**

**C214A2 The Kinematic Calibration checksum does not match the Shoulder checksum**

**C214A3 The Kinematic Calibration checksum does not match the Elbow checksum**

**C214A4 The Kinematic Calibration checksum does not match Wrist 1 checksum**

**C214A5 The Kinematic Calibration checksum does not match for Wrist 2 checksum**

**C214A6 The Kinematic Calibration checksum does not match for Wrist 3 checksum**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.110. C215 Kinematic Calibration does not match the robot

### EXPLANATION

The calibration checksum stored in the calibration.conf does not match the values from the joints

### SUGGESTION

Check if the serial number of the Robot Arm matches the Control Box

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.111. C216 The offset of the joint has changed

**C216A1 Base**

**C216A2 Shoulder**

**C216A3 Elbow**

**C216A4 Wrist 1**

**C216A5 Wrist 2**

**C216A6 Wrist 3**



If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.112. C217 White space detected at the beginning of a string token at line {unsigned}

### EXPLANATION

Leading white spaces in strings are ignored in this version but won't be ignored in future releases

### SUGGESTION

Make sure that these leading white spaces are intentional otherwise remove them

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.113. C218 A thread used a lot of time

### EXPLANATION

There may be an infinite loop or other expensive command that does not move the robot, this can cause protective stops.

### SUGGESTION

Add a Wait or sync() to split long program sequences.

### **C218A0 Main Robot Program.**

### **C218A1 Thread: {string}**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.114. C219 Change in offset is too high

### EXPLANATION

Following the specified offsets would result in the robot exceeding safety limits

### **C219A1 to meet joint speed safety limit**

### **C219A2 to meet tool speed safety limit**

### **C219A3 to meet momentum safety limit**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.115. C220 Kinematic Calibration

### **C220A1 Version {unsigned} on the robot arm is not supported**

### EXPLANATION

The kinematic calibration saved on the robot arm is an unsupported version.

### SUGGESTION

(A) Conduct a complete rebooting sequence, (B) Update software, (C) Contact your local Universal Robots service provider for assistance

### **C220A2 Kinematic Calibration file was replaced with file from the arm.**

**EXPLANATION**

The calibration.conf file was overwritten with the version stored in the arm. This is likely because the arm connected to the control box was changed

**C220A3 Kinematic Calibration uploaded to the arm.****EXPLANATION**

The calibration.conf file was changed and uploaded to the arm.

**C220A4 Kinematic Calibration reuploaded to the arm.****EXPLANATION**

The kinematic calibration was reuploaded to the arm as not all joints matching the calibration had it saved.

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.116. C221 GUI Communication

**C221A0 High load, messages dropped****EXPLANATION**

GUI Communication is under high load causing user messages to be dropped

**SUGGESTION**

(A) Reduce the number of `textmsg()` and `varmsg()` being executed in one time-step (B) Insert `wait()` or `sync()` in the thread or main program

**C221A1 Overload****EXPLANATION**

GUI Communication is overloaded

**SUGGESTION**

(A) Reduce the number of `textmsg()` and `varmsg()` being executed in one time-step (B) Insert `wait()` or `sync()` in the thread or main program

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.117. C257 An unexpected message was received (header {hex})

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.118. C258 Message contains invalid payload, data {unsigned}

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.119. C259 Filesystem-related issue

**C259A0 Critical error****EXPLANATION**

A critical error occurred in the filesystem

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Reimage SD card.

**C259A1 Init failed at sub-part number: {unsigned}**

**C259A2 Failed to delete file with id: {unsigned}**

**C259A3 Filesystem was reset**

**C259A4 Failed to copy file at FAT entry index: {unsigned}**

**C259A5 Failed to write a FAT entry, file id: {unsigned}**

**C259A6 Failed to open a file with ID {unsigned}**

**C259A7 Failed to store a file with ID {unsigned}**

**C259A8 Write and verify of FAT valid status failed**

**C259A9 Write and verify of file deleted status**

**C259A10 Corrupted data in sector status at filesystem init**

**C259A11 Failed to set sector deprecated/not deprecated status**

**C259A12 Failed reading the FAT entry**

**C259A13 Information about used sector is corrupted**

**C259A14 Find file function failed**

**C259A15 Wrong CRC - file corrupted**

**C259A16 Could not determine which sector to use**

**C259A17 Wrong length, got length: {unsigned}**

**C259A18 Wrong file revision, got revision: {unsigned}**

**C259A19 Expected file length: {unsigned}**

**C259A20 Expected file revision: {unsigned}**

**C259A21 Filesystem sector at {hex} was corrupted but has been restored**

**C259A22 Filesystem has been restored {unsigned} times**

**C259A23 Apptype that performed last restore operation: {unsigned}**

**C259A24 SVN revision of app that performed last restore operation: {unsigned}**

**C259A25 Wrong Offset, got offset: {hex}**

**C259A26 Filesystem sector {hex} failed FAT sanitycheck**

**C259A27 Filesystem failed sanity check. No sector contain data that can safely be used.**

**C259A28 Write and verify of file data failed**

**C259A29 Tried to use a filesystem functions, while the filesystem uninitialized**

**C259A30 Tried to save a file with length zero**

**C259A31 Tried to save a file which would exceed the memory bounds**

**C259A32 There is no space in FAT array for a new FAT entry**

**C259A33 Failed setting sector 1 as not empty**

- C259A34 Failed setting sector 1 as deprecated
- C259A35 Failed setting sector 0 as not empty
- C259A36 Write and verify of FAT entry data failed
- C259A37 Write and verify of CRC data failed
- C259A38 Failed reading the status of the file
- C259A39 Failed to read sector 0 status - empty
- C259A40 Failed to read sector 0 status - deprecated
- C259A41 Failed to read sector 1 status - empty
- C259A42 Failed to read sector 1 status - deprecated
- C259A43 Exceeded memory bounds
- C259A44 Failed to clean a sector
- C259A45 Failed to set sector empty/not empty status
- C259A46 The memory device failed to erase sector
- C259A47 Failed to set FAT entry deleted/not deleted status
- C259A48 Failed to set FAT entry empty/not empty status
- C259A49 The memory device failed to copy and verify the file
- C259A50 The memory device failed to read the file data
- C259A51 Examining need of garbage collection has failed
- C259A52 Garbage collection has failed
- C259A53 The memory device does not support direct read. Provide the pointer to a buffer
- C259A54 The File is too large
- C259A55 Saving the file has failed
- C259A56 A file transfer is already in progress, only one at a time!
- C259A57 File with ID: {unsigned} has been updated.
- C259A58 Old version: {unsigned}.
- C259A59 New version: {unsigned}.
- C259A60 File with ID: {unsigned} Failed to update.
- C259A61 Duplicate file with ID: {unsigned} configured in storage configuration.

**EXPLANATION**

File storage configuration has duplicate File IDs

**SUGGESTION**

- C259A62 Unknown file with ID: {unsigned} added in storage configuration.

**EXPLANATION**

File storage has no handlers for configured File IDs

**SUGGESTION**





**C259A63 Wrong filesystem revision, got revision: {unsigned}**

**C259A64 Expected filesystem revision: {unsigned}**

**C259A65 Filesystem experienced {unsigned} unexpected shutdowns.**

**C259A66 Volatile filesystem garbage collected {unsigned} times.**

**C259A67 Static filesystem garbage collected {unsigned} times.**

**C259A68 Git hash of app that performed last restore operation: {hex}**

**C259A69 Operation failed for file ID: {unsigned}**

**C259A70 File with ID {unsigned} not found, created new file.**

**C259A71 File with ID {unsigned} not found.**

**C259A72 File with ID {unsigned} was not completely saved.**

**C259A73 Cannot perform atomic store operation when processing runtime jobs.**

**C259A74 File with ID {unsigned} is already scheduled for storage.**

**C259A75 Starting recovery of filesystem sector at {hex}**

**C259A76 Starting garbage collection of volatile filesystem**

**C259A77 Starting garbage collection of static filesystem**

**C259A78 File with ID {unsigned} had a minimum file revision that was different from one**

**EXPLANATION**

This could indicate an implementation error that causes issues with backwards compatibility

**C259A79 Minimum file revision was {unsigned}**

**EXPLANATION**

The data stored in joint is obsolete

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Update soft- and firmware Note: updating firmware needs to be done incrementally from such old persistent joint data. Re-deploy the previous firmware, and perform incremental upgrade up to SW 5.5 before deploying this version. IMPORTANT: Power on the robot arm between each update and validate it reaches IDLE state. Contact your local Universal Robots service provider for assistance

**C259A81 Filesystem is not properly initialized**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.120. C260 Brake Release – old procedure

**C260A0 Critical error**

**EXPLANATION**

A critical error occurred during Brake Release

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure the mounted payload, TCP, and CoG matches your configuration.

**C260A1 Motor moved only: {float}**

**C260A2 Motor moved too far: {float}**



**C260A3 Failed, Microprocessor B wasn't ready.**

**C260A4 Unhandled state**

**C260A5 Solenoid boost too long**

**C260A6 Started boosting the solenoid too early after last boost**

**C260A12 Release of brake pin initiated**

**C260A13 Brake Pin successfully released**

**C260A14 Absolute Motor Encoder position offset unknown, searching for Motor Encoder Index Mark(s)**

**C260A15 Failed to determine Motor Encoder disc-type, {unsigned} Index Marks seen during Index Mark search.**

**C260A16 Absolute Motor Encoder position unknown after the Brake Release movement**

EXPLANATION

Not enough Index Marks detected to determine absolute Motor Encoder position offset.

SUGGESTION

**C260A17 Absolute Motor Encoder position offset found: {unsigned}**

EXPLANATION

Enough valid Index Marks were detected during the Brake Release to determine the absolute Motor Encoder position offset.

**C260A18 The robot did not come to a rest fast enough during Brake Release.**

EXPLANATION

A timeout occurred while waiting for the robot to settle after the Brake Release movement.

SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure the robot is not subject to excessive forces or vibrations during the Brake Release.

**C260A19 Commutation test started**

**C260A20 Joint speed too high during commutation test**

EXPLANATION

The Joint speed was too high, while waiting for the robot to settle after starting the servo- and motor-control loops.

SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure the robot is not subject to excessive forces or vibrations during the Brake Release. !

**C260A21 Joint speed not low enough, during commutation test**

EXPLANATION

A timeout occurred while waiting for the Joint speed to settle after starting the servo- and motor-control loops.

SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure the robot is not subject to excessive forces or vibrations during the Brake Release.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.



## 1.121. C261 Temperature Sensor

### C261A0 Critical error

#### EXPLANATION

A critical error occurred in the temperature sensor

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence.

### C261A1 Temperature is too high: {float} Celsius

### C261A2 Temperature is too low: {float} Celsius

### C261A3 Temperature changed more than allowed: {float} Celsius

### C261A4 Temperature is too high ({float} degrees Celsius)

#### EXPLANATION

Ambient temperature is too high or robot is overloaded

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Cool down the robot's environment and make sure the robot is operating within recommended limits, (B) Conduct a complete rebooting sequence.

### C261A5 Temperature is too low ({float} degrees Celsius)

#### EXPLANATION

Ambient temperature is too low

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Make sure the robot is operating within recommended limits, (B) Conduct a complete rebooting sequence.

### C261A6 Wrong device id {unsigned}

### C261A7 Wrong revision id {unsigned}

### C261A8 Wrong manufacturer id {unsigned}

### C261A9 Failed to initialize I2C communication

### C261A10 Failed to read from I2C

### C261A12 Caught in unhandled state: {unsigned}

### C261A13 Reading failed with timeout

### C261A14 Failed to initialize thermometer hardware

### C261A15 Temperature sensor {unsigned} read a temperature outside the allowed range.

#### EXPLANATION

A sensor read a temperature which is outside or close to robot operational limits. 0 = Core, 1 = Board.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.122. C262 Communication

### C262A0 Critical error

**EXPLANATION**

A critical error occurred in the communication framework

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for ESD noise, (C) Update software.

**C262A1 SPI length not accepted: {unsigned}**

**C262A2 Failed to transmit control data**

**C262A4 The {unsigned} message composed by the device was too long**

**C262A5 The device composed a message where the package destination and the message destination were different ({unsigned})**

**C262A6 The device composed a message where the package destination and the message destination were different ({unsigned})**

**C262A7 The received message has an invalid length, 4 byte data [status, type, source, length]: {hex}**

**C262A8 FIFO transfer error**

**C262A9 Memory allocation failed during the transfer operation**

**C262A10 SPI failed when flushing the RX buffer**

**C262A11 CRC error : Header {hex}**

**EXPLANATION**

A corrupted data package was received.

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check communication cables, (C) Update software.

**C262A12 Message not send to this device was received. Header : {hex}**

**C262A13 A message was received on an unknown interface: {unsigned}**

**C262A14 A message was received with an unknown RX channel: {unsigned}**

**C262A15 Unexpected message received from Joint to SCB. Header: {hex}**

**C262A16 Failed to send message to communication queues**

**EXPLANATION**

Communication queue is in an improper state.

**SUGGESTION**

**C262A17 Failed to communicate with Joint: {unsigned}**

**C262A18 Failed to communicate with TOOL:**

**C262A19 Received a non-finite float in a message, 4 byte data [0xFF, element index, type, source]: {hex}**

**C262A20 Received a non-finite float in a special command, 4 byte data [0xFF, element index, command, source]: {hex}**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.



## 1.123. C263 Motor Encoder

### C263A0 Critical error

#### EXPLANATION

A critical error occurred in the Motor Encoder.

#### SUGGESTION

Contact your local Universal Robots service provider for assistance.

### C263A1 Motor Encoder is unavailable

#### EXPLANATION

The Motor Encoder's sense signal indicates a bad connection.

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

### C263A2 Calibration has been invalidated and can lead to reduced performance.

#### EXPLANATION

An error in the file handling caused the invalid calibration, which can alter joint performance.

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

### C263A3 Calibration quality is poor, estimated error-reduction: {float\_5\_5}

### C263A4 Calibration quality is poor, estimated error-reduction: {float\_5\_5}

### C263A5 Calibration quality: estimated error-reduction = {float\_5\_5}

### C263A7 Failed to determine absolute Motor Encoder position. Distance {signed} not found in Index Mark LUT

#### EXPLANATION

If the distance between two adjacent Index Marks does not exist in the Index Mark LUT, one or more invalid Index Marks were detected

### C263A8 Failure: Not enough valid Index Marks detected to determine absolute Motor Encoder position during movement of {signed} ticks.

#### EXPLANATION

At least two valid Index Marks have not been detected during a large movement.

### C263A9 Missing Index Mark detected at absolute Motor Encoder position {unsigned}

### C263A10 Index drift detected at absolute Motor Encoder position {unsigned}

### C263A11 An Index Mark was expected at absolute Motor Encoder position {unsigned}

### C263A12 Previous Index Mark was detected at absolute Motor Encoder position {unsigned}

### C263A13 Joint velocity: {float\_2\_6} [rad/s]

### C263A14 Index Mark position lost due to a timing error

#### EXPLANATION

A new Index Mark was captured by the peripheral timer before the previously captured value was read, resulting in an over-capture event.

### C263A15 Index Mark position queue overflow

**EXPLANATION**

The queue used to hold the captured Index Mark positions was full. Writing an Index Mark position to the queue failed.

**SUGGESTION**

**C263A16 Index Mark was not detected when entering RUNNING mode**

**C263A17 Motor commutation-zero angle set to: ME position = {float\_2\_8} [rad]**

**C263A18 Failed to retrieve new memory block for Motor Encoder Index Marks**

**C263A19 The memory block swap failed**

**C263A20 Validation of the detected Index Mark ({signed}) failed**

**EXPLANATION**

Validation of the absolute Motor Encoder position failed because the detected Index Mark number is outside the required range.

**SUGGESTION**

**C263A21 Validation of the detected Index Mark ({signed}) failed**

**EXPLANATION**

The absolute Motor Encoder position cannot be validated because the Motor position calculated by the Joint Encoder is invalid.

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C263A22 Failed to determine the absolute position missing index detected, distance = {signed}.**

**EXPLANATION**

The detected distance is greater than the maximum allowed distance between any two Index Marks

**SUGGESTION**

**C263A23 Discarding Motor Encoder raw pos1: {unsigned}**

**C263A24 Motor Encoder raw pos1: {unsigned}**

**C263A25 Motor Encoder raw pos2: {unsigned}**

**C263A26 Failure to log missing Index Mark, index out of range: {unsigned}**

**C263A27 Failure to log index drift, position out of range: {unsigned}**

**C263A28 STAT command check failure: {unsigned}**

**C263A29 STAT special cmd boundary failure, type \*1000 + idx: {unsigned}**

**C263A30 The timer ratio is out of sync, actual ratio is {float}**

**C263A31 The motor encoder configuration file id:{unsigned} was not successfully loaded**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket

## 1.124. C264 Task Manager



### C264A0 Critical error

#### EXPLANATION

A critical error occurred in the task manager

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

### C264A1 Missed a systick

### C264A2 Overload, task-ID: {unsigned}, was not executed in time.

#### EXPLANATION

A system task was not executed at the appropriate time

#### SUGGESTION

### C264A3 The task was delayed by: {float} uS

#### EXPLANATION

A system task was delayed.

#### SUGGESTION

### C264A4 Overrun, task ID: {unsigned}, exceeded allowed execution window.

#### EXPLANATION

A system task exceeded its permitted execution time.

#### SUGGESTION

### C264A5 The task allowed execution time was exceeded by: {float} uS

#### EXPLANATION

A system task exceeded its permitted execution time.

#### SUGGESTION

### C264A6 CPU load is {float}\_2\_0}%.

### C264A7 SOC was required but not found after {unsigned}ms.

### C264A8 Systick and SOC are misaligned by {float}us.

### C264A9 Unexpected (+) or missing (-) SOC(s) detected within 1s check period: {signed}.

### C264A10 Invalid SOC(s) detected within 1s check period: {unsigned}.

### C264A11 Lost {unsigned} SOC(s).

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.125. C265 Joint Encoder

### C265A0 Joint encoder position invalid. Detailed error: {hex}

#### EXPLANATION

A critical error occurred in the Joint Encoder. The reported position is not valid.



#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for ESD noise, (C) Update software.

**C265A1 Data is invalid. Status: {hex}**

**C265A2 CRC failed**

**C265A3 Data is arriving late or not at all**

**C265A4 The Joint Encoder Firmware version {hex} is incorrect**

#### EXPLANATION

Joint Encoder version was not whitelisted

**C265A5 Near operation limits. Status: {hex}**

#### EXPLANATION

The joint encoder is close to operational limits. Reported positions have reduced precision.

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for ESD noise, (C) Update software.

**C265A6 Not present. Status: {hex}**

#### EXPLANATION

The Joint Encoder is not responding to commands

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for ESD noise, (C) Update software, (D) Contact your local Universal Robots service provider for assistance

**C265A7 Decoding error. Status: {hex}**

#### EXPLANATION

The module is out of alignment or the ring is damaged or external magnetic field present or encoder acceleration too high.

**C265A8 Internal speed data is not valid. Status: {hex}**

#### EXPLANATION

The time difference between two position requests exceeded 65 ms.

**C265A9 Circuit malfunction or inconsistent calibration. Status: {hex}**

**C265A10 Power supply voltage out of range. Status: {hex}**

**C265A11 The room temperature is out of range. Status: {hex}**

#### EXPLANATION

The room temperature is too high or the robot is overloaded.

#### SUGGESTION

Cool down the environment and make sure the robot is operating within the recommended limits.

**C265A12 Signal lost. Status: {hex}**

**C265A13 Signal amplitude low. Status: {hex}**

**C265A14 Signal amplitude too high. Status: {hex}**

**C265A15 Signal clipping. Status: {hex}**

**C265A16 Failed to initiate data transfer with the Joint Encoder**

#### EXPLANATION

Could not schedule asynchronous callback



**C265A17 Failed to initiate data transfer with the Joint Encoder. Could not acquire a DMA buffer**

**C265A18 The Zero-torque offset of the Motor model is not valid**

**C265A19 The position reported by the encoder does not convert to a valid floating point number. Binary data: {hex}**

**C265A20 Negative sampling delay (Value = {float\_5\_5}) can result in missing jointencoder feedback.**

EXPLANATION

If the sampling delay is negative, the requested data package can't be sampled and transferred from the joint encoder, to the joint, before the next deadline.

**C265A21 Sampling delay was negative: Actual Systick-time = {unsigned} us.**

EXPLANATION

Systick-time refers to the time, in microseconds, since the start of the current scheduling cycle.

**C265A22 Sampling delay was negative: Actual Sampling-time = {float\_5\_5} us.**

EXPLANATION

Sampling-time refers to the total time needed, from requesting a sample by asserting chip-select, until the requested package has been transmitted by the joint encoder and received in the joint MCU.

**C265A23 Sampling delay was negative: Actual Sample-deadline-time = {float\_5\_5} us.**

EXPLANATION

Sample-deadline-time refers to the future Systick-time, when the joint encoder sample must be ready for parsing.

**C265A24 Encoder acceleration too high. Status: {hex}**

**C265A25 Decoding error. Status: {hex}**

EXPLANATION

The module is out of alignment or the ring is damaged or external magnetic field present.

**C265A26 Decoding warning. Status: {hex}**

EXPLANATION

Encoder is close to invalid-decoding error. Check installation and magnetic fields.

**C265A27 System warning. Status: {hex}**

EXPLANATION

Encoder state is undefined (position is not yet calculated).

**C265A28 The jointencoder position filter {unsigned} is not valid**

EXPLANATION

The joint encoder position filter has to be one of the valid types

**C265A29 An attempt to initialize the position filter was made after it has already been initialized**

EXPLANATION

The position filter can only be initialized once (with one filter type)

**C265A30 Invalid pointer when initializing adaptive filter**

EXPLANATION

The adaptive position filter was initialized with an invalid pointer



If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.126. C266 Self-test

### C266A0 Critical error

#### EXPLANATION

A critical error occurred in the Joint Self-test

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

### C266A1 ADC calibration failed

### C266A3 Brake Test failed

### C266A4 Brake Test failed. An Index Mark should have been detected.

### C266A5 Cogging calibration failed

### C266A6 Joint calibration failed

### C266A7 Microprocessor B failed

### C266A8 Commutation offset calibration failed

### C266A10 uPB failed to sync with tag {unsigned}

### C266A11 ADC Calibration failed due to an invalid gain of ({float})

### C266A12 ADC Calibration failed due to an invalid offset of ({float})

### C266A13 Brake Test failed because it moved too far

### C266A14 Brake Test failed due to the current being ({float}A) too high.

### C266A15 Brake Test success: current {float}A

### C266A18 Brake Release procedure failed

### C266A19 Motor phases are connected in the wrong order, speed: {float}rad/s

### C266A20 uPA is in an abnormal state

### C266A21 Microprocessor A failed

### C266A22 Not all tests were completed.

### C266A23 Printed Circuit Board type has not been identified as being a Joint.

### C266A25 Joint moving to new mounting position: {float}rad

### C266A26 Joint failed to move to a new mounting position: {float}rad

### C266A27 Restarting the Self-test

### C266A28 External device failed to run Self-test

### C266A29 Serial calibration failed

### C266A30 Self-test was successfully validated with serial:{unsigned}

### C266A31 ADC calibration failed, too high current requested: {float}A

### C266A32 Doing ADC calibration with sample voltage: {float}V



C266A33 ADC calibration assumes nominal gain of {float}  
C266A34 ADC calibration cannot load ADC configuration file  
C266A36 Joint- and Motor-Encoder calibration failed  
C266A37 Start of invalid test have been requested. Test ID: {unsigned}  
C266A38 Invalid ADC test stage have been requested. stage ID: {unsigned}  
C266A39 Force-Torque sensor calibration did not start because the temperature is below the required threshold of {float} degrees Celsius  
C266A40 Tool was moved during calibration  
C266A41 Unable to reach target temperature for Joint calibration  
C266A42 Failure to save the Motor Encoder data file  
C266A43 Failure to save the index LUT data file  
C266A44 The motor constants calibration stage failed to load required files  
C266A45 The motor constants calibration stage entered illegal state  
C266A46 Stator calibration cannot load the Motor Parameters file  
C266A47 Stator calibration cannot load the ADC Configuration file  
C266A48 Stator calibration cannot load the Inverter Configuration file  
C266A49 Stator calibration failed, too high current requested: {float}A  
C266A50 Doing stator calibration with sample voltage: {float}V  
C266A51 Starting stator cooldown, temperature is: {float} degrees Celcius  
C266A52 Doing stator cooldown iteration, temperature is: {float} degrees Celcius  
C266A53 Stator not cooling down, temperature is: {float} degrees Celcius  
C266A54 Stator not cooling down fast enough, temperature is: {float} degrees Celcius  
C266A55 Stator is heating up, temperature is: {float} degrees Celcius  
C266A56 Unexpected PCB {unsigned}, unable to determine servo\_speed\_params  
C266A57 Selftest was expected to be in state: INIT but was in state: {unsigned} instead  
C266A58 State at last shutdown: {unsigned}  
C266A59 Commutation angle calibration does not support {unsigned} polepairs  
C266A60 Commutation angle calibration is unable to find the first pole  
C266A61 Commutation angle calibration is unable to settle in position  
C266A62 EMS ADC calibration data is missing or invalid, run new EMS test  
C266A63 The revision {unsigned} of the EMS ADC calibration is not supported by this firmware  
C266A64 Vibration measurement, unsupported PCB {unsigned}  
C266A65 The hardware info message revision is not supported {hex}  
C266A66 The enum version is not supported {hex}  
C266A67 Invalid amount of hardware types in one message {unsigned}  
C266A68 Information on hardware ID {hex} has already been received

C266A69 Received unknown hardware ID {unsigned}  
C266A70 Mismatch between rotor and stator type {hex}  
C266A71 Received unknown motor type {unsigned}  
C266A72 Mismatch between gear box and shaft type {unsigned}  
C266A73 Received unknown gear type {unsigned}  
C266A74 Received unknown motor encoder platform type {unsigned}  
C266A75 Hardware ID {unsigned} not received  
C266A76 Could not set motor parameters for the given type {unsigned}  
C266A77 Invalid amount of hardware types requested for storage {unsigned}  
C266A78 Timed out while waiting for hardware information. Waited {unsigned} milliseconds  
C266A79 Hardware info failed  
C266A80 Average D voltage in the positive direction was {float}  
C266A81 Average Q voltage in the positive direction was {float}  
C266A82 Average D voltage in the negative direction was {float}  
C266A83 Average Q voltage in the negative direction was {float}  
C266A87 Failed to load nominal shunt data  
C266A88 Zero current measurement not completed  
C266A89 The revision {unsigned} of the ADC calibration is not supported on this joint size, make sure correct EMS data is available.  
C266A90 Got {unsigned} bytes of magnetic field data.  
C266A91 Expected {unsigned} bytes of magnetic field data.  
C266A92 Got {unsigned} samples of magnetic field data.  
C266A93 At least {unsigned} samples of magnetic field data is required on a revolution. Reduce motor velocity for test.  
C266A94 Both regression lines have equal slope, no valid sensor tilt can be derived. Validate that no external magnetic field disturb the encoder.  
C266A95 Average D current in the positive direction was {float}  
C266A96 Average Q current in the positive direction was {float}  
C266A97 Average D current in the negative direction was {float}  
C266A98 Average Q current in the negative direction was {float}  
C266A99 Commutation angle optimization actual commutation angle: {float}  
C266A100 Commutation angle optimization iteration {unsigned} results:  
C266A101 The package size cannot contain a header and at least one hardware ID  
C266A102 The memory buffer pointer is invalid  
C266A103 Invalid distance {float} between polepairs



## C266A104 Invalid distance {float} between polepair measurements from positive and negative directions

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.127. C267 Bootloader error

### C267A0 Critical error

#### EXPLANATION

A critical error occurred during Firmware upgrade.

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

### C267A1 Bootloader is corrupted

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

### C267A2 Firmware is corrupted

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update soft- and firmware

### C267A3 Power on Self-test failed

### C267A4 The processor unique ID is wrong

#### SUGGESTION

### C267A5 The processor version is wrong

#### SUGGESTION

### C267A6 Unable to boot main application

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update soft- and Upgrade firmware

### C267A7 The AES key is corrupted

### C267A8 Decrypted data is corrupted

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update soft firmware.

### C267A9 Data sent but expected IV

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update soft firmware.

### C267A10 Data could not be correctly decrypted

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update soft firmware.

**C267A11 Hardware configuration issue****EXPLANATION**

Hardware configuration mismatch

**SUGGESTION**

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.128. C268 Special Command

**C268A0 Received unhandled command cmd:{unsigned}****C268A1 Recieved Set Zero Command at too high speed****C268A2 Self-test command with illegal key: {unsigned}****C268A3 Self-test command was not executed, key:{unsigned}****EXPLANATION**

The command was received in an illegal Self-test state

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.129. C269 Transceiver – deprecated

**C269A0 Hub : Framing error on port: {signed}****EXPLANATION**

A message with a malformed frame was passed to the HUB on specified port(0: Int 1: Ext0, 2: Ext1, 4: None)

**SUGGESTION****C269A1 Hub : Alignment error on port: {signed}****EXPLANATION**

A message with a malformed frame was passed to the HUB on specified port(0: Int 1: Ext0, 2: Ext1, 4: None)

**SUGGESTION****C269A2 Data transmission unit : FiFo overflow on port {unsigned}****EXPLANATION**

Transmission unit had a FiFo overflow on specified port (0: port a, 1: port b)

**C269A3 Data transmission unit : code error on port {unsigned}****EXPLANATION**

Transmission unit received a code error on specified port (0: port a, 1: port b), this should never happen

**SUGGESTION****C269A4 Data reception unit : Alignment error on port {unsigned}**



EXPLANATION

Reception unit was unaligned with message on specified port (0: port a, 1: port b)

SUGGESTION

**C269A5 Data reception unit : Alignment fault on port {unsigned}**

EXPLANATION

Reception unit was unable to align to incoming message on specified port (0: port a, 1: port b)

SUGGESTION

**C269A6 Data reception unit : Code error on port {unsigned}**

EXPLANATION

Reception unit saw an invalid control code on specified port (0: port a, 1: port b)

SUGGESTION

**C269A7 Data reception unit : Disparity error on port {unsigned}**

EXPLANATION

Reception unit got a disparity error on specified port (0: port a, 1: port b)

SUGGESTION

**C269A8 Data reception unit : FiFo overflow on port {unsigned}**

EXPLANATION

Reception unit had a FiFo overflow on specified port (0: port a, 1: port b)

SUGGESTION

**C269A9 Upstream transport layer : Package CRC error**

EXPLANATION

Upstream transport layer caught CRC error in package header, this might happen on occasion. Can be ignored if only happens rarely

**C269A10 Upstream transport layer : Bad package framing**

EXPLANATION

Upstream transport layer had found a framing error.

SUGGESTION

**C269A11 Upstream transport layer : Rx FiFo overflow**

EXPLANATION

Upstream transport layer had a FiFo overflow

SUGGESTION

**C269A12 Upstream transport layer : Tx FiFo overflow**

EXPLANATION

Slave transport layer had a Tx FiFo overflow

SUGGESTION



### **C269A13 Upstream transport layer : Invalid hub count**

#### EXPLANATION

Slave transport layer recieved a message with invalid hub-cnt

#### SUGGESTION

### **C269A14 Upstream transport layer : Request source not master.**

#### EXPLANATION

Slave transport layer recieved a message request from a device different from the master

#### SUGGESTION

### **C269A15 Upstream transport layer : Response source not slave.**

#### EXPLANATION

Slave transport layer recieved a message response from a device different from a slave

#### SUGGESTION

### **C269A16 Upstream transport layer : Sync package type received**

#### EXPLANATION

Master transport layer recieved a message where the type was Sync

#### SUGGESTION

### **C269A17 Upstream transport layer : Trigger package type received**

#### EXPLANATION

Master transport layer recieved a message where the type was a trigger

#### SUGGESTION

### **C269A18 Upstream transport layer : Request package type received**

#### EXPLANATION

Master transport layer recieved a message where the type was a request

#### SUGGESTION

### **C269A19 Upstream transport layer : Invalid response type received**

#### EXPLANATION

Master transport layer recieved a message where the type was an invalid response

#### SUGGESTION

### **C269A20 Upstream transport layer : Package from invalid source received**

#### EXPLANATION

Master transport layer recieved a package with an invalid source

#### SUGGESTION

### **C269A21 Upstream transport layer : Mismatch between HUB count and package source**



EXPLANATION

Master transport layer recieved a package where the src and HUB count did not match

SUGGESTION

**C269A22 Upstream transport layer : Package longer than expected**

EXPLANATION

Master transport layer recieved a package where the length was greate than expected, or lost a framing end

SUGGESTION

**C269A23 Upstream transport layer : Package shorter than expected**

EXPLANATION

Master transport layer recieved a package where the length was less than expected

SUGGESTION

**C269A24 Upstream transport layer : Package was misaligned**

EXPLANATION

Master transport layer recieved a package that did not align to 32bit

SUGGESTION

**C269A25 Downstream transport layer : Package was shorter than expected**

EXPLANATION

Downstream transport layer tried to transmit a package that was longer than the data available

SUGGESTION

**C269A26 Downstream transport layer : Package was longer than expected**

EXPLANATION

Downstream transport layer tried to transmit a package with more data than expected

SUGGESTION

**C269A27 Downstream transport layer : Invalid package type**

EXPLANATION

Master transport layer tried to transmit a package with an invalid package type

SUGGESTION

**C269A28 Downstream transport layer : Package type missing**

EXPLANATION

Master transport layer tried to transmit a package without a package type

SUGGESTION

**C269A29 Downstream transport layer : Message length missing**

EXPLANATION

Master transport layer tried to transmit a package without a message length



## SUGGESTION

### **C269A30 Downstream transport layer : Package destination missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a destination

#### SUGGESTION

### **C269A31 Downstream transport layer : Package source missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a source

#### SUGGESTION

### **C269A32 Downstream transport layer : Package NML missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a next message length

#### SUGGESTION

### **C269A33 Downstream transport layer : Package TTTL missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a time to live

#### SUGGESTION

### **C269A34 Downstream transport layer : Package timeout(high byte) missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a timeout the high byte

#### SUGGESTION

### **C269A35 Downstream transport layer : Package timeout(low byte) missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a timeout the low byte

#### SUGGESTION

### **C269A36 Downstream transport layer : Invalid message length**

#### EXPLANATION

Master transport layer tried to transmit a package with mismatch between stated and actual length

#### SUGGESTION

### **C269A37 BLVDS controller : Received control pkg in data phase**

#### EXPLANATION

BLVDS controller received a control package when not in the control phase

#### SUGGESTION

### **C269A38 BLVDS controller : Received data package in control phase**



EXPLANATION

BLVDS controller received a data package when not in the data phase

SUGGESTION

**C269A39 BLVDS controller : Got SOC before being ready**

EXPLANATION

BLVDS controller got a SOC interrupt while not ready

SUGGESTION

**C269A40 BLVDS scheduler : Got SOC before being ready**

EXPLANATION

BLVDS scheduler got a SOC interrupt while not ready

SUGGESTION

**C269A41 BLVDS scheduler : Node ID invalid**

EXPLANATION

BLVDS scheduler tried to send to Node ID outside valid range

SUGGESTION

**C269A42 Switch : Priority package timeout on ports: {hex}**

EXPLANATION

Switch timed out trying to provide priority package to specified ports (bitmask)

SUGGESTION

**C269A43 Switch : Data package timeout on ports: {hex}**

EXPLANATION

Switch timed out trying to provide data package to specified ports (bitmask)

SUGGESTION

**C269A44 Endpoint : Priority data debug channel overflow**

EXPLANATION

SCB Endpoint discarded priority data to debug channel as it was not consumed fast enough

SUGGESTION

**C269A45 Endpoint : data debug channel overflow**

EXPLANATION

SCB Endpoint discarded data to debug channel as it was not consumed fast enough

SUGGESTION

**C269A46 Endpoint : Priority data inbound timeout from port {hex}**

EXPLANATION

SCB Endpoint lost an inbound priority package on specified port as the data was not provided before timeout, data as bitmask

## SUGGESTION

### **C269A47 Endpoint : Data inbound timeout from port {hex}**

#### EXPLANATION

SCB Endpoint lost an inbound package on specified port as the data was not provided before timeout, data as bitmask

#### SUGGESTION

### **C269A48 Endpoint : Priority data outbound timeout to port {hex}**

#### EXPLANATION

SCB Endpoint lost an outbound priority package to specified port as the data was not consumed before timeout, data as bitmask

#### SUGGESTION

### **C269A49 Endpoint : Data outbound timeout to port {hex}**

#### EXPLANATION

SCB Endpoint lost an outbound package to specified port as the data was not consumed before timeout, data as bitmask

#### SUGGESTION

### **C269A50 UART : FiFo overflow**

#### EXPLANATION

UART lost incoming data as a result of a FiFo overflow

#### SUGGESTION

### **C269A51 UART : Length mismatch**

#### EXPLANATION

UART discarded a package as length of data did not match announced data

#### SUGGESTION

### **C269A52 UART : Unexpected SOM**

#### EXPLANATION

UART got a new start of message during transmission of a message, data will be lost

### **C269A53 uA SPI : FiFo underflow**

#### EXPLANATION

uA SPI FiFo ran out of data before message was complete

#### SUGGESTION

### **C269A54 uA SPI : Unexpected read command**

#### EXPLANATION

uA SPI received a read command without signaling data ready

#### SUGGESTION



### **C269A55 uA SPI : Unsupported command: {hex}**

#### EXPLANATION

uA SPI received an unsupported command

#### SUGGESTION

### **C269A56 uA SPI : FiFo overflow**

#### EXPLANATION

uA SPI received more data from device than could be stored.

#### SUGGESTION

### **C269A57 uB SPI : FiFo underflow**

#### EXPLANATION

uB SPI FiFo ran out of data before message was complete

#### SUGGESTION

### **C269A58 uB SPI : Unexpected read command**

#### EXPLANATION

uB SPI received a read command without signaling data ready

#### SUGGESTION

### **C269A59 uB SPI : Unsupported command: {hex}**

#### EXPLANATION

uB SPI received an unsupported command

#### SUGGESTION

### **C269A60 uB SPI : FiFo overflow**

#### EXPLANATION

uB SPI received more data from device than could be stored.

#### SUGGESTION

### **C269A61 The SoC arrived {unsigned} [ns] too early**

#### EXPLANATION

The ideal period of the SoC is 1000.00 us, and the allowed jitter is +/- 1000.0 ns

### **C269A62 Timeout while waiting for the SoC, the SoC was lost or delayed more than {unsigned} ns!**

#### EXPLANATION

The ideal period of the SoC is 1000.00 us, and the allowed jitter is +/- 1000.0 ns

#### SUGGESTION

### **C269A63 uA SPI : FiFo overflow on interface: {signed}**

#### EXPLANATION

uA SPI received more data than could be relayed to device.

### **C269A64 uA SPI : FiFo overflow cleared**

**EXPLANATION**

uA SPI is ready to relay messages to device.

**SUGGESTION****C269A65 uB SPI : FiFo overflow on interface: {signed}****EXPLANATION**

uB SPI received more data than could be relayed to device.

**SUGGESTION****C269A66 uB SPI : FiFo overflow cleared****EXPLANATION**

uB SPI is ready to relay messages to device.

**SUGGESTION****C269A67 PCIe Control-Data : Blocked for {unsigned} us****EXPLANATION**

PCIe control channel overflowed and was blocked, time to nearest us

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Reduce CPU load

**C269A68 PCIe Priority-Data : Blocked for {unsigned} us****EXPLANATION**

PCIe priority channel overflowed and was blocked, time to nearest us

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Reduce CPU load

**C269A69 PCIe data-data : Blocked for {unsigned} us****EXPLANATION**

PCIe data channel overflowed and was blocked, time to nearest us

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Reduce CPU load

**C269A70 Flash device is not supported, JEDEC data for device is: {hex}****EXPLANATION**

The flash device's JEDEC ID does not match a supported flash device

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.130. C270 Self-test SYNC

**C270A1 Unexpected ACK received with tag {unsigned}****C270A2 Unexpected NACK received with tag {unsigned}****C270A3 Timeout while waiting for ACK/NACK with tag {unsigned}**



---

## C270A4 Expected ACK received with tag {unsigned}.

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.131. C271 Low level real-time thread

### C271A1 Runtime is too much behind.

#### EXPLANATION

One of the threads might be using too much time (see log for more details).

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Use a Wait or sync() to split long program sequences that do not move the robot.

### C271A2 Too many invalid packets from the robot

### C271A3 Runtime and communication out of sync

### C271A4 Runtime and communication out of sync

### C271A5 Runtime and communication out of sync

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.132. C272 Missing calibration

### C272A0 Critical error - the calibration is missing

#### EXPLANATION

Calibration could not be loaded

### C272A1 ADC calibration is missing

### C272A2 Commutation offset calibration is missing

### C272A3 Cogging calibration is missing

### C272A5 Joint- and Motor-Encoder calibration is missing

### C272A6 Motor parameter calibration is missing

### C272A7 Joint-Encoder Legacy calibration is missing

### C272A8 Joint-Encoder DFT calibration is missing

### C272A9 Motor-Encoder calibration is missing

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.133. C273 Cross monitoring

### C273A0 Critical error

#### EXPLANATION

A critical disagreement error occurred in the safety system

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

#### **C273A1 Float value on A-side: {float}**

#### **C273A2 Float value on B-side: {float}**

#### **C273A3 Unsigned value on A-side: {unsigned}**

#### **C273A4 Unsigned value on B-side: {unsigned}**

#### **C273A5 Disagreement on Safety Control Board State**

#### EXPLANATION

A critical disagreement occurred within the safety system.

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

#### **C273A6 Disagreement on Robot State**

#### EXPLANATION

A critical disagreement occurred within the safety system.

#### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

#### **C273A7 Disagreement on Safety State**

#### EXPLANATION

A critical disagreement occurred within the safety system

#### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

#### **C273A8 Disagreement on position**

#### EXPLANATION

A critical disagreement occurred within the safety system

#### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

#### **C273A9 Disagreement on velocity**

#### EXPLANATION

A critical disagreement occurred within the safety system

#### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

#### **C273A10 Disagreement on current**

#### EXPLANATION

A critical disagreement occurred within the safety system

#### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.



## **C273A11 Disagreement on temperature**

### EXPLANATION

A critical disagreement occurred within the safety system

### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

## **C273A12 Disagreement on Teach Pendant State**

### EXPLANATION

A critical disagreement occurred within the safety system

### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

## **C273A13 Disagreement on Teach Pendant Emergency Stop**

### EXPLANATION

A critical disagreement occurred within the safety system

### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

## **C273A14 One processor entered Fault State**

### EXPLANATION

A critical disagreement occurred within the safety system

### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

## **C273A15 One processor entered Violation State**

### EXPLANATION

A critical disagreement occurred within the safety system

### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

## **C273A16 Joint State disagreement**

### EXPLANATION

A critical disagreement occurred within the safety system

### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

## **C273A17 Joint Constant Data CRC disagreement**

### EXPLANATION

A critical disagreement occurred within the safety system

### SUGGESTION

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

## **C273A18 Joint target current disagreement**



**EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A19 Torque Window disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A20 Torque Error disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A21 Target Velocity disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A22 Target Acceleration disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A23 Recovery Mode CRC disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A24 Robot Configuration CRC disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A25 User Configuration CRC disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A26 Maximum stopping time disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A27 Stopping Time Torque Overload disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A28 Disagreement error on joint {unsigned}****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A29 Tool speed disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A30 Safety Mode Limit disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A31 Hand Protection Distance disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A32 Elbow Sphere speed disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A33 Momentum disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A34 Power disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A35 Elbow position disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A36 Workpiece Rotation disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A37 Disagreement on Workpiece Position****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A38 Disagreement on motor parameter (R\_pp)****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A39 Disagreement on motor parameter (L\_pp)****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A40 Disagreement on motor parameter (Kb)****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A41 Disagreement on motor parameter (Kt)****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A42 Disagreement on motor parameter (T)****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A43 Disagreement on the Teach Pendant's Three-Position Enabling Device****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A44 Disagreement on the active status of the Teach Pendant's Three-Position Enabling Device****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A45 Disagreement on user safety configuration version, major****C273A46 Disagreement user safety configuration version, minor****C273A47 Disagreement on state****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A48 Disagreement on Injection-Molding-Machine-Interface Emergency Stop input**

**EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A49 Disagreement on Injection-Molding-Machine-Interface Emergency Stop output****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A50 Disagreement on Injection-Molding-Machine-Interface Safeguard input****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A51 Disagreement on Injection-Molding-Machine-Interface type****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A52 Disagreement on Torque Parameters CRC****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A53 Target Torque disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A54 Disagreement on hardware configuration CRC****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A55 Disagreement on compensation current****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A56 Disagreement on external torque target****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C273A57 Safety Target Torque disagreement****EXPLANATION**

A critical disagreement occurred within the safety system

**SUGGESTION**

Try the following actions to see if it which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.134. C274 Control box fan error

**C274A1 Fan is not running****EXPLANATION**

The control box fan must be running to prevent the control box from overheating

**SUGGESTION**

Try the following actions to see if it resolve the issue: (A) Conduct a complete rebooting sequence, (B) Ensure the fan in the control box can rotate freely and the connector is attached. The control box fan is located between the air filter and the energy eater in the control box. See the Service Manual for details.

**C274A2 Monitoring data timed out****EXPLANATION**

The monitoring signals for the fan speed was not received by the system in a timely manner

**SUGGESTION**

Try the following actions to see if it resolve the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C274A3 Fan speed is {float}****EXPLANATION**

Fan rotational speed in RPM

---

Try the following actions to resolve the issue: (A) Conduct a complete rebooting sequence, (B) Update software, (C) Contact your local Universal Robots service provider for assistance.

## 1.135. C275 Brake Pin

**C275A1 Boost on****C275A2 Boost off****C275A4 Released**

## C275A6 Locked

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.136. C276 Uart

### C276A0 Critical error

#### EXPLANATION

A critical error occurred in the UART driver

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

### C276A1 Wrong length received, data: {hex}

#### EXPLANATION

Byte 3: bytes recieved, Byte 2: pkg len, Byte 1: pkg dst, Byte 0: pkg src

### C276A2 Noise detected

### C276A3 Framing error

### C276A4 Overrun error

### C276A5 failed to start rx

### C276A6 Trying to start TX DMA while DMA in use

### C276A7 TX DMA transfer error, uart: {unsigned}

### C276A8 TX DMA FIFO error, uart: {unsigned}

### C276A9 Parity error

### C276A10 Interrupt flag unhandled: {unsigned}

### C276A11 The Commit function has not been initialized.

### C276A12 Cannot provide desired baudrate: {unsigned}

### C276A13 The package length is greater than 256 bytes, can't be sent: {unsigned}

### C276A14 Unhandled overflow detected

#### EXPLANATION

UART overflowed and driver did not clear it correctly

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.137. C277 Memory

### C277A1 Failed to allocate memory

### C277A2 Wrong memory pointer freed: {hex}

### C277A3 Pointer with value zero freed, caller: {hex}

### C277A4 Wrong memory pointer freed, caller: {hex}

### C277A5 Unable to push message to queue, id: {unsigned}



## C277A6 Report queue is full

### EXPLANATION

Report queue has run out of space, expect loss of messages

### SUGGESTION

**C277A7 The queue of available message buffers is nearly empty.**

**C277A8 Pointer with value zero pushed to queue, queueID: {unsigned}**

**C277A9 Memory Allocation fail data: {unsigned}**

**C277A10 Unable to latch report: {hex}**

### EXPLANATION

Specified report is already latched expect loss of report data

**C277A11 memory leak detected, due a full free queue**

### EXPLANATION

Free queue is in a bad state

### SUGGESTION

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.138. C278 Servo

### C278A0 Critical error

#### EXPLANATION

A critical error occurred in the servo module

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C278A1 Joint moment of inertia = {float\_5\_5} [kg\*m^2] received from the controller is not within the valid range**

**C278A2 The minimum required current loop bandwidth is greater than allowed**

#### EXPLANATION

The Speed loop damping is set too low, and/or the Speed LPF pole is set too high

**C278A3 Received a new control parameter with key {unsigned}**

#### EXPLANATION

Controller passed a new control parameter to the joints

**C278A4 Received a new control parameter with value {float}**

#### EXPLANATION

Controller passed a new control parameter value to the joints

**C278A5 Device mode function pointer initialized to NULL**

#### EXPLANATION

The function pointer to get device mode was initialized to NULL which is not valid

**C278A6 Joint target position is not a finite value, value: {float}**



- C278A7 Joint target speed is not a finite value, value: {float}
- C278A8 Joint target current is not a finite value, value: {float}
- C278A9 Joint current min is not a finite value, value: {float}
- C278A10 Joint current max is not a finite value, value: {float}
- C278A11 Joint actual inertia is not a finite value, value: {float}
- C278A12 Joint target acceleration is not a finite value, value: {float}
- C278A13 Joint target torque is not a finite value, value: {float}
- C278A14 Joint predicted torque is not a finite value, value: {float}
- C278A15 Joint control torque is not a finite value, value: {float}
- C278A16 Joint torque min is not a finite value, value: {float}
- C278A17 Joint torque max is not a finite value, value: {float}
- C278A18 The control message version that was received is not supported. Version received: {unsigned}
- C278A19 Previous device mode function pointer initialized to NULL

#### EXPLANATION

The function pointer to get previous device mode was initialized to NULL which is not valid

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.139. C279 Flash

### C279A0 Critical error

#### EXPLANATION

A critical error occurred in the flash driver

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

### C279A1 Unable to allocate data in Flash

### C279A2 Address is not aligned

### C279A3 Source is not aligned

### C279A4 Unable to read data

### C279A5 Tried writing to nonerasable address

### C279A6 Flash access error

### C279A7 Flash protection violation

### C279A8 Previous operation failed

### C279A9 Failed during execution

### C279A10 Write verification failed

### C279A11 Reading out of bounds

### C279A12 Write and verify operation failed



C279A13 Address to be erased is not aligned  
C279A14 Address to be erased is out of bounds  
C279A15 Erase verification failed  
C279A16 Collision of read and write  
C279A17 Init failed  
C279A18 Unable to write data  
C279A19 System voltage too low  
C279A20 Flash quality issue count: {unsigned}

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.140. C280 Real-time error

### C280A0 Critical error

#### EXPLANATION

A critical real-time error occurred

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software, (C) Check communication between joints.

C280A1 Missed {unsigned} CTRL message(s)

C280A2 CTRL data not sent in current cycle (delayed {unsigned}[us] into next cycle)

C280A3 {unsigned} CTRL messages in queue, discarding all but the most recent

C280A7 Oldest unparsed message on interface {unsigned} discarded

C280A8 Missed {unsigned} XCOM message(s)

C280A9 {unsigned} XCOM messages in queue, discarding all but the most recent

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.141. C281 Robot State Machine

### C281A0 Critical error

#### EXPLANATION

A critical State Machine error occurred

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

C281A1 An invalid transition occurred in the code:{unsigned}

C281A2 An invalid Robot State occurred

C281A3 {unsigned} joint entered the Fault State

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C281A4 {unsigned} joint entered the Violation State****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C281A5 Shutdown took too long, robot voltage is {float}****C281A6 Moved to an unhandled state: {unsigned}****C281A7 Teach Pendant entered the Fault State****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C281A8 Teach Pendant entered the Violation State****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C281A9 {unsigned} joint moved too far before robot entered RUNNING State****EXPLANATION**

A Joint moved more than the permissible range during the Brake Release procedure.

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure the mounted payload, TCP, and CoG matches your configuration, (C) Update software.

**C281A10 Failed to power on the Robot arm****C281A11 Caused by joint {unsigned}****C281A12 Caused by state {unsigned}****C281A13 Aggregate joint mode status {hex}****C281A14 IMMI entered the Fault State****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C281A15 IMMI entered the Violation State****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.142. C282 Systick

**C282A1 Systick Sync: SoC frequency synchronization started**



**C282A2 Systick Sync: SoC frequency synchronization in progress, sample number: {unsigned} of 16**

**C282A3 Systick Sync: SoC frequency synchronization in progress, received 'SoC period' sample of: {float\_4\_4} [us]**

**C282A4 Systick Sync: SoC frequency synchronization in progress, received 'SoC ISR Latency' sample of: {float\_3\_5} [us]**

**C282A5 Systick Sync: SoC period determined to be: {float} [us]**

**C282A6 Systick Sync: SysTick timer LOAD value set to: {unsigned} [cpu-clock-cycles]**

**C282A7 Systick Sync: SoC frequency synchronization finished**

**C282A8 Systick Sync: SoC Phase synchronization started**

**C282A9 Systick Sync: SysTick SoC Phase error: {signed}**

**EXPLANATION**

Negative number means the Systick counter was behind (too late), positive number means the Systick counter was ahead (too early)

**C282A10 Systick Sync: Estimated Systick counter value at SoC: {unsigned}**

**C282A11 Systick Sync: Estimated Systick counter ticks to next SoC: {unsigned}**

**C282A12 Systick Sync: SoC Phase synchronization finished**

**C282A13 The internal SoC count value has been resynchronized with the FPGA SoC count. Data: {hex}**

**EXPLANATION**

Data: [Number of resyncs, 16 bits][FPGA SoC count (new), 8 bit][Device SoC count (old), 8 bit]

**C282A14 SOC status data failed to update in a timely manner**

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.143. C283 Safety system

**C283A0 Critical error**

**EXPLANATION**

A critical error occurred in the safety system

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C283A1 Robot is not braking when in Stop Mode**

**C283A2 Robot is moving when in Stop Mode**

**C283A3 Power not removed from the motors while in Emergency Stop**

**C283A4 Failed to power on the Robot Arm**

**C283A5 Invalid pin-configuration received: {hex}**

**C283A6 Trying to reassign pin configuration with configuration {hex}**

**C283A7 {unsigned} joint exceeded the speed limit of the safety settings**

#### SUGGESTION

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

### **C283A8 The System Emergency Stop Output is not active**

#### EXPLANATION

Failed to activate the System Emergency Stop Output. The output is active when voltage is low

#### SUGGESTION

Make sure output is not short circuited to a power supply

### **C283A9 System Emergency Stop Output disagreement within the safety system**

#### EXPLANATION

The input signals are not switching simultaneously, or are incorrectly connected.

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Ensure both inputs are properly connected

### **C283A10 Robot Emergency Stop Input disagreement within the safety system**

#### EXPLANATION

The input signals are not switching simultaneously, or are incorrectly connected.

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Ensure both inputs are properly connected

### **C283A11 System Emergency Stop Input disagreement within the safety system**

#### EXPLANATION

The input signals are not switching simultaneously, or are incorrectly connected.

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Ensure both inputs are properly connected

### **C283A12 Safeguard Stop Input disagreement within the safety system**

#### EXPLANATION

The input signals are not switching simultaneously, or are incorrectly connected.

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Ensure both inputs are properly connected

### **C283A13 Safeguard Reset Input disagreement within the safety system**

#### EXPLANATION

The input signals are not switching simultaneously, or are incorrectly connected.

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Ensure both inputs are properly connected

### **C283A14 Operation Mode input disagreement within the safety system.**

#### EXPLANATION

The input signals are not switching simultaneously, or are incorrectly connected.

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Ensure both inputs are properly connected

### **C283A15 Three-Positional Enabling Device Input disagreement within the safety system**

#### EXPLANATION

The input signals are not switching simultaneously, or are incorrectly connected.

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Ensure both inputs are properly connected

**C283A16 Operation Mode Switch is defined and no Three-Positional Device is defined.****EXPLANATION**

Operation mode switch can only be enabled if a Three-Positional Device is present

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Ensure that a Three-Positional Device is enabled in the Safety Configuration (B) Conduct a complete rebooting sequence, (C) Update software, (D) Contact your local Universal Robots service provider for assistance

**C283A17 Lost {unsigned} Teach Pendant safety packages in a row****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Check that the teach pendant is properly connected, (B) Conduct a complete rebooting sequence, (C) Update software

**C283A18 Lost too many Joint safety packages in a row. Diagnostic data: {unsigned}****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Check that the teach pendant is properly connected, (B) Conduct a complete rebooting sequence, (C) Update software

**C283A19 Incorrect gravity vector sent from the controller****C283A20 Wrong payload mass sent from the controller****C283A21 Wrong payload center of gravity sent from the controller****C283A22 Teach Pendant is connected while it is disabled in robot configuration****EXPLANATION**

If the Teach Pendant is enabled, it is connected. If it is disabled, it is not connected.

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Disconnect the Teach Pendant or enable it in the configuration.

**C283A23 Lost {unsigned} safety packages in a row from other safety processor****C283A24 Got {unsigned} safety packages too early in a row from other safety processor****C283A25 Got a ready message from an unexpected source: {hex}****C283A26 Force limitation: A joint exceeded the torque window by {float}Nm****EXPLANATION**

If the target trajectory is very jerky, e.g. in case of sensor based control with path\_offset() or servoj(), the target joint torques can exceed safety system limits. Noisy sensors or communication jitter in external control can cause jerky trajectories

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Check that the target trajectory is smooth, (B) Conduct a complete rebooting sequence, (C) Update software.

**C283A27 Mismatch on Robot Configuration CRC between the safety system and PolyScope****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software



## **C283A28 Mismatch on User Configuration CRC between the safety system and PolyScope**

### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Make new installation, (C) Update software,

## **C283A29 Trying to reapply the {unsigned} part of the User Configuraton.**

## **C283A30 Trying to reapply the {unsigned} part of the Robot Configuraton,**

## **C283A31 Trying to reapply normal limits, part {unsigned}**

## **C283A32 Trying to reapply reduced limits, part {unsigned}**

## **C283A33 Trying to reapply safety CRC**

## **C283A34 Error while trying to apply safety configuration**

### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

## **C283A35 Reduced Mode Output disagreement within the safety system**

### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

## **C283A36 Not Reduced Mode Output disagreement within the safety system**

### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

## **C283A37 Robot Moving Output disagreement within the safety system**

### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

## **C283A38 Robot Not Stopping Output disagreement within the safety system**

### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

## **C283A39 {unsigned} safety packages were received too late from the SCB processor**

## **C283A40 Reduced Mode Input disagreement within the safety systems**

### **EXPLANATION**

The input signals are not switching simultaneously, or are incorrectly connected.

### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Ensure both inputs are correctly connected

## **C283A41 TCP Velocity violates limits of maximum stopping time**

### **SUGGESTION**

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

## **C283A42 TCP Velocity violates limits of maximum stopping distance**

**SUGGESTION**

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

**C283A43 {unsigned} joint moved too quickly toward a Joint position limit****SUGGESTION**

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

**C283A44 The tool moved too fast towards an orientation limit****SUGGESTION**

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

**C283A45 The Elbow moved too fast towards a safety plane****SUGGESTION**

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

**C283A46 The tool moved too fast towards a safety plane****SUGGESTION**

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

**C283A47 {unsigned} joint position limit exceeded****SUGGESTION**

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

**C283A48 Tool position limit exceeded****SUGGESTION**

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

**C283A49 Tool orientation limit exceeded****SUGGESTION**

Try each of the following actions (in order) to see which resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

**C283A50 Elbow position limit exceeded****SUGGESTION**

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings



### **C283A51 Robot moved with a speed of {float} mm/s at the tool. This exceeds the tool speed limit in the safety settings**

#### **SUGGESTION**

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

### **C283A52 Robot moved with a speed of {float} mm/s at the elbow. This exceeds the elbow speed limit in the safety settings**

#### **SUGGESTION**

Try each of the following actions (in order) to see if it resolves the issue: (A) Ensure the mounted payload and center of gravity matches your installation settings, (B) Slow down movements. You can exceed speed limits if you move the robot too fast in Freedrive, in that case, move the robot slower, (C) Check safety settings

### **C283A53 Maximum Tool Center Point Speed in Reduced Mode is invalid**

#### **SUGGESTION**

Ensure the Reduced Mode Limit is less than or equal to the Normal Mode limit.

### **C283A54 Maximum Elbow Speed in Reduced Mode is invalid**

#### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Ensure the Reduced Mode limit is less than or equal to the Normal Mode Limit, (B) Update software.

### **C283A55 Maximum Joint Speed of joint {unsigned} in Reduced Mode is invalid**

#### **SUGGESTION**

Ensure the Reduced Mode Limit is less than or equal to the Normal Mode Limit.

### **C283A56 Maximum Momentum in Reduced Mode is invalid**

#### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Ensure the Reduced Mode limit is less than or equal to the Normal Mode Limit, (B) Update software.

### **C283A57 Maximum stopping time in Reduced Mode is invalid**

#### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Ensure the Reduced Mode limit is less than or equal to the Normal Mode Limit, (B) Update software.

### **C283A58 Maximum stopping distance in Reduced Mode is invalid**

#### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Ensure the Reduced Mode limit is less than or equal to the Normal Mode Limit, (B) Update software.

### **C283A59 Reduced Mode Output is not active**

#### **EXPLANATION**

Failed to activate the Reduced Mode Output. The output is active when voltage is low

#### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Make sure output is not short circuited to a power supply, (B) Update software.

### **C283A60 Reduced Mode Output is not inactive**

#### **EXPLANATION**

Failed to deactivate the Reduced Mode Output. The output is inactive when voltage is high

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Make sure output is not short circuited to ground, (B) Update software.

**C283A61 Not Reduced Mode Output is not active****EXPLANATION**

Failed to activate the Not Reduced Mode Output. The output is active when voltage is low

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Make sure output is not short circuited to a power supply, (B) Update software.

**C283A62 Not Reduced Mode Output is not inactive****EXPLANATION**

Failed to deactivate the Not Reduced Mode Output. The output is inactive when voltage is high

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Make sure output is not short circuited to ground, (B) Update software.

**C283A63 Robot is moving while Robot Moving Output is not active****EXPLANATION**

Failed to activate the Robot Moving Output. The output is active when voltage is low

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Make sure output is not short circuited to a power supply, (B) Update software.

**C283A64 Tool Direction Vector Length for Normal Mode is {float}, not 1.0****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Reconfigure Tool orientation, (B) Update software.

**C283A65 Tool Direction Vector Length for Reduced Mode is {float}, not 1.0****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Reconfigure Tool orientation, (B) Update software.

**C283A66 Robot Momentum reached {float} kg \* m/s, which exceeds the Momentum limit****C283A67 Robot Power reached {float} W, which exceeds the Power limit****C283A68 Error caused by the {unsigned} Joint****EXPLANATION**

A critical safety error

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C283A69 Float value: {float}****C283A70 Unsigned value: {unsigned}****C283A71 Safety is disabled but the app type is not MAIN-NS (No Safety)****EXPLANATION**

It's only allowed to have Safety disabled if the app type is MAIN-NS (No Safety) (0x07)

**C283A72 The motor configuration sent by the Control Box is invalid**

**EXPLANATION**

The motor configuration sent is unusable with this firmware revision.

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C283A73 Safe Home Position Output disagreement within the safety system****C283A74 The Safe Home Position Output is active while not allowed****EXPLANATION**

The Safe Home Position Output is active while the robot is not in Safe Home Position

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Make sure output is not short circuited to power supply or ground, (B) Update software.

**C283A75 The user config versions received differ****C283A76 Controller reported a fault****EXPLANATION**

The Controller has faulted and requested the safety system to fault

**C283A77 The user config versions is higher than supported****C283A78 The user config versions is lower than supported****C283A79 Safe home position index: {unsigned} out of range****C283A80 Force limit calculation got an unsupported joint size {unsigned}****C283A81 The robot configuration specifies an unsupported joint size {signed}****EXPLANATION**

The safety system is not certified to work with the specified joint size

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Update software.

**C283A82 The connected Teach Pendant type does not match the configuration****EXPLANATION**

The connected Teach Pendant is not the same type as the one selected in the safety configuration

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Check that the Teach Pendant is properly connected and matches the one in the safety configuration, (B) Conduct a complete rebooting sequence, (C) Update the software.

**C283A83 The configured Teach Pendant has no Three-Positional Enabling Device****EXPLANATION**

The safety configuration enables the Teach Pendant's Three-Positional Enabling Device, but the configured Teach Pendant does not have a Three-Positional Enabling Device

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Check that the correct Teach Pendant is selected in the safety configuration, (B) Conduct a complete rebooting sequence, (C) Update the software.

**C283A84 Received an invalid Teach Pendant type in the user configuration: {unsigned}****C283A85 Automatic Safeguard Stop Input disagreement within the safety system****EXPLANATION**

The input signals are not switching simultaneously, or are incorrectly connected.

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Ensure both inputs are properly connected

**C283A86 Automatic Safeguard Reset Input disagreement within the safety system****EXPLANATION**

The input signals are not switching simultaneously, or are incorrectly connected.

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Ensure both inputs are properly connected.

**C283A87 Injection-Molding-Machine-Interface is connected while it is disabled in the robot configuration****EXPLANATION**

If the Injection-Molding-Machine-Interface is enabled, it must be connected. If it is disabled, it must be disconnected.

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Disconnect the Injection-Molding-Machine-Interface or enable it in the configuration.

**C283A88 Lost {unsigned} Injection-Molding-Machine-Interface safety packages in a row****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Check that the Injection-Molding-Machine-Interface is properly connected, (B) Conduct a complete rebooting sequence, (C) Update software.

**C283A89 The connected Injection-Molding-Machine-Interface type does not match the configuration****EXPLANATION**

The connected Injection-Molding-Machine-Interface is not the same type as the one selected in the safety configuration

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Check that the Injection-Molding-Machine-Interface is properly connected and matches the one in the safety configuration, (B) Conduct a complete rebooting sequence, (C) Update the software.

**C283A90 Invalid Injection-Molding-Machine-Interface type in the user configuration: {unsigned}****EXPLANATION**

The configuration provided by the user safety configuration is invalid

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Ensure the correct IMMI type is selected in the Safety Configuration (B) Conduct a complete rebooting sequence, (C) Update software.

**C283A91 The Injection-Molding-Machine-Interface System Emergency Stop Output is not active****EXPLANATION**

Failed to activate the System Emergency Stop Output on the Injection-Molding-Machine-Interface. The output is active when voltage is high

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Make sure output is not short circuited to ground (B) Conduct a complete rebooting sequence, (C) Update software.

**C283A92 Target torque of {float} is outside the allowed range**

**EXPLANATION**

The target torque received from the controller is outside the allowed range

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C283A93 Sanity check of target torque differs by {float}, which is outside the allowed range****EXPLANATION**

The target torque received from the controller is outside the allowed range

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C283A94 Automatic Safeguard Stop input is configured but no Three-Position Enabling device is configured****SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Ensure that a Three-Positional Device is enabled in the Safety Configuration (B) Conduct a complete rebooting sequence, (C) Update software, (D) Contact your local Universal Robots service provider for assistance

**C283A95 IO Data has not been updated before latching it****C283A96 Received an invalid IMMI type in the user configuration: {unsigned}****C283A97 The payload inertia diagonal sent from the controller must be non-negative****C283A98 The payload inertia sent from the controller must be within valid range****C283A99 Received an invalid value {float} as part of the runtime safety configuration****SUGGESTION**

Try the following actions to see if resolve the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C283A100 Multiple sources defined for controlling operational mode****SUGGESTION**

Try the following actions to see if it resolve the issue: (A) Make sure there are not set multiple sources in the Safety Config controlling the operational mode, (B) Update Software.

**C283A101 The PROFISafe System Emergency Stop Output is not active****EXPLANATION**

Failed to activate the PROFISafe System Emergency Stop Output.

**SUGGESTION**

Try the following actions to see if it resolve the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C283A102 Profisafe Reduced Mode Output is not active****EXPLANATION**

Failed to activate the PROFISafe Reduced Mode Output.

**SUGGESTION**

Try the following actions to see if it resolve the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C283A103 Profisafe Reduced Mode Output is not inactive**

**EXPLANATION**

Failed to deactivate the PROFISafe Reduced Mode Output.

**SUGGESTION**

Try the following actions to see if it resolve the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C283A104 Robot is moving while PROFISafe Robot Moving Output is not active****EXPLANATION**

Failed to activate the PROFISafe Robot Moving Output.

**SUGGESTION**

Try the following actions to see if it resolve the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C283A105 The Profisafe Safe Home Position Output is active while not allowed****EXPLANATION**

The PROFISafe Safe Home Position Output is active while the robot is not in Safe Home Position

**SUGGESTION**

Try the following actions to see if it resolve the issue: (A) Conduct a complete rebooting sequence, (B) Update software.

**C283A106 The PROFISafe Safeguard Stop Output is active while not allowed****EXPLANATION**

The PROFISafe Safeguard Stop Output is active while the robot is not in safeguard stop

**SUGGESTION**

Try the following actions to see if it resolve the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C283A107 The PROFISafe Safeguard Stop Output is inactive while not allowed****EXPLANATION**

The PROFISafe Safeguard Stop Output is inactive while the robot is in safeguard stop

**SUGGESTION**

Try the following actions to see if it resolve the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C283A108 Unknown input disagreement, value is {unsigned}****C283A109 Unknown output disagreement, value is {unsigned}**

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.144. C284 Brake Release

**C284A0 Critical error****EXPLANATION**

A critical error occurred during Brake Release

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure the mounted payload, TCP, and CoG matches your configuration

**C284A1 Brake release procedure aborted.****C284A2 Microprocessor B wasn't ready.**



**C284A3** Absolute position unknown, after successful completion of the find absolute position movement.

**C284A4** The motor did not move enough, during the find absolute position movement.

**C284A5** After successfully completing the free pin move the rotor was still not within the required window.

**C284A6** The motor was unable to move far enough during the free pin movement.

**C284A7** Peak speed of {float} rad/s was detected during enabling of motor control.

**C284A8** Speed was larger than 0.1 rad/s for more than 50ms, during enabling of motor control.

**C284A9** Motor control was not successfully started, due to lacking commutation offset calibration.

**C284A10** Absolute position was not known before attempting to release the brake pin.

**C284A11** Motor was not within the free pin window after enabling of control.

**C284A12** Brake release commutation was started while motor control was running.

**C284A13** Pin collision detected, during brake release move.

**C284A14** Brake release commutation did not move far enough.

**C284A15** Unhandled state.

**C284A16** Solenoid boost too long.

**C284A17** Started boosting the solenoid too early after last boost.

**C284A18** Absolute Motor Encoder position unknown after the Brake Release movement

#### EXPLANATION

Not enough Index Marks detected to determine absolute Motor Encoder position offset.

#### SUGGESTION

**C284A19** Brake release procedure took too long.

**C284A20** Commutation angle or absolute position was unknown, but is required.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.145. C285 Joint Keep-Alive System

### **C285A0** Critical error

#### EXPLANATION

A critical error occurred in the Joint Keep-Alive System

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C285A1** Joint Keep-Alive System message with wrong sequence received from SCB-uPA.



**C285A2 Timeout reached while waiting for a Joint Keep-Alive System message from SCB-uPA.**

**C285A3 Go-to-Fault command received a Joint Keep-Alive System message from SCB-uPA.**

**C285A4 A Joint Keep-Alive System message with wrong sequence received from SCB-uPB.**

**C285A5 Timeout reached while waiting for Joint Keep-Alive System message from SCB-uPB.**

**C285A6 Go-to-Fault command received in Joint Keep-Alive System message from SCB-uPB.**

**C285A7 Joint Keep-Alive System message received from an unauthorized source: {unsigned}**

**C285A8 uPA handler received an invalid value**

**C285A9 uPB handler received an invalid value**

**C285A10 Lost {unsigned} Keep-Alive System message(s) in a row from Safety Control Board-uPA**

**EXPLANATION**

An invalid amount of Keep-Alive System messages have been lost from the Safety Control Board Processor A

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C285A11 Lost {unsigned} Keep-Alive System message(s) in a row from Safety Control Board-uPB**

**EXPLANATION**

A invalid amount of Keep-Alive messages have been lost from the Safety Control Board Processor B

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C285A12 Go-to-Violation command received in Joint Keep-Alive System message from SCB-uPA.**

**C285A13 Go-to-Violation command received in Joint Keep-Alive System message from SCB-uPB.**

**C285A14 Invalid command received in Joint Keep-Alive System message from SCB-uPA.**

**C285A15 Invalid command received in Joint Keep-Alive System message from SCB-uPB.**

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.146. C286 Motor Controller

**C286A1 ME Index seen, commutation-zero set to: {float\_5\_5}**

**C286A2 PWM margin too small, ticks left: {signed}**



If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.147. C287 Saved files

### **C287A0 Critical error**

#### EXPLANATION

A critical error occurred during file loading/saving

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

### **C287A1 The file requested (id {unsigned}) is not saved or its loading failed**

### **C287A2 Re-sending a part of the file with ID {unsigned}, due to a missing ACK**

### **C287A3 Maximum re-sending tries ({unsigned}) reached**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.148. C288 IO control

### **C288A1 Wrong control mode**

### **C288A2 Wrong channel chosen**

### **C288A3 The pin is not configured as analog**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.149. C289 Tool Connector

### **C289A1 Short circuit detected on Digital Output: {unsigned} high side**

#### EXPLANATION

Tool Digital Output pin has been turned off due to either a short-circuit or an overload was detected.

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Update software, (B) Check connections to make sure Tool Digital Output currents are within specified limits.

### **C289A2 Short circuit detected on Digital Output: {unsigned} low side**

#### EXPLANATION

Tool Digital Output pin has been turned off due to either a short-circuit or an overload was detected.

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Update software, (B) Check connections to make sure Tool Digital Output currents are within specified limits.

### **C289A4 10 second Average tool IO Current of {float} A is outside of the allowed range.**

#### EXPLANATION

The average current sum of the Tool Connector Power and Digital Output pins is outside of the allowed range.

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Update software, (B) Check connections to make sure Tool Digital Output currents are within specified limits.

**C289A5 Unable to remove tool Digital Output fault.****EXPLANATION**

Unable to remove the overload on tool Digital Output, therefore the robot powered down.

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Update software, (B) Check connections to make sure Tool Digital Output currents are within specified limits.

**C289A6 Current of {float} A on the tool connector supply pins is outside of the allowed range.****EXPLANATION**

Too high current on tool connector supply pins

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Update software, (B) Check connections to make sure Tool Digital Output currents are within specified limits..

**C289A7 Current of {float} A on the Digital Output pins is outside of the allowed range.****EXPLANATION**

Too high current on tool connector Digital Output pins.

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Update software, (B) Check connections to make sure Tool Digital Output currents are within specified limits.

**C289A8 Current of {float} A on the ground pin is outside of the allowed range.****EXPLANATION**

Too high current on tool ground pin

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Update software, (B) Check connections to make sure Tool Digital Output currents are within specified limits.

**C289A9 Current of {float} A on the POWER pin is outside of the allowed range.****EXPLANATION**

Too high current on tool power pin

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Update software, (B) Check connections to make sure Tool Digital Output currents are within specified limits.

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.150. C290 I2C

**C290A1 The I2C bus was busy too long****C290A2 Function called too early after last call or the slave chip did not answer****C290A3 A peripheral unit has set the alert pin****C290A4 Communication timeout detected****C290A6 An error was detected in the i2c acknowledge handshake**

**C290A7 I2C detected arbitration loss**

**C290A8 I2C detected error on the I2C-bus**

**C290A9 I2C error interrupt called with unhandled error-flag**

**C290A10 I2C peripheral issue, unhandled events: {hex}**

**EXPLANATION**

the hexadecimal number is an event code generated by integration of the two status registers

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.151. C291 EEPROM

**C291A1 Addressed data is out of memory bounds**

**C291A2 I2C communication error**

**C291A3 Write to EEPROM failed**

**C291A4 Read from EEPROM failed**

**C291A5 Verification of written data failed**

**C291A6 Difference in data when comparing the source and the data written**

**C291A7 Writing of a page in EEPROM failed**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.152. C292 Online RAM test

**C292A0 Critical error**

**EXPLANATION**

A critical error occurred during RAM test

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C292A1 Uninitialized return value, internal error**

**C292A2 Databus test failure**

**C292A3 Address bus stuck high**

**C292A4 Address bus stuck low**

**C292A5 Address bus shorted**

**C292A6 Memory cell test case 1 failed**

**C292A7 Memory cell test case 2 failed**

**C292A8 Memory cell test case 3 failed**

**C292A9 Incorrect test type on DMA test**

**C292A10 Runtime RAM test round period too long**



C292A11 Tested data/address: {hex}  
C292A12 Unexpected test state: {unsigned}  
C292A13 Not tested DMA buffers: {hex}  
C292A14 Wrong DMA buffer pointer: {hex}  
C292A15 RAM test error reported at line code: {unsigned}

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.153. C293 Exception

C293A1 Unexpected exception/interrupt: {unsigned}  
C293A2 HardFault exception status: {hex}  
C293A3 HardFault Stack Pointer (SP): {hex}  
C293A4 HardFault Link Register (LR): {hex}  
C293A5 HardFault Program Counter (PC): {hex}  
C293A6 HardFault Program Status Register (PSR): {hex}  
C293A7 HardFault R0 register: {hex}  
C293A8 HardFault R1 register: {hex}  
C293A9 HardFault R2 register: {hex}  
C293A10 HardFault R3 register: {hex}  
C293A11 HardFault R12 register: {hex}  
C293A12 MemManage exception status: {hex}  
C293A13 MemManage exception address: {hex}  
C293A14 BusFault exception status: {hex}  
C293A15 BusFault exception address: {hex}  
C293A16 UsageFault exception status: {hex}  
C293A17 Tool exception status: {hex}  
C293A18 Tool exception address 1: {hex}  
C293A19 Tool exception address 2: {hex}  
C293A20 HardFault CFSR register: {hex}  
C293A21 HardFault BFAR register: {hex}  
C293A22 HardFault MMFAR register: {hex}  
C293A23 HardFault HFSR register: {hex}  
C293A24 HardFault SHCSR register: {hex}  
C293A25 HardFault ICSR register: {hex}  
C293A26 HardFault exception caught  
C293A27 MemManage exception caught

### **C293A28 BusFault exception caught**

### **C293A29 UsageFault exception caught**

### **C293A30 Additional data: {hex}**

#### **EXPLANATION**

Additional data from Main app, version and application specific.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## **1.154. C294 ADC**

### **C294A0 Critical error**

#### **EXPLANATION**

A critical error occurred in the ADC driver

#### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

### **C294A1 ADC0 triggered before finishing previous conversion**

### **C294A2 ADC1 triggered before finishing previous conversion**

### **C294A4 ADC driver called with an invalid ADC pointer**

#### **EXPLANATION**

ADC initialization has failed

### **C294A5 ADC initialization has failed to get a fresh memory block**

#### **EXPLANATION**

ADC initialization has failed

### **C294A6 ADC initialization has failed: {unsigned}**

#### **EXPLANATION**

ADC initialization has failed

### **C294A7 ADC channel {unsigned} sampled an out of range value**

### **C294A8 ADC sample ({hex}) out of range**

### **C294A9 The value was sampled {float}ms ago**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## **1.155. C295 PCB**

### **C295A0 Wrong PCB type ({hex})**

#### **EXPLANATION**

The printed circuit board is defective

#### **SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software



If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.156. C296 Start up check

### **C296A0 Critical error**

#### EXPLANATION

A critical error occurred during startup

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

### **C296A1 SCB IO failed to power on**

#### SUGGESTION

Ensure the IO Power Connector on the Safety Control Board is connected to the 24VDC

### **C296A2 One or more Motor phases is short circuited to ground. Diagnostic data: {hex}**

#### EXPLANATION

Bit 0 high indicates short circuit

#### SUGGESTION

### **C296A3 Motor Indication Signal does not work. Diagnostic data: {hex}**

#### EXPLANATION

Bit 1 low indicates that the diagnostics feature is broken

#### SUGGESTION

### **C296A4 Phase 1 is not connected. Diagnostic data: {hex}**

#### EXPLANATION

Bit pattern 0b0110 indicates that phase 1 is not connected

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Make sure all Motor phases are connected correctly, (B) Update software

### **C296A5 Phase 2 is not connected. Diagnostic data: {hex}**

#### EXPLANATION

Bit pattern 0b1010 indicates that phase 2 is not connected

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Make sure all Motor phases are connected correctly, (B) Update software

### **C296A6 Phase 3 is not connected. Diagnostic data: {hex}**

#### EXPLANATION

Bit pattern 0b0010 indicates that phase 3 is not connected

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Make sure all Motor phases are connected correctly, (B) Update software

### **C296A7 Motor test results were invalid. Diagnostic data: {hex}**

#### EXPLANATION

Bit0 high indicates short circuit. Bit1 is phase 3 test. Bit2 is phase 2 test. Bit3 is phase 1 test

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Make sure all Motor phases are connected correctly, (B) Update software

### **C296A8 Motor PWM output is not zero in Joint State {unsigned}**

#### EXPLANATION

No PWM signals are expected to be active in the current Joint State.

#### SUGGESTION

### **C296A9 Robot Voltage was present during self-diagnostics**

#### EXPLANATION

Robot Voltage rose above acceptable levels before both processors powered it on

#### SUGGESTION

### **C296A10 Time out during self-diagnostics**

#### EXPLANATION

A processor timed out while waiting for the other processor to finish self-diagnostics

#### SUGGESTION

### **C296A11 Data was received while trying to disable communication**

#### EXPLANATION

A validation that theof communication could be suppressioned failed to preventin preventing a message from passing through.

#### SUGGESTION

### **C296A12 Sequence number did not match expected sequence**

#### EXPLANATION

After communication was disabled and reenabled the sequence number did not match what was expected

#### SUGGESTION

### **C296A13 The expected sequence number was {unsigned}**

#### EXPLANATION

After communication was disabled and reenabled the sequence number did not match what was expected

### **C296A14 The actual sequence number was {unsigned}**

#### EXPLANATION

After communication was disabled and reenabled the sequence number did not match what was expected

#### SUGGESTION

### **C296A15 Interval between messages did not match expectations**

#### EXPLANATION

After communication was disabled and reenabled the message interval did not match what expectations

### **C296A16 The expected interval was {unsigned} ticks**





EXPLANATION

After communication was disabled and reenabled the message interval did not match what was expected

SUGGESTION

**C296A17 The measured interval was {unsigned} ticks**

EXPLANATION

After communication was disabled and reenabled the message interval did not match what was expected

SUGGESTION

**C296A18 Motor Kt value {float} is outside manufacturer specifications**

EXPLANATION

Calibrated motor parameter Kt (torque sensitivity) falls outside manufacturer rated values

SUGGESTION

**C296A19 Motor Kb value {float} is outside manufacturer specifications**

EXPLANATION

Calibrated motor parameter Kb (back EMF constant) falls outside manufacturer rated values

**C296A20 Motor R value {float} is outside manufacturer specifications**

EXPLANATION

Calibrated motor parameter R (phase-phase resistance) falls outside manufacturer rated values

SUGGESTION

**C296A21 Motor L value {float} is outside manufacturer specifications**

EXPLANATION

Calibrated motor parameter L (phase-phase inductance) falls outside manufacturer rated values

SUGGESTION

**C296A22 Processor uB has been in Booting state for too long**

EXPLANATION

**C296A23 Cross-monitoring data was invalid for too long while booting**

EXPLANATION

uB timed out while waiting for cross-monitoring data to agree before changing from Booting to Idle state

**C296A24 Motor Tau value {float} is outside manufacturer specifications**

EXPLANATION

Calibrated motor parameter Tau (phase-phase time constant) falls outside manufacturer rated values

SUGGESTION

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.157. C297 Joint validation



## C297A0 Critical error

### EXPLANATION

A critical error occurred during Joint validation

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check that SD card and robot type match, (C) Update software

## C297A1 Received Node ID from an unexpected device ({unsigned})

### EXPLANATION

The Safety Control Board received a message from a device other than A or B

### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure that the robot configuration is correct, (C) Update software

## C297A2 Received Node ID an unexpected node ({unsigned})

### EXPLANATION

The Safety Control Board received a message from a node outside the expected range of Node IDs.

### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure that the robot configuration is correct, (C) Update software

## C297A3 Joint processors disagree on Joint Size ({hex})

### EXPLANATION

There is a mismatch between the Joint Size reported from A and B. byte0: A, byte1: B

### SUGGESTION

## C297A4 Joints disagree with configuration on Joint Size ({hex})

### EXPLANATION

There is a mismatch between the Joint Size and the configuration, byte0: Joint, byte1: Configuration

### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure that the robot configuration is correct, (C) Update software

## C297A5 Found ({unsigned}) Joint disabled in configuration

### EXPLANATION

There is a mismatch between joints attached and the configuration

### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure that the robot configuration is correct, (C) Update software

## C297A6 Joint processors disagree on Joint ID. Diagnostic data: {hex}

### EXPLANATION

There is a mismatch between reported Node ID from A and B, byte0: A, byte1: B

### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Run Joint ID assignment, (C) Update software.

## C297A7 Node ID differs from the stored ID. Diagnostic data: {hex}

### EXPLANATION

There is a mismatch between current Node ID and the expected ID, byte0: Current, byte1: Stored

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Run Joint ID assignment, (C) Update software

**C297A8 Invalid robot configuration****EXPLANATION**

The robot does not match Robot Configuration

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure that the robot configuration is correct, (C) Update software

**C297A9 Joint IDs need updating****EXPLANATION**

The stored Node ID differs from the current ID on one or more joints and needs to be updated

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Run Joint ID assignment, (C) Update software

**C297A10 Timeout while waiting for Node IDs****EXPLANATION**

One or more of the configured devices are not responding with Node IDs

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Ensure that the robot configuration is correct, (C) Update software

**C297A11 The Robot arm does not match the Control Box****EXPLANATION**

One or more joints do not match stored Robot Configuration

**SUGGESTION**

Try the following actions to see if it resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check that SD card and robot type match, (C) Update software

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.158. C298 Hand protection

**C298A0 Tool is too close to the lower arm: {float\_2\_4} meter.****EXPLANATION**

The tool is too close to the lower Robot arm

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check wrist position, (B) Verify mounting, (C) Conduct a complete rebooting sequence, (D) Update software

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket

## 1.159. C299 Tool communication

## C299A0 Communication error detected

### EXPLANATION

A problem with the Tool communication was detected.

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

## C299A1 TX buffer overflow

### EXPLANATION

The output buffer of the tool has overflown

### SUGGESTION

## C299A2 New message started unexpectedly

### EXPLANATION

A new message started before all data from previous message was received

### SUGGESTION

## C299A3 RX framing error

### EXPLANATION

Framing error detected on received data

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check external equipment connection, (B) Verify the communication configuration matches the hardware, (C) Conduct a complete rebooting sequence, (D) Update software

## C299A4 RX Parity error

### EXPLANATION

Parity error detected on received data

### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check external equipment connection, (B) Verify the communication configuration matches the hardware, (C) Conduct a complete rebooting sequence, (D) Update software

## C299A5 RX buffer overflow.

### EXPLANATION

The input buffer has overflown

### SUGGESTION

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket

## 1.160. C300 Safety message

**C300A1 Safety message received from an unexpected node. Diagnostic data: {unsigned}**

**C300A2 Safety message response received with an unexpected sequence number. Diagnostic data: {unsigned}**



---

## C300A3 Duplicate safety message response received with sequence number. Diagnostic data: {unsigned}

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket

## 1.161. C301 Safety message monitor

### C301A0 Critical error

#### EXPLANATION

A critical error occurred in safety message monitoring

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

### C301A2 Mode data mismatch

### C301A3 Position data mismatch

### C301A4 Revolution data mismatch

### C301A5 Temperature data mismatch

### C301A6 Torque data mismatch

### C301A7 Velocity data mismatch

### C301A8 Input state data disagreement: {unsigned}

#### EXPLANATION

Data bit 0-7 is xmon values. Data bit 8-15 is safety data values

### C301A10 Safety monitor: Don't have the corresponding x-mon data

### C301A12 Target current data mismatch

### C301A14 Target Velocity data mismatch

### C301A15 Target Acceleration data mismatch

### C301A16 Issue with setting up the UART mon RX address in TP

### C301A17 Issue with setting up the UART mon RX CITER register in TP

### C301A18 Issue with setting up the UART mon RX BITER register in TP

### C301A19 Issue with setting up the MK02 UART TX, address is incorrect

### C301A20 Issue with setting up the MK02 UART TX, CITER REG is incorrect

### C301A21 Issue with setting up the MK02 UART TX, BITER REG is incorrect

### C301A25 Node {unsigned} uA's communication to SCB disabled

### C301A26 Motor parameter (R\_pp) data mismatch

### C301A27 Motor parameter (L\_pp) data mismatch

### C301A28 Motor parameter (Kb) data mismatch

### C301A29 Motor parameter (Kt) data mismatch

### C301A30 Motor parameter (T) data mismatch

### C301A31 Safety Message was not received in the last {unsigned} milliseconds

- C301A32 Function indicating if we should monitor data is not configured
- C301A33 Function to parse messages is not configured
- C301A34 Function to handle messages is not configured
- C301A35 Function to handle disable communication requests is not configured
- C301A36 IMMI Safety IO estop input mismatch
- C301A37 IMMI Safety IO estop output mismatch
- C301A38 IMMI Safety IO safeguard input mismatch
- C301A39 Target torque data mismatch
- C301A40 compensation current mismatch

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket

## 1.162. C302 Tool Configuration

### C302A1 Invalid Robot Type {unsigned}

#### EXPLANATION

The tool received an invalid robot type

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (C) Update software

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket

## 1.163. C303 System status

### C303A0 Critical error

#### EXPLANATION

A critical system error occurred

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

### C303A1 Starting up

### C303A2 Shutting down

### C303A3 Reset caused by unknown reasons

### C303A4 Reset caused by power loss

### C303A5 Reset caused by window watchdog

### C303A6 Reset caused by independent watchdog

### C303A7 Reset caused by software

### C303A8 Reset caused by power on

### C303A9 Reset caused by reset pin



**C303A10 Reset caused by brown out**

**C303A11 Reset caused by a loss of lock in the PLL**

**C303A12 Reset caused by a loss of external clock.**

**C303A13 Reset caused by LLWU module wakeup source**

**C303A14 Reset caused by peripheral failure to acknowledge attempt to enter Stop Mode**

**C303A15 Reset caused by EzPort receiving the RESET command while the device is in EzPort mode**

**C303A16 Reset caused by host debugger system setting of the System Reset Request bit**

**C303A17 Reset caused by core LOCKUP event**

**C303A18 Reset caused by JTAG**

**C303A19 Unexpected core frequency configured: {unsigned}**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket

## 1.164. C304 Self monitoring

### **C304A0 Critical error**

#### EXPLANATION

A critical error occurred in physical, logical, and temporal monitoring (PLATM)

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C304A1 Temperature sensor failure (diff: {float} degC)**

**C304A2 Phase current sensor failure (diff: {float\_5\_3} A)**

**C304A3 Close to the gearbox shear limit. Encoders disagree {float} [rad] on the Joint position**

#### EXPLANATION

The Joint acceleration or deceleration is too high, or there is a mechanical problem in the gear related to encoder mounting.

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Reduce acceleration in the user program, (B) Conduct a complete rebooting sequence, (C) Update software, (D) Replace Joint if necessary

**C304A4 Either the encoder was inappropriately mounted, or the gearbox is loose or broken. Difference between the encoders is {float} [rad].**

#### EXPLANATION

Mechanical problem in gear related to encoder mounting.

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Reduce acceleration in the user program, (B) Check TCP, Payload, and Cog, (C) Conduct a complete rebooting sequence, (D) Update software, (E) Replace Joint if necessary

**C304A5 Disagreement on cross-monitored data**

### **C304A6 Motor phase {unsigned}'s resistance is too high.**

#### EXPLANATION

The lead/connector is broken, or the Motor phase lead has become disconnected or loose.

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket

## 1.165. C305 Robot Power Control

### **C305A0 Critical error**

#### EXPLANATION

A critical error in power control module, supply voltage is >50V

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software,

### **C305A1 Power supply voltage too low**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check for loose connections, (B) Conduct a complete rebooting sequence, (C) Update software,

### **C305A2 Robot cable not connected**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Make sure the cable between Control Box and Robot Arm is correctly connected and it has no damage, (B) Check for loose connections, (C) Conduct a complete rebooting sequence, (D) Update software,

### **C305A3 Short circuit in Robot detected or the wrong Robot is connected to the Control Box.**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check for loose connections, (B) Make sure the cable between Control Box and Robot Arm is correctly connected and it has no damage, (C) Conduct a complete rebooting sequence, (D) Update software,

### **C305A4 Robot voltage rising slower than expected**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Verify the power supply, (B) Verify Control Box and Robot Arm are correctly paired,

### **C305A5 Attempted to start Energy Eater with powered robot**

### **C305A6 Power supply voltage too high: {float} V**

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check for loose connections, (B) Make sure the cable between Control Box and Robot Arm is correctly connected and it has no damage, (C) Conduct a complete rebooting sequence, (D) Update software,

### **C305A7 Energy Eater was active when trying to turn on the Robot arm**

### **C305A8 The Robot Voltage is too high ({float})V when powering on the Robot**



**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software,

**C305A9 The Power State was not OFF ({unsigned}) when trying to power on the Robot****SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software,

**C305A10 The Delay Callback setup failed at the {unsigned} stage****C305A11 The power to the robot arm was not removed fast enough after violation**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.166. C306 Joint

**C306A0 Critical error****EXPLANATION**

A critical error occurred in a Joint

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C306A1 Not stopping fast enough****EXPLANATION**

Joint was unable to come to a full stop fast enough.

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Either an incorrect payload is mounted, or an external force is pushing the robot, (B) Conduct a complete rebooting sequence, (C) Update software

**C306A2 Velocity failed to pass sanity check****C306A3 Acceleration failed to pass sanity check****C306A4 Joint does not have a stored id****EXPLANATION**

Joint was unable to locate an assigned id, most likely because it has never been used in a robot.

**SUGGESTION**

New Joint ID assignment should happen automatically

**C306A5 Joint ID could not be stored****EXPLANATION**

Something went wrong while trying to store the Joint ID, new ID verification will be needed.

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C306A6 control-package sequence number mismatched with expected sequence number**



**C306A7 {unsigned} instances of mismatched control-package sequence numbers within last second**

**C306A8 Sanity check of control-package sequence numbers recovered after detecting {unsigned} bad sequence numbers**

**C306A9 Joint moved more than allowable limit**

EXPLANATION

Potential mechanical failure of the joint's brakes

SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C306A10 Current detected in motor exceeded limits, current was {float}A**

**C306A11 PWM duty cycle for motor phase A is {float}**

**C306A12 PWM duty cycle for motor phase B is {float}**

**C306A13 PWM duty cycle for motor phase C is {float}**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket

## 1.167. C307 Data B: {data}

EXPLANATION

Data dump from MCU B, argument indicates index of data.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.168. C308 Data A: {data}

EXPLANATION

Data dump from MCU A, argument indicates index of data.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.169. C309 Keep-Alive System

**C309A0 Critical error**

EXPLANATION

A critical error occurred in the Keep-Alive System

SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C309A1 Keep-Alive System message with wrong sequence received from SCB-uPA.**

**C309A2 Timeout reached while waiting for a Keep-Alive System message from SCB-uPA.**

**C309A3 Go-to-Fault command received a Keep-Alive System message from SCB-uPA.**



- C309A4 A Keep-Alive System message with wrong sequence received from SCB-uPB.  
C309A5 Timeout reached while waiting for Keep-Alive System message from SCB-uPB.  
C309A6 Go-to-Fault command received in Keep-Alive System message from SCB-uPB.  
C309A7 Keep-Alive System message received from an unauthorized source:  
{unsigned}  
C309A8 uPA handler received an invalid value  
C309A9 uPB handler received an invalid value  
C309A10 Lost {unsigned} Keep-Alive System message(s) in a row from Safety Control Board-uPA

EXPLANATION

An invalid amount of Keep-Alive System messages have been lost from the Safety Control Board Processor A

SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

- C309A11 Lost {unsigned} Keep-Alive System message(s) in a row from Safety Control Board-uPB

EXPLANATION

A invalid amount of Keep-Alive messages have been lost from the Safety Control Board Processor B

SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

- C309A12 Go-to-Violation command received in Keep-Alive System message from SCB-uPA.  
C309A13 Go-to-Violation command received in Keep-Alive System message from SCB-uPB.  
C309A14 Invalid command received in Keep-Alive System message from SCB-uPA.  
C309A15 Invalid command received in Keep-Alive System message from SCB-uPB.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.170. C311 Delay Callback

### C311A0 The timer is not available

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.171. C312 Data validation

### C312A0 Critical error

EXPLANATION

A critical error occurred during data validation

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for ESD noise, (C) Update software

**C312A1 Missed {unsigned} packages****C312A2 Unexpected sequence ({signed})****C312A3 {unsigned} failures in a row****C312A4 Received a package at an unexpected time****C312A5 Package had type {unsigned}**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.172. C313 App version

**C313A0 Build version is: {signed}****C313A1 Git sha is: {hex}****C313A2 CRC code is: {hex}****C313A3 Build major version is: {unsigned}****C313A4 Build minor version is: {unsigned}****C313A5 Build patch version is: {unsigned}**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.173. C314 SPI IO

**C314A0 Critical error****EXPLANATION**

A critical error occurred related to IO

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for IO connections, (C) Update software

**C314A1 Control bits read wrongly as: {hex}****C314A2 Output readback does not match the produced value: {hex}****EXPLANATION**

High 8 bit - set, low 8 bit - readback

**C314A3 Safeguard bit transition to low****C314A4 Emergency Stop bit transition to low****C314A5 Expected OSSD pulse were not detected on CO{unsigned}****EXPLANATION**

The generated OSSD pulses on the safety output were not seen during readback

**SUGGESTION**

Try any of the following actions to resolve the issue: (A) Verify safety output is not connected to any power supply or another safety output, (B) Update software

**C314A6 An unexpected OSSD pulse was detected on CO{unsigned}****EXPLANATION**

An OSSD pulse was detected on the safety output readback, but was not generated by the hardware

**SUGGESTION**

Try any of the following actions to resolve the issue: (A) Verify safety output is not connected to ground or another safety output, (B) Update software

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.174. C315 Watchdog

**C315A0 Self-test failed****EXPLANATION**

The system watchdog is not working as expected

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C315A1 Patrol post {unsigned}****C315A2 Checked in at {float\_1\_3} mS which is outside permitted window****C315A3 Checked in {unsigned} times which is outside permitted window****C315A4 Has not been checked in for {float\_1\_3} mS times which is outside permitted window****C315A5 There is no more space in the wdog keeper module.****EXPLANATION**

The number of allowed checkpoints has exceeded what is allowed

**SUGGESTION**

Configure the wdog keeper to allow more checkpoints if possible.

**C315A6 The wdog keeper is not initialized, trying to register a checkpoint.****EXPLANATION**

Trying to register, before the wdog keeper has been initialized.

**SUGGESTION**

Make sure the wdog keeper has been initialized, before registering.

**C315A7 The wdog keeper failed to initialize, already initialized.****EXPLANATION**

The watchdog keeper cannot be initialized multiple times.

**SUGGESTION**

Make sure not to initialize multiple times.

**C315A8 Program counter at time of reset: {hex}****EXPLANATION**

Program counter at watchdog reset.

---

## SUGGESTION

### **C315A9 Active watchpoint bitmask: {hex}**

#### EXPLANATION

Bitmask indicating if a watchpoint is active.

#### SUGGESTION

### **C315A10 ID {unsigned} failed to meet checkin requirements**

#### EXPLANATION

ID of watchpoint that failed validation.

#### SUGGESTION

### **C315A11 Additional data: {hex}**

#### EXPLANATION

Additional data from Main app, version and application specific.

### **C315A12 Last system state reported before watchdog reset {unsigned}**

#### EXPLANATION

System status at watchdog reset.

#### SUGGESTION

### **C315A13 Stack Pointer (SP): {hex}**

### **C315A14 Link Register (LR): {hex}**

### **C315A15 Program Counter (PC): {hex}**

### **C315A16 Status Register (PSR): {hex}**

### **C315A17 R0 register: {hex}**

### **C315A18 R1 register: {hex}**

### **C315A19 R2 register: {hex}**

### **C315A20 R3 register: {hex}**

### **C315A21 R12 register: {hex}**

### **C315A22 Number of checkins: {unsigned}**

### **C315A23 Time between last two checkins: {float} mS**

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.175. C316 MCU

### **C316A0 Unknown ID**

#### EXPLANATION

The Microcontroller Identifier does not match an expected value



SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C316A1 This version of the firmware is obsolete and needs to be updated**

EXPLANATION

The firmware in the robot is too old and needs to be updated

SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.176. C317 Failure injection

**C317A0 Injecting type {unsigned}**

EXPLANATION

Failure of the specified type has been injected to the system.

SUGGESTION

**C317A1 Missing handler for type {unsigned}**

EXPLANATION

There is no failure handler for the specified type.

SUGGESTION

**C317A2 Invalid data provided to type {unsigned}**

EXPLANATION

The data for the failure type is incorrect. The failure has not been injected.

SUGGESTION

**C317A3 Throw report**

EXPLANATION

The failure has been injected.

SUGGESTION

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.177. C318 Stack monitor

**C318A0 The stack level watermark at {unsigned}% is breached**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.178. C319 Filesys Diagnostic Tool

**C319A0 Read operation started, at start address {hex}**

**C319A1 Read operation was successfully completed**

**C319A2 Read operation failed, due to illegal address {hex}**

### EXPLANATION

This tool does not support reading out the requested address

**C319A3 Received data for unexpected address {hex}**

**C319A4 Expected address to be {hex}**

**C319A5 Erased sector at address {hex}**

**C319A6 Write operation was successfully completed**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.179. C320 REDnet BLVDS

**C320A0 Hub : Framing error on port: {signed}**

### EXPLANATION

A message with a malformed frame was passed to the HUB on specified port(0: Int 1: Ext0, 2: Ext1, 4: None)

### SUGGESTION

**C320A1 Hub : Alignment error on port: {signed}**

### EXPLANATION

A message with a malformed frame was passed to the HUB on specified port(0: Int 1: Ext0, 2: Ext1, 4: None)

### SUGGESTION

**C320A2 Data transmission unit : FiFo overflow on port {unsigned}**

### EXPLANATION

Transmission unit had a FiFo overflow on specified port (0: port a, 1: port b)

**C320A3 Data transmission unit : code error on port {unsigned}**

### EXPLANATION

Transmission unit received a code error on specified port (0: port a, 1: port b), this should never happen

### SUGGESTION

**C320A4 Data reception unit : Alignment error on port {unsigned}**

### EXPLANATION

Reception unit was unaligned with message on specified port (0: port a, 1: port b)

### SUGGESTION

**C320A5 Data reception unit : Alignment fault on port {unsigned}**





EXPLANATION

Reception unit was unable to align to incoming message on specified port (0: port a, 1: port b)

SUGGESTION

**C320A6 Data reception unit : Code error on port {unsigned}**

EXPLANATION

Reception unit saw an invalid control code on specified port (0: port a, 1: port b)

SUGGESTION

**C320A7 Data reception unit : Disparity error on port {unsigned}**

EXPLANATION

Reception unit got a disparity error on specified port (0: port a, 1: port b)

SUGGESTION

**C320A8 Data reception unit : FiFo overflow on port {unsigned}**

EXPLANATION

Reception unit had a FiFo overflow on specified port (0: port a, 1: port b)

SUGGESTION

**C320A9 Upstream transport layer : Package CRC error**

EXPLANATION

Upstream transport layer caught CRC error in package header

SUGGESTION

This might happen on occasion. Can be ignored if only happens rarely

**C320A10 Upstream transport layer : Bad package framing**

EXPLANATION

Upstream transport layer had found a framing error.

SUGGESTION

**C320A11 Upstream transport layer : Rx FiFo overflow**

EXPLANATION

Upstream transport layer had a FiFo overflow

**C320A12 Upstream transport layer : Tx FiFo overflow**

EXPLANATION

Slave transport layer had a Tx FiFo overflow

SUGGESTION

**C320A13 Upstream transport layer : Invalid hub count**

EXPLANATION

Slave transport layer received a message with invalid hub-cnt

SUGGESTION

**C320A14 Upstream transport layer : Request source not master.**

**EXPLANATION**

Slave transport layer recieved a message request from a device different from the master

**SUGGESTION****C320A15 Upstream transport layer : Response source not slave.****EXPLANATION**

Slave transport layer recieved a message response from a device different from a slave

**SUGGESTION****C320A16 Upstream transport layer : Sync package type received****EXPLANATION**

Master transport layer recieved a message where the type was Sync

**SUGGESTION****C320A17 Upstream transport layer : Trigger package type received****EXPLANATION**

Master transport layer recieved a message where the type was a trigger

**SUGGESTION****C320A18 Upstream transport layer : Request package type received****EXPLANATION**

Master transport layer recieved a message where the type was a request

**SUGGESTION****C320A19 Upstream transport layer : Invalid response type received****EXPLANATION**

Master transport layer recieved a message where the type was an invalid response

**SUGGESTION****C320A20 Upstream transport layer : Package from invalid source received****EXPLANATION**

Master transport layer recieved a package with an invalid source

**SUGGESTION****C320A21 Upstream transport layer : Mismatch between HUB count and package source****EXPLANATION**

Master transport layer recieved a package where the src and HUB count did not match

**SUGGESTION****C320A22 Upstream transport layer : Package longer than expected****EXPLANATION**

Master transport layer recieved a package where the length was greater than expected, or lost a framing end



SUGGESTION

**C320A23 Upstream transport layer : Package shorter than expected**

EXPLANATION

Master transport layer received a package where the length was less than expected

SUGGESTION

**C320A24 Upstream transport layer : Package was misaligned**

EXPLANATION

Master transport layer received a package that did not align to 32bit

SUGGESTION

**C320A25 Downstream transport layer : Package was shorter than expected**

EXPLANATION

Downstream transport layer tried to transmit a package that was longer than the data available

SUGGESTION

**C320A26 Downstream transport layer : Package was longer than expected**

EXPLANATION

Downstream transport layer tried to transmit a package with more data than expected

**C320A27 Downstream transport layer : Invalid package type**

EXPLANATION

Master transport layer tried to transmit a package with an invalid package type

SUGGESTION

**C320A28 Downstream transport layer : Package type missing**

EXPLANATION

Master transport layer tried to transmit a package without a package type

SUGGESTION

**C320A29 Downstream transport layer : Message length missing**

EXPLANATION

Master transport layer tried to transmit a package without a message length

SUGGESTION

**C320A30 Downstream transport layer : Package destination missing**

EXPLANATION

Master transport layer tried to transmit a package without a destination

**C320A31 Downstream transport layer : Package source missing**

EXPLANATION

Master transport layer tried to transmit a package without a source

SUGGESTION

### **C320A32 Downstream transport layer : Package NML missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a next message length

#### SUGGESTION

### **C320A33 Downstream transport layer : Package TTTL missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a time to live

#### SUGGESTION

### **C320A34 Downstream transport layer : Package timeout(high byte) missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a timeout the high byte

#### SUGGESTION

### **C320A35 Downstream transport layer : Package timeout(low byte) missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a timeout the low byte

#### SUGGESTION

### **C320A36 Downstream transport layer : Invalid message length**

#### EXPLANATION

Master transport layer tried to transmit a package with mismatch between stated and actual length

#### SUGGESTION

### **C320A37 REDnet controller : Received control pkg in data phase**

#### EXPLANATION

REDnet controller received a control package when not in the control phase

### **C320A38 REDnet controller : Received data package in control phase**

#### EXPLANATION

REDnet controller received a data package when not in the data phase

#### SUGGESTION

### **C320A39 REDnet controller : Got SOC before being ready**

#### EXPLANATION

REDnet controller got a SOC interrupt while not ready

#### SUGGESTION

### **C320A40 REDnet scheduler : Got SOC before being ready**

#### EXPLANATION

REDnet scheduler got a SOC interrupt while not ready

#### SUGGESTION

.



### **C320A41 REDnet scheduler : Node ID invalid**

#### EXPLANATION

REDnet scheduler tried to send to Node ID outside valid range

### **C320A42 Data reception unit : Alignment error on port A, {unsigned} seen since last**

#### EXPLANATION

Reception unit was unaligned with message on port A

#### SUGGESTION

### **C320A43 Data reception unit : Alignment fault on port A, {unsigned} seen since last**

#### EXPLANATION

Reception unit was unable to align to incoming message on port A

#### SUGGESTION

### **C320A44 Data reception unit : Code error on port A, {unsigned} seen since last**

#### EXPLANATION

Reception unit saw an invalid control code on port A

#### SUGGESTION

### **C320A45 Data reception unit : Disparity error on port A, {unsigned} seen since last**

#### EXPLANATION

Reception unit got a disparity error on port A

### **C320A46 Data reception unit : FiFo overflow on port A, {unsigned} seen since last**

#### EXPLANATION

Reception unit had a FiFo overflow on port A

#### SUGGESTION

### **C320A47 Data reception unit : Alignment error on port B, {unsigned} seen since last report**

#### EXPLANATION

Reception unit was unaligned with message on port B

#### SUGGESTION

### **C320A48 Data reception unit : Alignment fault on port B, {unsigned} seen since last report**

#### EXPLANATION

Reception unit was unable to align to incoming message on port B

#### SUGGESTION

### **C320A49 Data reception unit : Code error on port B, {unsigned} seen since last report**

#### EXPLANATION

Reception unit saw an invalid control code on port B

#### SUGGESTION

### **C320A50 Data reception unit : Disparity error on port B, {unsigned} seen since last report**

#### EXPLANATION

Reception unit got a disparity error on port B

### **C320A51 Data reception unit : FiFo overflow on port B, {unsigned} seen since last report**

#### EXPLANATION

Reception unit had a FiFo overflow on port B

#### SUGGESTION

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.180. C321 REDnet RS485

### **C321A0 Hub : Framing error on port: {signed}**

#### EXPLANATION

A message with a malformed frame was passed to the HUB on specified port(0: Int 1: Ext0, 2: Ext1, 4: None)

#### SUGGESTION

### **C321A1 Hub : Alignment error on port: {signed}**

#### EXPLANATION

A message with a malformed frame was passed to the HUB on specified port(0: Int 1: Ext0, 2: Ext1, 4: None)

#### SUGGESTION

### **C321A2 Data transmission unit : FiFo overflow on port {unsigned}**

#### EXPLANATION

Transmission unit had a FiFo overflow on specified port (0: port a, 1: port b)

#### SUGGESTION

### **C321A3 Data transmission unit : code error on port {unsigned}**

#### EXPLANATION

Transmission unit received a code error on specified port (0: port a, 1: port b), this should never happen

#### SUGGESTION

### **C321A4 Data reception unit : Alignment error on port {unsigned}**

#### EXPLANATION

Reception unit was unaligned with message on specified port (0: port a, 1: port b)

#### SUGGESTION

### **C321A5 Data reception unit : Alignment fault on port {unsigned}**

#### EXPLANATION

Reception unit was unable to align to incoming message on specified port (0: port a, 1: port b)



SUGGESTION

**C321A6 Data reception unit : Code error on port {unsigned}**

EXPLANATION

Reception unit saw an invalid control code on specified port (0: port a, 1: port b)

SUGGESTION

Contact your local Universal Robots service provider for assistance.

**C321A7 Data reception unit : Disparity error on port {unsigned}**

EXPLANATION

Reception unit got a disparity error on specified port (0: port a, 1: port b)

SUGGESTION

**C321A8 Data reception unit : FiFo overflow on port {unsigned}**

EXPLANATION

Reception unit had a FiFo overflow on specified port (0: port a, 1: port b)

SUGGESTION

**C321A9 Upstream transport layer : Package CRC error**

EXPLANATION

Upstream transport layer caught CRC error in package header

SUGGESTION

This might happen on occasion. Can be ignored if only happens rarely

**C321A10 Upstream transport layer : Bad package framing**

EXPLANATION

Upstream transport layer had found a framing error.

SUGGESTION

**C321A11 Upstream transport layer : Rx FiFo overflow**

EXPLANATION

Upstream transport layer had a FiFo overflow

SUGGESTION

**C321A12 Upstream transport layer : Tx FiFo overflow**

EXPLANATION

Slave transport layer had a Tx FiFo overflow

SUGGESTION

**C321A13 Upstream transport layer : Invalid hub count**

EXPLANATION

Slave transport layer recieved a message with invalid hub-cnt

SUGGESTION

**C321A14 Upstream transport layer : Request source not master.**



**EXPLANATION**

Slave transport layer recieved a message request from a device different from the master

**C321A15 Upstream transport layer : Response source not slave.****EXPLANATION**

Slave transport layer recieved a message response from a device different from a slave

**SUGGESTION****C321A16 Upstream transport layer : Sync package type received****EXPLANATION**

Master transport layer recieved a message where the type was Sync

**SUGGESTION****C321A17 Upstream transport layer : Trigger package type received****EXPLANATION**

Master transport layer recieved a message where the type was a trigger

**SUGGESTION****C321A18 Upstream transport layer : Request package type received****EXPLANATION**

Master transport layer recieved a message where the type was a request

**SUGGESTION****C321A19 Upstream transport layer : Invalid response type received****EXPLANATION**

Master transport layer recieved a message where the type was an invalid response

**SUGGESTION****C321A20 Upstream transport layer : Package from invalid source received****EXPLANATION**

Master transport layer recieved a package with an invalid source

**SUGGESTION****C321A21 Upstream transport layer : Mismatch between HUB count and package source****EXPLANATION**

Master transport layer recieved a package where the src and HUB count did not match

**SUGGESTION****C321A22 Upstream transport layer : Package longer than expected****EXPLANATION**

Master transport layer recieved a package where the length was greater than expected, or lost a framing end

**SUGGESTION**



### **C321A23 Upstream transport layer : Package shorter than expected**

#### EXPLANATION

Master transport layer recieved a package where the length was less than expected

#### SUGGESTION

### **C321A24 Upstream transport layer : Package was misaligned**

#### EXPLANATION

Master transport layer recieved a package that did not align to 32bit

#### SUGGESTION

### **C321A25 Downstream transport layer : Package was shorter than expected**

#### EXPLANATION

Downstream transport layer tried to transmit a package that was longer than the data available

#### SUGGESTION

### **C321A26 Downstream transport layer : Package was longer than expected**

#### EXPLANATION

Downstream transport layer tried to transmit a package with more data than expected

#### SUGGESTION

### **C321A27 Downstream transport layer : Invalid package type**

#### EXPLANATION

Master transport layer tried to transmit a package with an invalid package type

#### SUGGESTION

### **C321A28 Downstream transport layer : Package type missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a package type

#### SUGGESTION

### **C321A29 Downstream transport layer : Message length missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a message length

#### SUGGESTION

### **C321A30 Downstream transport layer : Package destination missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a destination

#### SUGGESTION

### **C321A31 Downstream transport layer : Package source missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a source

## SUGGESTION

### **C321A32 Downstream transport layer : Package NML missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a next message length

#### SUGGESTION

### **C321A33 Downstream transport layer : Package TTTL missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a time to live

#### SUGGESTION

### **C321A34 Downstream transport layer : Package timeout(high byte) missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a timeout the high byte

### **C321A35 Downstream transport layer : Package timeout(low byte) missing**

#### EXPLANATION

Master transport layer tried to transmit a package without a timeout the low byte

#### SUGGESTION

### **C321A36 Downstream transport layer : Invalid message length**

#### EXPLANATION

Master transport layer tried to transmit a package with mismatch between stated and actual length

#### SUGGESTION

### **C321A37 REDnet controller : Received control pkg in data phase**

#### EXPLANATION

REDnet controller received a control package when not in the control phase

#### SUGGESTION

### **C321A38 REDnet controller : Received data package in control phase**

#### EXPLANATION

REDnet controller received a data package when not in the data phase

#### SUGGESTION

### **C321A39 REDnet controller : Got SOC before being ready**

#### EXPLANATION

REDnet controller got a SOC interrupt while not ready

#### SUGGESTION

### **C321A40 REDnet scheduler : Got SOC before being ready**

#### EXPLANATION

REDnet scheduler got a SOC interrupt while not ready



## C321A41 REDnet scheduler : Node ID invalid

### EXPLANATION

REDnet scheduler tried to send to Node ID outside valid range

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.181. C322 Switch

### C322A0 Switch : Priority package timeout on ports: {hex}

#### EXPLANATION

Switch timed out trying to provide priority package to specified ports (bitmask)

#### SUGGESTION

### C322A1 Switch : Data package timeout on ports: {hex}

#### EXPLANATION

Switch timed out trying to provide data package to specified ports (bitmask)

#### SUGGESTION

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.182. C323 SCB Endpoint

### C323A0 Endpoint : Priority data debug channel overflow

#### EXPLANATION

SCB Endpoint discarded priority data to debug channel as it was not consumed fast enough

#### SUGGESTION

### C323A1 Endpoint : data debug channel overflow

#### EXPLANATION

SCB Endpoint discarded data to debug channel as it was not consumed fast enough

#### SUGGESTION

### C323A2 Endpoint : Priority data inbound timeout from port {hex}

#### EXPLANATION

SCB Endpoint lost an inbound priority package on specified port as the data was not provided before timeout, data as bitmask

#### SUGGESTION

### C323A3 Endpoint : Data inbound timeout from port {hex}

#### EXPLANATION

SCB Endpoint lost an inbound package on specified port as the data was not provided before timeout, data as bitmask

---

## SUGGESTION

### **C323A4 Endpoint : Priority data outbound timeout to port {hex}**

#### EXPLANATION

SCB Endpoint lost an outbound priority package to specified port as the data was not consumed before timeout, data as bitmask

#### SUGGESTION

### **C323A5 Endpoint : Data outbound timeout to port {hex}**

#### EXPLANATION

SCB Endpoint lost an outbound package to specified port as the data was not consumed before timeout, data as bitmask

#### SUGGESTION

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.183. C324 TP UART

### **C324A0 UART : FiFo overflow**

#### EXPLANATION

UART lost incoming data as a result of a FiFo overflow

#### SUGGESTION

### **C324A1 UART : Length mismatch**

#### EXPLANATION

UART discarded a package as length of data did not match announced data

#### SUGGESTION

### **C324A2 UART : Unexpected SOM**

#### EXPLANATION

UART got a new start of message during transmission of a message, data will be lost

#### SUGGESTION

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.184. C325 SPI uA

### **C325A53 uA SPI : FiFo underflow**

#### EXPLANATION

uA SPI FiFo ran out of data before message was complete

#### SUGGESTION



### C325A54 uA SPI : Unexpected read command

#### EXPLANATION

uA SPI received a read command without signaling data ready

#### SUGGESTION

### C325A55 uA SPI : Unsupported command: {hex}

#### EXPLANATION

uA SPI received an unsupported command

#### SUGGESTION

### C325A56 uA SPI : FiFo overflow

#### EXPLANATION

uA SPI received more data from device than could be stored.

### C325A63 uA SPI : FiFo overflow on interface: {signed}

#### EXPLANATION

uA SPI received more data than could be relayed to device.

### C325A64 uA SPI : FiFo overflow cleared

#### EXPLANATION

uA SPI is ready to relay messages to device.

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.185. C326 SPI uB

### C326A57 uB SPI : FiFo underflow

#### EXPLANATION

uB SPI FiFo ran out of data before message was complete

#### SUGGESTION

### C326A58 uB SPI : Unexpected read command

#### EXPLANATION

uB SPI received a read command without signaling data ready

#### SUGGESTION

### C326A59 uB SPI : Unsupported command: {hex}

#### EXPLANATION

uB SPI received an unsupported command

#### SUGGESTION

### C326A60 uB SPI : FiFo overflow

#### EXPLANATION

uB SPI received more data from device than could be stored.

---

## SUGGESTION

### **C326A65 uB SPI : FiFo overflow on interface: {signed}**

#### EXPLANATION

uB SPI received more data than could be relayed to device.

#### SUGGESTION

### **C326A66 uB SPI : FiFo overflow cleared**

#### EXPLANATION

uB SPI is ready to relay messages to device.

#### SUGGESTION

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.186. C327 PCIe

### **C327A0 PCIe Control-Data : Blocked for {unsigned} us**

#### EXPLANATION

PCIe control channel overflowed and was blocked, time to nearest us

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Update software, (B) Reduce CPU load

### **C327A1 PCIe Priority-Data : Blocked for {unsigned} us**

#### EXPLANATION

PCIe priority channel overflowed and was blocked, time to nearest us

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Update software, (B) Reduce CPU load

### **C327A2 PCIe data-data : Blocked for {unsigned} us**

#### EXPLANATION

PCIe data channel overflowed and was blocked, time to nearest us

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Update software, (B) Reduce CPU load

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket

## 1.187. C328 Transceiver miscellaneous

### **C328A0 The SoC arrived {unsigned} [ns] too early**

#### EXPLANATION

The ideal period of the SoC is 1000.00 us, and the allowed jitter is +/- 1000.0 ns

#### SUGGESTION





### **C328A1 Timeout while waiting for the SoC, the SoC was lost or delayed more than {unsigned} ns!**

#### EXPLANATION

The ideal period of the SoC is 1000.00 us, and the allowed jitter is +/- 1000.0 ns

#### SUGGESTION

### **C328A2 Flash device is not supported, JEDEC data for device is: {hex}**

#### EXPLANATION

The flash device's JEDEC ID does not match a supported flash device

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.188. C329 AXI STREAM

### **C329A1 FiFo overflow on interface: {signed}**

#### EXPLANATION

AXI stream received more data than could be relayed to device.

#### SUGGESTION

Contact your local Universal Robots service provider for assistance.

### **C329A2 FiFo overflow cleared**

#### EXPLANATION

AXI stream is ready to relay messages to device.

#### SUGGESTION

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.189. C330 IMMI IO

### **C330A1 Injection-Molding-Machine-Interface E-Stop output readback does not match produced value: {hex}**

#### EXPLANATION

First byte: produced value, second byte: read value

### **C330A2 Injection-Molding-Machine-Interface Moulding Area Free output readback does not match produced value: {hex}**

#### EXPLANATION

First byte: produced value, second byte: read value

### **C330A3 Injection-Molding-Machine-Interface 24V IO voltage outside acceptable range**

#### EXPLANATION

The voltage measured on the 24V IO rail is lower than expected.

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check the fuses on the Injection-Molding-Machine-Interface. (B) Verify there are no short circuits on the 24V IO connectors.

**C330A4 Injection-Molding-Machine-Interface 48V voltages outside acceptable range****EXPLANATION**

The voltages measured on the 48V rails are lower than expected.

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Check the fuses on the Injection-Molding-Machine-Interface. (B) Verify there are no short circuits on the IO connectors.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.190. C331 Friction model

**C331A0 Critical error****EXPLANATION**

A critical error occurred in the friction model module

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.191. C332 Servo configuration

**C332A0 Critical error****EXPLANATION**

A critical error occurred in the servo configuration module

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software,

**C332A1 The configuration file could not be loaded****C332A2 The configuration file could not be updated****C332A3 Failed to create configuration file, due to unknown PCB\_type {unsigned}.****C332A4 Failed to acquire the motor datasheet, due to unsupported motor id {unsigned}**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.192. C333 File message

**C333A0 Critical error****EXPLANATION**

A critical error occurred in the file message module



SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C333A1 File type {unsigned} is not supported**

**C333A2 All arguments are mandatory**

**C333A3 Protocol version {unsigned} is not supported**

**C333A4 File part {unsigned} is unexpected**

**C333A5 CRC {hex} is invalid**

**C333A6 Expected CRC {hex}**

**C333A7 Unique ID {hex} is invalid**

**C333A8 Expected unique ID {hex}**

**C333A9 File version {unsigned} is not supported**

**C333A10 File ID {unsigned} is deleted**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.193. C334 Robot deviated from constrained axes while in Constrained Freedrive.

EXPLANATION

The robot moved in one or more axes that were not allowed.

SUGGESTION

Check the settings on the Freedrive panel.

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.194. C336 Hardware configuration manager

**C336A1 An illegal write request to a memory area, at line {unsigned}**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.195. C337 Control parameters

**C337A0 Critical error**

EXPLANATION

A critical error occurred during setup of the control parameters

SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

**C337A1 A selected set of control parameters with id {unsigned}, was not allowed in this application**

**C337A2 A selected set of control parameters with id {unsigned}, was not known or was incorrectly applied**

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.196. C338 PROFIsafe

### **C338A0 Critical error**

#### EXPLANATION

A critical error occurred in the PROFIsafe logic

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software,

**C338A1 A hard error was triggered by the Siemens Profisafe Driver with instance ID {unsigned}**

**C338A2 A hard error was triggered by the Siemens Profisafe Driver at line number {unsigned}**

**C338A3 A hard error was triggered by the Siemens Profisafe Driver in file {unsigned}**

**C338A4 Invalid protocol version for PROFIsafe crosscommunication detected**

**C338A5 Invalid message length for PROFIsafe crosscommunication detected for msg id {unsigned}**

**C338A6 A PROFIsafe message was received, but there is no valid configuration**

#### EXPLANATION

A PROFIsafe message was received before a valid safety configuration

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Verify the PROFIsafe Host settings and review the robot safety configuration, see PROFIsafe (B) Do not start a PROFIsafe host before the robot is ready (C) Conduct a complete rebooting sequence

**C338A7 A PROFIsafe message was received and PROFIsafe was disabled.**

#### EXPLANATION

A PROFIsafe message was received while PROFIsafe is disabled in the safety configuration

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Verify the PROFIsafe Host settings and review the robot safety configuration, see PROFIsafe (B) Do not start a PROFIsafe host before the robot is ready (C) Conduct a complete rebooting sequence

**C338A8 The robot rejected the PROFIsafe F-Parameter set**

#### EXPLANATION

A PROFIsafe F-Parameterset was received from the PLC but was not accepted

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Check the diagnosis messages from the PLC and set a valid F-Parameter configuration, (B) Conduct a complete rebooting sequence

**C338A9 An error occurred during param state with code {unsigned}**



---

## C338A10 An error occurred during operational state with code {unsigned}

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.197. C339 Cross communication

### C339A0 Critical error

#### EXPLANATION

A critical error occurred in the cross communication module

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software

### C339A1 Requested transmit queue size {unsigned} larger than fifo size

### C339A2 The transmit queue size must not be larger than {unsigned}

---

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.198. C340 Energy Monitoring

### C340A0 Idle power consumption too high

#### EXPLANATION

The system is drawing more power than expected while idle

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Ensure supply is not delivering more than 48V, (B) Check Energy Eaters cable and connections, (C) Check Energy Eater, (D) Update software,

### C340A1 Energy surplus shutdown

#### EXPLANATION

The power supply is sending energy to the energy eater

#### SUGGESTION

Try the following actions to see if it resolves the issue: (A) Ensure supply is not delivering more than 48V, (B) Update software,

If you are unable to resolve the issue, login or create an account at <http://myUR.universal-robots.com> and post a new ticket.

## 1.199. C400 Elbow position close to safety plane limits

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.200. C401 Exceeding user safety settings for stopping time

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.201. C402 Exceeding user safety settings for stopping distance

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.202. C403 Danger of clamping between the Robot's lower arm and tool

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.203. C404 Unexpected behavior

### **C404A0 Runtime sends data too often**

### **C404A1 Runtime tries to receive data too often**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.204. C450 Force-Torque sensor

### **C450A0 Sensor data invalid**

#### EXPLANATION

Force-Torque sensor is defective or not mounted correctly

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for loose connections, (C) Update software, (D) Contact your local Universal Robots service provider for assistance

### **C450A1 Sensor can not be used, therefore it is disabled**

#### EXPLANATION

Force-Torque sensor version is newer than the Robot software

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for loose connections, (C) Update software, (D) Contact your local Universal Robots service provider for assistance

### **C450A2 Channel {unsigned} signal became invalid**

### **C450A3 Frequency is: {float}**

### **C450A4 Force-Torque sensor is expected, but it cannot be detected**

#### EXPLANATION

Force-Torque sensor is expected, but no signals from the sensor can be detected.

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for loose connections, (C) Check for damages to the Tool/sensor, (D) Update software, (E) Contact your local Universal Robots service provider for assistance

### **C450A5 Force-Torque sensor is detected but not calibrated**

**EXPLANATION**

Force-Torque sensor is installed, but no calibration was found.

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Contact your local Universal Robots service provider for assistance

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.205. C499 Motorencoder calibration

**C499A0 Actual position isn't stable. Position error: {float} [ticks]**

**C499A1 Actual position has a large error. Position error: {float} [ticks]**

**C499A2 Actual position has a large error and isn't stable. Position error: {float} [ticks]**

**C499A3 Target position is: {unsigned} [ticks]**

**C499A4 Actual average position is: {float} [ticks]**

**C499A5 Actual position variance is: {float} [ticks]**

**C499A6 Actual position min to max delta is: {signed} [ticks]**

**C499A7 Actual sample position number is: {unsigned}**

**C499A8 Average position isn't stable. Position variance: {float} [ticks]**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.206. C500 Self-test step

**C500A0 ADC calibration started**

**C500A1 ADC calibration done**

**C500A2 Commutation offset calibration started**

**C500A3 Commutation offset calibration done**

**C500A4 Brake Test started**

**C500A5 Brake Test done**

**C500A6 Burn-in started**

**C500A7 Burn-in done**

**C500A8 Cogging started**

**C500A9 Cogging done**

**C500A12 Joint calibration started**

**C500A13 Joint calibration done**

**C500A17 Motor phase order start**

**C500A18 Motor phase order done**

**C500A19 Awaiting acceptance started**

**EXPLANATION**

The Self-test awaits acceptance using serial number.



C500A20 Joint Encoder calibration started  
C500A21 Joint Encoder calibration done  
C500A22 Force-Torque started  
C500A23 Force-Torque done  
C500A24 Motor Encoder calibration started  
C500A25 Motor Encoder calibration done  
C500A26 Gear Zero Torque calibration started  
C500A27 Gear Zero-torque calibration done  
C500A28 RLS encoder signal quality test started  
C500A29 RLS encoder signal quality test done  
C500A30 Get motor encoder statistics started  
C500A31 Get motor encoder statistics done  
C500A32 Started calibration of motor parameters  
C500A33 Completed calibration of motor parameters  
C500A34 Started calibration of stator parameters  
C500A35 Completed calibration of stator parameters  
C500A36 Started thermal test  
C500A37 Completed thermal test  
C500A38 Started vibration test  
C500A39 Completed vibration test  
C500A40 Started store hardware information step  
C500A41 Completed store hardware information step  
C500A42 Commutation offset correction started  
C500A43 Commutation offset correction done  
C500A46 Kinematic error calibration started  
C500A47 Kinematic error calibration done

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.207. C501 PC Selftest message

C501A0 Unhandled exception during subtest transition  
C501A1 Exception occurred when accessing limits file  
C501A2 Received Selftest step when state was not in running state  
C501A3 Joint was disconnected prematurely  
C501A4 Illegally transitioned into bootloader while the selftest was running  
C501A5 Low-Level Spam Violation  
C501A6 Startup Failed



C501A7 Selftest aborted

C501A8 Repeats of log entries (SPAM) caused the selftest setup to fail the selftest

C501A9 Repeats of log entries (SPAM) caused the selftest setup to attempt reboot of joint FPGA

C501A10 The scanned hardware type is not valid. The scanned string was: {string}

C501A11 {string} was not validated correctly. Ensure that the test has been run

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.208. C502 Additional information

C502A0 Min limit was {float}

C502A1 Max limit was {float}

C502A2 Value on uA was {float}

C502A3 Value on uB was {float}

C502A4 Maximum deviation between uA and uB was larger than limit of {float}

C502A5 The deviation was {float}

C502A6 Deviation calculation was based on value {float} from uA

C502A7 Deviation calculation was based on value {float} from uB

C502A8 Expected negative value, but tested {float}

C502A9 Expected positive value, but tested {float}

C502A10 Joint ID was {unsigned}

C502A11 Device ID was {unsigned}

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.209. C503 Limit Violation – ADC calibration

C503A0 Calibration data was not found for uA

C503A1 Calibration data was not found for uB

C503A2 phase\_A gain exceeded limit

C503A3 phase\_B gain exceeded limit

C503A4 phase\_C gain exceeded limit

C503A5 phase\_A offset exceeded limit

C503A6 phase\_B offset exceeded limit

C503A7 phase\_C offset exceeded limit

C503A8 Current samples not found for uA

C503A9 Current samples not found for uB

C503A10 Phase A coefficient of determination below minimum limit

C503A11 Phase B coefficient of determination below minimum limit

C503A12 Phase C coefficient of determination below minimum limit

C503A13 Phase {string} on uA, did not have a reference current measured at 0A

C503A14 Phase {string} on uB, did not have a reference current measured at 0A

C503A15 Phase {string} on uA, the applied offset did not match the 0A sample

C503A16 Phase {string} on uB, the applied offset did not match the 0A sample

C503A17 Phase {string} on uA, the applied offset deviated to much from the linear offset

C503A18 Phase {string} on uB, the applied offset deviated to much from the linear offset

C503A19 The ADC calibration on uA had illegal revision {unsigned}, make sure that ems calibration data is available

C503A20 The ADC calibration on uB had illegal revision {unsigned}, make sure that ems calibration data is available

---

If you unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.210. C504 Limit Violation – Commutation offset calibration

C504A0 Calibration data was not found for uA

C504A1 Calibration data was not found for uB

C504A2 Commutation offset exceeded limit

C504A3 Difference between uA and uB exceeded limit

C504A4 The standard deviation of pole {unsigned} from the positive direction exceeded maximum level

C504A5 The standard deviation of pole {unsigned} from the negative direction exceeded maximum level

C504A6 The difference in position of pole {unsigned} measured from the positive and negative direction exceeded limit

C504A7 The Uncertainty of the commutation offset exceeded limit

C504A8 The estimated torque error at pole {unsigned} exceeded limit

C504A9 Received data from fewer poles than expected

---

If you unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.211. C505 Limit Violation – Brake test

C505A0 Test data was not found

---

If you unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.212. C506 Limit Violation – Zero torque offset calibration



---

## C506A0 Missing calibration data. No data received

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.213. C507 Limit Violation – Joint Calibration

**C507A0 Missing calibration data for uA**

**C507A1 Missing calibration measurements for uA**

**C507A2 Missing measurements count for uA**

**C507A3 Missing calibration data for uB**

**C507A4 Missing calibration measurements for uB**

**C507A5 Missing measurements count for uB**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.214. C508 Deviation – Joint Calibration

**C508A0 Maximum Q-axis currents deviation**

**C508A1 Maximum D-axis currents deviation**

**C508A2 Maximum velocity deviation**

**C508A3 Maximum deviation from target pct.**

**C508A4 Wrong sign on Q-axis current from uA, positive expected**

**C508A5 Wrong sign on Q-axis current from uA, negative expected**

**C508A6 Temperature limit violation**

**C508A7 Wrong sign on Q-axis current from uB, positive expected**

**C508A8 Wrong sign on Q-axis current from uB, negative expected**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.215. C509 Limit Violation – Cogging calibration

**C509A0 Calibration summary was not found for uA**

**C509A1 Calibration summary was not found for uB**

**C509A2 Received too many coefficient pairs uA**

**C509A3 Received too many coefficient pairs uB**

**C509A4 Received too few coefficient pairs uA**

**C509A5 Received too few coefficient pairs uB**

**C509A6 Cogging summary - std. residual error exceeded maximum limit**

**C509A7 Cogging summary - peak residual error exceeded maximum limit**

**C509A8 Cogging summary - mean speed error exceeded maximum limit**

**C509A9 Cogging summary - std. speed error exceeded maximum limit**

**C509A10 Cogging summary - peak speed error exceeded maximum limit**

**C509A11 Cogging coefficients - max signal amplitude exceeded max absolute limit**

**C509A12 Cogging coefficients - difference between the frequency component measured by uA and uB at index {float} exceeded the limit**

**C509A13 Joint type {string} is not supported by the test**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.216. C510 Limit Violation – Temperature

**C510A0 Joint temperature exceeded limits**

**C510A1 Processor temperature exceeded difference limits**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.217. C511 Limit Violation – Joint encoder calibration

**C511A0 Calibration summary was not found**

**C511A1 Incorrect amount of calibration LUT values**

**C511A2 Incorrect amount of validation LUT values**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.218. C512 Limit Violation – Motor encoder calibration

**C512A0 Calibration summary was not found**

**C512A1 Incorrect amount of calibration LUT pairs**

**C512A2 Incorrect amount of validation LUT pairs**

**C512A3 Motor Encoder Calibration residual error, std. dev. limit violation**

**C512A4 Motor Encoder Calibration residual error, peak limit violation**

**C512A5 Incorrect amount of raw calibration samples**

**C512A6 Incorrect amount of raw validation samples**

**C512A7 Motor Encoder Calibration error reduction factor violation**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.219. C513 Motor encoder statistics

**C513A0 Missing calibration data. Data not found**

**C513A1 Did not receive expected amount of drift data**

**C513A2 Did not receive expected amount of missing data**

**C513A3 Missed more indexes than max allowed**

**C513A4 Detected more drifted indexes than max allowed**



If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.220. C514 Limit Violation – RLS Encoder Signal Quality

**C514A0 Data was not found, missing calibration data**

**C514A1 Height exceeded limits**

**C514A2 Distance exceeded limits**

**C514A3 Tilt exceeded limits**

**C514A4 Airgap exceeded limits**

**C514A5 Radial sensor offset exceeded limits**

**C514A6 Disc tilt exceeded limits**

**C514A7 The encoder variant {string} is not valid for this joint type**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.221. C515 Limit Violation – Motor Parameters

**C515A0 Calculated back-emf constant (Kb) exceeded limits**

**C515A1 Calculated torque constant (Kt) exceeded limits**

**C515A2 Measured phase resistance (Rpp) exceeded limits**

**C515A3 Measured phase inductance (Lpp) exceeded limits**

**C515A4 Measured phase time constant (Tau\_pp) exceeded limits**

**C515A5 Coulomb friction in negative direction exceeded limits**

**C515A6 Coulomb friction in positive direction exceeded limits**

**C515A7 Friction Model. Viscous friction coefficient limit violation in the negative direction**

**C515A8 Friction Model. Viscous friction coefficient limit violation in the positive direction**

**C515A9 Quality of linear fit  $r^2$  limit violation in the negative direction**

**C515A10 Quality of linear fit  $r^2$  limit violation in the positive direction**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.222. C516 Selftest disagreement

**C516A0 Torque information disagreement between uA and uB**

**C516A1 Size disagreement between uA and uB**

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.223. C517 Limit Violation – Vibration Measurement

**C517A0 Not all vibration samples received from joint**



If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.224. C518 Joint Selftest Data Message

### **C518A0 Received unhandled message:{unsigned}**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.225. C519 Limit Violation – Hardware Information

### **C519A0 Mismatch between rotor and stator type {hex}**

### **C519A1 Mismatch between gear box and shaft type {hex}**

### **C519A2 Microprocessor A did not echo the correct hardware info back**

### **C519A3 Microprocessor B did not echo the correct hardware info back**

### **C519A4 Timed out after {unsigned} seconds while loading hardware serial numbers from QDA**

### **C519A5 The received serial number {string} is not a recognized gear serial number**

### **C519A6 The received serial number {string} is not a recognized motor serial number**

### **C519A7 The received serial number {string} is not a recognized motor encoder platform serial number**

### **C519A8 Hardware serial numbers was received while the joint was in {string} state, which is not allowed**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.226. C520 Limit Violation – Commutation Offset Correction

### **C520A0 The commutation offset correction brings the offset outside of the uncertainty area measured in the commutation offset calibration**

### **C520A1 No data was received for the commutation offset correction step**

### **C520A2 The Q axis voltage of {float} V was higher than expected after the calibration**

### **C520A3 The current of {float} A was higher than expected after the calibration**

### **C520A4 The D voltage was less symmetric after the calibration than before**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.227. C522 Limit Violation – Kinematic Error Calibration

### **C522A0 Did not receive data from all the expected velocities**

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.





## 1.228. C710 ROM Test

### C710A0 Critical error

#### EXPLANATION

A critical error occurred during ROM validation

#### SUGGESTION

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software, (C) Contact your local Universal Robots service provider for assistance

### C710A1 ROM corrupted

#### EXPLANATION

Failed to validate CRC on ROM

#### SUGGESTION

Reboot or contact your local Universal Robots service provider for assistance.

### C710A2 Failed to validate CRC on invariant data in RAM

#### EXPLANATION

Safety critical data stored in RAM was corrupted

#### SUGGESTION

Reboot or contact your local Universal Robots service provider for assistance.

### C710A3 Unexpected size of invariant data, size: {hex}

#### EXPLANATION

Size is in bytes. Size must be 32bit aligned

#### SUGGESTION

Contact your local Universal Robots service provider for assistance.

### C710A4 Failed to validate CRC on code segment in RAM

#### EXPLANATION

Parts of the Firmware stored in RAM was corrupted

#### SUGGESTION

Contact your local Universal Robots service provider for assistance.

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.229. C720 LVD (low voltage detection)

### C720A1 Reset due to LVD or power off

### C720A2 Low Voltage warning level reached

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.230. C740 Hardware monitoring

### C740A0 Critical error

#### EXPLANATION

A critical error occurred during hardware monitoring

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Update software, (C) Contact your local Universal Robots service provider for assistance

**C740A1 1V2 voltage is outside of the allowed range: {float}**

**C740A2 1V8 voltage is outside of the allowed range: {float}**

**C740A3 2V5 voltage is outside of the allowed range: {float}**

**C740A4 3V3 voltage is outside of the allowed range: {float}**

**C740A5 PC's 3V3 voltage is outside of the allowed range: {float}**

**C740A6 uA's 3V3voltage is outside of the allowed range: {float}**

**C740A7 uB's 3V3 voltage is outside of the allowed range: {float}**

**C740A8 5V voltage is outside of the allowed range: {float}**

**C740A9 12V voltage is outside of the allowed range: {float}**

**C740A10 24V voltage is outside of the allowed range: {float}**

**C740A11 48V voltage is outside of the allowed range: {float}**

**C740A12 58V voltage is outside of the allowed range: {float}**

**C740A13 -4V voltage is outside of the allowed range: {float}**

**C740A14 Robot voltage is outside of the allowed range: {float}**

**C740A15 Robot current is outside of the allowed range: {float}**

**C740A17 Inrush protected 48V voltage is outside of the allowed range: {float}**

**C740A20 24V SPI IO voltage is outside of the allowed range: {float}**

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for loose connections, (C) Check for damages to the Tool/sensor, (D) Update software, (E) Contact your local Universal Robots service provider for assistance

**C740A21 24V SPI IO current is outside of the allowed range: {float}**

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Conduct a complete rebooting sequence, (B) Check for loose connections, (C) Check for damages to the Tool/sensor, (D) Update software, (E) Contact your local Universal Robots service provider for assistance

**C740A22 The solenoid voltage is not 0 before activation: {float}**

**C740A23 The solenoid voltage is not 48V after activation: {float}**

**C740A24 The left Three-Position Enabling button is inconsistent**

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Do not press the button repeatedly, (B) Remove any pressure off the button, (C) Press the button with more pressure. Light pressing may not work, (D) Update software, (E) contact your local Universal Robots service provider for assistance.

**C740A25 The right Three-Position Enabling button is inconsistent**

**SUGGESTION**

Try the following actions to see which resolves the issue: (A) Do not press the button repeatedly, (B) Remove any pressure off the button, (C) Press the button with more pressure. Light pressing may not work, (D) Update software, (E) contact your local Universal Robots service provider for assistance.



## C740A26 State for the Three-Position Enabling button: {hex}

### EXPLANATION

Bit 0: Button, Bit 4: Button negated, Bit 8: Monitor 1, Bit 12: Monitor 2

---

If you are unable to resolve the issue, login to <http://myUR.universal-robots.com> and create a new case.

## 1.231. C900 Debug message data: {data}

Software Name: PolyScope 5

Software Version: 5.20

Document Version: 10.10.14

