

The following photos show the failure that a recently restored vessel suffered during hydraulic testing. The photos show undermining and lack of fusion in welds; as well as laminations in the material that were probably the causes of this failure. This demonstrates the importance of properly carrying out the tests so that this type of breakage does not occur during the service of the equipment.

