

Teensy 4.0 GRBL Pin Assignment working document

V 0.2

Goals:

1. Common Function on TH Pins for easy prototyping/testing. Simple machine should be possible with TH pins only.
2. Less Common Function of SMT “Back Side” Pins
3. Grouping of similar functions on nearby pins to simplify usage and PCB layout.

Issues/questions:

1. No onboard EEPROM. Use EEPROM emulation? How frequently does EEPROM get written? See (alt) Pin assignment.
2. Does USB use Ser 1? Pins need to be reserved?
3. Pin 13 is LED, output only. Currently on spindle enable. Is there a better use for that pin as a diagnostic?
4. Stepper enable is often unused in simple machines. Move that to back side to free up a TH pin?

Standard vs alternate assignment. Most pin assignments are the same for both. Main difference is the use of I2C channels on the through hole pins.

Through Hole Pins

| Pin | Standard assignment | Alternate assignment |
|--------------------------|---------------------|----------------------|
| 0 | Reserved RX1 | Reserved RX1 |
| 1 | Reserved TX1 | Reserved TX1 |
| 2 | Step X | Step X |
| 3 | Dir X | Dir X |
| 4 | Step Y | Step Y |
| 5 | Dir Y | Dir Y |
| 6 | Step Z | Step Z |
| 7 | Dir Z | Dir Z |
| 8 | Step A | Step A |
| 9 | Dir A | Dir A |
| 10 | Stepper Enable 0 | Stepper Enable 0 |
| 11 | Spindle Dir | Spindle Dir |
| 12 | Spindle Enable | Spindle Enable |
| 13 LED | Spindle PWM | Spindle PWM |
| 14 | Reset/Abort | Reset/Abort |
| 15 | Probe | Probe |
| 16 I ² C 0 | Feed/Hold | I2C SCL ch 0 |
| 17 I ² C 0 | Cycle Start | I2C SDA ch 0 |

| | | |
|--------------------------|--------------|--------------|
| 18 I ² C 1 | Mist Enable | I2C SDA ch 1 |
| 19 I ² C 1 | Flood Enable | I2C SCL ch 1 |
| 20 | Lim X | Lim X |
| 21 | Lim Y | Lim Y |
| 22 | Lim Z | Lim Z |
| 23 | Lim A | Lim A |

Back Side SMT Pins

| Pin | Function assignment | Alternate assignment |
|-------------|---------------------|----------------------|
| 24 I2C 2 | I2C SCL ch 2 | Feed/Hold |
| 25 I2C 2 | I2C SDA ch 2 | Cycle Start |
| 26 | Step B | Step B |
| 27 | Dir B | Dir B |
| 28 | Lim B | Lim B |
| 29 | Door | Door |
| 30 | Stepper Enable 1 | Stepper Enable 1 |
| 31 | Relay 5 | Relay 5 |
| 32 | Relay 6 | Relay 6 |
| 33 | GPIO 1 | Relay 7 |
| 34 | Stepper Enable 2 | Stepper Enable 2 |
| 35 | Stepper Enable 3 | Mist Enable |
| 36 | Stepper Enable 4 | Flood Enable |
| 37 | | |
| 38 | | |
| 39 | | |

Simple Machine Definition

This section defines the functions needed to build a simple CNC/Laser machine. The goal is to be able to do this only with through hole pins. This allows easy prototyping and testing.

Note that strictly speaking, Stepper Enable is unnecessary and Feed/Hold, Cycle Start are often omitted in basic machines. For Lasers, I believe Spindle pins are used for control.

| | | | |
|--------|------------------|-------|--|
| Step X | Stepper Enable 0 | Lim Y | |
| Dir X | Spindle PWM | Lim Z | |
| Step Y | Spindle Enable | Lim A | |

| | | | |
|--------|-------------|-------------|--|
| Dir Y | Reset/Abort | Feed/Hold | |
| Step Z | Probe | Cycle Start | |
| Dir Z | Lim X | | |

Note this is somewhat stating the obvious but I think it worthwhile to have written down.