



## L6470 Bipolar Stepper Motor Driver API

### Class instances;

<b>cL6470();</b>	
In this instance you do not need to pass anyparameter.just create the instance and after that assign the Pin (for assigning the Pin please check the x_Set_x function, x means CS, MOIS,MISO,Reset,Busy)	
Example	cL6470 Motor();

<b>cL6470(MOSI, MISO, CS, CLK, BUSY , RESET );</b>					
<b>Param1</b>	<b>Param2</b>	<b>Param3</b>	<b>Param4</b>	<b>Param5</b>	<b>Param6</b>
Type Int	Type Int	Type Int	Type Int	Type Int	Type Int
MOSI Pin	MISO Pin	CS Pin	CLK Pin	BUSY Pin	RESET Pin
Example	cL6470 Motor(11,12,10,13,5,6);				

### Pin Assigning Functions

if you create the instance without parameters then you can use these function to assign the Pin Number to the instance.

<b>x_Set_MOSI(MOSI_Pin_Number);</b>	
<b>Param</b>	
Type	Integer
MOSI Pin Number	
Example	Motor. x_Set_MOSI(11);

<b>x_Set_MISO (MISO_Pin_Number);</b>	
<b>Param</b>	
Type	Integer
MISO Pin Number	
Example	Motor. x_Set_MISO(12);

<b>x_Set_CS (CS_Pin_Number);</b>	
<b>Param</b>	
Type	Integer
CS Pin Number	
Example	Motor. x_Set_CS(10);
<b>x_Set_CLK (CLK_Pin_Number);</b>	
<b>Param</b>	
Type	Integer
CLK Pin Number	
Example	Motor. x_Set_CLK(13);



## L6470 Bipolar Stepper Motor Driver API

<b>x_Set_BUSY (BUSY_Pin_Number);</b>		
<b>Param</b>		
Type	Integer	
	BUSY Pin Number	
Example	Motor. x_Set_BUSY(5);	

<b>x_Set_RESET(RESET_Pin_Number);</b>		
<b>Param</b>		
Type	Integer	
	RESET Pin Number	
Example	Motor. x_Set_RESET(6);	

You can also Get the PiNumber. Here the Some Function to get the Pin Number

- **\_Get\_MOSI0;**
- **\_Get\_MISO0;**
- **\_Get\_CS0;**
- **\_Get\_CLK0;**
- **\_Get\_BUSY0;**
- **\_Get\_RESET0;**

return Type is Integer.



## L6470 Bipolar Stepper Motor Driver API

### initialization

so first thing come first. please initialization the pins. for this we design the function.

please use initialization in the Setp of the code. for more understanding please check the example .

<code>init0;</code>	
He has no Parameters	
Example	<code>Motor. init0;</code>

After the initialization, You need to adjust the some parameters for the Motor, to adjust the parameters we have two functions. please Check the L6470 DataSheet for defination of these parameters. P40

### Parameters Micros

- `x_ABS_POS`
- `x_EL_POS`
- `x_MARK`
- `x_SPEED`
- `x_ACC`
- `x_DEC`
- `x_MAX_SPEED`
- `x_MIN_SPEED`
- `x_FS_SPD`
- `x_KVAL_HOLD`
- `x_KVAL_RUN`
- `x_KVAL_ACC`
- `x_KVAL_DEC`
- `x_INT_SPD`
- `x_ST_SLP`
- `x_FN_SLP_ACC`
- `x_FN_SLP_DEC`
- `x_K_THERM`
- `x_ADC_OUT`
- `x_OCD_TH`
- `x_STALL_TH`
- `x_STEP_MODE`
- `x_ALARM_EN`
- `x_CONF`
- `x_STATUS`



## L6470 Bipolar Stepper Motor Driver API

<b>_GetParam(ParametersMicros)</b>	
<b>Param</b>	
Type	Byte
Please use the above define Micros. to get the parameters value.the return type is Byte.	
Example <code>Motor._GetParam(x_CONFIG) == 0x2E88</code>	

<b>_SetParam(ParametersMicros, Value );</b>	
<b>Param1</b>	<b>Param2</b>
Type	Type
Byte	unsigned Long
Please use the above defined micros.	
Value for this Specified Parameters.	
Example <code>Motor._SetParam(x_INT_SPD, 0x3550);</code>	

When you are Setting the over current thresholds parameters (x\_OCD\_TH). we have some predefined Micros.

- x\_OCD\_TH\_375mA
- x\_OCD\_TH\_750mA
- x\_OCD\_TH\_1125mA
- x\_OCD\_TH\_1500mA
- x\_OCD\_TH\_1875mA
- x\_OCD\_TH\_2250mA
- x\_OCD\_TH\_2625mA
- x\_OCD\_TH\_3000mA
- x\_OCD\_TH\_3375mA
- x\_OCD\_TH\_3750mA
- x\_OCD\_TH\_4125mA
- x\_OCD\_TH\_4500mA
- x\_OCD\_TH\_4875mA
- x\_OCD\_TH\_5250mA
- x\_OCD\_TH\_5625mA
- x\_OCD\_TH\_6000mA

For example

```
Motor._SetParam(x_OCD_TH, x_OCD_TH_6000mA);
```

When you are Setting the StepMode parameters (x\_STEP\_MODE ).we have some predefined Micros.

- x\_STEP\_SEL\_1



## L6470 Bipolar Stepper Motor Driver API

- `x_STEP_SEL_1_2`
- `x_STEP_SEL_1_4`
- `x_STEP_SEL_1_8`
- `x_STEP_SEL_1_16`
- `x_STEP_SEL_1_32`
- `x_STEP_SEL_1_64`
- `x_STEP_SEL_1_128`

For example

```
Motor._SetParam(x_STEP_MODE,  
                !x_SYNC_EN | x_STEP_SEL_1_128 |  
                x_SYNC_SEL_1);
```

`x_SYNC_EN` controls whether the BUSY/SYNC pin reflects the step frequency or the BUSY status of the chip. We want it to be the BUSY status, so we pass the inverted Value.

`x_STEP_SEL_x` is the microstepping rate- we'll go full step 128.

`x_SYNC_SEL_x` is the ratio of (micro)steps to toggles on the BUSY/SYNC pin (when that pin is

used for SYNC). but we are using Busy because we connect the Blue light to this Pin.

Some Predefined Micros for the configuration Parameters.

Oscillator options. The x needs to know what the clock frequency is because it uses that for some calculations during operation.

<code>x_CONFIG_OSC_SEL</code>	Mask for this bit field.
<code>x_CONFIG_INT_16MHZ</code>	Internal 16MHz, no output
<code>x_CONFIG_INT_16MHZ_OSCOUT_2MHZ</code>	Default; internal 16MHz, 2MHz output
<code>x_CONFIG_INT_16MHZ_OSCOUT_4MHZ</code>	Internal 16MHz, 4MHz output
<code>x_CONFIG_INT_16MHZ_OSCOUT_8MHZ</code>	Internal 16MHz, 8MHz output
<code>x_CONFIG_INT_16MHZ_OSCOUT_16MHZ</code>	Internal 16MHz, 16MHz output
<code>x_CONFIG_EXT_8MHZ_XTAL_DRIVE</code>	External 8MHz crystal
<code>x_CONFIG_EXT_16MHZ_XTAL_DRIVE</code>	External 16MHz crystal
<code>x_CONFIG_EXT_24MHZ_XTAL_DRIVE</code>	External 24MHz crystal
<code>x_CONFIG_EXT_32MHZ_XTAL_DRIVE</code>	External 32MHz crystal
<code>x_CONFIG_EXT_8MHZ_OSCOUT_INVERT</code>	External 8MHz crystal, output inverted
<code>x_CONFIG_EXT_16MHZ_OSCOUT_INVERT</code>	External 16MHz crystal, output inverted



## L6470 Bipolar Stepper Motor Driver API

`x_CONFIG_EXT_24MHZ_OSCOUT_INVERT`      External 24MHz crystal, output inverted

`x_CONFIG_EXT_32MHZ_OSCOUT_INVERT`      External 32MHz crystal, output inverted

Configure the functionality of the external switch input

`x_CONFIG_SW_HARD_STOP`      Default; hard stop motor on switch.

`x_CONFIG_SW_USER`      Tie to the GoUntil and ReleaseSW

Configure the motor voltage compensation mode (see page 34 of datasheet)

`x_CONFIG_VS_COMP_DISABLE`      Disable motor voltage compensation

`x_CONFIG_VS_COMP_ENABLE`      Enable motor voltage compensation

Configure overcurrent detection event handling

`x_CONFIG_OC_SD_DISABLE`      Bridges do NOT shutdown on OC detect

`x_CONFIG_OC_SD_ENABLE`      Bridges shutdown on OC detect

Configure the slew rate of the power bridge output

`x_CONFIG_SR_180V_us`

`x_CONFIG_SR_290V_us`

`x_CONFIG_SR_530V_us`

Integer divisors for PWM sinewave generation

See page 32 of the datasheet for more information on this.

`x_CONFIG_PWM_MUL_0_625`

`x_CONFIG_PWM_MUL_0_75`

`x_CONFIG_PWM_MUL_0_875`

`x_CONFIG_PWM_MUL_1`

`x_CONFIG_PWM_MUL_1_25`

`x_CONFIG_PWM_MUL_1_5`

`x_CONFIG_PWM_MUL_1_75`

`x_CONFIG_PWM_MUL_2`

Multiplier for the PWM sinewave frequency

`x_CONFIG_PWM_DIV_1`

`x_CONFIG_PWM_DIV_2`

`x_CONFIG_PWM_DIV_3`

`x_CONFIG_PWM_DIV_4`

`x_CONFIG_PWM_DIV_5`

`x_CONFIG_PWM_DIV_6`

`x_CONFIG_PWM_DIV_7`



## L6470 Bipolar Stepper Motor Driver API

### Example

```
Motor._SetParam(x_CONFIG,  
    x_CONFIG_PWM_DIV_1 |  
    x_CONFIG_PWM_MUL_2 |  
    x_CONFIG_SR_180V_us |  
    x_CONFIG_OC_SD_DISABLE |  
    x_CONFIG_VS_COMP_DISABLE |  
    x_CONFIG_SW_HARD_STOP |  
    x_CONFIG_INT_16MHZ);
```



### Functions

Fetch and return the 16-bit value in the STATUS register. Resets any warning flags and exits any error states. return Type is integer.

`_GetStatus();`

This is a 20-bit value, so we need to make sure the value is at or below 0xFFFFF. return type is unsigned Long.

`_SpdCalc(float);`

This is a 14-bit value, so we need to make sure the value is at or below 0x3FFF. return type is unsigned Long.

`_IntSpdCalc(float);`

\_FSCalc contains a threshold value above which microstepping is disabled return type is unsigned Long.

`_FSCalc(float);`

Adjust the minimum Speed. This is a 12-bit value, so we need to make sure the value is at or below 0xFFF. return type is unsigned Long.

`_MinSpdCalc(float);`

Adjust the maximum Speed. This is a 10-bit value, so we need to make sure it remains at or below 0x3FF. return type is unsigned Long.

`_MaxSpdCalc(float);`

The calculation for DEC is the same as for ACC. Value is 0x08A on boot. This is a 12-bit value, so we need to make sure the value is at or below 0xFFF. return type is unsigned Long.

`_DecCalc(float);`

`_AccCalc(float);`

Enable or disable the low-speed optimization option.

`_SetLSPDOpt(boolean);`

RUN sets the motor spinning in a direction (defined by the constants.FWD and REV). Maximum speed and minimum speed are defined by the MAX\_SPEED and MIN\_SPEED registers; exceeding the FS\_SPD value will switch the device into full-





## L6470 Bipolar Stepper Motor Driver API

step mode. The SpdCalc() function is provided to convert steps/s values into appropriate integer values for this function.

**\_Run(byte, unsigned long);**

STEP\_CLOCK puts the device in external step clocking mode. When active, pin 13, STCK, becomes the step clock for the device, and steps it in the direction (set by the FWD and REV constants) imposed by the call of this function. Motion commands (RUN, MOVE, etc) will cause the device to exit step clocking mode.

**\_Step\_Clock(byte);**

MOVE will send the motor n\_step steps (size based on step mode) in the direction imposed by dir (FWD or REV constants may be used). The motor will accelerate according the acceleration and deceleration curves, and will run at MAX\_SPEED. Stepping mode will adhere to FS\_SPD value, as well.

**\_Move(byte, unsigned long);**

GOTO operates much like MOVE, except it produces absolute motion instead of relative motion. The motor will be moved to the indicated position in the shortest possible fashion.

**\_GoTo(unsigned long);**

Same as GOTO, but with user constrained rotational direction.

**\_GoTo\_DIR(byte, unsigned long);**

GoUntil will set the motor running with direction dir (REV or FWD) until a falling edge is detected on the SW pin. Depending on bit SW\_MODE in CONFIG, either a hard stop or a soft stop is performed at the falling edge, and depending on the value of act (either RESET or COPY) the value in the ABS\_POS register is either RESET to 0 or COPY-ed into the MARK register.

**\_GoUntil(byte, byte, unsigned long);**

Similar in nature to GoUntil, ReleaseSW produces motion at the higher of two speeds: the value in MIN\_SPEED or 5 steps/s. The motor continues to run at this speed until a rising edge is detected on the switch input, then a hard stop is performed and the ABS\_POS register is either COPY-ed into MARK or RESET to 0, depending on whether RESET or COPY was passed to the function for act.

**\_ReleaseSW(byte, byte);**

GoHome is equivalent to GoTo(0), but requires less time to send. Note that no direction is provided; motion occurs through shortest path. If a direction is required, use GoTo\_DIR().

**\_GoHome();**



## L6470 Bipolar Stepper Motor Driver API

GoMark is equivalent to GoTo(MARK), but requires less time to send. Note that no direction is provided; motion occurs through shortest path. If a direction is required, use GoTo\_DIR().

`_GoMark();`

Sets the ABS\_POS register to 0, effectively declaring the current position to be "HOME".

`_ResetPos();`

Reset device to power up conditions. Equivalent to toggling the STBY pin or cycling power.

`_ResetDev();`

Bring the motor to a halt using the deceleration curve.

`_SoftStop();`

Stop the motor with infinite deceleration.

`_HardStop();`

Decelerate the motor and put the bridges in Hi-Z state.

`_SoftHiZ();`

Put the bridges in Hi-Z state immediately with no deceleration.

`_HardHiZ();`