

PROCESS IMPROVEMENT QUALITY MANAGEMENT_6

08/05/2023

MELINDA KÖNYVES

DEPARTMENT OF MANAGEMENT AND BUSINESS ECONOMICS

FACULTY OF ECONOMIC AND SOCIAL SCIENCES

BUDAPEST UNIVERSITY OF TECHNOLOGY AND ECONOMICS

KONYVES.MELINDA@GTK.BME.HU

Memo – Quality Control

- Mass production
 - Shewhart: 1924 Bell Labs
- Measures conducted during the manufacturing process on an appropriate sample
- Main aim to control and regulate the processes, to prevent defective products



SPC methods to be learned

- Control charts
 - Detecting problems within the process
- Process capability indices
 - The process' ability to meet the customers' requirements





SPC methods

- **Control charts**
 - Achieving process stability
 - Checking whether the parameters are stable over time
 - Detecting deviations in the production process that would lead to nonconforming units
- **Process capability analysis**
 - Evaluating the process performance
 - Reducing the variability in order to continuously meet customers' requirements
 - Predicting the number of defective items



Common and special causes

- Common causes (in-control process)
 - Cumulative effect of many, small, unavoidable causes
 - Always assumed to be present in the process
 - Humidity, temperature....



Common and special causes

- Special causes (out-of-control process)
 - Occasionally present
 - Result in an unacceptable level of process performance
 - Defective raw material, improperly adjusted machines, operator errors




Objective of control charts

- Distinguish common and special causes
- Detect the occurrence of special causes
 - Operator action is necessary to eliminate them
- Prevent the production of flawed product



Mathematical background

- Normal distribution $N \sim (\mu; \sigma)$
 - Central limit theorem
 - Natural tolerance limits at $\mu - 3\sigma; \mu + 3\sigma$




σ is standard deviation - spread around the mean; the shape of the curve

μ is the expected value - the center of the distribution

Processes in- and out-of control


Out-of-control process

Special causes shift the process mean/variability and many nonconforming units are produced




In-control process

Only common causes, parameters are stable over time
 $\mu_0; \sigma_0$





Control charts



Establishing the control charts

- m samples of size n:
 $x_{i,1}, x_{i,2}, \dots, x_{i,n}$
- R-chart for monitoring the standard deviation of the process
- \bar{X} -chart to monitor the expected value
- The control limits are dependent on the sampling distribution of the quality characteristics



Performance of control charts


- Due to sampling error
- Type I error, α -risk
 - In-control process is thought to be out-of-control (false alarm)
 - Normally distributed process: $\alpha = 0,27\%$
 - Unnecessary process adjustments
- Type II error, β -risk
 - Out-of-control process is thought to be in-control
 - Not detecting a process shift

Phase I and II application of Control Charts

- Phase I.
 - Retrospective analysis
 - Based on 20-25 samples
 - Trial control limits
 - Bringing the process into the state of statistical control
- Phase II.
 - Monitoring process performance
 - OCAP: Out-of-control Action Plan
 - Actions necessary to eliminate the special causes

Control charts for \bar{X} and R

- m samples of size n: $x_{i,1}, x_{i,2}, \dots, x_{i,n}$
- Range of the sample: $R_i = X_{i,max} - X_{i,min}$
- Average range: $\bar{R} = \frac{\sum_{i=1}^m R_i}{m} = \frac{R_1 + R_2 + \dots + R_m}{m}$
- Control limits for the R chart
 - $UCL = D_4 \bar{R}$
 - Center line = \bar{R}
 - $LCL = D_3 \bar{R}$



Control charts for \bar{X} and R

- Average of the i -th sample:

$$\bar{X}_i = \frac{\sum_{j=1}^n X_{i,j}}{n} = \frac{X_{i,1} + X_{i,2} + \dots + X_{i,n}}{n}$$

- Grand average (average of the averages):

$$\bar{\bar{X}} = \frac{\sum_{i=1}^m \bar{X}_i}{m} = \frac{\bar{X}_1 + \bar{X}_2 + \dots + \bar{X}_m}{m}$$

- Control limits for the \bar{X} chart:

- Process variability must be in-control (check the R chart!)

- $UCL = \bar{\bar{X}} + A_2 \bar{R}$

- Center line: $\bar{\bar{X}}$

- $LCL = \bar{\bar{X}} - A_2 \bar{R}$

Benefits of control chart application

- Improving productivity
- Preventing defects
- Avoiding unnecessary process adjustments
- Providing diagnostic information
- Estimating process capability




Monitoring the process' performance

- m samples of size n
- $R_i = X_{i,max} - X_{i,min}$
- $\bar{X}_i = \frac{\sum_{j=1}^n X_{i,j}}{n}$
- $\bar{R} = \frac{\sum_{i=1}^m R_i}{m}$
- $\bar{\bar{X}} = \frac{\sum_{i=1}^m \bar{X}_i}{m}$

Establishing the control limits

- R chart (standard deviation of the process)
 - $UCL_R = D_4 \bar{R}$
 - $CL_R = \bar{R}$
 - $LCL_R = D_3 \bar{R}$
- \bar{X} chart (process' mean)
 - $UCL_{\bar{X}} = \bar{\bar{X}} + A_2 \bar{R}$
 - $CL_{\bar{X}} = \bar{\bar{X}}$
 - $LCL_{\bar{X}} = \bar{\bar{X}} - A_2 \bar{R}$



Estimating the parameters (example)- data sheet

Sample no.	Data on nominal output voltage					Sample range	Sample average
	X ₁	X ₂	X ₃	X ₄	X ₅		
1	15,8	16,3	16,2	16,1	16,6	0,8	16,2
2	16,3	15,9	15,9	16,2	16,4	0,5	16,14
3	16,1	16,2	16,5	16,4	16,3	0,4	16,3
4	16,3	16,2	15,9	16,4	16,2	0,5	16,2
5	16,1	16,1	16,4	16,5	16	0,5	16,22
6	16,1	15,8	16,7	16,6	16,4	0,9	16,32
7	16,1	16,3	16,5	16,1	16,5		
8	16,2	16,1	16,2	16,1	16,3	0,2	16,18
9	16,3	16,2	16,4	16,3	16,5	0,3	16,34
10	16,6	16,3	16,4	16,1	16,5	0,5	16,38
11	16,2	16,4	15,9	16,3	16,4	0,5	16,24
12	15,9	16,6	16,7	16,2	16,5	0,8	16,38
13	16,4	16,1	16,6	16,4	16,1	0,5	16,32
14	16,5	16,3	16,2	16,3	16,4	0,3	16,34
15	16,4	16,1	16,3	16,2	16,2	0,3	16,24
16	16	16,2	16,3	16,3	16,2		
17	16,4	16,2	16,4	16,3	16,2	0,2	16,3
18	16	16,2	16,4	16,5	16,1	0,5	16,24
19	16,4	16	16,3	16,4	16,4	0,4	16,3
20	16,4	16,4	16,5	16	15,8	0,7	16,22
Average range							-----
Grand average (average of the subgroups' average)						-----	

$$R_i = X_{i,max} - X_{i,min}$$

$$\bar{R} = \frac{\sum_{i=1}^m R_i}{m}$$

$$\bar{X}_i = \frac{\sum_{j=1}^n X_{i,j}}{n}$$


$$\bar{\bar{X}} = \frac{\sum_{i=1}^m \bar{X}_i}{m}$$



R-chart

Range of the first sample


Upper control limit



Range of the last sample

Lower control limit

\bar{X} chart





Process capability analysis

- Only for in-control process
- Analyzing the process' variability relative to product requirements
- Main objectives:
 - Predicting the number of nonconformities
 - Selecting between suppliers
 - Reducing the variability of the process
 - Meeting customers' expectations
 - Decreasing the number of nonconforming products

Capability of our process



Not capable



Capable


Histograms

- Visual impression of the process performance



Histograms


- Possible causes of poor process performance
 - Poorly located center (shift in the mean)
 - Excess variability



Process capability ratio

- As σ decreases, the C_p increases
- The higher the value of C_p , the less nonconforming units are produced

$$C_p = \frac{USL - LSL}{6 \cdot \sigma}$$



Process capability ratio


Requirements and process fallout

C_p	Sigma level ($SL = 3C_p$)	ppm (process fallout)	
1,00	± 3	2700	
1,33	± 4	63,5	Standard minimum value in most industries
1,67	± 5	0,57	Parameters related to safety
2,00	± 6	0,002	World-class organizations, SixSigma

Process capability indices

$$C_p = \frac{USL - LSL}{6 \cdot \sigma}$$

The C_p index does not take into account whether the process is centered at the midpoint of the specification interval or not



$$C_p = 1$$


$$C_p = 1$$




C_{pk} index – off-center process

$$C_{pk} = \min\{C_{pl}, C_{pu}\} = \left\{ \frac{\mu - LSL}{3 \cdot \sigma}; \frac{USL - \mu}{3 \cdot \sigma} \right\}_{\min}$$



Relationship between C_p and C_{pk}

- C_{pk} : Current capability of the process
- C_p : Potential capability of the process
 - Can be achieved by centering the process



Control vs. specification limits

- **Control limits**
 - Determined based on the current variability of the process
 - A point outside the control limit indicates that there is a shift in the process mean / standard deviation, that is, the process is NOT stable over time
 - **In-control process: its parameters are stable over time**
- **Specification limits**
 - Determined externally
 - The 3 sigma deviation of the process is compared to the specification limits
 - The area outside of the specification limits is proportional to the process fallout
 - **A capable process: able to meet the customers' requirements**

MSA – Measurement System Analysis

- Measurement system: the totality of the measuring devices, environment, measuring persons, measurement method, procedure and measured component.
- Features:
 - Accuracy: if the mean value of the measured value is the same as the true value of the measured characteristic
 - Resolution: the smallest difference that the measurement system can consistently detect
 - Display resolution: the smallest difference that that the measuring device can display
 - Stability: if the measurements are repeated at different intervals, the same result is obtained
 - Repeatability: inherent fluctuation in measurement results in the case of a measuring person
 - Reproducibility: inherent fluctuation in measurement results in the case of several measuring persons

R&R

R&R%	Evaluation
$> 30\%$	Not acceptable
$10\% < R\&R\% < 30\%$	Partly acceptable
$< 10\%$	Acceptable

Thank you for your attention.

Melinda Könyves