



TOP AUTO SURVEY

Claims

XXXXXX



TOP AUTO SURVEY



DAMAGE SURVEY REPORT

FILE NUMBER	12981122
POLICY NUMBER	FKQRTY

TOP AUTO SURVEY

GENERAL INFORMATION

SURVEY PREPARED FOR	XXXXXXXXXX
VEHICLE MAKE	JEEP
VEHICLE MODEL	Compass Limited
TYPE OF SURVEY	Condition and Value
OVERALL VEHICLE RATING .	FAIR
ESTIMATED MARKET VALUE	\$53,200.00
ESTIMATED REPLACEMENT COST .	\$40,500.00
YEAR BUILT	2012
MODEL YEAR	2012
VEHICLE IDENTIFICATION NUMBER (VIN)	XXXXXXXXXX
OWNER	XXXXXXXXXXXXXX
PLACE OF SURVEY	Franklin Square, NY.
DATE/TIME OF SURVEY	September 10, 2015 0800 to 1300
VEHICLE MATERIAL	
VEHICLE TYPE	SUV
LENGTH OVER ALL (L.O.A).	
FUEL CAPACITY	60 gallons

ADDITIONAL EQUIPMENT AND ACCESSORIES

GENERAL EQUIPMENT:

- Storage cabin

Comments (if any):

TOP AUTO SURVEY

DEFINITION OF TERMS:

The terms and words used in this report have the following meanings as used in this Report of survey:

APPEARS:

Indicates that a very close inspection of the particular system, component or item was not possible due to constraints imposed upon the surveyor (e.g. no power available, inability to remove panels, or requirements not to conduct destructive tests).

FIT FOR INTENDED USE:

Use which is intended by Survey (present or prospective owner).

SERVICEABLE: ADEQUATE:

Sufficient for a specific requirement.

POWERS UP:

Power was applied only. This does not refer to the operation of any system or component unless specifically indicated.

EXCELLENT CONDITION:

New or like new.

GOOD CONDITION:

Nearly new, with only minor cosmetic or structural discrepancies noted.

FAIR CONDITION:

Denotes that system, component or item is functional as is with minor repairs. (MONITOR OFTEN)

POOR CONDITION:

Unusable as is. Requires repairs or replacement of system, component or item to be considered functional.

TOP AUTO SURVEY

PARTIES INVOLVED

SURVEY PREPARED FOR	ABCDEFGH
VEHICLE MAKE	JEEP
VEHICLE MODEL	Compass Sports
TYPE OF SURVEY	Condition and Value
OVERALL VEHICLE RATING .	FAIR
ESTIMATED MARKET VALUE	\$43,200.00
ESTIMATED REPLACEMENT COST .	\$30,500.00
YEAR BUILT	2010
MODEL YEAR	2010
VEHICLE IDENTIFICATION NUMBER (VIN)	ABC123456WER
OWNER	XXXXXXXXXXXXX
PLACE OF SURVEY	Franklin Square, NY.
DATE/TIME OF SURVEY	September 10, 2015 0800 to 1300
VEHICLE MATERIAL	
VEHICLE TYPE	SUV
LENGTH OVER ALL (L.O.A).	
FUEL CAPACITY	60 gallons

Comments (if any):

TOP AUTO SURVEY

CIRCUMSTANCES

Circumstances:

Vehicle 1 & Vehicle 2 were travelling south bound on I-75 (sr93). V1 was travelling in the right outside centre lane. V2 was travelling in the outside lane. Driver of V1 advised that he slowed down due to hearing loud clanking noises coming from his truck. V1 changed his lanes to the right from the right outside centre lane into the outside lane. V1 upon entering into the lane interrupted the path of travel of V2. V2's left front side and entire left side collided with V1's right side. V2 after impact veered to the right traveling into the west emergency lane than into the grass shoulder. Driver 2 attempting to regain control of V2 veered sharply back to the left, but was unable to re-gain control and over turned. V2 rolled over and came to final rest on its wheels in the west grass shoulder facing in an easterly direction. V1 came to final rest in the west emergency lane south of V2.

Comments (if any)

TOP AUTO SURVEY

DETAILS ABOUT THE SURVEY

Claimant: XXXXXXXX

Survey Place / Town / Country: Franklin Square, NY.

Survey Date & Hour: September 10, 2015 0800 to 1300

Parties invited for the survey

Parties present during the survey

Name:	Company:	Representing:

Comments (if any)

TOP AUTO SURVEY

ASPECT OF THE DAMAGE

Aspect of the damage:

There has been damage to the front portion of the vehicle the bumper and the engine parts. Air bags have been releases during the accident. There has been a leak in the floor of the car.

Engine is bolted to welded steel frames which are bolted. Engine mounts are in serviceable condition as noted by visual inspection except for underbody which is badly rusted.

Exhaust system shows age but appears serviceable except where noted in Findings section.

Below normal level of coolant has been maintained.

TOP AUTO SURVEY

NATURE OF THE DAMAGE

Nature of the damage:

Damage to the vehicle, damage to the third party vehicle and the property.

Comments (if any)

TOP AUTO SURVEY

Summary:

In accordance with the request for auto survey of the vehicle, for the purpose of evaluating its present condition and Replacement Cost, I herewith submit my conclusion based on the preceding report. The subject vehicle was personally inspected by the undersigned on September 10, 2015.

TOP AUTO SURVEY



LIST OF PICTURES

No	PICTURES
1	

TOP AUTO SURVEY

This report is drawn up to the best of our knowledge, true and correct and without prejudice to our principal's liability, reserving the right to extend it when and where required.

Claims Coordinator:

Name: Mark Mathew

Surveyor :

Name: John Joseph

Report Issued at:

Report Issued on:

TOP AUTO SURVEY

Financial worksheet:

Vehicle 1

#	itemize losses	replacement cost	depreciation	actual cash value
1	Bumper	1500	750	750
2	Bumper Painting	750		750
3	A/M RT Head lamp	143	71.5	71.5
4	A/M RT Head lamp	143	71.5	71.5
5	Horn Low note BX	38.5	9.625	28.875
6	Horn Low note EX HX Radiator Support	38.5	9.625	28.875
7	RT Side Panel Clear Coat			71
8	LT Side Panel Overlap Mirror Clear Coat			150
9	Lock Support	25	12.5	12.5
10	Upper Tie Bar	65	16.25	48.75
11	A/M Radiator	200	40	160
12	A/M Condenser	115	23	92
13	AC Line Cord	25	5	20
14	A/M CMDA Hood	255	42.5	212.5
15	Lock EX	65	13	52
16	LT Front Seal	20	4	16
17	Labour	1014.9		1014.9

TOP AUTO SURVEY

Vehicle 2

#	itemize losses	replacement cost	depreciation	actual cash value
1	Bumper	2500	750	1750
2	Bumper Painting	750		750
3	A/M RT Tail lamp	185.9	92.95	92.95
4	A/M RT Tail lamp	185.9	92.95	92.95
5	RT Side Panel Clear Coat			71
6	LT Side Panel Overlap Mirror Clear Coat			150
7	Lock Support	25	12.5	12.5
8	Upper Tie Bar	84.5	21.125	63.375
9	Lock EX	65	13	52
10	LT Rear Seal	20	4	16
11	Labour	1346.49		1346.49