

main CVE / 2021 / CVE-2021-34201 /

liyansong2018 D-Link 2640 Out-of-bounds Write &amp; Fix Bugs ...

on Jul 3, 2021 History

..

images

last year

README.md

last year

README.md

# Out-of-bounds Write in DIR-2640-US Router

## Overview

- CVE ID: [CVE-2021-34201](#)
- Type: Out-of-bounds Write - (787)
- Vendor: D-LINK (<https://www.dlink.com/>)
- Products: WiFi Router, such as DIR-2640-US.
- Version: Firmware (1.01B04)
- Fix:  
<https://support.dlink.com/productinfo.aspx?m=DIR-2640-US>  
[https://support.dlink.com/resource/SECURITY\\_ADVISEMENTS/DIR-2640/REVA/DIR-2640\\_REVA\\_FIRMWARE\\_v1.11B02\\_BETA01\\_HOTFIX.zip](https://support.dlink.com/resource/SECURITY_ADVISEMENTS/DIR-2640/REVA/DIR-2640_REVA_FIRMWARE_v1.11B02_BETA01_HOTFIX.zip)

## Severity

High 7.1 CVSS:3.1/AV:L/AC:L/PR:L/UI:N/S:U/C:N/I:H/A:H

## Description

Multiple out-of-bounds vulnerabilities in some processes of D-Link AC2600(DIR-2640). Local ordinary users can overwrite the global variables in the .bss section, causing the process crashes or changes.

Ordinary users can run nl\_server .

```
admin@dlinkrouter:~$ ls -l ./usr/bin/nl_server
-rwxr-xr-x  1      18616 May 23  2021 ./usr/bin/nl_server
```

nl\_server

```
admin@dlinkrouter:~$ ps
nl_server -i br0 -s dlinkrouter -s dlinkrouter3485 -s dlinkrouter.local -s dlinkrouter3485.local &
```

The decompiled code is as follows, the process does not limit the length of parameters entered by the user.

```
while ( v4 != 's' );
v5 = *(_DWORD *)align_414888;
if ( *(int *)align_414888 >= 4 )
    break;
v9 = optarg;
v6 = strlen(optarg);
strncpy((char *)8byte_414948 + 128 * v5, v9, v6);
*(_DWORD *)align_414888 = v5 + 1;
```

Is this parameter controllable externally?

```
admin@dlinkrouter:~$ cat /tmp/hosts
192.168.0.1 dlinkrouter
192.168.0.1 dlinkrouter3458
192.168.0.1 dlinkrouter.local
192.168.0.1 dlinkrouter3458.local
127.0.0.1 localhost
```

```

445 v8 = fopen("/dev/console", "w");
446 if ( v8 )
447 {
448     fprintf(v8, "%s: enter\n", "start_dev_mgt_link");
449     fclose(v8);
450 }
451 snprintf(v14, 8, "%s%d", "lan", 0);
452 v0 = sub_42C390(v14, "management_link", &v16);
453 v4 = (const char *)wRSConfigGet(v0);
454 if ( *v4 )
455 {
456     v16 = 0;
457     v17 = 0;
458     v18 = 0;
459     v19 = 0;
460     v20 = 0;
461     v21 = 0;
462     v22 = 0;
463     v23 = 0;
464     v2 = sub_42C390(v14, "ipaddr", &v16);
465     v5 = (const char *)wRSConfigGet(v2);
466     if ( *v5 )
467     {
468         v3 = sub_42C390(v14, "ifname", &v16);
469         v6 = (const char *)wRSConfigGet(v3);
470         v11 = socket(2, 3, 255);
471         if ( v11 >= 0 )
472         {
473             strncpy(v26, v6, 32);
474             if ( !ioctl(v11, 35111, v26) )
475                 snprintf(v15, 8, "%02X%02X", (unsigned __int8)v26[22], (unsigned __int8)v26[23]);
476             close(v11);
477         }
478     }
479 }

```

v0 = lan0\_management\_link

```
./etc_ro/Wireless/RT2860AP/RT2860_default_vlan-factory:393:lan0_management_link=dlinkrouter
./etc_ro/Wireless/RT2860AP/RT2860_default_vlan:416:lan0 management link=dlinkrouter
```

Is this parameter controllable externally?

[illegible]

- 8-Feb-2021 Discovered the vulnerability
- 9-Feb-2021 Responsibly disclosed vulnerability to vendor
- 10-Feb-2021 D-Link PSIRT would raise to R&D
- 31-Mar-2021 D-Link R&D was investigating the report
- 2-Jun-2021 Requested for CVE-ID assignment
- 10-Jun-2021 CVE-ID Assigned
- 13-Jun-2021 Notified CVE about a publication
- 22-Jun-2021 Fixed