

# DFU UPLOAD buffer overflow revised

**High** liydu published GHSA-m9p8-xrp7-vvqp 22 days ago

## Package

**USBX** (Azure RTOS)

## Affected versions

< 6.1.12

## Patched versions

6.1.12

## Description

### Impact

The USB DFU UPLOAD functionality may be utilized to introduce a buffer overflow resulting in overwrite of memory contents. In particular cases this may allow an attacker to bypass security features or execute arbitrary code.

The implementation of `ux_device_class_dfu_control_request` function prevents buffer overflow during handling of DFU UPLOAD command when current state is `UX_SYSTEM_DFU_STATE_DFU_IDLE`. Validation for this condition is implemented as in the following snippet.

```
case UX_SLAVE_CLASS_DFU_COMMAND_UPLOAD:
```

```
/* bitCanUpload != 1, or length = 0, or length > wTransferSize (we can support max of control bu
if (!(_ux_system_slave -> ux_system_slave_device_dfu_capabilities & UX_SLAVE_CLASS_DFU_CAPAB
(request_length == 0) ||
(request_length > UX_SLAVE_REQUEST_CONTROL_MAX_LENGTH))
{
    _ux_device_stack_endpoint_stall(&device -> ux_slave_device_control_endpoint);
```

```
/* In the system, state the DFU state machine to DFU ERROR. */
_ux_system_slave -> ux_system_slave_device_dfu_state_machine = UX_SYSTEM_DFU_STATE_DFU_ERROR;
```

```
break;
}
```



Once a correct DFU UPLOAD control request transfer is handled the DFU state machine transitions to UX\_SYSTEM\_DFU\_STATE\_DFU\_UPLOAD\_IDLE state which lacks the required validation.

```
case UX_SLAVE_CLASS_DFU_STATUS_STATE_DFU_UPLOAD_IDLE:

/* Here we process only the request we can accept in the DFU mode UPLOAD IDLE state. */
switch (request)
{

case UX_SLAVE_CLASS_DFU_COMMAND_UPLOAD:

/* Length 0 case undefined, just keep state. */
if (request_length == 0)
break;

/* We received a UPLOAD command with length > 0. */

/* Read the next block from the firmware. */
status = dfu -> ux_slave_class_dfu_read(dfu, request_value,
transfer_request -> ux_slave_transfer_request_data_pointer,
request_length,
&actual_length);

/* Application can actively reject and set error state. */
if (status != UX_SUCCESS)
{
ux_device_stack_endpoint_stall(&device -> ux_slave_device_control_endpoint);
ux_system_slave -> ux_system_slave_device_dfu_state_machine = UX_SYSTEM_DFU_STATE_DFU_ERROR;
break;
}

/* If it's short frame, switch to dfu IDLE. */
if (actual_length < request_length)
{

/* Send a notification to the application. */
dfu -> ux_slave_class_dfu_notify(dfu, UX_SLAVE_CLASS_DFU_NOTIFICATION_END_UPLOAD);

/* In the system, state the DFU state machine to dfu IDLE. */
ux_system_slave -> ux_system_slave_device_dfu_state_machine = UX_SYSTEM_DFU_STATE_DFU_IDLE;
}

/* We have a request to upload DFU firmware block. */
ux_device_stack_transfer_request(transfer_request, actual_length, request_length);

break;
```

With state machine in UX\_SLAVE\_CLASS\_DFU\_STATUS\_STATE\_DFU\_UPLOAD\_IDLE processing a control transfer request for UX\_SLAVE\_CLASS\_DFU\_COMMAND\_UPLOAD with wLength greater than UX\_SLAVE\_REQUEST\_CONTROL\_MAX\_LENGTH will result in a buffer overflow ( dfu->ux\_slave\_class\_dfu\_read will overflow the UX\_SLAVE\_REQUEST\_CONTROL\_MAX\_LENGTH buffer) which in turn may result in a RCE with attacker code injected to flash either by utilizing DFU DOWNLOAD command or manipulating contents of an external flash chip (when used).

## Patches

We analyzed this bug and determined that we needed to fix it. This fix has been included in USBX release [6.1.12](#)

## Workarounds

Add the `UPLOAD_LENGTH` check in all possible states

## For more information

If you have any questions or comments about this advisory:

Open an issue in [azure-rtos/usbx](#)

Post question on [Microsoft Q&A](#)

### Severity

High

---

### CVE ID

CVE-2022-39344

---

### Weaknesses

No CWEs