

TP-Link Cross Site Scripting

Authored by [Kautubh G. Padwad](#), [Smriti Gaba](#)

Posted [Mar 26, 2021](#)

Multiple TP-Link devices suffer from an unauthenticated persistent cross site scripting vulnerability. Affected models include TD-W9977, TL-WA801ND, TL-WA801N, TL-WR802N, and Archer-C3150.

tags | [exploit_xss](#)

advisories | [CVE-2021-3275](#)

SHA-256 | [e35e1937104dc66eacb185dee5eb8adeeab2b99d9f05fd8364987d6dd5a729bd](#)

[Download](#) | [Favorite](#) | [View](#)

Related Files

Share This

Like

Twitter

LinkedIn

Reddit

Digg

StumbleUpon

[Change Mirror](#)[Download](#)

Unauthenticated Stored Cross-site Scripting in Multiple TP-Link Devices

Overview

Title:- Unauthenticated Stored Cross-site Scripting in TP-Link Devices.
CVE-ID :- CVE-2021-3275
Author: Smriti Gaba, Kautubh Padwad
Vendor: TP-LINK (<https://www.tp-link.com>)
Products:
1. DSL and DSL Gateway
2. Access Points
3. WIFI Routers

Tested Version: : Multiple versions of DSL & DSL Gateway, WIFI Routers and Access Points including:

Model	Firmware Version
TD-W9977	
TD-W9977v1_0.1.0_0.9.1_up_boot(161123)_2016-11-23_15.36.15	
TL-WA801ND	TL-WA801NDv5_US_0.9.1_3.16_up_boot[170905-rel156404]
TL-WA801N	TL-WA801Nv6_EU_0.9.1_3.16_up_boot[200116-rel161815]
TL-WR802N	TL-WR802Nv4_US_0.9.1_3.17_up_boot[200421-rel138950]
Archer-C3150	ArcherC3150(US)_V2_170926

Severity: Med-High

About the Product:

* The (products from above list) are high performance WIFI Routers(Wireless AC routers), Access Points, ADSL + DSL Gateways and Routers.
* Provides Configuration modes: Access Point mode, Router Mode, Range Extender mode.
* Provide Ethernet and other interfaces to meet the access requirements of different devices.
* It can provide high-performance functionalities, services for home users, individual users, and businesses.
* Supports multiple functionalities including CWM management, TR069 Configuration, SNMP management, Traffic statistics, etc.

Description:

An issue was discovered, common to all the TP-Link products including WIFI Routers(Wireless AC routers), Access Points, ADSL + DSL Gateways and Routers.
This affected TD-W9977v1, TL-WA801NDv5, TL-WA801Nv6, TL-WA802Nv5, Archer C3150v2 devices.
A malicious XSS payload if injected in hostname of Wireless Client devices connected to TP-Link device, allows remote attackers to execute unauthenticated malicious scripts because of improper validation of hostname. Some of the pages including dhcp.htm, networkMap.htm, dhcpClient.htm, qEdit.htm, qReview.htm and others use this vulnerable hostname function(setDefaultHostname()) without sanitization and push the value of hostname (\$defaulthostname) directly to the ACT stack along with other parameters. The ACT stack is called on for multiple operation ids covering LAN, WAN and while initialisation of multiple tables (arp, dhcp, client list) across the device. For example, ACT_SET stack for WAN_IP_CONN is called while dhcp operation, during which value of vulnerable defaulthostname is being assigned to parameter X_TP_Hostname and pushed to stack.
This causes XSS at all the endpoints which display hostname for example: Wireless client information table, ARP bind table such as networkMap, DHCP.

Additional Information

The hostname value is only validated on ASCII characters, while there is no validation for Non-ASCII characters which allows hostname with XSS payload say "<script>alert('XSS')</script>" to execute.
This value of hostname is pushed to an array as plain text along with IP address and MAC address in initClientListTable() function, and other tables use the same value of hostname across the device. This array is then returned to the callback function which in turn is called from proxy.js. This data is pushed to stack corresponding to operation:"LAN_HOST_ENTRY" (vary for different firmware), operation id: "gl" (gl is getList function). As client initiates request with operation id:"LAN_HOST_ENTRY" and oid: "gl", \$dm.getList and \$act is called which fetches the corresponding stack and sends data to ajax call. The crafted value of hostname is sent to the device and results in execution of payload.

[Affected Component]
hostName parameter inside different htm pages including DHCP, dhcpAP, ArpBind, networkMap.

[Attack Type]
Remote

[Impact Code execution]
true

[Attack Vectors]
Malicious payload execution on initiating request for Wireless Client List table or DHCP html page.

[Vulnerability Type]
Stored Cross-site Scripting

How to Reproduce: (POC):

1. Change the default hostname of wireless client by using following command (for Linux):
a. vi /etc/dhcp/dhclient.conf
b. Insert and change the value of hostname to xss payload
"<script>alert('XSS')</script>"

File Archive: December 2022 <

Su	Mo	Tu	We	Th	Fr
Sa					
				1	2
3					
4	5	6	7	8	9
10					
11	12	13	14	15	16
17					
18	19	20	21	22	23
24					
25	26	27	28	29	30
31					

Top Authors In Last 30 Days

Red Hat 157 files
Ubuntu 76 files
LiquidWorm 23 files
Debian 21 files
nu11security 11 files
malvuln 11 files
Gentoo 9 files
Google Security Research 8 files
Julien Ahrens 4 files
T. Weber 4 files

File Tags

ActiveX (932)	December 2022
Advisory (79,754)	November 2022
Arbitrary (15,694)	October 2022
BBS (2,859)	September 2022
Bypass (1,619)	August 2022
CGI (1,018)	July 2022
Code Execution (8,926)	June 2022
Conference (673)	May 2022
Cracker (840)	April 2022
CSRF (3,290)	March 2022
DoS (22,602)	February 2022
Encryption (2,349)	January 2022
Exploit (50,359)	Older

File Inclusion (4,165)

File Upload (946)

Firewall (821)

Info Disclosure (2,660)

Intrusion Detection (867)

Java (2,899)

JavaScript (821)

Kernel (6,291)

Local (14,201)

Magazine (586)

Overflow (12,419)

Perl (1,418)

PHP (5,093)

Proof of Concept (2,291)

Protocol (3,435)

Python (1,467)

Remote (30,044)

Root (3,504)

Ruby (594)

Scanner (1,631)

Security Tool (7,777)

Shell (3,103)

Shellcode (1,204)

Sniffer (886)

File Archives

December 2022

November 2022

October 2022

September 2022

August 2022

July 2022

June 2022

May 2022

April 2022

March 2022

February 2022

January 2022

Older

Systems

AIX (426)

Apple (1,926)

BSD (370)

CentOS (55)

Cisco (1,917)

Debian (6,634)

Fedora (1,600)

FreeBSD (1,242)

Gentoo (4,272)

HPUX (878)

IOS (330)

iPhone (108)

IRIX (220)

Juniper (67)

Linux (44,315)

Mac OS X (684)

Mandriva (3,105)

NetBSD (255)

OpenBSD (479)

RedHat (12,469)

Slackware (941)

Solaris (1,607)

```
2. Renew IP address by sending DHCP request to TP-Link device via
following command:
a. vi /etc/network/interfaces
b. Add these lines:
    auto wlan0
    iface wlan0 inet dhcp
    c. On Terminal run command: ifup wlan0
3. Login to the router web interface, navigate to DHCP settings or
Wireless Client tab.
4. As soon as DHCP or Wireless client table is requested Xss payload
executes and pops up alert box.
```

Mitigation

Model	Mitigation	Firmware Version
TL-WA801ND		TL-WA801NDv5_US_0.9.1_3.16_up_boot[170905-rel156404]
	Patched	
TL-WA801N		TL-WA801Nv6_EU_0.9.1_3.16_up_boot[200116-rel161815]
	Patched	
TL-WR802N		TL-WR802Nv4_US_0.9.1_3.17_up_boot[200421-rel138950]
	Patched	
Archer-C3150		ArcherC3150(US)_V2_170926
	EOL Product	
TD-W9977		
TD-W9977v1		0.1.0_0.9.1_up_boot[161123]_2016-11-23_15.36.15 EOL Product

Link for patched software version for products:

1. TL-WA801ND -
[https://tp-link.com/beta/2021/202101/20210120/TL-WA801NDv5_US_0.9.1_3.16_up_boot\[210119-rel161453\].zip](https://tp-link.com/beta/2021/202101/20210120/TL-WA801NDv5_US_0.9.1_3.16_up_boot[210119-rel161453].zip)
2. TL-WA801N -
[https://tp-link.com/beta/2021/202101/20210120/TL-WA801Nv6_EU_0.9.1_3.16_up_boot\[210119-rel162190\].zip](https://tp-link.com/beta/2021/202101/20210120/TL-WA801Nv6_EU_0.9.1_3.16_up_boot[210119-rel162190].zip)
3. TL-WR802N -
[https://tp-link.com/beta/2021/202101/20210120/TL-WR802Nv4_US_0.9.1_3.17_up_boot\[210119-rel163071\].zip](https://tp-link.com/beta/2021/202101/20210120/TL-WR802Nv4_US_0.9.1_3.17_up_boot[210119-rel163071].zip)

[Vendor of Product]

TP-LINK (<https://www.tp-link.com>)

Disclosure Timeline:

24-July-2020 Discovered the vulnerability
11-Aug-2020 Responsibly disclosed vulnerability to vendor
15-Aug-2020 Vendor Acknowledged the disclosure
17-Nov-2020 Communicated with vendor after 90 days for updates
19-Nov-2020 Vendor asked for model and version details
20-Nov-2020 Provided the required details to vendor
25-Nov-2020 Vendor provided software build to verify the issue
9-Dec-2020 Issue not fixed in the provided software.
4-Jan-2021 Asked Updates on the status of the issue.
20-Jan-2021 Vendor provided software build to verify the issue.
20-Jan-2021 Issue found fixed in the provided software.
21-Jan-2021 Requested for CVE-ID assignment
25-March-2021 CVE-ID Assigned.

credits:

* Smriti Gaba
* Security Researcher
* smritigaba548@gmail.com
* <https://www.linkedin.com/in/smriti-gaba-658795135/>

* Kaustubh Padwad
* Information Security Researcher
* kingkaustubh@gmail.com
* <https://twitter.com/s3curityb3ast>

Spoof (2,166) SUSE (1,444)
SQL Injection (16,102) Ubuntu (8,199)
TCP (2,379) UNIX (9,159)
Trojan (686) UnixWare (185)
UDP (676) Windows (6,511)
Virus (662) Other
Vulnerability (31,136)
Web (9,365)
Whitepaper (3,729)
x86 (946)
XSS (17,494)
Other

[Login](#) or [Register](#) to add favorites

packet storm

© 2022 Packet Storm. All rights reserved.

Site Links

News by Month
News Tags
Files by Month
File Tags
File Directory

About Us

History & Purpose
Contact Information
Terms of Service
Privacy Statement
Copyright Information

Hosting By

[Rokasec](#)

[Follow us on Twitter](#)

[Subscribe to an RSS Feed](#)