

main

...

CVE / CVE-2021-3275



smriti548 Create CVE-2021-3275 ...

History

1 contributor

136 lines (108 sloc) | 7.25 KB

...

```
1 =====
2 Unauthenticated Stored Cross-site Scripting in TP-Link Devices
3 =====
4
5 . contents:: Table Of Content
6
7 Overview
8 =====
9
10 Title:- Unauthenticated Stored Cross-site Scripting via hostname in TP-Link Devices.
11 CVE-ID :- CVE-2021-3275
12 Author: Smriti Gaba, Kaustubh Padwad
13 Vendor: TP-LINK (https://www.tp-link.com)
14 Products:
15     1. DSL and DSL Gateway
16     2. Access Points
17     3. WIFI Routers
18
19
20 Tested Version: : Multiple versions of DSL & DSL Gateway, WIFI Routers and Access Points including:
21
22 -----
23 Model          | Firmware Version          |
24 -----
25 TD-W9977       | TD-W9977v1_0.1.0_0.9.1_up_boot(161123)_2016-11-23_15.36.15 |
26 TL-WA801ND     | TL-WA801NDv5_US_0.9.1_3.16_up_boot[170905-rel156404] |
27 TL-WA801N      | TL-WA801Nv6_EU_0.9.1_3.16_up_boot[200116-rel161815] |
28 TL-WR802N      | TL-WR802Nv4_US_0.9.1_3.17_up_boot[200421-rel138950] |
29 Archer-C3150   | ArcherC3150(US)_V2_170926 |
30 -----
31
32 Severity: Med-High
33
34
35 About the Product:
36 =====
37
38 * The (products from above list) are high performance WIFI Routers(Wireless AC routers), Access Points, ADSL + DSL Gateways and Routers.
39 * Provides Configuration modes: Access Point mode, Router Mode, Range Extender mode.
40 * Provide Ethernet and other interfaces to meet the access requirements of different devices.
41 * It can provide high-performance functionalities, services for home users, individual users, and businesses.
42 * Supports multiple functionalities including CWMN management, TR069 Configuration, SNMP management, Traffic statistics, etc.
43
44 Description:
45 =====
46 An issue was discovered, common to all the TP-Link products including WIFI Routers(Wireless AC routers), Access Points, ADSL + DSL Gateways and Routers.
47 This affected TD-W9977v1,TL-WA801NDv5, TL-WA801Nv6, TL-WA802Nv5, Archer C3150v2 devices.
48 A malicious XSS payload if injected in hostname of Wireless Client devices connected to TP-Link device, allows remote attackers to execute unauthenticated malicious scripts because
49 This causes XSS at all the endpoints which display hostname for example: Wireless client information table, ARP bind table such as networkMap, DHCP.
50
51
52 Additional Information
53 =====
54 The hostname value is only validated on ASCII characters, while there is no validation for Non-ASCII characters which allows hostname with XSS payload say "<script>alert('XSS')</script>"
55 This value of hostname is pushed to an array as plain text along with IP address and MAC address in initClientListTable() function, and other tables use the same value of hostname
56 As client initiates request with operation id:"LAN_HOST_ENTRY" and oid: "gl", $dm.getList and $.act is called which fetches the corresponding stack and sends data to ajax call. The
57
58
59 [Affected Component]
60 hostName parameter inside different htm pages including DHCP, DhcpAP, ArpBind, networkMap.
61
62 -----
63 [Attack Type]
64 Remote
65 -----
66 [Impact Code execution]
67 true
68
69 -----
70 [Attack Vectors]
71 Malicious payload execution on initiating request for Wireless Client List table or DHCP html page.
72
73 [Vulnerability Type]
74 =====
75 Stored Cross-site Scripting
76
77 How to Reproduce: (POC):
78 =====
```

```

79
80 1. Change the default hostname of wireless client by using following command (for Linux):
81   a. vi /etc/dhcp/dhclient.conf
82   b. Insert and change the value of hostname to xss payload "<script>alert('XSS')</script>"
83 2. Renew IP address by sending DHCP request to TP-Link device via following command:
84   a. vi /etc/network/interfaces
85   b. Add these lines:
86       auto wlan0
87       iface wlan0 inet dhcp
88   c. On Terminal run command: ifup wlan0
89 3. Login to the router web interface, navigate to DHCP settings or Wireless Client tab.
90 4. As soon as DHCP or Wireless client table is requested Xss payload executes and pops up alert box.
91
92 Mitigation
93 =====
94
95 -----
96 | Model          | Firmware Version                               | Mitigation Comments |
97 -----
98 | TL-WA801ND     | TL-WA801NDv5_US_0.9.1_3.16_up_boot[170905-rel56404] | Patched              |
99 | TL-WA801N      | TL-WA801Nv6_EU_0.9.1_3.16_up_boot[200116-rel61815] | Patched              |
100 | TL-WR802N      | TL-WR802Nv4_US_0.9.1_3.17_up_boot[200421-rel38950] | Patched              |
101 | Archer-C3150   | ArcherC3150(US)_V2_170926)                     | EOL Product          |
102 | TD-W9977       | TD-W9977v1_0.1.0_0.9.1_up_boot(161123)_2016-11-23_15.36.15 | EOL Product          |
103 -----
104
105 [Vendor of Product]
106 TP-LINK (https://www.tp-link.com)
107
108 Disclosure Timeline:
109 =====
110 24-July-2020 Discovered the vulnerability
111 11-Aug-2020 Responsibly disclosed vulnerability to vendor
112 15-Aug-2020 Vendor Acknowledged the disclosure
113 17-Nov-2020 Communicated with vendor after 90 days for updates
114 19-Nov-2020 Vendor asked for model and version details
115 20-Nov-2020 Provided the required details to vendor
116 25-Nov-2020 Vendor provided software build to verify the issue
117 9-Dec-2020 Issue not fixed in the provided software.
118 4-Jan-2021 Asked Updates on the status of the issue.
119 20-Jan-2021 Vendor provided software build to verify the issue.
120 20-Jan-2021 Issue found fixed in the provided software.
121 21-Jan-2021 Requested for CVE-ID assignment
122 25-March-2021 CVE-ID Assigned.
123
124 credits:
125 =====
126
127 * Smriti Gaba
128 * Security Researcher
129 * smritigaba548@gmail.com
130 * https://www.linkedin.com/in/smriti-gaba-658795135/
131
132 * Kaustubh Padwad
133 * Information Security Researcher
134 * kingkaustubh@me.com
135 * https://twitter.com/s3curityb3ast
136

```