

main

...

CVE-vulns / tenda_i22 / formwrlSSIDget / formWifiMacFilterGet.md

Haizhen Qi(祁海珍) add i22

History

0 contributors

46 lines (31 sloc) | 3.43 KB

...

Tenda i22 V1.0.0.3(4687) was discovered to contain a buffer overflow via the list parameter in the formwrlSSIDget function.

Description

Tenda Router i22 V1.0.0.3(4687) was discovered to contain a buffer overflow in the httpd module when handling /goform/wifiSSIDget request.

Firmware information

- Manufacturer's address: <https://www.tenda.com.cn/>
- Firmware download address : <https://www.tenda.com.cn/download/detail-2747.html>

Affected version

i22

i22 1200M 高密度带机100人吸顶AP [资料下载](#)
首页 / i22 / 资料下载




Vulnerability details

This vulnerability lies in the /goform/wifiSSIDget page, The details are shown below:

```
index_value = (char *)get_value_from_web(a1, "index", "0");
wl_radio_value = (char *)get_value_from_web(a1, "wl_radio", "0");
v109 = atoi(index_value);
if ( v109 < 0 || v109 > 7 )
    return printf("Bad index in %s).\n", "formwrlSSIDget");
if ( !strcmp(wl_radio_value, "0") )
{
    strcmp(index_value, "0");
    sprintf((char *)v106, "wl2g.ssid%s.", index_value);
    v2 = sub_343B0(v106, "enable", s);
    GetValue(v2, src);
    strcat(v97, "{\"ssidEnable\":\"");
    strcat(v97, src);
    strcat(v97, "\",");
}
```

POC

This POC can result in a Dos.

[illegible]

```
qemu: uncaught target signal 11 (Segmentation fault) - core dumped
Segmentation fault
```