

1.3.1 Displaying Diagnosis Screen

- (1) Press function key .
- (2) Press soft key [DGNOS], then a diagnosis screen is displayed.

1.3.2 Contents Displayed

Causes when the machine does not travel in spite of giving a command

| | | |
|----------------------|--------------|--|
| Diagnosis | <div>0</div> | <div>CNC internal state 1</div> |
| [Data type] | Bit | |
| NAME | | Internal state when "1" is displayed |
| INPOSITION CHECK | | In-position check is being done. |
| FEEDRATE OVERRIDE 0% | | Feedrate override is 0%. |
| JOG FEED OVERRIDE 0% | | Jog feedrate override is 0%. |
| INTER/START LOCK ON | | Interlock/start lock is on. |
| SPEED ARRIVAL ON | | The system is waiting for the speed arrival signal to turn on. |

| | |
|---------------------|--|
| WAIT REVOLUTION | The system is waiting for the spindle one-rotation signal in threading. |
| STOP POSITION OCDER | The system is waiting for the rotation of the position coder in spindle feed per revolution. |
| FEED STOP | A feed stop was made. |

| | | |
|---|----------|------------------------------|
| Diagnosis | 2 | Dwell execution state |
| When a dwell is being executed, "1" is displayed. | | |

| | | |
|--------------------|--|-----------------------------|
| Diagnosis | 8 | CNC internal state 2 |
| [Data type] | Bit | |
| NAME | Internal state when "1" is displayed | |
| FOREGROUND READING | Data is being input in the foreground. | |
| BACKGROUND READING | Data is being input in the background. | |

Reader/puncher interface output state

| | | |
|---|-----------|--|
| Diagnosis | 10 | Reader/puncher interface output state |
| When data is being output through the reader/puncher interface, "1" is indicated. | | |

State of TH alarm

| | | |
|--|-------------|---|
| Diagnosis | 30 | TH alarm character count (foreground edit) |
| [Data type] | 2-word axis | |
| The position where the TH alarm occurred in foreground input is indicated by the number of characters from the beginning of the block. | | |

| | | |
|--|-------------|--|
| Diagnosis | 31 | TH alarm character code (foreground edit) |
| [Data type] | 2-word axis | |
| The character code of the character at which the TH alarm occurred in foreground input is indicated. | | |

| | | |
|--|-------------|---|
| Diagnosis | 32 | TH alarm character count (background edit) |
| [Data type] | 2-word axis | |
| The position where the TH alarm occurred in background input is indicated by the number of characters from the beginning of the block. | | |

| | | |
|--|-------------|--|
| Diagnosis | 33 | TH alarm character code (background edit) |
| [Data type] | 2-word axis | |
| The character code of the character at which the TH alarm occurred in background input is indicated. | | |

Display language of the CNC screen

| | | |
|-------------|-----------|---|
| Diagnosis | 43 | Number of the current display language of the CNC screen |
| [Data type] | Byte | |

The number of the current display language of the CNC screen is indicated.
The correspondence between languages and numbers is show below.

| | | |
|---|---|----------------------------------|
| 0 | : | English |
| 1 | : | Japanese |
| 2 | : | German |
| 3 | : | French |
| 4 | : | Chinese (traditional characters) |
| 5 | : | Italian |
| 6 | : | Korean |
| 7 | : | Spanish |
| 8 | : | Dutch |

- 9 : Danish
- 10 : Portuguese
- 11 : Polish
- 12 : Hungarian
- 13 : Swedish
- 14 : Czech
- 15 : Chinese (simplified characters)
- 16 : Russian
- 17 : Turkish

Details of serial Pulsecoder

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|-----|----|-----|-----|-----|-----|-----|-----|
| Diagnosis | 200 | OVL | LV | OVC | HCA | HVA | DCA | FBA | OFA |

- #0 **OFA** Overflow alarm
- #1 **FBA** Disconnection alarm
- #2 **DCA** Discharge alarm
- #3 **HVA** Overvoltage alarm
- #4 **HCA** Abnormal current alarm
- #5 **OVC** Over current alarm
- #6 **LV** Insufficient voltage alarm
- #7 **OVL** Overload alarm

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|-----|-----|----|-----|----|----|----|----|
| Diagnosis | 201 | ALD | PCR | | EXP | | | | |

- #4 **EXP**
- #7 **ALD**

| | ALD | EXP | Description |
|---------------------|-----|-----|---|
| Overload alarm | 0 | - | Motor overheat |
| | 1 | - | Amplifier overheat |
| Disconnection alarm | 1 | 0 | Built-in Pulsecoder (hard) |
| | 1 | 1 | Disconnection of separated type Pulsecoder (hard) |
| | 0 | 0 | Disconnection of Pulsecoder (software) |

- #6 **PCR** The one-rotation signal of the position detector was caught before a manual reference position return is performed. Since the manual reference position return grid was established, a manual reference position return is enabled.

NOTE

This bit is valid only when the operation of the manual reference position return mode is started.

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|----|-----|-----|-----|-----|-----|-----|-----|
| Diagnosis | 202 | | CSA | BLA | PHA | RCA | BZA | CKA | SPH |

- #0 **SPH** Serial Pulsecoder or feedback cable is faulty.
Counting of feedback cable is erroneous.
- #1 **CKA** Serial Pulsecoder is faulty.
Internal block stopped.
- #2 **BZA** Battery voltage became 0.
Replace the battery and set the reference position.
- #3 **RCA** Serial Pulsecoder is faulty.
The speed was incorrectly counted.
- #4 **PHA** Serial Pulsecoder or feedback cable is erroneous.
Counting of feedback cable is erroneous.
- #5 **BLA** Battery voltage is low (warning)
- #6 **CSA** Hardware of serial Pulsecoder is abnormal

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|-----|-----|-----|-----|----|----|----|----|
| Diagnosis | 203 | DTE | CRC | STB | PRM | | | | |

#4 PRM A parameter failure was detected on the digital servo side. See the cause and measure described in diagnosis No. 352.

#5 STB Communication failure of serial Pulsecoder.
Transferred data is erroneous.

#6 CRC Communication failure of serial Pulsecoder.
Transferred data is erroneous.

#7 DTE Communication failure of serial Pulsecoder.
There is no response for communication.

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|----|-----|-----|-----|-----|----|----|----|
| Diagnosis | 204 | | OFS | MCC | LDA | PMS | | | |

#3 PMS Feedback is not correct due to faulty serial Pulsecoder C or feedback cable.

#4 LDA Serial Pulsecoder LED is abnormal

#5 MCC Contacts of MCC of servo amplifier is melted.

#6 OFS Abnormal current value result of A/D conversion of digital servo

Details of separate serial Pulsecoder alarms

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| Diagnosis | 205 | OHA | LDA | BLA | PHA | CMA | BZA | PMA | SPH |

#0 SPH A soft phase data error occurred in the separate Pulsecoder.

#1 PMA A pulse error occurred in the separate Pulsecoder.

#2 BZA The battery voltage for the separate Pulsecoder is zero.

#3 CMA A count error occurred in the separate Pulsecoder.

#4 PHA A phase data error occurred in the separate linear scale.

#5 BLA A low battery voltage occurred in the separate Pulsecoder.

#6 LDA An LED error occurred in the separate Pulsecoder.

#7 OHA Overheat occurred in the separate Pulsecoder.

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|-----|-----|-----|----|----|----|----|----|
| Diagnosis | 206 | DTE | CRC | STB | | | | | |

#5 STB A stop bit error occurred in the separate Pulsecoder.

#6 CRC A CRC error occurred in the separate Pulsecoder.

#7 DTE A data error occurred in the separate Pulsecoder.

Details of invalid servo parameter alarms (on the CNC side)

When servo alarm No. 417 is issued, and diagnosis No. 203#4 = 0, its cause is indicated.

When diagnosis No. 203#4 = 1, see diagnosis No. 352.

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|----|----|----|-----|-----|-----|----|-----|
| Diagnosis | 280 | | | | DIR | PLS | PLC | | MOT |

#0 MOT The motor type specified in parameter No. 2020 falls outside the predetermined range.

#2 PLC The number of velocity feedback pulses per motor revolution, specified in parameter No. 2023, is zero or less. The value is invalid.

#3 PLS The number of position feedback pulses per motor revolution, specified in parameter No. 2024, is zero or less. The value is invalid.

#4 DIR The wrong direction of rotation for the motor is specified in parameter No. 2022 (the value is other than 111 or -111).

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|----|----|----|----|----|----|----|-----|
| Diagnosis | 281 | | | | | | | | TDM |

#0 TDM Four-winding motor drive (bit 7 of parameter No. 2211) or two-winding motor drive (bit 6 of parameter No. 2211) is enabled when no option for tandem control is present.

Position error amountDiagnosis **300**

Position error of an axis in detection unit

$$\text{Position error} = \frac{\text{Feed rate [mm/min]} \times 100}{60 \times \text{servo loop gain [1/sec]}} \times \frac{1}{\text{Detection unit}}$$

Machine positionDiagnosis **301**

Distance from reference position of an axis in detection unit

Distance from the end of the deceleration dog to the first grid pointDiagnosis **302**

Distance from the end of the deceleration dog to the first grid point

[Data type] Real axis

[Unit of data] Machine unit

[Valid data range] 0 to ±99999999

NOTE

For the reference position setting without a dog, the distance from the beginning of the reference position setting without a dog to the first grid point is assumed.

Reference counterDiagnosis **304**

Reference counter amount in each axis

[Data type] 2-word axis

[Unit of data] Detection unit

[Valid data range] -99999999 to 99999999

Motor temperature informationDiagnosis **308**

Servo motor temperature (°C)

[Data type] Byte axis

[Unit of data] °C

[Valid data range] 0 to 255

The temperature of the coil of the servo motor is indicated. When the temperature reaches 140°C, a motor overheat alarm is issued.

Diagnosis **309**

Pulsecoder temperature (°C)

[Data type] Byte axis

[Unit of data] °C

[Valid data range] 0 to 255

The temperature of the printed circuit board in the Pulsecoder is indicated. When the temperature reaches 100°C (approximately 85°C for the temperature of atmosphere in the Pulsecoder), a motor overheat alarm is issued.

NOTE

1 Temperature information has the following error:

- 50°C to 160°C ±5°C
- 160°C to 180°C ±10°C

2 The temperature at which an overheat alarm is issued has an error of up to 5°C.

Cause that sets bit 4 (APZ) of parameter No. 1815 to 0

You can find the cause that sets bit 4 (APZ) of parameter No. 1815 to 0 by checking diagnosis Nos. 310 and 311.

Once diagnosis No. 310 or 311 is set to 1, this setting is kept unchanged until the zero point of the absolute position detector of the corresponding axis is set again. Possible causes that set APZ to 0 are as follows:

| | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 | |
|-----------|--|----|-----|-----|----|-----|-----|-----|-----|
| Diagnosis | 310 | | DTH | ALP | | BZ2 | BZ1 | PR2 | PR1 |
| #0 PR1 | One of the following parameters was changed: No.1815#0, No.1815#1, No.1815#6, No.1817#3, No.1820, No.1821, No.1822, No.1823, No.1850, No.1868, No.1869, No.1874, No.1875, No.1876, No.1883, No.1884, No.2022, No.2084, No.2085, No.2179 | | | | | | | | |
| #1 PR2 | Bit 1 (ATS) of parameter No. 8303 was changed. Alternatively, when bit 7 (SMA) of parameter No. 8302 was set to 1, APZ of the axis to be synchronized together was set to 0. | | | | | | | | |
| #2 BZ1 | A battery voltage of 0 V was detected. (Inductosyn) | | | | | | | | |
| #3 BZ2 | A battery voltage of 0 V was detected. (Separate position detector) | | | | | | | | |
| #5 ALP | The zero point was set by MDI when the α pulse coder had not rotate one or more turns. Alternatively, the CNC could not obtain a correct value from the absolute pulse coder. | | | | | | | | |
| #6 DTH | An axis detach operation was performed by the controlled-axis detach signal DTCH <G124> or by setting bit 7 (RMV) of parameter No. 0012. | | | | | | | | |

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|---|-----|-----|-----|-----|-----|-----|-----|
| Diagnosis | 311 | | DUA | XBZ | GSG | AL4 | AL3 | AL2 | AL1 |
| #0 | AL1 | An SV alarm (SV301 to SV305) was issued. | | | | | | | |
| #1 | AL2 | When bit 1 (CRF) of parameter No. 1819 was set to 1, alarm SV0445, “SOFT DISCONNECT ALARM”, SV0447, “HARD DISCONNECT(EXT)”, or SV0646, “ABNORMAL ANALOG SIGNAL(EXT)”, was detected. | | | | | | | |
| #2 | AL3 | A battery voltage of 0 V was detected. (Built-in serial Pulsecoder) | | | | | | | |
| #3 | AL4 | Alarm SV0367, “COUNT MISS(INT)”, was detected. | | | | | | | |
| #4 | GSG | The status of broken-wire alarm ignore signal NDCAL (G202) changed from 1 to 0. | | | | | | | |
| #5 | XBZ | A battery voltage of 0 V or alarm SV0382, “COUNT MISS(EXT)”, was detected. (Separate serial position detector) | | | | | | | |
| #6 | DUA | When bit 1 (CRF) of parameter No. 1819 was set to 1, alarm SV0421, “EXCESS ERROR(SEMI-FULL)”, was detected. | | | | | | | |

Details of invalid servo parameter setting alarms (on the servo side)

| | | | | | | | | | | | |
|-----------|-----|---|--|--|--|--|--|--|--|--|--|
| Diagnosis | 352 | Detail number for invalid servo parameter setting alarm | | | | | | | | | |
| | | Indicates information that can be used to identify the location (parameter) and cause of an invalid servo parameter setting alarm (servo alarm No. 417). | | | | | | | | | |
| | | This diagnosis information is valid when the following conditions are satisfied. | | | | | | | | | |
| | | <ul style="list-style-type: none">• Servo alarm No. 417 has occurred.• Bit 4 of diagnosis No. 203 (PRM) = 1 | | | | | | | | | |
| | | See the following table for the displayed detail numbers and the corresponding causes. For further detail information that could be used to take measures, refer to FANUC AC Servo Motor α is/ α i/ β is series Parameter Manual (B-65270EN). | | | | | | | | | |

• Detailed descriptions about invalid servo parameter setting alarms

| Detail number | Parameter No. | Cause | Action |
|---------------|---------------|---|---|
| 83 | 2019 | Parameter settings related to learning control are illegal → See Supplementary. | Change the parameter settings so that they fall in the applicable range. |

| Detail number | Parameter No. | Cause | Action |
|------------------------------|---------------|--|---|
| 0233 | 2023 | When initialization bit 0 is set to 1, the number of velocity pulses exceeds 13100. | Correct the number of velocity pulses so that it is within 13100. |
| 0234 | 2023 | When a DD motor is used, a value smaller than 512 is set as the number of velocity pulses. | Set 512 or a greater number as the number of velocity pulses, or disable the DD motor. Bit 0 of parameter No. 2300=0 |
| 0243 | 2024 | When initialization bit 0 is set to 1, the number of position pulses exceeds 13100. | Correct the number of position pulses so that it is within 13100. Use the position feedback pulse conversion coefficient (parameter No. 2185). |
| 0434 0435 | 2043 | The internal value of the velocity loop integral gain overflowed. | Decrease the value of the velocity loop integral gain parameter. |
| 0443 0444 0445 | 2044 | The internal value of the velocity loop proportional gain overflowed. | Use the function for changing the internal format of the velocity loop proportional gain (bit 6 of parameter No. 2200). Alternatively, decrease the parameter setting. |
| 0474 0475 | 2047 | The internal value of the observer parameter (POA1) overflowed. | Correct the setting to $(-1) \times (\text{desired value})/10$. |
| 0534 0535 | 2053 | The internal value of a parameter related to dead zone compensation overflowed. | Decrease the setting to the extent that the illegal servo parameter setting alarm is not caused. |
| 0544 0545 | 2054 | The internal value of a parameter related to dead zone compensation overflowed. | Decrease the setting to the extent that the illegal servo parameter setting alarm is not caused. |
| 0694 0695 0696 0699 | 2069 | The internal value of the velocity feed-forward coefficient overflowed. | Decrease the velocity feed-forward coefficient. |
| 0754 0755 | 2075 | The setting for this parameter has overflowed. | This parameter is not used at present. Set 0. |
| 0764 0765 | 2076 | The setting for this parameter has overflowed. | This parameter is not used at present. Set 0. |
| 0843 | 2084 | A positive value is not set as the flexible feed gear numerator. Alternatively, the following condition exists: $\text{Feed gear numerator} > \text{denominator} \times 16$ | Set a positive value as the flexible feed gear numerator. Alternatively, satisfy the following condition: $\text{Feed gear numerator} \leq \text{denominator} \times 16$ (except for phase A-/B-specific separate detector). |
| 0853 | 2085 | A positive value is not set as the flexible feed gear denominator. | Set a positive value as the flexible feed gear denominator. |
| 0883 | 2088 | For an axis with a serial type separate detector, a value exceeding 100 is set as the machine velocity feedback coefficient. | For an axis with a serial type separate detector, the upper limit of the machine velocity feedback coefficient is 100. Correct the coefficient so that it does not exceed 100. |
| 0884 0885 0886 | 2088 | The internal value of the machine velocity feedback coefficient overflowed. | Decrease the machine velocity feedback coefficient. Alternatively, use the vibration-damping control function that has an equivalent effect. |

| Detail number | Parameter No. | Cause | Action |
|------------------------------|----------------------|---|---|
| 0994 0995 0996 | 2099 | The internal value for N pulse suppression overflowed. | Disable the N pulse suppression function. Alternatively, decrease the parameter setting so that no overflow will occur. |
| 1033 | 2103 | The retract distance related to an abnormal load differs between the L and M axes (if the same-axis retract function is in use). | Set the same value for both the L and M axes. |
| 1123 | 2112 | Although a linear motor is used, the AMR conversion coefficient parameter is not input. | Set the AMR conversion coefficient. |
| 1182 | 2118 2078 2079 | The dual position feedback conversion coefficient has not been specified. | Specify the dual position feedback conversion coefficient. |
| 1284 1285 | 2128 | When a small value is set as the number of velocity pulses, the internal value of a parameter related to current control overflows. | Decrease the value in this parameter to the extent that the alarm is not caused. |
| 1294 1295 | 2129 | When a large value is set as the number of velocity pulses, the internal value of a parameter related to current control overflows. | When the value set in this parameter is resolved to the form $a \times 256 + b$, set a smaller value in a again. |
| 1393 | 2139 | The AMR offset setting value of a linear motor exceeds ± 45 . | Enlarge the AMR offset setting range (bit 0 of parameter N. 2270=1) to input a value within a range of ± 60 . |
| 1454 1455 1456 1459 | 2145 | Velocity feed-forward coefficient for cutting overflowed. | Decrease the velocity feed-forward coefficient. |
| 1493 | 2149 | A value greater than 6 is specified in this parameter. | Only 6 or less can be specified in this parameter. Change the setting to 6 or below 6. |
| 1503 | 2150 | A value equal to or greater than 10 is set. | Set a value less than 10. |
| 1786 | 2178 | Bit 6 of No. 2212 or bit 6 of No. 2213 is set to 1, and No. 2621=0 is set. | Set bit 6 of No. 2212 or bit 6 of No. 2213 to 0. |
| 1793 | 2179 | A negative value or a value greater than the setting of parameter No. 1821 is set. | Set a positive value less than the setting of parameter No. 1821. |
| 1853 | 2185 | A negative value or a value greater than the setting of parameter No. 2023 is set. | Set a positive value less than the setting of parameter No. 2023. |
| 2203 | 2220#0 | If pole detection is enabled (bit 7 of No. 2213=1) and a non-binary detector is enabled (bit 0 of No. 2220=1), an illegal servo parameter setting alarm is issued when any of the following is set: - AMR conversion coefficient 1 \leq 0 - AMR conversion coefficient 2 \leq 0 - AMR conversion coefficient 2 $>$ 512 (The settable range is 1 (2 poles) to 512 (1024 poles).) | Set the AMR conversion coefficients correctly. |
| 2243 | 2224#5 | This alarm is issued when a setting is made to neglect the invalid setting of the parameter for the feed-forward timing adjustment function (bit 5 of No. 2224=1) and a command for nano interpolation is issued. | Use either one. |

| Detail number | Parameter No. | Cause | Action |
|---------------|------------------------------------|---|---|
| 2632 | 2263 | When the lifting function against gravity is enabled (bit 7 of No. 2298=1) or the post-servo-off travel distance monitor function is enabled (bit 5 of No. 2278=1), the function for enabling the CNC software to post the detection unit to the servo software is not supported and the setting of the detection unit (No. 2263) is disabled. | Take one of the following actions: 1) Set a value in parameter No. 2263. 2) Disable the lifting function against gravity and the post-servo-off travel distance monitor function. 3) Use CNC software that supports the function for enabling the detection unit to be posted to the servo software. |
| 2780 | 2277#5,6,7 2278#0,2,4 24096 | When the first SDU unit is not used (No.24096=0), a setting is made to connect a detector (acceleration sensor, temperature detection circuit, or analog check interface unit) to the first SDU unit. | Check the FSSB setting (No.24096) or the detector setting (bits 0, 2, and 4 of No. 2278). |
| 2781 | 2277#5,6,7 2278#1,3,4 24097 | When the second SDU unit is not used (No.24097=0), a setting is made to connect a detector (acceleration sensor, temperature detection circuit, or analog check interface unit) to the second SDU unit. | Check the FSSB setting (No.24097) or the detector setting (bits 1, 3, and 4 of No. 2278). |
| 2782 | 2277#5,6,7 2278#0,4 24096 | Any of the following settings is made: • For use with the first SDU unit, both of an acceleration sensor and temperature detection circuit are enabled. • Settings are made to use the first SDU unit (No.24096>0), disable an acceleration sensor (bits 5, 6, 7 of No. 2277=0,0,0), and read acceleration data from the second unit (bit 1 of No. 2278=1). | Check the settings of the acceleration sensor and temperature detection circuit. |
| 2783 | 2277#5,6,7 2278#1,4 24097 | Any of the following settings is made: • For use with the second SDU unit, both of an acceleration sensor and temperature detection circuit are enabled. • Settings are made to use the second SDU unit (No.24097>0), disable an acceleration sensor (bits 5, 6, 7 of No. 2277=0,0,0), and read acceleration data from the second unit (bit 1 of No. 2278=1). | Check the settings of the acceleration sensor and temperature detection circuit. |
| 2784 | 1815#1 2277#5,6,7 2278#0,1,4 | At the time of full-closed system setting, a detector other than a separate position detector is connected (with the first/second SDU unit). | Modify the setting of the detector. |
| 2785 | 1815#1 2277#5,6,7 2278#0,4 | At the time of full-closed system setting, a detector other than a separate position detector is connected (with the first SDU unit). | Modify the setting of the detector. |
| 2786 | 1815#1 2277#5,6,7 2278#1,4 | At the time of full-closed system setting, a detector other than a separate position detector is connected (with the second SDU unit). | Modify the setting of the detector. |

| Detail number | Parameter No. | Cause | Action |
|-------------------------|--|---|--|
| 2787 | 2278#0,#1 | A setting is made to connect two temperature detection circuits. | Only one temperature detection circuit can be connected. Modify the setting so that data is read from one of the first and second SDU units. |
| 2788 | 1815#1 2277#5,6,7 2278#4 2278#0,1 24096 24097 | A setting is made to connect two temperature detection circuits. | Only one temperature detection circuit can be connected. Modify the setting so that data is read from one of the first and second SDU units. |
| 3002 | 2300#3,#7 | The αi CZ detection circuit and linear motor position detection circuit do not support overheat signal connection. | Replace the αi CZ detection circuit and linear motor position detection circuit with those circuits that support overheat signal connection. Alternatively, modify the setting so that the overheat signal is read from a DI signal (bit 3 of parameter No. 2300=0). |
| 3012 | 2301#2,#7 | <ul style="list-style-type: none"> When bit 2 of No. 2301=1 Hardware (PS, SV) that does not support DC link voltage information output is connected, but bit 2 of No. 2301 is set to 1. When bit 7 of No. 2301=1 The CNC software does not support the torque control setting range extension function. | <ul style="list-style-type: none"> When bit 2 of No. 2301=1 Set bit 2 of No. 2301 to 0. When bit 7 of No. 2301=1 Use CNC software that supports the function. |
| 3553 3603 | 2355 | The value 4 or a smaller number is set. | Set the value 5 or a greater number. |
| 3603 | 2113 2360 2363 2366 | The value 95 or smaller number is set. | Set the value 96 or a greater number. Alternatively, if no resonance elimination filter is used, set all of the center frequency, band width, and dumping value to 0. |
| 3603 3663 | 2366 | The value 4 or a smaller number is set. | Set the value 5 or a greater number. |
| 4553 | 2455 | A negative value is set. | Set the value 0 or a greater number. |
| 4563 | 2456 | A value not within 0 to 12 is set. | Set a value within 0 to 12. |
| 8213 | 1821 | A positive value is not set in the reference counter capacity parameter. | Set a positive value in this parameter. |
| 8254 8255 8256 | 1825 | A position gain of 0 is set, or the internal position gain value has overflowed. | <ul style="list-style-type: none"> Set a value other than 0 (when setting = 0). Use the function for automatic format change for position gain setting range. (Set bit 6 of parameter No. 2209 to 1.) |
| 9053 | 1815#1 24096 24097 | At the time of full-closed system setting, no separate detector interface unit is set. | Set a separate detector interface unit. |
| 10010 10016 10019 | 2200#0 | The internal value of a parameter used to detect runaway has overflowed. | Do not use the runaway detection function (specify bit 0 = 1). |
| 10033 | 2004 | Illegal control cycle setting This error occurs if automatic modification is carried out for the control cycle. | Correct this parameter related to interrupt cycle setting. |
| 10053 | 2018#0 | When a linear motor is used, the scale reverse connection bit is set. | When the linear motor is used, the scale reverse connection bit cannot be used. |

| Detail number | Parameter No. | Cause | Action |
|----------------|--------------------------|--|--|
| 10062 | 2209#4 | The amplifier used does not support the HC alarm prevention function. | When you use the current amplifier continuously, set the function bit shown to the left to 0. When using the HC alarm prevention function, use an appropriate amplifier that supports the function. |
| 10092 10093 | 2004 2013#0 2014#0 | Different control cycles are set within one servo CPU. | Set the same control cycle for axes controlled by one servo CPU. |
| | | When HRV4 is enabled, a detector that does not support HRV4 is used. | Replace the detector with a detector supporting HRV4. Alternatively, disable HRV4. |
| | | When HRV4 is enabled, a servo amplifier that does not support HRV4 is connected. | Replace the servo amplifier with a servo amplifier supporting HRV4. Alternatively, disable HRV4. |
| 10103 | 2004 2013#0 | HRV1 is set. | The Series 30i does not allow HRV1 setting. Set HRV2, HRV3 or HRV4. |
| 10113 | 2013#0 | Current cycle mismatch alarm. This alarm is issued if the specified current cycle does not match the actual setting. | An axis for which HRV3 is specified exists on the same optical cable. Review the placement of the amplifier, or disable HRV3. |
| 10123 | 2013#0 | Alarm for indicating the disability of HRV3 setting. This alarm is issued when the axis supports HRV3 but the other axis of the pair does not support HRV3. | Eliminate the cause of the disability in setting the other axis. Alternatively, cancel the HRV3 setting. |
| 10133 | 2013#0 2014#0 | When HRV4 is set, this alarm is issued if any of the following conditions is met. <ul style="list-style-type: none"> Servo software not supporting HRV4 is used. The same FSSB system includes axes with HRV4 setting and axes with HRV2 or HRV3 setting. The limitation in the number of axes is not observed. (In HRV4 control, one axis/DSP is set.) | Eliminate the causes listed on the left. Alternatively, cancel the HRV4 setting. |
| 10133 | 2013#0 2014#0 | This alarm is issued when HRV3 or HRV4 is set, but the amplifier does not support these control types. | HRV3 or HRV4 is unusable for the axis on which the alarm was issued. |
| 10202 | 2277#5,6,7 2278#0,2,4 | The ID of the detector connected to the first SDU unit differs from the parameter setting. | Check the detector-related parameter or the state of detector connection. |
| 10212 | 2277#5,6,7 2278#1,3,4 | The ID of the detector connected to the second SDU unit differs from the parameter setting. | Check the detector-related parameter or the state of detector connection. |

Supplementary: Details of an illegal learning control parameter

Set parameter No. 2115 to 0, and parameter No. 2151 to 6265 to change the value of DGN No. 353 to a binary number. You can find a detailed cause from the bit position of the obtained binary number at which 1 is set.

| Position | Cause |
|----------|--|
| B3 | The band-pass filter (No. 2512) is not in the range. |

| Position | Cause |
|----------|---|
| B4 | The profile number (No. 2511) is not in the range. |
| B5 | The specified data period (No. 251, 2519, 2521, 2523, or 2525) is not in the range. |
| B6 | The total number of profiles (No. 2510) is not in the range. |
| B7 | This alarm is issued when G05 starts during a memory clear operation. |
| B8 | This alarm is issued when the total number of profiles (No. 2510) is not 0, and the profile number (No. 2511) is 0. |
| B9 | This alarm is issued when the automatically-set thinning shift value exceeds the range because the specified data period is too long. |

| | | |
|-----------|-----|--|
| Diagnosis | 355 | Communication alarm ignore counter (separate type) |
| Diagnosis | 356 | Link processing counter (built-in type) |
| Diagnosis | 357 | Link processing counter (separate type) |

The number of times a communication error occurred during serial communication with the detector is indicated.

Data transmitted during communication is guaranteed unless another alarm occurs. However, if the counter value indicated in this diagnosis information increases in a short period, there is a high probability that serial communication is disturbed by noise. So, take sufficient measures to prevent noise.

* For details, refer to a relevant manual on FANUC SERVO MOTOR *ai* series.

| | | |
|-----------|-----|-------------------------|
| Diagnosis | 358 | V ready-off information |
|-----------|-----|-------------------------|

This information is provided to analyze the cause of the V ready-off alarm (servo alarm SV0401).

Convert the indicated value to a binary representation, and check bits 5 to 14 of the binary representation.

When amplifier excitation is turned on, these bits are set to 1 sequentially from the lowest bit, which is bit 5. If the amplifier is activated normally, bits 5 to 14 are all set to 1.

Therefore, check the bits sequentially from the lowest bit to find the first bit that is set to 0. This bit indicates that the corresponding processing could not be completed and so the V ready-off alarm was caused.

| #15 | #14 | #13 | #12 | #11 | #10 | #09 | #08 |
|-----|------|------|------|-----|------|-----|-----|
| | SRDY | DRDY | INTL | | CRDY | | |

| #07 | #06 | #05 | #04 | #03 | #02 | #01 | #00 |
|-----|------|-----|-----|-----|-----|-----|-----|
| | *ESP | | | | | | |

| | | |
|-----|------|---|
| #06 | *ESP | Converter emergency stop state released |
| #10 | CRDY | Converter ready |
| #12 | INTL | DB relay released |
| #13 | DRDY | Amplifier ready (amplifier) |
| #14 | SRDY | Amplifier ready (software) |

* For details, refer to a relevant manual on FANUC SERVO MOTOR *ai* series.

| | | |
|-----------|-----|---|
| Diagnosis | 359 | Communication alarm neglect counter (built-in type) |
|-----------|-----|---|

The diagnosis information is the same as that of diagnosis No. 355.

See the descriptions in diagnoses No.355 to 357.

Diagnosis **360**

Cumulative value of specified pulses (NC)

[Data type] 2-word

[Unit of data] Detection unit

[Valid data range] -99999999 to 99999999

Cumulative value of move commands distributed from the CNC since power-on is indicated.

Diagnosis **361**

Compensation pulses (NC)

[Data type] 2-word

[Unit of data] Detection unit

[Valid data range] -99999999 to 99999999

Cumulative value of compensation pulses (backlash compensation, pitch error compensation, and so on) distributed from the CNC since power-on is indicated.

Diagnosis **362**

Cumulative value of specified pulses (SV)

[Data type] 2-word

[Unit of data] Detection unit

[Valid data range] -99999999 to 99999999

Cumulative value of move pulses and compensation pulses received by the servo system since power-on is indicated.

Diagnosis **363**

Cumulative feedback (SV)

[Data type] 2-word

[Unit of data] Detection unit

[Valid data range] -99999999 to 99999999

Cumulative value of positional feedback pulses the servo system received from the pulse coder since power-on is indicated.

Diagnosis data related to the Inductosyn absolute position detector

Diagnosis **380**

Difference between the absolute position of the motor and offset data

[Data type] 2-word axis

[Unit of data] Detection unit

$$\frac{M (\text{absolute position of the motor}) - S (\text{offset data})}{\lambda (\text{pitch interval})}$$

The remainder resulting from the division is displayed.

Diagnosis **381**

Offset data from the Inductosyn

[Data type] 2-word axis

[Unit of data] Detection unit

Off set data is displayed when CNC calculates the machine position.

Diagnosis data related to the serial spindles

Diagnosis **400**

| #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----|----|----|----|----|----|----|----|
| LNK | | | | | | | |

#7 LNK Communication with the spindle control side has been established.

Diagnosis **403**

Temperature of spindle motor

[Data type] Byte spindle

[Unit of data] °C

[Valid data range] 0 to 255

The temperature of the winding of the spindle motor is indicated.

This information can be used to determine the overheat alarm of the spindle.

(The temperature that causes an overheat alarm varies from motor to motor.)

NOTE

- 1 Temperature information has the following error:
 - 50°C to 160°C $\pm 5^{\circ}\text{C}$
 - 160°C to 180°C $\pm 10^{\circ}\text{C}$
- 2 The indicated temperature and the temperature causing an overheat alarm have the following error:
 - For lower than 160°C 5°C maximum
 - For 160 to 180°C 10°C maximum

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|-----|----|-----|-----|-----|-----|-----|-----|
| Diagnosis | 408 | SSA | | SCA | CME | CER | SNE | FRE | CRE |

#0 **CRE** A CRC error occurred (warning).

#1 **FRE** A framing error occurred (warning).

#2 **SNE** The sender or receiver is not correct.

#3 **CER** An abnormality occurred during reception.

#4 **CME** No response was returned during automatic scanning.

#5 **SCA** A communication alarm was issued on the spindle amplifier side.

#7 **SSA** A system alarm was issued on the spindle amplifier side.

(The above conditions are major causes of alarm SP0749. These conditions are caused mainly by noise, a broken wire, a momentary failure of power, and so on.)

| | | |
|-----------|-----|-----------------------------------|
| Diagnosis | 410 | Spindle load meter indication [%] |
|-----------|-----|-----------------------------------|

[Data type] Word spindle

[Unit of data] %

| | | |
|-----------|-----|---|
| Diagnosis | 411 | Spindle load meter indication [min^{-1}] |
|-----------|-----|---|

[Data type] Word spindle

[Unit of data] min^{-1}

| | | |
|-----------|-----|---|
| Diagnosis | 417 | Spindle position coder feedback information |
|-----------|-----|---|

[Data type] 2-word spindle

[Unit of data] Detection unit

| | | |
|-----------|-----|---|
| Diagnosis | 418 | Positional deviation of spindle in position loop mode |
|-----------|-----|---|

[Data type] 2-word spindle

[Unit of data] Detection unit

| | | |
|-----------|-----|-------------------------------|
| Diagnosis | 425 | Spindle synchronization error |
|-----------|-----|-------------------------------|

[Data type] 2-word spindle

[Unit of data] Detection unit

When the spindles are in synchronization mode, the absolute value of the synchronization error when each spindle is set as the slave axis is indicated.

| | | |
|-----------|-----|-----------------------|
| Diagnosis | 445 | Spindle position data |
|-----------|-----|-----------------------|

[Data type] Word spindle

[Unit of data] Pulse

[Valid data range] 0 to 4095

For the serial spindle, position coder signal pulse data from the one-rotation signal is indicated as the position data of the spindle.

This data is valid when bit 1 of parameter No. 3117 is set to 1.

To display spindle position data, spindle orientation must be performed once.

Diagnosis data related to rigid tapping

| | | |
|-----------|-----|---|
| Diagnosis | 450 | Spindle position error during rigid tapping |
|-----------|-----|---|

[Data type] 2-word spindle

[Unit of data] Detection unit

| | | |
|-----------|-----|---|
| Diagnosis | 451 | Spindle distribution during rigid tapping |
|-----------|-----|---|

[Data type] 2-word spindle

[Unit of data] Detection unit

| | | |
|-----------|-----|--|
| Diagnosis | 452 | Difference in error amount between spindle and tapping axis during rigid tapping (momentary value) |
|-----------|-----|--|

[Data type] 2-word spindle

[Unit of data] %

| | | |
|-----------|-----|--|
| Diagnosis | 453 | Difference in error amount between spindle and tapping axis during rigid tapping (maximum value) |
|-----------|-----|--|

[Data type] 2-word spindle

[Unit of data] %

| | | |
|-----------|-----|--|
| Diagnosis | 454 | Accumulated spindle distribution during rigid tapping (cumulative value) |
|-----------|-----|--|

[Data type] 2-word spindle

[Unit of data] Detection unit

| | | |
|-----------|-----|---|
| Diagnosis | 455 | Difference in spindle-converted move command during rigid tapping (momentary value) |
|-----------|-----|---|

[Data type] 2-word spindle

[Unit of data] Detection unit

| | | |
|-----------|-----|---|
| Diagnosis | 456 | Difference in spindle-converted positional deviation during rigid tapping (momentary value) |
|-----------|-----|---|

[Data type] 2-word spindle

[Unit of data] Detection unit

| | | |
|-----------|-----|---|
| Diagnosis | 457 | Width of synchronization error during rigid tapping (maximum value) |
|-----------|-----|---|

[Data type] 2-word spindle

[Unit of data] Detection unit

| | | |
|-----------|-----|--|
| Diagnosis | 458 | Tapping axis distribution amount during rigid tapping (cumulative value) |
|-----------|-----|--|

[Data type] 2-word spindle

[Unit of data] Detection unit

| | | |
|-----------|-----|--|
| Diagnosis | 459 | Selected spindle number during rigid tapping |
|-----------|-----|--|

[Data type] 2-word path

| | | |
|-----------|-----|---|
| Diagnosis | 460 | Difference in spindle-converted move command during rigid tapping (maximum value) |
|-----------|-----|---|

[Data type] 2-word spindle

[Unit of data] Detection unit

| | | |
|-----------|-----|---|
| Diagnosis | 461 | Difference in spindle-converted machine position during rigid tapping (momentary value) |
|-----------|-----|---|

[Data type] 2-word spindle

[Unit of data] Detection unit

| | | |
|-----------|-----|---|
| Diagnosis | 462 | Difference in spindle-converted machine position during rigid tapping (maximum value) |
|-----------|-----|---|

[Data type] 2-word spindle

[Unit of data] Detection unit

Diagnosis data related to polygon machining with two spindles

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|-----|-----|----|-----|-----|-----|-----|-----|
| Diagnosis | 470 | SC0 | LGE | | SCF | PSC | PEN | PSU | SPL |

#0 **SPL** Polygon synchronization with two spindles under way

#1 **PSU** Polygon synchronization mode with two spindles being activated

NOTE

If only PSU becomes 1, but no change occurs, and the program stops in a block containing a G51.2 command, the speed of an spindle does not reach the targeted polygon synchronization speed, for example, because bit 7 (PST) of parameter No. 7603 = 0 keeps the spindle from being energized.

#2 **PEN** Polygon synchronization mode with two spindles released

#3 **PSC** Spindle speed being changed during polygon synchronization mode with two spindles

#4 **SCF** Spindle speed changed during polygon synchronization mode with two spindles

#6 **LGE** The loop gain is different between the spindles during polygon synchronization mode with two spindles.

NOTE

When the speed is changed during polygon synchronization mode, LGE is set to 1 if the spindle synchronization control loop gain used by the serial spindle control unit is different between the master spindle and polygon synchronization axis.

Diagnosis display indicates the loop gain because this function requires that both spindles be controlled with the same loop gain. However, no alarm is issued even if the loop gain is different between the spindles.

(For the serial spindle control unit, the parameters used are changed according to the state of the CTH1 and CTH2 signals.)

#7 **SC0** Actual speed command is 0 during polygon synchronization mode with two spindles.

NOTE

Signal SC0 is not a value specified by the program. It is set to 1 under any of the following conditions:

1. When the S command value is adjusted according to the signals related to spindle control, SSTP<Gn029.6> and SOV0-SOV7<Gn030> and the signal related to multi-spindle control <Gn027>, the result is 0.
2. The S command value is smaller than the spindle control resolution (the result of multiplying the S command value by a value of 4095/(maximum spindle speed) is less than 1).
The S command value is specified by SIND control <Gn032, Gn033>, and it is 0.

If SC0 = 1, the spindle speed becomes 0 and bit 0 of diagnosis display No. 471 becomes 1. In this case, the polygon synchronization rotation ratio is impractical, but alarm PS5018 does not occur, because it is regarded as the result of the command.

If the following status is indicated during the polygon synchronization mode, there are no abnormalities.

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|----|----|----|----|----|----|----|----|
| Diagnosis | 470 | 0 | 0 | 0 | 1 | - | 0 | 0 | 1 |

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|-----|-----|-----|-----|-----|-----|----|-----|
| Diagnosis | 471 | NPQ | PQE | QMS | NSP | SUO | QCL | | SCU |

Polygon turning with two spindles

Indication of causes for alarms PS5018, PS0314, and PS0218

#0 to #3 Causes for alarm PS5018

Alarm PS5018 is cleared by a reset, but the indication of its causes remains until the causes are cleared or the polygon synchronization mode is released.

SCU The specified speed is too low during polygon synchronization mode with two spindles.
(The unit of speed calculated internally becomes 0.)

NOTE

SCU becomes 1 also when the specified spindle speed is 0 (diagnosis display No. 470#7 = 1). In this case, however, alarm PS5018 is not issued (because the command is 0). When diagnosis display No. 470#7 = 0 and diagnosis display No. 471#0 = 1, alarm PS5018 occurs. Normally this does not occur with speed at which the spindle can rotate.

QCL The polygon synchronization axis is clamped.

NOTE

QCL becomes 1, when the polygon synchronization axis receives a command with a polygon synchronization speed that is higher than the value specified in parameter No. 7621 and is clamped at that speed.

SUO The specified speed is too high during the polygon synchronization mode with two spindles.
(It is clamped to the upper limit calculated internally.)

NOTE

SUO occurs, if a result of (speed specified for the master spindle)/(value specified at P) is higher than 59998. In other words, the master spindle must rotate at a speed lower than 59998 min^{-1} assuming $P = 1$.

#4 Causes for alarm PS0314

When alarm PS0314 occurs, the polygon synchronization mode is released, but the indication of its causes remains until the alarm PS0314 is cleared by a reset.

NSP A spindle necessary for control is not connected.
(For example, there is not a serial spindle or the second spindle.)
The axis settings for polygon turning are not correct.

#5 to #7 Causes for alarm PS0218

When alarm PS0218 occurs, the polygon synchronization mode is released, but the indication of its causes remains until the alarm PS0218 is cleared by a reset.

QMS When bit 1 (QDR) of parameter No. 7603 = 1, a negative value is specified at Q.

PQE In a G51.2, either P or Q has a value out of the specifiable range.
Or, P and Q are not specified as a pair.

NPQ In a G51.2, R is specified when P and Q have not been specified at all, or none of P, Q, and R has been specified.

Indication of values specified during the polygon synchronization mode with two spindles

| | | |
|-----------|-----|--|
| Diagnosis | 474 | Rotation ratio for the master axis during the polygon synchronization mode with two spindles (P command value) |
|-----------|-----|--|

This indication is the current rotation ratio (P command value) of the master axis during the polygon synchronization mode with two spindles.

| | | |
|-----------|-----|---|
| Diagnosis | 475 | Rotation ratio for the polygon synchronization axis during the polygon synchronization mode with two spindles (Q command value) |
|-----------|-----|---|

This indication is the current rotation ratio (Q command value) of the polygon synchronization axis during the polygon synchronization mode with two spindles.

Diagnosis data related to the small-hole peck drilling cycle

| | | |
|-----------|-----|---|
| Diagnosis | 520 | Total number of times a retraction operation has been performed during drilling since G83 was specified |
|-----------|-----|---|

| | | |
|-----------|-----|--|
| Diagnosis | 521 | Total number of times a retraction operation has been performed in response to the reception of the overload torque detection signal during drilling since G83 was specified |
|-----------|-----|--|

The total numbers of times output in Nos.520 and 521 are cleared to zero by a G83 command issued after the small-hole peck drilling cycle mode is entered.

| | | |
|-----------|-----|--|
| Diagnosis | 522 | Coordinate value of the drilling axis at which retraction operation starts (least input increment) |
|-----------|-----|--|

| | | |
|-----------|-----|--|
| Diagnosis | 523 | Difference between the coordinate value of the drilling axis at which the previous retraction operation started and the coordinate value of the drilling axis at which the current retraction operation starts (least input increment: previous value minus current value) |
|-----------|-----|--|

Diagnosis data related to the dual position feedback function

| | | |
|-----------|-----|-------------------|
| Diagnosis | 550 | Closed loop error |
|-----------|-----|-------------------|

[Data type] 2-word axis

[Unit of data] Detection unit

[Valid data range] -99999999 to +99999999

| | | |
|-----------|-----|------------------------|
| Diagnosis | 551 | Semi-closed loop error |
|-----------|-----|------------------------|

[Data type] 2-word axis

[Unit of data] Detection unit

[Valid data range] -99999999 to +99999999

| | | |
|-----------|-----|--|
| Diagnosis | 552 | Error between semi-closed and closed loops |
|-----------|-----|--|

[Data type] Word axis

[Unit of data] Detection unit

[Valid data range] -32768 to +32767

Diagnosis **553**


Amount of dual position compensation

[Data type] 2-word axis

[Unit of data] Detection unit

[Valid data range] -999999999 to +999999999

The data items displayed on the diagnosis screen are obtained at the following positions:



Automatic alteration of tool position compensation

Diagnosis **0560**

Manual tool compensation state number

[Data type] Byte

[Unit of data] None

[Valid data range] 0 to 255

When incomplete operation was performed in manual tool compensation, one of the following numbers is used for notification.

- 0 : Manual tool compensation was completed normally.
- 1 : The data of T code command falls outside the allowable range.
- 2 : The offset value falls outside the range.
- 3 : The offset number falls outside the range.
- 4 : Automatic operation or axis movement is being performed in the CNC.
- 5 : The CNC is in the tool-nose radius compensation mode.
- 6 : The CNC is in a mode other than the JOG mode, HNDL (INC) mode, and REF mode.
- 7 : A CNC parameter is illegal.
- 8 : The CNC is in the 3-dimensional cutter compensation mode or tool center point control mode.

Data for adjusting the compensation of the start position of thread cutting when the spindle speed is changed

| | | |
|-----------|-----|---|
| Diagnosis | 670 | Delay in acceleration/deceleration after interpolation that is calculated in the NC |
| Diagnosis | 671 | Servo delay calculated in the NC |
| Diagnosis | 672 | Delay in one-rotation signal detection that is calculated in the NC |

[Data type] 2-word path

[Unit of data] Metric input: 0.00001mm

Inch input : 0.000001inch

[Valid data range] 0 to 99,999,999

Compensation amounts calculated by the NC are indicated. Use them to set adjustment parameters Nos. 1446 to 1449.

State of high-speed HRV current control

| | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|-----|----|----|----|----|-------|-----|-----|
| Diagnosis | 700 | | | | | DCLNK | HOK | HON |

[Data type] Bit axis

The state of high-speed HRV current control is displayed.

#0 HON The motor is controlled in the high-speed HRV current control mode.

#1 HOK This bit is set to 1 when high-speed HRV current control is enabled.

High-speed HRV current control is enabled when the following conditions are satisfied:

- Bit 0 (HR3) of parameter No. 2013 is set to 1.
- Bit 0 (HR4) of parameter No. 2014 is set to 1.
- Servo software, servo modules, and servo amplifiers suitable for high-speed HRV current control are used.
- When a separate detector interface unit is used, the separate detector interface unit is suitable for high-speed HRV current control.

#2 DCLNK This bit is set to 1 when voltage information can be output to the diagnosis screen.

Thermal growth compensation along tool vector

| | | |
|-----------|-----|--|
| Diagnosis | 705 | Thermal growth compensation amount for each axis |
|-----------|-----|--|

[Data type] Word axis

[Unit of data] Detection unit

[Valid data range] -32768 to +32767

The compensation amount for each axis in thermal growth compensation along the tool vector is indicated.

Spindle error and warning states

| | | |
|-----------|-----|---------------------|
| Diagnosis | 710 | Spindle error state |
|-----------|-----|---------------------|

[Data type] Word spindle

| | | |
|-----------|-----|-----------------------|
| Diagnosis | 712 | Spindle warning state |
|-----------|-----|-----------------------|

[Data type] Word spindle

When an error (yellow LED ON + error number indication) or a warning occurs in a Spindle Amplifier (SP), the number is indicated on the diagnosis screen.

If neither error nor warning occurs, 0 is indicated.

For spindle errors, refer to "FANUC SERVO MOTOR α i series Maintenance Manual" (B-65285EN).

For warnings, see Subsection 10.1.4, "Spindle Warning Interface" in this manual.

OVC level

| | | |
|-----------|-----|-----------|
| Diagnosis | 750 | OVC level |
|-----------|-----|-----------|

[Data type] Word axis

[Unit of data] %

The proportion of soft thermal (OVC) in the alarm issuance level is indicated.

Linear inclination compensation function

| | | |
|-----------|-----|---|
| Diagnosis | 751 | Each axis linear inclination compensation |
|-----------|-----|---|

[Data type] Word axis

[Unit of data] Detection unit

[Valid data range] -32768 to +32767

Compensation of linear inclination compensation for each axis is indicated.

DC link voltage information

| | | |
|-----------|-----|-----------------------------|
| Diagnosis | 752 | DC link voltage information |
|-----------|-----|-----------------------------|

[Data type] Word axis

[Unit of data] Vrms

[Valid data range] 0 to 452 (200 Vrms input amplifier)

0 to 905 (400 Vrms input amplifier)

DC link voltage information is indicated.

Servo motor

| | | |
|-----------|-----|-----------------------|
| Diagnosis | 760 | R phase current value |
|-----------|-----|-----------------------|

[Data type] Word axis

[Unit of data] Value 6554 is equivalent to the maximum amplifier current.

[Valid data range] -6554 to +6554

The actual R phase current value of the servo motor is indicated.

| | | |
|-----------|-----|-------------------------|
| Diagnosis | 761 | Effective current value |
|-----------|-----|-------------------------|

[Data type] Word axis

[Unit of data] Value 8027 is equivalent to the maximum amplifier current.

[Valid data range] -8027 to +8027

The effective current value of the servo motor is indicated.

| | | |
|-----------|-----|------------------|
| Diagnosis | 762 | Activating phase |
|-----------|-----|------------------|

[Data type] Word axis

[Unit of data] Value 256 is equivalent to 360 degrees.

[Valid data range] 0 to 255

The activating phase (electrical angle) of the servo motor is indicated.

Reason why a start cannot be performed

| | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|------|----|----|----|----|----|-----|-----|
| Diagnosis | 1006 | | | | | | ALM | *SP |

[Data type] Bit

The reason why a start cannot be performed is displayed.

#0 *SP The feed hold signal (*SP) is 0.

#1 ALM An alarm occurs.

Automatic data backup

| | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|------|-----|-----|----|-----|-----|-----|-----|
| Diagnosis | 1016 | ANG | ACM | | DT3 | DT2 | DT1 | AEX |

[Data type] Bit

The execution state of backup is indicated.

#0 AEX Automatic data backup is being performed.

- #1 **DT1** Data 1 was updated in the previous backup.
- #2 **DT2** Data 2 was updated in the previous backup.
- #3 **DT3** Data 3 was updated in the previous backup.
- #6 **ACM** Automatic data backup was performed.
- #7 **ANG** An error occurred in automatic data backup.

Fan rotation speed

| | | |
|-----------|------|---------------------|
| Diagnosis | 1002 | FAN1 rotation speed |
| Diagnosis | 1003 | FAN2 rotation speed |
| Diagnosis | 1490 | FAN3 rotation speed |
| Diagnosis | 1491 | FAN4 rotation speed |

[Data type] 2-word

[Unit of data] 1/min

FAN1, FAN2

The rotation speed of the fans in the CNC controller are indicated.

FAN3, FAN4

The rotation speed of the fans in the stand-alone CNC with 15" LCD display are indicated.

If there is no applicable fan, 0 is indicated.

Custom macro / execution macro / auxiliary macro

| | | |
|-----------|------|---|
| Diagnosis | 1493 | Number of blocks in the macro statements executed by a custom macro/execution macro |
|-----------|------|---|

[Data type] 2-word

[Unit of data] Block

Displays the number of blocks in the macro statements executed by a custom macro/execution macro per 1024 ms.

It provides an indication of the actual processing speed of macro statements.

| | | |
|-----------|------|--|
| Diagnosis | 1494 | Number of blocks in executed by an auxiliary macro |
|-----------|------|--|

[Data type] 2-word

[Unit of data] Block

Displays the number of blocks executed by an auxiliary macro per 1024 ms.

It provides an indication of the actual processing speed of auxiliary macros.

Spindle revolution number history function

| | | |
|-----------|------|-----------------------------------|
| Diagnosis | 1520 | Spindle total revolution number 1 |
|-----------|------|-----------------------------------|

| | | |
|-----------|------|-----------------------------------|
| Diagnosis | 1521 | Spindle total revolution number 2 |
|-----------|------|-----------------------------------|

[Data type] 2-word spindle

[Unit of data] 1000 min⁻¹

[Valid data range] 0 to 999999999

The number of revolutions of the spindle is counted and the total number of revolutions is indicated.

Built-in 3D interference check

| | |
|------|--|
| 1900 | Built-in 3D interference check processing time |
|------|--|

[Data type] Word

[Unit of data] msec

[Description] Displays the current processing time required for 3D interference check.

| | |
|------|---|
| 1901 | Additional width for Built-in 3D interference check |
|------|---|

[Data type] Real
 [Unit of data] mm, inch (machine unit)
 [Description] Displays the current additional width to be considered for 3D interference check.
 The display unit is the same as the unit set for the reference axis (parameter No. 1031).

Detector battery exhaustion

| | | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
|-----------|------|----|----|-----|-----|-----|----|----|----|
| Diagnosis | 3019 | | | EXP | INP | ABP | | | |

[Data type] Bit axis
 If a detector battery low alarm is issued, the cause can be checked.

- #3 **ABP** The battery of the A/B phase is low.
 #4 **INP** The battery of the serial pulse coder (built-in position detector) is low.
 #5 **EXP** The battery of the separate detector of serial type is low.

Diagnosis data related to axis synchronous control

| | | |
|-----------|------|------------------------------|
| Diagnosis | 3500 | Synchronization error amount |
|-----------|------|------------------------------|

[Data type] 2-word axis
 [Unit of data] Detection unit
 [Valid data range] -99999999 to +99999999
 The difference in position (synchronization error amount) between the master axis and slave axis is indicated. This data is indicated for the slave axis.

| | | |
|-----------|------|--|
| Diagnosis | 3501 | Synchronization error compensation value |
|-----------|------|--|

[Data type] 2-word axis
 [Unit of data] Detection unit
 [Valid data range] -99999999 to +99999999
 Cumulative value of compensation pulses (synchronization error compensation value) output to the slave axis is indicated. This data is indicated for the slave axis.

Diagnosis data related to synchronous/composite control

| | | |
|-----------|------|--|
| Diagnosis | 3502 | Indication of synchronization error amount for each axis |
|-----------|------|--|

[Data type] 2-word axis
 [Unit of data] Detection unit
 [Valid data range] -99999999 to +99999999
 When synchronization deviation is detected (bit 1 (SERx) of parameter No. 8162 is set to 1), the positional deviation difference of the slave axis from the master axis is indicated.
 The positional deviation difference is:
 (Positional deviation of master axis) \pm (positional deviation of slave axis)
 ↑
 { +when mirror image is applied to synchronization command
 { -when mirror image is not applied to synchronization command

Details of invalid FSSB setting alarms

| | | |
|-----------|------|-------------------|
| Diagnosis | 3510 | FSSB alarm number |
|-----------|------|-------------------|

[Data type] Word
 Information is output for identifying the location (parameter) and cause of an FSSB-related alarm which has been issued. For the displayed detail numbers and corresponding causes and actions, see the table below. When multiple FSSB alarm numbers appear, address the alarms in ascending order of the FSSB alarm number.

| Detail alarm No. | Parameter number | Cause | Action |
|-------------------|-----------------------------------|--|---|
| 120 451 452 | - | The FSSB internal status did not change to open. | Check the connection between the CNC and each amplifier. Alternatively, the servo card may be faulty. |
| 140 450 | 24000 to 24095 | The ATR value is inconsistent with the connected slave (servo, spindle, or separate detector). | Set the ATR value corresponding to the connected slave. |
| 271 | 3717 24000 to 24095 | The spindle amplifier number corresponding to the ATR value setting is not set. | Make the spindle amplifier number consistent with the ATR value setting. |
| 272 | 24000 to 24031 24064 to 24095 | The fifth to eighth separate detector is set for the first FSSB line (third FSSB line). | Do not set the fifth to eighth separate detectors for the first FSSB line (third FSSB line). |
| 273 | 24032 to 24063 | The first to fourth (ninth to twelfth) separate detector is set for the second FSSB line. | Do not set the first to fourth (ninth to twelfth) separate detectors for the second FSSB line. |
| 276 | 24000 to 24095 | The setting for a separate detector is made more than once. | Make the setting for each separate detector only once in the servo card. |
| 290 | 24000 to 24095 | The maximum number of slaves per FSSB line is exceeded for an FSSB line of servo HRV2 control. | Reduce the number of slaves to 32 (maximum number of slaves per FSSB line of servo HRV2 control) or less. |
| 291 | 24000 to 24095 | The maximum number of slaves per FSSB line is exceeded for an FSSB line of servo HRV3 control. | Reduce the number of slaves to 15 (maximum number of slaves per FSSB line of servo HRV3 control) or less. |
| 293 | 24000 to 24095 | The maximum number of slaves per FSSB line is exceeded for an FSSB line of servo HRV4 control. | Reduce the number of slaves to 7 (maximum number of slaves per FSSB line of servo HRV4 control) or less. |
| 310 | 1023 24104 to 24199 | The servo axis number corresponding to the ATR value setting of a separate detector is not set for parameter No. 1023. | Set the value corresponding to the ATR value setting for parameter No. 1023. |
| 313 | 1023 14476#5 24104 to 24199 | The servo axis number corresponding to the ATR value setting of a separate detector is not set for parameter No. 1023. | Set the value corresponding to the ATR value setting for parameter No. 1023. |
| 314 | 1023 14476#5 24104 to 24199 | The ATR value setting of a separate detector is invalid. | Correct the settings of parameters Nos. 24104 to 24199. |
| 383 | - | Manual setting 1 cannot be performed when a separate detector is used. | Disconnect the separate detector. Alternatively, perform manual setting or automatic setting. |
| 453 | - | Servo initialization has not completed successfully. | An optical cable may be faulty or the connection between the amplifier and another module may be incorrect. |
| 454 | - | Alarm No. 550 to 556 of diagnostic data No. 3511 occurred. | Check diagnostic data No. 3511. |
| 460 | 24000 to 24095 | The ATR value of a spindle or separate detector is set for a slave which is not connected. | Set the ATR value corresponding to the connected slave. |
| 471 | 24000 to 24095 | Although a separate detector is connected, the separate detector setting is not made. | Set the value for the separate detector in the corresponding parameter. |
| 480 | 24000 to 24095 | In ATR value setting, a servo axis number exceeds 80. | Make settings so that any servo axis number does not exceed 80. |

Diagnosis **3511****FSSB alarm number**

[Data type] Word axis

Information is output for identifying the location (parameter) and cause of an FSSB-related alarm which has been issued. For the displayed detail numbers and corresponding causes and actions, see the table below. When multiple FSSB alarm numbers appear, address the alarms in ascending order of the FSSB alarm number.

| Detail alarm No. | Parameter number | Cause | Action |
|------------------|--------------------------------------|---|---|
| 210 | 24096 to 24103 | Although a separate detector is not set, a value is set in parameter No. 24096 to 24103. | Set parameter Nos. 24096 to 24103 to all 0. |
| 220 | 1023 | An unavailable servo axis number is set. | Change the servo axis number. |
| 221 | 1023 | A servo axis number is set more than once. | Change the servo axis number. |
| 250 | 24096 to 24103 | For a specific servo axis, two or more separate detectors are used and the paired separate detectors are two of the first, third, fifth, and seventh units or the second, fourth, sixth, and eighth units. | To use two separate detectors for a specific servo axis, one separate detector must have an odd number and the other must have an even number. Three or more separate detectors cannot be used. |
| 270 | 1023 24000 to 24095 | <ul style="list-style-type: none"> The servo axis number corresponding to the ATR value setting is not set for parameter No. 1023. An unavailable servo axis number is set. A servo axis number is set more than once. | Check the conditions on the left. |
| 292 | 1023 2013#0 | For an FSSB line of servo HRV3 control, only the following servo axis numbers can be used: (1 + 8n, 2 + 8n, 3 + 8n, 4 + 8n (n = 0, 1, ..., 9)) | For the FSSB line of servo HRV3 control, set the servo axis numbers on the left. |
| 294 | 1023 2014#0 | For an FSSB line of servo HRV4 control, only the following servo axis numbers can be used: (1+8n(n=0,1,...,9)) | For the FSSB line of servo HRV4 control, set the servo axis numbers on the left. |
| 311 | 24096 to 24103 | A connector number is invalid. | Specify a value between 0 and 8. |
| 314 | 24096 to 24103 | A connector number is set more than once. | Make setting so that each connector number is used only once for one separate detector. |
| 350 | 2013#0 2014#0 | Different current loops (HRV) are used for FSSB lines. | Set the same current loop (HRV) for the FSSB lines. |
| 360 | 1023 2013#0 2014#0 | Different current loops (HRV) are set for the first and second FSSB lines and parameter No. 1023 setting is invalid. | Set servo axis numbers so that each set of (1 to 6), (9 to 14), (17 to 22), (25 to 30), (33 to 38), and (41 to 46) is set for the same FSSB line. |
| 370 | 1902#0 1902#1 2013#0 2014#0 | When servo HRV3 or HRV4 control is set, manual setting 1 cannot be performed. | To set servo HRV3 or HRV4 control, perform manual setting or automatic setting. |
| 380 | 1023 | When a servo axis number is skipped, manual setting 1 cannot be performed. | Set servo axis numbers without skipping any number. |

| Detail alarm No. | Parameter number | Cause | Action |
|-------------------|------------------------|--|--|
| 382 | 1023 | An attempt was made to perform manual setting 1 though the maximum number of controlled axes per FSSB line is exceeded. | Reduce the number of connected servo axes to the maximum number of controlled axes or less. |
| 470 | 24000 to 24095 | An ATR value is set more than once. | Set each ATR value only once. |
| 481 | 1023 24000 to 24095 | A servo axis number is inconsistent with the ATR value setting or the servo motor having a servo axis number is not connected. | Check whether the value set in parameter No. 1023 is consistent with ATR value setting and whether the servo motor corresponding to each servo axis number is connected. |
| 520 | 2165 | At power-on, amplifier ID information could not be read. | Check the connection between the CNC and each amplifier. Alternatively, an amplifier may be faulty. |
| 550 | 1023 24000 to 24095 | The ATR value setting is inconsistent with the servo axis number setting. | Make the value set in parameter No. 1023 consistent with the ATR value setting. |
| 551 | 24000 to 24095 | The number of ATR value settings exceeds the number of slaves connected to the CNC. | Make as many settings as the number of slaves connected to the CNC. |
| 552 | 1023 | An unavailable servo axis number is set. | Change the servo axis number. |
| 553 | 1023 | A servo axis number is set more than once. | Change the servo axis number. |
| 554 | 24096 to 24103 | A value is set in parameter No. 24096 to 24103 though no separate detector is connected. | Set parameters Nos. 24096 to 24103 to all 0. |
| 555 557 558 | 2165 | The maximum current of an amplifier (parameter No. 2165) differs from that of a motor. | Set the maximum current of the amplifier (parameter No. 2165) to that of the motor. |
| 1023 | 1023 | An invalid servo axis number is set. | Set a correct servo axis number. |

Diagnosis **3513****FSSB alarm number**

[Data type] Word spindle

Information is output for identifying the location (parameter) and cause of an FSSB-related alarm which has been issued.

For the displayed detail numbers and corresponding causes and actions, see the table below. When multiple FSSB alarm numbers appear, address the alarms in ascending order of the FSSB alarm number.

| Detail alarm No. | Parameter number | Cause | Action |
|------------------|------------------------|---|--|
| 271 | 3717 24000 to 24095 | An ATR value is set more than once. | Make each spindle amplifier consistent with the ATR value setting. |
| 381 | 3717 | When a spindle amplifier number is skipped, manual setting 1 cannot be performed. | Set spindle amplifier numbers without skipping any number. |

Diagnosis data related to linear scale with absolute address reference marks

Diagnosis **3545****Linear scale with absolute address reference marks: Measurement point 1**Diagnosis **3546****Linear scale with absolute address reference marks: Measurement point 2**Diagnosis **3547****Linear scale with absolute address reference marks: Measurement point 3**

| | | |
|-----------|------|---|
| Diagnosis | 3548 | Linear scale with absolute address reference marks: Measurement point 4 |
|-----------|------|---|

[Data type] 2-word axis

[Unit of data] Detection unit

[Valid data range] -999999999 to 999999999

| | | |
|-----------|------|--|
| Diagnosis | 3549 | Linear scale with absolute address reference marks: Status display |
|-----------|------|--|

| | | |
|-----------|------|---|
| Diagnosis | 3550 | Linear scale with absolute address reference marks: Scale value |
|-----------|------|---|

[Data type] 2-word axis

[Unit of data] Detection unit

[Valid data range] -999999999 to 999999999

| | | |
|-----------|------|--|
| Diagnosis | 3551 | Linear scale with absolute address reference marks: Scale value (High) |
|-----------|------|--|

[Data type] 2-word axis

[Unit of data] Detection unit

[Valid data range] -999 to 999

Linear scale with absolute address reference marks

Scale value = Diagnosis No.3551 × 1,000,000,000 + Diagnosis No.3550

Wrong operation prevention function

| | | | | | | | | |
|-----------|------|----|----|----|----|----|----|-----|
| | #7 | #6 | #5 | #4 | #3 | #2 | #1 | #0 |
| Diagnosis | 3570 | | | | | | | MSC |

[Data type] Bit path

#0 MSC Memory operation is stopped due to the reconfirming of midway block start.
In a multipath system, the bit is set to 1 on only the path on which the cursor is position in the middle of the program.

Diagnosis data related to flexible path axis assignment

| | | |
|-----------|------|---|
| Diagnosis | 4000 | Reason number of alarm in flexible path axis assignment |
|-----------|------|---|

The cause of the alarm that may be issued in flexible path axis assignment is displayed.

- 1 The number of axes in the path is 0.
- 2 The number of axes in the path is larger than its allowable maximum value.
- 3 The removal command has no ID specification.
- 4 The removal command has a duplicate ID specification.
- 5 An axis specified with removal command P does not exist in the path or has been removed from the path.
- 6 An axis specified with removal command Q does not exist in the path or has been removed from the path.
- 7 An axis specified with removal command R does not exist in the path or has been removed from the path.
- 8 An axis specified with the removal command does not exist in the path or has been removed from the path.
- 9 The removal command has no axis specification or has an ID specification.
- 10 In flexible path axis assignment, the ID specification is incorrect.
- 11 The assignment command has no ID specification.
- 12 The assignment command has a duplicate ID specification.
- 13 The assignment command has a duplicate axis arrangement specification.
- 14 The path specified with the arrangement command has no target axis or the arrangement command has no ID specification.
- 15 The path specified with the arrangement command has an invalid axis assignment specification.

- 16 An axis whose removal a command is waiting for belongs to the path where the command was issued.
- 18 An axis whose removal an exchange command is waiting for belongs to the path paired with the path where the exchange command was issued.
- 19 An axis for which an assignment command was issued is yet to be removed. (Bit 1 of parameter No. 11561 is set to 1.)
- 20 An axis for which an assignment command is issued in a path belongs to another path where a removal command for it has been issued.
- 21 An axis for which an assignment command was issued is yet to be removed.
- 22 The assignment command has no axis specification or has an ID specification.
- 24 An axis at which an exchange command is targeted belongs to the path where the exchange command was issued.
- 25 The exchange command has no ID specification.
- 26 The exchange command has a duplicate ID specification.
- 27 In a system having 3 or more paths, an exchange command has no L specification.
- 28 An axis targeted by an exchange command was not found in the source path (path where this exchange command was issued).
- 29 An axis specified in the exchange command is being processed by another command or has already been removed.
- 30 An axis targeted by an exchange command was not found in the destination path (path paired with a path where another exchange command was issued for the axis).
- 32 The exchange command has no target axis.
- 33 The exchange command has a conflict.
- 34 The exchange command has no axis specification or has an ID specification.
- 35 A cycle other than flexible path axis assignment is under way.
- 36 An attempt was made to perform flexible path axis assignment during the SV rotation control mode.
- 37 An attempt was made to perform flexible path axis assignment during the polygon turning mode.
- 38 An attempt was made to perform flexible path axis assignment during PMC axis control.
- 39 An attempt was made to perform flexible path axis assignment during the chopping mode.
- 40 An attempt was made to perform flexible path axis assignment during mirror imaging.
- 41 An attempt was made to perform flexible path axis assignment during 3-dimensional coordinate conversion.
- 42 An attempt was made to perform flexible path axis assignment during coordinate system rotation.
- 43 An attempt was made to perform flexible path axis assignment during scaling.
- 44 An attempt was made to perform flexible path axis assignment during axis synchronization.
- 45 An attempt was made to perform flexible path axis assignment for an axis already removed.
- 46 An attempt was made to perform flexible path axis assignment for an axis under composite control.
- 47 An attempt was made to perform flexible path axis assignment for an axis under synchronous control.
- 48 An attempt was made to perform flexible path axis assignment for an axis under superimposed control.
- 55 An attempt was made to perform flexible path axis assignment simultaneously with an axis move command.
- 56 An attempt was made to perform flexible path axis assignment during tool compensation.

| | | |
|--|------|---|
| Diagnosis | 4001 | Belonging path of axis in flexible path axis assignment |
| A path (specified by parameter No. 981) to which an axis specified for flexible path axis assignment belongs is displayed. | | |
| 0 : Source path | | |
| 1 to 10 : Destination path (because of assignment or exchange) | | |
| -1 to -10 : Already removed | | |

Pulse superimposed function

| | | |
|----------------|--|---|
| Diagnosis | 4110 | Number of accumulated pulses specified by the pulse superimposed function |
| [Data type] | Floating point number axis | |
| [Unit of data] | Input unit | |
| | The number of accumulated pulses specified by pulse superimposition is indicated. The number multiplied by the travel distance magnification is indicated. | |

| | | |
|----------------|--|---|
| Diagnosis | 4110 | Number of accumulated pulses specified by the pulse superimposed function |
| [Data type] | Floating point number axis | |
| [Unit of data] | Input unit | |
| | When the maximum cutting feedrate is to be exceeded by the specified pulse superimposition, the pulses exceeding the allowable number (set in parameter No. 7117) are discarded. | |
| | This diagnosis data indicates the number of accumulated pulses that are actually discarded in pulse superimposition. | |

$|\text{Number of pulses specified by pulse superimposition} \times \text{travel distance magnification}| > |\text{maximum cutting feedrate} + \text{allowable number of pulses}|$

→ Number of discarded pulses

$= \text{Number of pulses specified by pulse superimposition} \times \text{travel distance magnification} - \text{maximum cutting feedrate} - \text{allowable number of pulses}$

$|\text{Number of pulses specified by pulse superimposition} \times \text{travel distance magnification}| < |\text{maximum cutting feedrate} + \text{allowable number of pulses}|$

→ Number of discarded pulses = 0

NOTE

When the pulse superimposed function is disabled (bit 0 (PSI) of parameter No. 10350 is set to 0), reset operation clears the indicated number of accumulated/discarded pulses.

Total of the current actual power consumption of all servo axes/spindles

| | | |
|----------------|--------|---|
| Diagnosis | 4900 | Total of current actual power consumption of all axes |
| [Data type] | 2-word | |
| [Unit of data] | W | |

NOTE

The actual power consumption is obtained by subtracting the regenerative power from the power consumption. If the regenerative power exceeds the power consumption, the actual power consumption becomes a negative value.

Current actual power consumption of each servo axis

| | | |
|-------------|-------------|---|
| Diagnosis | 4901 | Current actual power consumption of each servo axis |
| [Data type] | 2-word axis | |

[Unit of data] W

NOTE

This power consumption becomes a negative value during regeneration of power such as reduction in servo axis speed.

Current actual power consumption of each spindle

Diagnosis 4902

Current actual power consumption of each spindle

[Data type] 2-word spindle

[Unit of data] W

NOTE

This power consumption becomes a negative value during regeneration of power such as reduction in spindle speed.

Accumulated value of the total power consumption of all servo axes/spindles

Diagnosis 4910

Accumulated value of the total actual power consumption of all axes

Diagnosis 4911

Accumulated value of the total power consumption of all axes

Diagnosis 4912

Accumulated value of the total regenerated power of all axes

[Data type] 2-word

[Unit of data] 0.001kWh

NOTE

These values are accumulated after power-on.

Accumulated value of power consumption of each servo axis

Diagnosis 4920

Accumulated value of the actual power consumption of each servo axis

Diagnosis 4921

Accumulated value of the power consumption of each servo axis

Diagnosis 4922

Accumulated value of the regenerated power of each servo axis

[Data type] 2-word axis

[Unit of data] 0.001kWh

NOTE

These values are accumulated after power-on.

Accumulated value of power consumption of each spindle

Diagnosis 4930

Accumulated value of the actual power consumption of each spindle

Diagnosis 4931

Accumulated value of the power consumption of each spindle

Diagnosis 4932

Accumulated value of the regenerated power of each spindle

[Data type] 2-word spindle

[Unit of data] W

NOTE

These values are accumulated after power-on.

Interpolation stateDiagnosis **5000****Smoothing mode**

[Data type] Bit

NAME Interpolation state when "1" is indicated

Smooth IPL on When smooth interpolation G5.1 Q2 is specified and all conditions are satisfied, "1" is indicated. The G5.1 Q2 command turns on AI contour control at the same time. Therefore, the AI contour control mode signal AICC<Fn062.0> turns on and AICC1/AICC2 blinks in the state display at the lower right of the screen.

SMOOTHING ON When nano smoothing G5.1 Q3 is specified and all conditions are satisfied, "1" is indicated. The G5.1 Q3 command turns on AI contour control at the same time. Therefore, the AI contour control mode signal AICC<Fn062.0> turns on and AICC1/AICC2 blinks in the state display at the lower right of the screen.

3-dimensional machine position compensationDiagnosis **5302****Compensation amount of 3-dimensional machine position compensation**

[Data type] 2-word axis

[Unit of data] Detection unit

The compensation value of 3-dimensional machine position compensation is indicated.

Diagnosis data related to automatic phase synchronization for flexible synchronous controlDiagnosis **5600****Error of automatic phase synchronization (group A)**Diagnosis **5601****Error of automatic phase synchronization (group B)**Diagnosis **5602****Error of automatic phase synchronization (group C)**Diagnosis **5603****Error of automatic phase synchronization (group D)**

[Data type] Real path

[Unit of data] mm, inch, deg (machine unit)

Error between master axis and slave axis after executing automatic phase Synchronization for flexible synchronous control is displayed.

This data is displayed in the path of slave axis in inter-path flexible synchronous control.

Diagnosis **5604****Maximum error of Automatic Phase Synchronization (group A)**Diagnosis **5605****Maximum error of Automatic Phase Synchronization (group B)**Diagnosis **5606****Maximum error of Automatic Phase Synchronization (group C)**Diagnosis **5607****Maximum error of Automatic Phase Synchronization (group D)**

[Data type] Real path

[Unit of data] mm, inch, deg (machine unit)

Maximum error between master axis and slave axis after executing automatic phase synchronization for flexible synchronous control is displayed.

This data is displayed in the path of slave axis in inter-path flexible synchronous control.

This data is cleared when automatic operation is started in auto mode.

This data is cleared when flexible synchronous control is started in manual mode.