



Department of Electronic and Telecommunication Engineering  
University of Moratuwa

EN2160 – Preliminary Design Report  
Morse Code Encoder Decoder


THILAKARATHNE D.L.J.

200650U


This report is submitted as partial fulfilment of the module EN2160 - Electronic Design Realization  
16 June 2023

# Schematic and Solid work design of the implemented design


## Schematic



## Solid work design



According to the draft analysis, this cannot be injection moulded.



### Problems identified by you considering the course content delivered by Prof. Jayasinghe

#### Schematic

- The annotations do not adhere to the expected professional standards as mentioned by Prof. Jayasinghe. Specifically, they are not arranged in a sequential manner from left to right and top to bottom as required.
- The placement of inputs and outputs is incorrect. Prof. Jayasinghe recommended that inputs be positioned on the right side, while outputs should be positioned on the left side.
- The schematic is hard to read and comprehend. It should be simplified. The example schematic design provided by Prof. Jayasinghe is a proper reference to how a professional schematic should be.

#### Solid work design

- I was previously unaware of the intricacies involved in injection moulding and the manufacturing process of a product. However, thanks to the invaluable teachings of Prof. Jayasinghe, I have gained a newfound understanding. Upon examining the draft analysis, I have come to the realization that the enclosure of my product is unsuitable for injection moulding. Notably, the yellow-coloured areas depicted in the images present challenges as they cannot be effectively moulded, particularly the intricate lettering.

### Problems/Improvements identified/proposed by members of your group



- One suggestion was made to increase the volume of the buzzer. The resistance value of the resistor which connects to the buzzer was then reduced.
- Another suggestion was made to increase the button debounce time. Since that typically causes errors. That was adjusted as required.

### Problems/Improvements identified/proposed by users


- One user suggested to make the ports reside a little bit inwards. (Not to make them pop out of the enclosure.) That was adjusted as required.

### Schematic and Solid work design of the improved design

Schematic – Simplified to 2 pages. Corrected all the mistakes.



## Solid work design



Draft analysis – There are no yellow-coloured regions now

