




ECE 802, Electric Motor Control

Synchronous Machines

Synchronous Machines (Chapter 5)



voltage equations (stator)

$$v_{as} = r_s i_{as} + p \lambda_{as}$$

$$v_{bs} = r_s i_{bs} + p \lambda_{bs}$$

$$v_{cs} = r_s i_{cs} + p \lambda_{cs}$$

compress equations

$$\mathbf{v}_{abcs} = \mathbf{r}_s \mathbf{i}_{abcs} + p \boldsymbol{\lambda}_{abcs}$$

voltage equations (rotor)

$$v_{kq1} = r_{rkq1} i_{kq1} + p \lambda_{kq1}$$


$$v_{kq2} = r_{rkq2} i_{kq2} + p \lambda_{kq2}$$

$$v_{fd} = r_{fd} i_{fd} + p \lambda_{fd}$$

$$v_{kd} = r_{rkd} i_{kd} + p \lambda_{kd}$$

compress equations

$$\mathbf{v}_{qdr} = \mathbf{r}_r \mathbf{i}_{qdr} + p \boldsymbol{\lambda}_{qdr}$$



Flux Linkage Equations

$$\begin{bmatrix} \lambda_{abcs} \\ \lambda_{qdr} \end{bmatrix} = \begin{bmatrix} \mathbf{L}_s & \mathbf{L}_{sr} \\ (\mathbf{L}_{sr})^T & \mathbf{L}_r \end{bmatrix} \begin{bmatrix} \mathbf{i}_{abcs} \\ \mathbf{i}_{qdr} \end{bmatrix}$$

$$\mathbf{L}_s = \begin{bmatrix} L_{ls} + L_A - L_B \cos 2\theta_r & -\frac{1}{2}L_A - L_B \cos 2\left(\theta_r - \frac{\pi}{3}\right) & -\frac{1}{2}L_A - L_B \cos 2\left(\theta_r + \frac{\pi}{3}\right) \\ -\frac{1}{2}L_A - L_B \cos 2\left(\theta_r - \frac{\pi}{3}\right) & L_{ls} + L_A - L_B \cos 2\left(\theta_r - \frac{2\pi}{3}\right) & -\frac{1}{2}L_A - L_B \cos 2(\theta_r + \pi) \\ -\frac{1}{2}L_A - L_B \cos 2\left(\theta_r + \frac{\pi}{3}\right) & -\frac{1}{2}L_A - L_B \cos 2(\theta_r + \pi) & L_{ls} + L_A - L_B \cos 2\left(\theta_r + \frac{2\pi}{3}\right) \end{bmatrix}$$

Stator-to-Rotor Inductance Matrix

$$\mathbf{L}_{sr} = \begin{bmatrix} L_{skq1} \cos \theta_r & L_{skq2} \cos \theta_r & L_{sfd} \sin \theta_r & L_{skd} \sin \theta_r \\ L_{skq1} \cos \left(\theta_r - \frac{2\pi}{3} \right) & L_{skq2} \cos \left(\theta_r - \frac{2\pi}{3} \right) & L_{sfd} \sin \left(\theta_r - \frac{2\pi}{3} \right) & L_{skd} \sin \left(\theta_r - \frac{2\pi}{3} \right) \\ L_{skq1} \cos \left(\theta_r + \frac{2\pi}{3} \right) & L_{skq2} \cos \left(\theta_r + \frac{2\pi}{3} \right) & L_{sfd} \sin \left(\theta_r + \frac{2\pi}{3} \right) & L_{skd} \sin \left(\theta_r + \frac{2\pi}{3} \right) \end{bmatrix}$$

define inductances

$$L_{mq} = \frac{3}{2} (L_A - L_B)$$

$$L_{md} = \frac{3}{2} (L_A + L_B)$$

using chapter 1 procedures, magnetizing inductance can be written in terms of L_{mq} and L_{md} as

$$L_{skq1} = \left(\frac{N_{kq1}}{N_s} \right) \left(\frac{2}{3} \right) L_{mq}$$

$$L_{sfd} = \left(\frac{N_{fd}}{N_s} \right) \left(\frac{2}{3} \right) L_{md}$$

$$L_{skq2} = \left(\frac{N_{kq2}}{N_s} \right) \left(\frac{2}{3} \right) L_{mq}$$

$$L_{skd} = \left(\frac{N_{kd}}{N_s} \right) \left(\frac{2}{3} \right) L_{md}$$

Rotor Inductance Matrix

$$\mathbf{L}_r = \begin{bmatrix} L_{lkq1} + L_{mkq1} & L_{kq1kq2} & 0 & 0 \\ L_{kq1kq2} & L_{lkq2} + L_{mkq2} & 0 & 0 \\ 0 & 0 & L_{lfd} + L_{mfd} & L_{fdkd} \\ 0 & 0 & L_{fdkd} & L_{lkd} + L_{mkd} \end{bmatrix}$$

$$L_{mkq1} = \left(\frac{N_{kq1}}{N_s} \right)^2 \left(\frac{2}{3} \right) L_{mq}$$

$$L_{mfd} = \left(\frac{N_{fd}}{N_s} \right)^2 \left(\frac{2}{3} \right) L_{md}$$

$$L_{kq1kq2} = \left(\frac{N_{kq2}}{N_{kq1}} \right) L_{mkq1} = \left(\frac{N_{kq1}}{N_{kq2}} \right) L_{mkq2}$$

$$L_{fdkd} = \left(\frac{N_{kd}}{N_{fd}} \right) L_{mfd} = \left(\frac{N_{fd}}{N_{kd}} \right) L_{mkd}$$

$$L_{mkq2} = \left(\frac{N_{kq2}}{N_s} \right)^2 \left(\frac{2}{3} \right) L_{mq}$$

$$L_{mkd} = \left(\frac{N_{kd}}{N_s} \right)^2 \left(\frac{2}{3} \right) L_{md}$$

Refer Rotor to Stator

define new rotor variables

$$v'_j = \left(\frac{N_s}{N_j} \right) v_j \quad \lambda'_j = \left(\frac{N_s}{N_j} \right) \lambda_j \quad i'_j = \left(\frac{2}{3} \right) \left(\frac{N_j}{N_s} \right) i_j$$

where j can be used as $kq1$, $kq2$, fd , or kd

$$v_{fd}^r = r_{fd} i_{fd}^r + p \lambda_{fd}^r \quad i_{fd}^r = \frac{3}{2} \frac{N_s}{N_j} i_{fd}'^r$$

$$r'_{fd} = \frac{3}{2} \left(\frac{N_s}{N_{fd}} \right)^2 r_{fd}$$

Refer Voltage Equations

rotor equations

$$\mathbf{r}'_r = \begin{bmatrix} r'_{kq1} & 0 & 0 & 0 \\ 0 & r'_{kq2} & 0 & 0 \\ 0 & 0 & r'_{fd} & 0 \\ 0 & 0 & 0 & r'_{kd} \end{bmatrix} \quad r'_j = \left(\frac{3}{2}\right) \left(\frac{N_s}{N_j}\right)^2 r_j$$

stator equations

$$\mathbf{v}_{abcs} = r_s \mathbf{i}_{abcs} + p \boldsymbol{\lambda}_{abcs}$$

Refer Stator Flux Linkage Equations

$$\mathbf{L}'_{sr} = \begin{bmatrix} L_{mq} \cos \theta_r & L_{mq} \cos \theta_r & L_{md} \sin \theta_r & L_{md} \sin \theta_r \\ L_{mq} \cos \left(\theta_r - \frac{2\pi}{3} \right) & L_{mq} \cos \left(\theta_r - \frac{2\pi}{3} \right) & L_{md} \sin \left(\theta_r - \frac{2\pi}{3} \right) & L_{md} \sin \left(\theta_r - \frac{2\pi}{3} \right) \\ L_{mq} \cos \left(\theta_r + \frac{2\pi}{3} \right) & L_{mq} \cos \left(\theta_r + \frac{2\pi}{3} \right) & L_{md} \sin \left(\theta_r + \frac{2\pi}{3} \right) & L_{md} \sin \left(\theta_r + \frac{2\pi}{3} \right) \end{bmatrix}$$

Note: all magnetizing flux linkages are now in terms of L_{mq} and L_{md}

Refer Rotor Flux Linkages

$$\left(\frac{N_s}{N_j}\right)\lambda_{qdr} = \lambda'_{qdr} = \left(\frac{N_s}{N_j}\right)(\mathbf{L}_{sr})^T \mathbf{i}_{abcs} + \left(\frac{3}{2}\right)\left(\frac{N_s}{N_j}\right)^2 \mathbf{L}_r \mathbf{i}'_{qdr} = \left(\frac{2}{3}\right)(\mathbf{L}'_{sr})^T \mathbf{i}_{abcs} + \mathbf{L}'_r \mathbf{i}'_{qdr}$$

$$\mathbf{L}'_r = \begin{bmatrix} L'_{lkq1} + L_{mq} & L_{mq} & 0 & 0 \\ L_{mq} & L'_{lkq2} + L_{mq} & 0 & 0 \\ 0 & 0 & L'_{lfd} + L_{md} & L_{md} \\ 0 & 0 & L_{md} & L'_{lkd} + L_{md} \end{bmatrix}$$

where $L'_{lj} = \left(\frac{3}{2}\right)\left(\frac{N_s}{N_j}\right)^2 L_{lj}$

finally, we have

$$\begin{bmatrix} \lambda_{abcs} \\ \lambda'_{qdr} \end{bmatrix} = \begin{bmatrix} \mathbf{L}_s & \mathbf{L}'_{sr} \\ \frac{2}{3}(\mathbf{L}'_{sr})^T & \mathbf{L}'_r \end{bmatrix} \begin{bmatrix} \mathbf{i}_{abcs} \\ \mathbf{i}'_{qdr} \end{bmatrix}$$

Field Energy


$$W_f = \frac{1}{2} (\mathbf{i}_{abcs})^T (\mathbf{L}_s - L_{ls} \mathbf{I}) \mathbf{i}_{abcs} (\mathbf{i}_{abcs})^T \mathbf{L}'_{sr} \mathbf{i}'_{qdr} + \frac{1}{2} (\frac{3}{2}) (\mathbf{i}'_{qdr})^T (\mathbf{L}'_r - \mathbf{L}'_{lr} \mathbf{I}) \mathbf{i}'_{qdr}$$

where $\mathbf{L}'_{lr} = \begin{bmatrix} L'_{lkq1} & 0 & 0 & 0 \\ 0 & L'_{lkq2} & 0 & 0 \\ 0 & 0 & L'_{lfd} & 0 \\ 0 & 0 & 0 & L'_{lkd} \end{bmatrix}$

note: for a P pole machine,

$$\theta_r = \frac{P}{2} \theta_{rm}$$

also note positive torque
opposes rotation in chapter 5



Torque Equation

$$W_c = W_f$$

$$\frac{\partial W_c}{\partial \theta_{rm}} = \frac{\partial W_c}{\frac{2}{P} \partial \theta_r} = \frac{P}{2} \frac{\partial W_c}{\partial \theta_r}$$

$$T_e = \left(\frac{P}{2} \right) \left\{ \begin{aligned} & \frac{(L_{md} - L_{mq})}{3} \left[\left(i_{as}^2 - \frac{1}{2} i_{bs}^2 - \frac{1}{2} i_{cs}^2 - i_{as} i_{bs} - i_{as} i_{cs} + 2 i_{bs} i_{cs} \right) \sin(2\theta_r) \right. \\ & \quad \left. + \frac{\sqrt{3}}{2} (i_{bs}^2 + i_{cs}^2 - 2 i_{as} i_{bs} + 2 i_{as} i_{cs}) \cos(2\theta_r) \right] \\ & + L_{mq} (i'_{kq1} + i'_{kq2}) \left[\left(i_{as} - \frac{1}{2} i_{bs} - \frac{1}{2} i_{cs} \right) \sin(\theta_r) - \frac{\sqrt{3}}{2} (i_{bs} - i_{cs}) \cos(\theta_r) \right] \\ & + L_{md} (i'_{fd} + i'_{kd}) \left[\left(i_{as} - \frac{1}{2} i_{bs} - \frac{1}{2} i_{cs} \right) \cos(\theta_r) + \frac{\sqrt{3}}{2} (i_{bs} - i_{cs}) \sin(\theta_r) \right] \end{aligned} \right\}$$

Rotor Reference Frame Model

- Inductances do not vary with θ_r
- Inductance matrices are sparse
- There is a constant dc operating point
(model linearization and classical
control theory apply)

Transform to Rotor Reference Frame (Park's Equations)

stator voltage equation

$$\mathbf{v}_{abcs} = r_s \mathbf{i}_{abcs} + p \boldsymbol{\lambda}_{abcs}$$

$$K_s^r \mathbf{v}_{abcs} = r_s K_s^r \mathbf{i}_{abcs} + K_s^r p \boldsymbol{\lambda}_{abcs}$$

$$K_s^r = \frac{2}{3} \begin{bmatrix} \cos(\theta_r) & \cos(\theta_r - \frac{2\pi}{3}) & \cos(\theta_r + \frac{2\pi}{3}) \\ \sin(\theta_r) & \sin(\theta_r - \frac{2\pi}{3}) & \sin(\theta_r + \frac{2\pi}{3}) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix}$$

$$\mathbf{v}_{qd0s}^r = r_s \mathbf{i}_{qd0s}^r + K_s^r p \left\{ \left(K_s^r \right)^{-1} \boldsymbol{\lambda}_{qd0s}^r \right\}$$

$$\mathbf{v}_{qd0s}^r = r_s \mathbf{i}_{qd0s}^r + K_s^r p \left\{ \left(K_s^r \right)^{-1} \right\} \boldsymbol{\lambda}_{qd0s}^r + K_s^r \left(K_s^r \right)^{-1} p \boldsymbol{\lambda}_{qd0s}^r$$

$$K_s^r p \left\{ \left(K_s^r \right)^{-1} \right\} = \omega_r \begin{bmatrix} 0 & 1 & 0 \\ -1 & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix}$$

$$\mathbf{v}_{qd0s}^r = r_s \mathbf{i}_{qd0s}^r + \omega_r \boldsymbol{\lambda}_{dqs}^r + p \boldsymbol{\lambda}_{qd0s}^r$$

where $\boldsymbol{\lambda}_{dqs}^r = \begin{bmatrix} \lambda_{ds}^r \\ -\lambda_{qs}^r \\ 0 \end{bmatrix}$

Transform Flux Linkages

stator

$$\lambda_{abcs} = \mathbf{L}_s \mathbf{i}_{abcs} + \mathbf{L}'_{sr} \mathbf{i}'_{qdr}$$

$$\mathbf{K}_s^r \mathbf{L}_s (\mathbf{K}_s^r)^{-1} = \begin{bmatrix} L_{ls} + L_{mq} & 0 & 0 \\ 0 & L_{ls} + L_{md} & 0 \\ 0 & 0 & L_{ls} \end{bmatrix}$$

$$\mathbf{K}_s^r \mathbf{L}'_{sr} = \begin{bmatrix} L_{mq} & L_{mq} & 0 & 0 \\ 0 & 0 & L_{md} & L_{md} \\ 0 & 0 & 0 & 0 \end{bmatrix}$$

rotor

$$\lambda'_{qdr} = \frac{2}{3} (\mathbf{L}_{sr})^T \mathbf{i}_{abcs} + \mathbf{L}'_r \mathbf{i}'_{qdr}$$

$$\frac{2}{3} (\mathbf{L}'_{sr})^T (\mathbf{K}_s^r)^{-1} = \begin{bmatrix} L_{mq} & 0 & 0 \\ L_{mq} & 0 & 0 \\ 0 & L_{md} & 0 \\ 0 & L_{md} & 0 \end{bmatrix}$$

Final Set of Equations (Expanded)

voltage equations

$$v_{qs}^r = r_s i_{qs}^r + \omega_r \lambda_{ds}^r + p \lambda_{qs}^r$$

$$v_{ds}^r = r_s i_{ds}^r - \omega_r \lambda_{qs}^r + p \lambda_{ds}^r$$

$$v_{0s} = r_s i_{0s} + p \lambda_{0s}$$

$$v_{kq1}^{'r} = r'_{kq1} i_{kq1}^{'r} + p \lambda_{kq1}^{'r}$$

$$v_{kq2}^{'r} = r'_{kq2} i_{kq2}^{'r} + p \lambda_{kq2}^{'r}$$

$$v_{fd}^{'r} = r'_{fd} i_{fd}^{'r} + p \lambda_{fd}^{'r}$$

$$v_{kd}^{'r} = r'_{kd} i_{kd}^{'r} + p \lambda_{kd}^{'r}$$

flux linkage equations

$$\lambda_{qs}^r = L_{ls} i_{qs}^r + L_{mq} (i_{qs}^r + i_{kq1}^{'r} + i_{kq2}^{'r})$$

$$\lambda_{ds}^r = L_{ls} i_{ds}^r + L_{md} (i_{ds}^r + i_{fd}^{'r} + i_{kd}^{'r})$$

$$\lambda_{0s} = L_{ls} i_{0s}$$

$$\lambda_{kq1}^{'r} = L'_{lkq1} i_{kq1}^{'r} + L_{mq} (i_{qs}^r + i_{kq1}^{'r} + i_{kq2}^{'r})$$

$$\lambda_{kq2}^{'r} = L'_{lkq2} i_{kq2}^{'r} + L_{mq} (i_{qs}^r + i_{kq1}^{'r} + i_{kq2}^{'r})$$

$$\lambda_{fd}^{'r} = L'_{lfd} i_{fd}^{'r} + L_{md} (i_{ds}^r + i_{fd}^{'r} + i_{kd}^{'r})$$

$$\lambda_{kd}^{'r} = L'_{lkd} i_{kd}^{'r} + L_{md} (i_{ds}^r + i_{fd}^{'r} + i_{kd}^{'r})$$

Transform Torque Equation

$$W_c = W_f = \frac{1}{2} (\mathbf{i}_{abcs})^T (\mathbf{L}_s - L_{ls} \mathbf{I}) \mathbf{i}_{abcs} (\mathbf{i}_{abcs})^T \mathbf{L}'_{sr} \mathbf{i}'_{qdr} + \frac{1}{2} \left(\frac{3}{2}\right) (\mathbf{i}'_{qdr})^T (\mathbf{L}'_r - \mathbf{L}'_{lr} \mathbf{I}) \mathbf{i}'_{qdr}$$

$$T_e = -\frac{\partial W_c}{\partial \theta_{rm}} \quad \theta_r = \frac{P}{2} \theta_{rm}$$


substituting equations of transformation

$$T_e = \frac{3}{2} \left(\frac{P}{2} \right) (\lambda_{qs}^r i_{ds}^r - \lambda_{ds}^r i_{qs}^r)$$

in terms of currents

$$\begin{aligned} T_e &= \frac{3}{2} \left(\frac{P}{2} \right) \left[L_{mq} (i_{qs}^r + i'_{kq1} + i'_{kq2}) i_{ds}^r - L_{md} (i_{ds}^r + i'_{fd} + i'_{kd}) i_{qs}^r \right] \\ &= \frac{3}{2} \left(\frac{P}{2} \right) \left[(L_{md} - L_{mq}) i_{qs}^r i_{ds}^r + L_{md} i'_{fd} i_{qs}^r + L_{md} i'_{kd} i_{qs}^r + L_{mq} (i'_{kq1} + i'_{kq2}) i_{ds}^r \right] \end{aligned}$$

Stator Currents Positive Out of Machine



Synchronous Machine q-d Equivalent Circuit

voltage equations

$$v_{qs}^r = -r_s i_{qs}^r + \omega_r \lambda_{ds}^r + p \lambda_{qs}^r$$

$$v_{ds}^r = -r_s i_{ds}^r - \omega_r \lambda_{qs}^r + p \lambda_{ds}^r$$

$$v_{0s} = -r_s i_{0s} + p \lambda_{0s}$$

$$v_{kq1}^{'r} = r'_{kq1} i_{kq1}^{'r} + p \lambda_{kq1}^{'r}$$

$$v_{kq2}^{'r} = r'_{kq2} i_{kq2}^{'r} + p \lambda_{kq2}^{'r}$$

$$v_{fd}^{'r} = r'_{fd} i_{fd}^{'r} + p \lambda_{fd}^{'r}$$

$$v_{kd}^{'r} = r'_{kd} i_{kd}^{'r} + p \lambda_{kd}^{'r}$$

Torque equation

$$T_e = \frac{3}{2} \left(\frac{P}{2} \right) (\lambda_{qs}^r i_{ds}^r - \lambda_{ds}^r i_{qs}^r)$$

flux linkage equations

$$\lambda_{qs}^r = -L_{ls} i_{qs}^r + L_{mq} (-i_{qs}^r + i_{kq1}^{'r} + i_{kq2}^{'r})$$

$$\lambda_{ds}^r = -L_{ls} i_{ds}^r + L_{md} (-i_{ds}^r + i_{fd}^{'r} + i_{kd}^{'r})$$

$$\lambda_{0s} = -L_{ls} i_{0s}$$

$$\lambda_{kq1}^{'r} = L'_{lkq1} i_{kq1}^{'r} + L_{mq} (-i_{qs}^r + i_{kq1}^{'r} + i_{kq2}^{'r})$$




$$\lambda_{kq2}^{'r} = L'_{lkq2} i_{kq2}^{'r} + L_{mq} (-i_{qs}^r + i_{kq1}^{'r} + i_{kq2}^{'r})$$

$$\lambda_{fd}^{'r} = L'_{lfd} i_{fd}^{'r} + L_{md} (-i_{ds}^r + i_{fd}^{'r} + i_{kd}^{'r})$$

$$\lambda_{kd}^{'r} = L'_{lkd} i_{kd}^{'r} + L_{md} (-i_{ds}^r + i_{fd}^{'r} + i_{kd}^{'r})$$

Mechanical equation

$$T_I - T_e = J \left(\frac{2}{P} \right) p \omega_r$$



Synchronous Machine Simulation

Solving for Currents

1. Invert the inductance matrix

$$\begin{bmatrix} -i_{qs}^r \\ i_{kq1}^{'r} \\ i_{kq2}^{'r} \end{bmatrix} = \begin{bmatrix} L_{ls} + L_{mq} & L_{mq} & L_{mq} \\ L_{mq} & L'_{lkq1} + L_{mq} & L_{mq} \\ L_{mq} & L_{mq} & L'_{lkq2} + L_{mq} \end{bmatrix}^{-1} \begin{bmatrix} \lambda_{qs}^r \\ \lambda_{kq1}^{'r} \\ \lambda_{kq2}^{'r} \end{bmatrix}$$

$$\begin{bmatrix} -i_{ds}^r \\ i_{fd}^{'r} \\ i_{kd}^{'r} \end{bmatrix} = \begin{bmatrix} L_{ls} + L_{md} & L_{md} & L_{md} \\ L_{md} & L'_{lfd} + L_{md} & L_{md} \\ L_{md} & L_{md} & L'_{lkd} + L_{md} \end{bmatrix}^{-1} \begin{bmatrix} \lambda_{ds}^r \\ \lambda_{fd}^{'r} \\ \lambda_{kd}^{'r} \end{bmatrix}$$

Note: inductance matrix is constant in the q - d model

Currents in Terms of Flux Linkages

2. write in terms of magnetizing flux linkages

Book Simulation Example

TABLE 5.10-2. Steam Turbine Generator

Rating: 835 MVA

Line to line voltage: 26 kV

Power factor: 0.85

Poles: 2

Speed: 3600 r/min

Combined inertia of generator and turbine

$$J = 0.0658 \times 10^6 \text{ J} \cdot \text{s}^2, \text{ or } WR^2 = 1.56 \times 10^6 \text{ lbm} \cdot \text{ft}^2 \quad H = 5.6 \text{ seconds}$$

Parameters in ohms and per unit

$$r_s = 0.00243 \, \Omega, 0.003 \text{ pu}$$

$$X_{ls} = 0.1538 \, \Omega, 0.19 \text{ pu}$$

$$X_q = 1.457 \, \Omega, 1.8 \text{ pu} \quad X_d = 1.457 \, \Omega, 1.8 \text{ pu}$$


$$r'_{kq1} = 0.00144 \, \Omega, 0.00178 \text{ pu} \quad r'_{fd} = 0.00075 \, \Omega, 0.000929 \text{ pu}$$

$$X'_{lkq1} = 0.6578 \, \Omega, 0.8125 \text{ pu} \quad X'_{lfd} = 0.1145 \, \Omega, 0.1414 \text{ pu}$$

$$r'_{kq2} = 0.00681 \, \Omega, 0.00841 \text{ pu} \quad r'_{kd} = 0.01080 \, \Omega, 0.01334 \text{ pu}$$

$$X'_{lkq2} = 0.07602 \, \Omega, 0.0939 \text{ pu} \quad X'_{lkd} = 0.06577 \, \Omega, 0.08125 \text{ pu}$$

Book Simulation Example (Step Change in Torque)



5.10-6. Dynamic performance of a steam turbine generator during a step increase in torque from 0% to 50% rated.

Book Simulation Example (Three-Phase Fault)




Figure 5.10-10. Dynamic performance of a steam turbine generator during a three-phase fault at the terminals.

Synchronous Machine Substitute Variables

Define

$$\Psi = \omega_b \lambda$$

$$X = \omega_b L$$

where ω_b is the base, or rated, electrical frequency

Machine Equations

$$v_{qs}^r = -r_s i_{qs}^r + \frac{\omega_r}{\omega_b} \psi_{ds}^r + \frac{p}{\omega_b} \psi_{qs}^r$$

$$v_{ds}^r = -r_s i_{ds}^r - \frac{\omega_r}{\omega_b} \psi_{qs}^r + \frac{p}{\omega_b} \psi_{ds}^r$$

$$v_{0s} = -r_s i_{0s} + \frac{p}{\omega_b} \psi_{0s}$$

$$v_{kq1}^{r'} = r'_{kq1} i_{kq1}^{r'} + \frac{p}{\omega_b} \psi_{kq1}^{r'}$$

$$v_{kq2}^{r'} = r'_{kq2} i_{kq2}^{r'} + \frac{p}{\omega_b} \psi_{kq2}^{r'}$$

$$v_{fd}^{r'} = r'_{fd} i_{fd}^{r'} + \frac{p}{\omega_b} \psi_{fd}^{r'}$$

$$v_{kd}^{r'} = r'_{kd} i_{kd}^{r'} + \frac{p}{\omega_b} \psi_{kd}^{r'}$$

$$\psi_{qs}^r = -X_{ls} i_{qs}^r + X_{mq} (-i_{qs}^r + i_{kq1}^{r'} + i_{kq2}^{r'})$$

$$\psi_{ds}^r = -X_{ls} i_{ds}^r + X_{md} (-i_{ds}^r + i_{fd}^{r'} + i_{kd}^{r'})$$

$$\psi_{0s} = -X_{ls} i_{0s}$$

$$\psi_{kq1}^{r'} = X'_{lkq1} i_{kq1}^{r'} + X_{mq} (-i_{qs}^r + i_{kq1}^{r'} + i_{kq2}^{r'})$$

$$\psi_{kq2}^{r'} = X'_{lkq2} i_{kq2}^{r'} + X_{mq} (-i_{qs}^r + i_{kq1}^{r'} + i_{kq2}^{r'})$$

$$\psi_{fd}^{r'} = X'_{lfd} i_{fd}^{r'} + X_{md} (-i_{ds}^r + i_{fd}^{r'} + i_{kd}^{r'})$$

$$\psi_{kd}^{r'} = X'_{lkd} i_{kd}^{r'} + X_{md} (-i_{ds}^r + i_{fd}^{r'} + i_{kd}^{r'})$$

Steady-State Calculations

constant V_s and constant $\omega_e = 2\pi f$

also, $\omega_r = \omega_e$ and $V_{0s} = I_{0s} = \Lambda_{0s} = 0$

$$\begin{aligned}v_{as} &= \sqrt{2} V_s \cos(\omega_e t + \theta_{ev}(0)) & i_{as} &= \sqrt{2} I_s \cos(\omega_e t + \theta_{ei}(0)) \\v_{bs} &= \sqrt{2} V_s \cos(\omega_e t + \theta_{ev}(0) - \frac{2\pi}{3}) & i_{bs} &= \sqrt{2} I_s \cos(\omega_e t + \theta_{ei}(0) - \frac{2\pi}{3}) \\v_{cs} &= \sqrt{2} V_s \cos(\omega_e t + \theta_{ev}(0) + \frac{2\pi}{3}) & i_{cs} &= \sqrt{2} I_s \cos(\omega_e t + \theta_{ei}(0) + \frac{2\pi}{3})\end{aligned}$$

voltages and currents in the rotor reference frame

$$\begin{aligned}V_{qs}^r &= \sqrt{2} V_s \cos(-\delta) & \delta &= \theta_r - \theta_{ev} & \theta_{ev} &= \omega_e t + \theta_{ev}(0) \\V_{ds}^r &= -\sqrt{2} V_s \sin(-\delta) \\I_{qs}^r &= \sqrt{2} I_s \cos(\theta_{ei}(0) - \theta_{ev}(0) - \delta) \\I_{ds}^r &= -\sqrt{2} I_s \sin(\theta_{ei}(0) - \theta_{ev}(0) - \delta)\end{aligned}$$

Voltage and Current Phasors

$$\tilde{V}_{as} = V_s e^{j0} \quad \tilde{I}_{as} = I_s e^{j[\theta_{ei}(0) - \theta_{ev}(0)]}$$

note

$$\begin{aligned} V_{qs}^r &= \operatorname{Re} \left\{ \sqrt{2} V_s e^{-j\delta} \right\} & I_{qs}^r &= \operatorname{Re} \left\{ \sqrt{2} I_s e^{j[\theta_{ei}(0) - \theta_{ev}(0)]} e^{-j\delta} \right\} \\ V_{ds}^r &= \operatorname{Re} \left\{ j\sqrt{2} V_s e^{-j\delta} \right\} & I_{ds}^r &= \operatorname{Re} \left\{ j\sqrt{2} I_s e^{j[\theta_{ei}(0) - \theta_{ev}(0)]} e^{-j\delta} \right\} \end{aligned}$$

also

$$V_{qs}^r - jV_{ds}^r = \sqrt{2} V_s [\cos(-\delta) + j\sin(-\delta)] = \sqrt{2} V_s e^{-j\delta}$$

so

$$\sqrt{2} \tilde{V}_{as} e^{-j\delta} = V_{qs}^r - jV_{ds}^r$$

Steady-State Equations

steady-state q - d variables are dc so

$$p\Psi_{qs}^r = p\Psi_{ds}^r = p\Psi_{kq1}^{'r} = p\Psi_{kq2}^{'r} = p\Psi_{fd}^{'r} = p\Psi_{kd}^{'r} = 0$$

$$\text{also } I_{kq1}^{'r} = I_{kq2}^{'r} = I_{kd}^{'r} = 0 \quad \text{because } V_{kq1}^{'r} = V_{kq2}^{'r} = V_{kd}^{'r} = 0$$

$$V_{qs}^r = -r_s I_{qs}^r - \frac{\omega_e}{\omega_b} X_d I_{ds}^r + \frac{\omega_e}{\omega_b} X_{md} I_{fd}^{'r} \quad X_d = X_{ls} + X_{md}$$

$$V_{ds}^r = -r_s I_{ds}^r + \frac{\omega_e}{\omega_b} X_q I_{qs}^r \quad X_q = X_{ls} + X_{mq}$$

$$V_{fd}^{'r} = r_{fd}' I_{fd}^{'r}$$

Phasor Diagram Development

Per-Phase Circuit Model

Steady-State Torque

$$P_{mech} = -\frac{3}{2} \left[\frac{\omega_e}{\omega_b} (X_d - X_q) I_{qs}^r I_{ds}^r - \frac{\omega_e}{\omega_b} X_{md} I_{fd}^r I_{qs}^r \right] = T_{e,ss} \omega_{rm} = T_{e,ss} \left(\frac{2}{P} \right) \omega_r$$

$$\omega_r = \omega_e$$

$$T_{e,ss} = -\frac{3}{2} \left(\frac{P}{2} \right) \left(\frac{1}{\omega_b} \right) \left[(X_d - X_q) I_{qs}^r I_{ds}^r - X_{md} I_{fd}^r I_{qs}^r \right]$$

Solving Steady-State Equations

$$\begin{bmatrix} V_{qs}^r \\ V_{ds}^r \end{bmatrix} = \begin{bmatrix} -r_s & -\frac{\omega_e}{\omega_b} X_d \\ \frac{\omega_e}{\omega_b} X_q & -r_s \end{bmatrix} \begin{bmatrix} I_{qs}^r \\ I_{ds}^r \end{bmatrix} + \begin{bmatrix} \frac{\omega_e}{\omega_b} X_{md} I_{fd}'^r \\ 0 \end{bmatrix}$$

$$\begin{bmatrix} I_{qs}^r \\ I_{ds}^r \end{bmatrix} = \frac{\begin{bmatrix} -r_s & \frac{\omega_e}{\omega_b} X_d \\ -\frac{\omega_e}{\omega_b} X_q & -r_s \end{bmatrix} \begin{bmatrix} V_{qs}^r - \frac{\omega_e}{\omega_b} X_{md} I_{fd}'^r \\ V_{ds}^r \end{bmatrix}}{r_s^2 + \left(\frac{\omega_e}{\omega_b} \right)^2 X_q X_d}$$

Steady-State Torque in Terms of Voltage

$$T_{e,ss} = \frac{3}{2} \left(\frac{P}{2} \right) \left(\frac{1}{\omega_b} \right) \left\{ \frac{r_s X_{md} I'_{fd}{}^r}{r_s^2 + \left(\frac{\omega_e}{\omega_b} \right)^2 X_q X_d} \left(V_{qs}^r - \frac{\omega_e}{\omega_b} X_{md} I'_{fd}{}^r - \frac{\omega_e}{\omega_b} \frac{X_d}{r_s} V_{ds}^r \right) \right. \\ \left. + \frac{X_d - X_q}{\left[r_s^2 + \left(\frac{\omega_e}{\omega_b} \right)^2 X_q X_d \right]^2} \left[r_s \frac{\omega_e}{\omega_b} X_q \left(V_{qs}^r - \frac{\omega_e}{\omega_b} X_{md} I'_{fd}{}^r \right)^2 + \right. \right. \\ \left. \left. \left(r_s^2 - \left(\frac{\omega_e}{\omega_b} \right)^2 X_q X_d \right) V_{ds}^r \left(V_{qs}^r - \frac{\omega_e}{\omega_b} X_{md} I'_{fd}{}^r \right) - r_s \frac{\omega_e}{\omega_b} X_d V_{ds}^{r2} \right] \right\}$$

Torque in Terms of Delta Angle (Neglecting Stator Resistance)

$$T_{e,ss} = \frac{3}{2} \left(\frac{P}{2} \right) \left(\frac{1}{\omega_b} \right) \left[\frac{E'_{r_{xfd}} \sqrt{2} V_s}{\left(\frac{\omega_e}{\omega_b} \right) X_d} \sin(\delta) + \left(\frac{\omega_b}{\omega_e} \right)^2 \left(\frac{1}{X_q} - \frac{1}{X_d} \right) V_s^2 \sin(2\delta) \right]$$

where $E'_{r_{xfd}} = X_{md} I'_{fd}$

Example Machine

$$\omega_b := 2 \cdot \pi \cdot 60 \text{ Hz}$$

$$\text{kVA} := \text{kV} \cdot \text{A}$$

given parameters

$$P := 24 \quad r_s := 7.8 \text{ m}\Omega \quad X_{ls} := 0.02 \Omega \quad r_{fd} := 3.8 \Omega$$

$$\text{lagging} := 1$$

$$\text{RPM} := \frac{2 \cdot \pi \cdot \text{rad}}{\text{min}}$$

open-circuit test data

$$V_{s_oc} := \frac{208}{\sqrt{3}} \cdot V$$

$$V_{s_oc} = 120V$$

$$I_{fd_oc} := 30 \text{ A}$$

$$\omega_{e_oc} := \omega_b$$

open-circuit test calculations

$$V_{qsr_oc} := \sqrt{2} \cdot V_{s_oc}$$

$$V_{dsr_oc} := 0 \cdot V$$

$$\delta_{oc} := \text{atan} \left(\frac{-V_{dsr_oc}}{V_{qsr_oc}} \right)$$

$$\delta_{oc} = 0 \text{ deg}$$

$$E'_{xfl} := \frac{\omega_b}{\omega_{e_oc}} \cdot V_{qsr_oc}$$

$$E'_{xfl} = 170V$$

Inductive Load Test

inductive load test (same I_{fd} as the open-circuit test)

$$V_{s_L} := \frac{158}{\sqrt{3}} \cdot V$$

$$V_{s_L} = 91V$$

$$I_{s_L} := 100A$$

$$\omega_{e_L} := \omega_b$$

$$\delta_L := 0 \cdot \text{deg}$$

$$\theta_{ev0_L} := 0 \cdot \text{deg}$$

$$\theta_{ei0_L} := -90 \cdot \text{deg}$$

Inductive Load Calculations

inductive load calculations

$$V_{qsr_L} := \sqrt{2} \cdot V_{s_L} \cdot \cos(-\delta_L)$$

$$V_{dsr_L} := -\sqrt{2} \cdot V_{s_L} \cdot \sin(-\delta_L)$$

$$I_{qsr_L} := \sqrt{2} \cdot I_{s_L} \cdot \cos(\theta_{ei0_L} - \theta_{ev0_L} - \delta_L)$$

$$I_{dsr_L} := -\sqrt{2} \cdot I_{s_L} \cdot \sin(\theta_{ei0_L} - \theta_{ev0_L} - \delta_L)$$

$$X_d := \frac{\left(\frac{\omega_{e_oc}}{\omega_b} \right) \cdot E'_{xfl} - V_{qsr_L}}{\left(\frac{\omega_{e_oc}}{\omega_b} \right) I_{dsr_L}}$$

$$X_{md} := X_d - X_{ls}$$

$$X_{mq} := \frac{2}{3} \cdot X_{md}$$

$$X_q := X_{ls} + X_{mq}$$

Open-Circuit Test Calculations with Magnetizing Reactance

return to open-circuit test with magnetizing reactances

$$I'_{fd_oc} := \frac{E'_{x\text{fd}}}{X_{md}}$$

$$N_{fd} := \frac{3}{2} \cdot \frac{I'_{fd_oc}}{I_{fd_oc}} \quad N_s := 1$$

$$r'_{fd} := \frac{3}{2} \cdot \left(\frac{N_s}{N_{fd}} \right)^2 \cdot r_{fd}$$

Rated Operation

rated generator operation

$$V_s := \frac{208}{\sqrt{3}} \cdot V$$

$$V_s = 120V$$

$$S := 90 \text{ kVA}$$

$$\text{pf} := 0.8 \text{ lagging}$$

$$f_e := 60 \text{ Hz}$$

$$I_{fd} := 60 \text{ A}$$

$$\omega_e := 2 \cdot \pi \cdot f_e$$

$$\omega_e = 377 \frac{\text{rad}}{\text{s}}$$

$$I_s := \frac{S}{3 \cdot V_s}$$

$$I_s = 250 \text{ A}$$

$$\theta_{ev0} := 0 \cdot \text{deg}$$

$$\theta_{ei0} := \theta_{ev0} - \arccos(\text{pf})$$

$$\theta_{ei0} = -36.9 \text{ deg}$$

$$V_{as} := V_s \cdot e^{j \cdot 0 \cdot \text{deg}}$$

$$I_{as} := I_s \cdot e^{j \cdot (\theta_{ei0} - \theta_{ev0})}$$

Rated Operation Calculations

back-emf and torque angle

$$E_a := V_{as} + \left(r_s + j \cdot \frac{\omega_e}{\omega_b} \cdot X_q \right) \cdot I_{as}$$

$$r_s := 0 \cdot \Omega$$

$$E_a := V_{as} + \left(r_s + j \cdot \frac{\omega_e}{\omega_b} \cdot X_q \right) \cdot I_{as}$$

$$\delta := \arg(E_a)$$

$$V_{qsr} := \sqrt{2} \cdot V_s \cdot \cos(-\delta)$$

$$V_{dsr} := -\sqrt{2} \cdot V_s \cdot \sin(-\delta)$$

$$I_{qsr} := \sqrt{2} \cdot I_s \cdot \cos(\theta_{ei0} - \theta_{ev0} - \delta)$$

$$I_{dsr} := -\sqrt{2} \cdot I_s \cdot \sin(\theta_{ei0} - \theta_{ev0} - \delta)$$

Phasor Diagram

Rated Operation Torque

torque

$$I'_{fd} := \frac{2}{3} \cdot \left(\frac{N_{fd}}{N_s} \right) I_{fd}$$

$$E'_{x\text{fd}} := X_{md} I'_{fd}$$

$$T_e := \frac{3}{2} \cdot \left(\frac{P}{2} \right) \cdot \left(\frac{1}{\omega_b} \right) \cdot \left[\frac{E'_{x\text{fd}} \cdot \sqrt{2} \cdot V_s}{\left(\frac{\omega_e}{\omega_b} \right) \cdot X_d} \cdot \sin(\delta) + \left(\frac{\omega_b}{\omega_e} \right)^2 \cdot \left(\frac{1}{X_q} - \frac{1}{X_d} \right) \cdot V_s^2 \cdot \sin(2 \cdot \delta) \right]$$

Synchronous Machine Impedances and Time Constants (Chapter 7)

Stator Flux Linkages

Write the flux linkages in terms of general transfer functions

$$\Psi_{qs}^r = -X_q(s) i_{qs}^r$$

$$\Psi_{ds}^r = -X_d(s) i_{ds}^r + G(s) v_{fd}'^r$$

note: $X_q(s)$ and $X_d(s)$ are not the synchronous reactances X_q and X_d


The transfer functions do not restrict the model to a specific form.
They can be found by:

$$X_q(s) = -\frac{\Psi_{qs}^r}{i_{qs}^r}$$

$$X_d(s) = -\frac{\Psi_{ds}^r}{i_{ds}^r} \bigg|_{v_{fd}'^r=0}$$

$$G(s) = \frac{\Psi_{ds}^r}{v_{fd}'^r} \bigg|_{i_{ds}^r=0}$$

Standard Q-Axis Model



For this structure, the impedance $X_q(s)$ is

$$X_q(s) = X_q \frac{1 + (\tau_{q4} + \tau_{q5})s + \tau_{q4}\tau_{q6}s^2}{1 + (\tau_{q1} + \tau_{q2})s + \tau_{q1}\tau_{q3}s^2}$$

where

$$\tau_{q1} = \frac{1}{\omega_b r'_{kq1}} (X'_{lkq1} + X_{mq})$$

$$\tau_{q2} = \frac{1}{\omega_b r'_{kq2}} (X'_{lkq2} + X_{mq})$$

$$\tau_{q3} = \frac{1}{\omega_b r'_{kq2}} \left(X'_{lkq2} + \frac{X_{mq} X'_{lkq1}}{X'_{lkq1} + X_{mq}} \right)$$

$$\tau_{q4} = \frac{1}{\omega_b r'_{kq1}} \left(X'_{lkq1} + \frac{X_{mq} X_{ls}}{X_{ls} + X_{mq}} \right)$$

$$\tau_{q5} = \frac{1}{\omega_b r'_{kq2}} \left(X'_{lkq2} + \frac{X_{mq} X_{ls}}{X_{ls} + X_{mq}} \right)$$

$$\tau_{q6} = \frac{1}{\omega_b r'_{kq2}} \left(X'_{lkq2} + \frac{X_{mq} X_{ls} X'_{lkq1}}{X_{mq} X_{ls} + X_{mq} X'_{lkq1} + X_{ls} X'_{lkq1}} \right)$$

The standard q -axis impedance can be seen as a collection of time constants and reactances

By a similar procedure, $X_d(s)$ can be written in terms of reactances and time constants

Standard Reactances

synchronous reactances

$$X_q = X_{ls} + X_{mq}$$

$$X_d = X_{ls} + X_{md}$$

note: $X_q(0) = X_q$

$$X_d(0) = X_d$$

transient reactances

$$X'_q = X_{ls} + \frac{X_{mq}X'_{lkq1}}{X'_{lkq1} + X_{mq}}$$

$$X'_d = X_{ls} + \frac{X_{md}X'_{lfd}}{X'_{lfd} + X_{md}}$$

sub-transient reactances

$$X''_q = X_{ls} + \frac{X_{mq}X'_{lkq1}X'_{lkq2}}{X_{mq}X'_{lkq1} + X_{mq}X'_{lkq2} + X'_{lkq1}X'_{lkq2}}$$

$$X''_d = X_{ls} + \frac{X_{md}X'_{lfd}X'_{lkd}}{X_{md}X'_{lfd} + X_{md}X'_{lkd} + X'_{lfd}X'_{lkd}}$$

note: $X_q(\infty) = X''_q$

$$X_d(\infty) = X''_d$$

Notes About Time Constants

- In the d -axis, the field acts in the transient time scale and the damper winding acts in the sub-transient period.
- In the q -axis, the $kq1$ winding acts in the transient period and the $kq2$ in the sub-transient period.
- Open-circuit time constants represent the time for transients to decay with the stator windings open-circuited.
- Short-circuit time constants represent the time for transients to decay with the stator short-circuited.

$$X_q(s) = X_q \frac{(1 + \tau'_q s)(1 + \tau''_q s)}{(1 + \tau'_{qo} s)(1 + \tau''_{qo} s)}$$

$$X_d(s) = X_d \frac{(1 + \tau'_d s)(1 + \tau''_d s)}{(1 + \tau'_{do} s)(1 + \tau''_{do} s)}$$

Standard Time Constants (Approximate)

Table 7.5-1 Standard Synchronous Machine Time Constants

Open-Circuit Time Constants

$$\tau'_{qo} = \frac{1}{\omega_b r'_{kq1}} (X'_{lkq1} + X_{mq})$$

$$\tau'_{do} = \frac{1}{\omega_b r'_{fd}} (X'_{lfd} + X_{md})$$

$$\tau''_{qo} = \frac{1}{\omega_b r'_{kq2}} \left(X'_{lkq2} + \frac{X_{mq} X'_{lkq1}}{X_{mq} + X'_{lkq1}} \right)$$

$$\tau''_{do} = \frac{1}{\omega_b r'_{kd}} \left(X'_{lkd} + \frac{X_{md} X'_{lfd}}{X_{md} + X'_{lfd}} \right)$$

Short-Circuit Time Constants

$$\tau'_q = \frac{1}{\omega_b r'_{kq1}} \left(X'_{lkq1} + \frac{X_{mq} X_{ls}}{X_{mq} + X_{ls}} \right)$$

$$\tau'_d = \frac{1}{\omega_b r'_{fd}} \left(X'_{lfd} + \frac{X_{md} X_{ls}}{X_{md} + X_{ls}} \right)$$

$$\tau''_q = \frac{1}{\omega_b r'_{kq2}} \left(X'_{lkq2} + \frac{X_{mq} X_{ls} X'_{lkq1}}{X_{mq} X_{ls} + X_{mq} X'_{lkq1} + X_{ls} X'_{lkq1}} \right)$$

$$\tau''_d = \frac{1}{\omega_b r'_{kd}} \left(X'_{lkd} + \frac{X_{md} X_{ls} X'_{lfd}}{X_{md} X_{ls} + X_{md} X'_{lfd} + X_{ls} X'_{lfd}} \right)$$

obtained from simple R-L time constant relationships

Derived Time Constants

Table 7.6-1 Derived Synchronous Machine Time Constants

Open-Circuit Time Constants

$$\tau'_{qo} = \frac{1}{\omega_b r'_{kq1}} (X'_{lkq1} + X_{mq}) + \frac{1}{\omega_b r'_{kq2}} (X'_{lkq2} + X_{mq})$$

$$\tau'_{do} = \frac{1}{\omega_b r'_{fd}} (X'_{lfd} + X_{md}) + \frac{1}{\omega_b r'_{kd}} (X'_{lkd} + X_{md})$$

$$\tau''_{qo} = \frac{(1/\omega_b r'_{kq2})[X'_{lkq2} + (X_{mq}X'_{lkq1}/X'_{lkq1} + X_{mq})]}{1 + [(1/\omega_b r'_{kq2})(X'_{lkq2} + X_{mq})/(1/\omega_b r'_{kq1})(X'_{lkq1} + X_{mq})]}$$

$$\tau''_{do} = \frac{(1/\omega_b r'_{kd})[X'_{lkd} + (X_{md}X'_{lfd}/X'_{lfd} + X_{md})]}{1 + [(1/\omega_b r'_{kd})(X'_{lkd} + X_{md})/(1/\omega_b r'_{fd})(X'_{lfd} + X_{md})]}$$

Short-Circuit Time Constants

$$\tau'_q = \frac{1}{\omega_b r'_{kq1}} \left(X'_{lkq1} + \frac{X_{mq}X_{ls}}{X_{ls} + X_{mq}} \right) + \frac{1}{\omega_b r'_{kq2}} \left(X'_{lkq2} + \frac{X_{mq}X_{ls}}{X_{ls} + X_{mq}} \right)$$

$$\tau'_d = \frac{1}{\omega_b r'_{fd}} \left(X'_{lfd} + \frac{X_{md}X_{ls}}{X_{ls} + X_{md}} \right) + \frac{1}{\omega_b r'_{kd}} \left(X'_{lkd} + \frac{X_{md}X_{ls}}{X_{ls} + X_{md}} \right)$$

$$\tau''_q = \frac{(1/\omega_b r'_{kq2})[X'_{lkq2} + (X_{mq}X_{ls}X'_{lkq1}/X_{mq}X_{ls} + X_{mq}X'_{lkq1} + X_{ls}X'_{lkq1})]}{1 + \{(1/\omega_b r'_{kq2})[X'_{lkq2} + (X_{mq}X_{ls}/X_{ls} + X_{mq})]/(1/\omega_b r'_{kq1})[X'_{lkq1} + (X_{mq}X_{ls}/X_{ls} + X_{mq})]\}}$$

$$\tau''_d = \frac{(1/\omega_b r'_{kd})[X'_{lkd} + (X_{md}X_{ls}X'_{lfd}/X_{md}X_{ls} + X_{md}X'_{lfd} + X_{ls}X'_{lfd})]}{1 + \{(1/\omega_b r'_{kd})[X'_{lkd} + (X_{md}X_{ls}/X_{ls} + X_{md})]/(1/\omega_b r'_{fd})[X'_{lfd} + (X_{md}X_{ls}/X_{ls} + X_{md})]\}}$$

derived from the inverse of the roots of the characteristic equations of $X_q(s)$ and $X_d(s)$

Synchronous Machine Example:

Extract parameters from given reactances and time constants

number of poles $P := 24$

$$\text{kVA} := \text{kV} \cdot \text{A}$$

$$\text{m}\Omega := 10^{-3} \cdot \Omega$$

rated operation

$$S_{\text{out}} := 100 \text{ kVA}$$

$$P_{\text{out}} := 75 \text{ kW}$$

$$f_e := 400 \text{ Hz}$$

$$V_{\text{LL}} := 208 \text{ V}$$

$$I_{\text{fd}} := 10 \text{ A}$$

base impedance

$$\omega_b := 2 \cdot \pi \cdot f_e$$

$$\omega_b = 2513 \frac{\text{rad}}{\text{s}}$$

$$V_b := \frac{V_{\text{LL}}}{\sqrt{3}}$$

$$V_b = 120 \text{ V}$$

$$I_b := \frac{S_{\text{out}}}{3 \cdot V_b}$$

$$I_b = 278 \text{ A}$$

$$Z_b := \frac{V_b}{I_b}$$

$$Z_b = 0.433 \Omega$$

resistances

$$r_s := 0.003 \Omega$$

$$r_{\text{fd}} := 2 \cdot \Omega$$

synchronous reactances

$$X_d := 70\% \cdot Z_b$$

$$X_d = 0.303\Omega$$

$$X_q := 50\% \cdot Z_b$$

$$X_q = 0.216\Omega$$

stator leakage reactance

$$X_{ls} := 5\% \cdot Z_b$$

$$X_{ls} = 0.022\Omega$$

transient reactances and time constants

$$X'_d := 15\% \cdot Z_b$$

$$\tau'_d := 0.05\text{ s}$$

$$\tau'_{d0} := 0.150\text{ s}$$

$$X'_q := 25\% \cdot Z_b$$

$$\tau'_q := 0.03\text{ s}$$

$$\tau'_{q0} := 0.035\text{ s}$$

subtransient reactances

$$X''_d := 12\% \cdot Z_b$$

$$\tau''_d := 0.001\text{ s}$$

$$\tau''_{d0} := 0.002\text{ s}$$

$$X''_q := 13\% \cdot Z_b$$

$$\tau''_q := 0.0005\text{ s}$$

$$\tau''_{q0} := 0.001\text{ s}$$

calculate magnetizing reactances

$$X_{md} := X_d - X_{ls}$$

$$X_{md} = 0.281 \Omega$$

$$X_{mq} := X_q - X_{ls}$$

$$X_{mq} = 0.1947 \Omega$$

leakage reactances from transient and sub-transient reactances

guess values --->

$$X'_{lkq1} := X_{ls} \quad X'_{lfd} := X_{ls}$$

$$X'_{lkq2} := X_{ls} \quad X'_{lkd} := X_{ls}$$

Given

$$X'_q = X_{ls} + \frac{X_{mq} \cdot X'_{lkq1}}{X'_{lkq1} + X_{mq}}$$

$$X'_d = X_{ls} + \frac{X_{md} \cdot X'_{lfd}}{X'_{lfd} + X_{md}}$$

$$X''_q = X_{ls} + \frac{X_{mq} \cdot X'_{lkq1} \cdot X'_{lkq2}}{X_{mq} \cdot X'_{lkq1} + X_{mq} \cdot X'_{lkq2} + X'_{lkq1} \cdot X'_{lkq2}}$$

$$X''_d = X_{ls} + \frac{X_{md} \cdot X'_{lfd} \cdot X'_{lkd}}{X_{md} \cdot X'_{lfd} + X_{md} \cdot X'_{lkd} + X'_{lfd} \cdot X'_{lkd}}$$

$$\begin{pmatrix} X'_{lkq1} \\ X'_{lkq2} \\ X'_{lfd} \\ X'_{lkd} \end{pmatrix} := \text{Find}(X'_{lkq1}, X'_{lkq2}, X'_{lfd}, X'_{lkd})$$

$$X'_{lfd} = 0.051 \Omega$$

$$X'_{lkd} = 0.101 \Omega$$

$$X'_{lkq1} = 0.156 \Omega$$

$$X'_{lkq2} = 0.058 \Omega$$

**guess values for resistances
based on standard open-circuit equations**

$$r'_{kq1o} := \frac{1}{\omega_b \cdot \tau'_{qo}} \cdot (X'_{lkq1} + X_{mq})$$

$$r'_{kq1o} = 3.98 \text{m}\Omega$$

$$r'_{fdo} := \frac{1}{\omega_b \cdot \tau'_{do}} \cdot (X'_{lfd} + X_{md})$$

$$r'_{fdo} = 0.882 \text{m}\Omega$$

$$r'_{kq2o} := \frac{1}{\omega_b \cdot \tau''_{qo}} \cdot \left(X'_{lkq2} + \frac{X_{mq} \cdot X'_{lkq1}}{X_{mq} + X'_{lkq1}} \right)$$

$$r'_{kq2o} = 57.38 \text{m}\Omega$$

$$r'_{kdo} := \frac{1}{\omega_b \cdot \tau''_{do}} \cdot \left(X'_{lkd} + \frac{X_{md} \cdot X'_{lfd}}{X_{md} + X'_{lfd}} \right)$$

$$r'_{kdo} = 28.69 \text{m}\Omega$$

resistances from derived synchronous machine open-circuit time constants

Given

$$\tau'_{qo} = \frac{1}{\omega_b \cdot r'_{kq1o}} \cdot (X'_{lkq1} + X_{mq}) + \frac{1}{\omega_b \cdot r'_{kq2o}} \cdot (X'_{lkq2} + X_{mq})$$

$$\tau'_{do} = \frac{1}{\omega_b \cdot r'_{fdo}} \cdot (X'_{lfd} + X_{md}) + \frac{1}{\omega_b \cdot r'_{kdo}} \cdot (X'_{lkd} + X_{md})$$

$$\tau''_{qo} = \frac{\frac{1}{\omega_b \cdot r'_{kq2o}} \cdot \left(X'_{lkq2} + \frac{X_{mq} \cdot X'_{lkq1}}{X'_{lkq1} + X_{mq}} \right)}{1 + \frac{\frac{1}{\omega_b \cdot r'_{kq2o}} \cdot (X'_{lkq2} + X_{mq})}{\frac{1}{\omega_b \cdot r'_{kq1o}} \cdot (X'_{lkq1} + X_{mq})}}$$

$$\tau''_{do} = \frac{\frac{1}{\omega_b \cdot r'_{kdo}} \cdot \left(X'_{lkd} + \frac{X_{md} \cdot X'_{lfd}}{X'_{lfd} + X_{md}} \right)}{1 + \frac{\frac{1}{\omega_b \cdot r'_{kdo}} \cdot (X'_{lkd} + X_{md})}{\frac{1}{\omega_b \cdot r'_{fdo}} \cdot (X'_{lfd} + X_{md})}}$$

$$\begin{pmatrix} r'_{kq1o} \\ r'_{kq2o} \\ r'_{fdo} \\ r'_{kdo} \end{pmatrix} := \text{Find}(r'_{kq1o}, r'_{kq2o}, r'_{fdo}, r'_{kdo})$$

$$r'_{kq1o} = 4.21 \text{m}\Omega$$

$$r'_{fdo} = 0.915 \text{m}\Omega$$

$$r'_{kq2o} = 54.35 \text{m}\Omega$$

$$r'_{kdo} = 27.64 \text{m}\Omega$$

**guess resistance values
based on standard short-circuit equations**

$$r'_{kq1s} := \frac{1}{\omega_b \cdot \tau'_q} \cdot \left(X'_{lkq1} + \frac{X_{mq} \cdot X_{ls}}{X_{mq} + X_{ls}} \right)$$

$$r'_{kq1s} = 2.32\text{m}\Omega$$

$$r'_{fds} := \frac{1}{\omega_b \cdot \tau'_d} \cdot \left(X'_{lfd} + \frac{X_{md} \cdot X_{ls}}{X_{md} + X_{ls}} \right)$$

$$r'_{fds} = 0.567\text{m}\Omega$$

$$r'_{kq2s} := \frac{1}{\omega_b \cdot \tau''_q} \cdot \left(X'_{lkq2} + \frac{X_{mq} \cdot X_{ls} \cdot X'_{lkq1}}{X_{mq} \cdot X_{ls} + X_{mq} \cdot X'_{lkq1} + X_{ls} \cdot X'_{lkq1}} \right)$$

$$r'_{kq2s} = 59.68\text{m}\Omega$$

$$r'_{kds} := \frac{1}{\omega_b \cdot \tau''_d} \cdot \left(X'_{lkd} + \frac{X_{md} \cdot X_{ls} \cdot X'_{lfd}}{X_{md} \cdot X_{ls} + X_{md} \cdot X'_{lfd} + X_{ls} \cdot X'_{lfd}} \right)$$

$$r'_{kds} = 45.9\text{m}\Omega$$

resistances from derived synchronous machine short-circuit time constants

Given

$$\tau'_q = \frac{1}{\omega_b \cdot r'_{kq1s}} \cdot \left(X'_{lkq1} + \frac{X_{mq} \cdot X_{ls}}{X_{ls} + X_{mq}} \right) + \frac{1}{\omega_b \cdot r'_{kq2o}} \cdot \left(X'_{lkq2} + \frac{X_{mq} \cdot X_{ls}}{X_{ls} + X_{mq}} \right)$$

$$\tau'_d = \frac{1}{\omega_b \cdot r'_{fds}} \cdot \left(X'_{lfd} + \frac{X_{md} \cdot X_{ls}}{X_{ls} + X_{md}} \right) + \frac{1}{\omega_b \cdot r'_{kdo}} \cdot \left(X'_{lkd} + \frac{X_{md} \cdot X_{ls}}{X_{ls} + X_{md}} \right)$$

$$\tau''_q = \frac{\frac{1}{\omega_b \cdot r'_{kq2s}} \cdot \left(X'_{lkq2} + \frac{X_{mq} \cdot X_{ls} \cdot X'_{lkq1}}{X_{mq} \cdot X_{ls} + X_{mq} \cdot X'_{lkq1} + X_{ls} \cdot X'_{lkq1}} \right)}{1 + \frac{\frac{1}{\omega_b \cdot r'_{kq2s}} \cdot \left(X'_{lkq2} + \frac{X_{mq} \cdot X_{ls}}{X_{ls} + X_{mq}} \right)}{\frac{1}{\omega_b \cdot r'_{kq1s}} \cdot \left(X'_{lkq1} + \frac{X_{mq} \cdot X_{ls}}{X_{ls} + X_{mq}} \right)}}$$

$$\tau''_d = \frac{\frac{1}{\omega_b \cdot r'_{kds}} \cdot \left(X'_{lkd} + \frac{X_{md} \cdot X_{ls} \cdot X'_{lfd}}{X_{md} \cdot X_{ls} + X_{md} \cdot X'_{lfd} + X_{ls} \cdot X'_{lfd}} \right)}{1 + \frac{\frac{1}{\omega_b \cdot r'_{kds}} \cdot \left(X'_{lkd} + \frac{X_{md} \cdot X_{ls}}{X_{ls} + X_{md}} \right)}{\frac{1}{\omega_b \cdot r'_{fds}} \cdot \left(X'_{lfd} + \frac{X_{md} \cdot X_{ls}}{X_{ls} + X_{md}} \right)}}$$

$$\begin{pmatrix} r'_{kq1s} \\ r'_{kq2s} \\ r'_{fds} \\ r'_{kds} \end{pmatrix} := \text{Find}(r'_{kq1s}, r'_{kq2s}, r'_{fds}, r'_{kds})$$

$$r'_{kq1s} = 2.37 \text{m}\Omega$$

$$r'_{fds} = 0.587 \text{m}\Omega$$

$$r'_{kq2s} = 58.55 \text{m}\Omega$$

$$r'_{kds} = 44.9 \text{m}\Omega$$

final resistances

$$r'_{kq1} := \frac{1}{2} \cdot (r'_{kq1o} + r'_{kq1s})$$

$$r'_{fd} := \frac{1}{2} \cdot (r'_{fdo} + r'_{fds})$$

$$r'_{kq2} := \frac{1}{2} \cdot (r'_{kq2o} + r'_{kq2s})$$

$$r'_{kd} := \frac{1}{2} \cdot (r'_{kdo} + r'_{kds})$$

Synchronous Machine Linearized Equations (Chapter 8)

Applications:

- Eigenvalue analysis
- Transfer functions
- Stability analysis
- Classical control

Taylor Series

single variable

$$g(f) = g(f_0) + \left. \frac{dg(f)}{df} \right|_{f_0} \Delta f + \left. \frac{d^2 g(f)}{df^2} \right|_{f_0} \frac{\Delta f^2}{2} + \left. \frac{d^3 g(f)}{df^3} \right|_{f_0} \frac{\Delta f^3}{6} + \dots$$

where $f = f_0 + \Delta f$

f_0 - operating point

Δf - change in f about operating point

linear approximation

$$g(f) \approx g(f_0) + \left. \frac{dg(f)}{df} \right|_{f_0} \Delta f = g_o + \Delta g$$

express equations in delta variables

$$\Delta g(\Delta f) = \left. \frac{dg(f)}{df} \right|_{f_0} \Delta f$$

Approximate Function of Two Variables

$$g(f_1, f_2) \approx g(f_{1o}, f_{2o}) + \left. \frac{\partial g(f_1, f_2)}{\partial f_1} \right|_{f_{1o}, f_{2o}} \Delta f_1 + \left. \frac{\partial g(f_1, f_2)}{\partial f_2} \right|_{f_{1o}, f_{2o}} \Delta f_2$$

Per Unit System

base speed: ω_b - rated ω_e

base power: $P_B = 3 V_{B(abc)} I_{B(abc)} = \frac{3}{2} V_{B(qd0)} I_{B(qd0)}$

base voltage: $V_{B(abc)}$ - rated rms value of v_{as}

base current: $I_{B(abc)}$ - rated rms value of i_{as}

base torque: $T_B = \frac{P_B}{\left(\frac{2}{P}\right) \omega_b} = \frac{\left(\frac{3}{2}\right) V_{B(qd0)} I_{B(qd0)}}{\left(\frac{2}{P}\right) \omega_b}$

Torque in Per Unit

using substitute variables

$$T_e = \left(\frac{3}{2}\right) \left(\frac{P}{2}\right) \left(\frac{1}{\omega_b}\right) (\Psi_{ds}^r i_{qs}^r - \Psi_{qs}^r i_{ds}^r) = \frac{\frac{3}{2} \Psi_{ds}^r i_{qs}^r - \frac{3}{2} \Psi_{qs}^r i_{ds}^r}{\frac{2}{P} \omega_b}$$

in per-unit

$$T_e = \Psi_{ds}^r i_{qs}^r - \Psi_{qs}^r i_{ds}^r = X_{md} (-i_{ds}^r + i_{fd}^{\prime r} + i_{kd}^{\prime r}) i_{qs}^r - X_{mq} (-i_{qs}^r + i_{kq1}^{\prime r} + i_{kq2}^{\prime r}) i_{ds}^r \quad (\text{in p.u.})$$

mechanical equations

$$T_I - T_e = \left(\frac{2}{P}\right) J p \omega_r$$

in per-unit

$$T_I - T_e = \left(\frac{2}{P}\right) \frac{J \omega_b}{T_B} p \frac{\omega_r}{\omega_b} = 2H p \frac{\omega_r}{\omega_b} \quad (\text{in p.u.})$$

where $H = \left(\frac{1}{2}\right) \left(\frac{2}{P}\right) \frac{J \omega_b}{T_B}$

Linearized Torque Equation

$$T_I = T_e + 2H p \frac{\omega_r}{\omega_b} = T_{Io} + \Delta T_I$$

$$\Delta T_I = \left. \frac{\partial T_I}{\partial i_{qs}^r} \right|_o \Delta i_{qs}^r + \left. \frac{\partial T_I}{\partial i_{ds}^r} \right|_o \Delta i_{ds}^r + \dots$$

where o represents the operating point

$$i_{qso}^r, i_{dso}^r, i_{fdo}^{'r}, i_{kdo}^{'r}, i_{kq1o}^{'r}, i_{kq2o}^{'r}, \omega_{ro}$$

see (8.3-19) for full equation

Torque Angle Equation

$$\delta = \theta_r - \theta_{ev}$$

$$p\delta = \omega_r - \omega_e$$

$$p\Delta\delta = \Delta\omega_r - \Delta\omega_e$$

$$p\Delta\delta = \omega_b \left(\frac{\Delta\omega_r}{\omega_b} \right) \quad \text{if } \Delta\omega_e = 0$$

Synchronous Machine Linearized Equations

$$\begin{bmatrix} \Delta v_{qs}^r \\ \Delta v_{ds}^r \\ \Delta v_{kq1}^{r'} \\ \Delta v_{kq2}^{r'} \\ \Delta e_{afd}^{r'} \\ \Delta v_{kd}^{r'} \\ \Delta T_I \\ 0 \end{bmatrix} = \begin{bmatrix} -r_s - \frac{p}{\omega_b} X_q & -\frac{\omega_c}{\omega_b} X_d & \frac{p}{\omega_b} X_{mq} & \frac{p}{\omega_b} X_{mq} & \frac{\omega_c}{\omega_b} X_{md} & \frac{\omega_c}{\omega_b} X_{md} & -X_d i_{dso}^r + X_{md} i_{fdo}^{r'} & 0 \\ \frac{\omega_c}{\omega_b} X_q & -r_s - \frac{p}{\omega_b} X_d & -\frac{\omega_c}{\omega_b} X_{mq} & -\frac{\omega_c}{\omega_b} X_{mq} & \frac{p}{\omega_b} X_{md} & \frac{p}{\omega_b} X_{md} & X_q i_{qso}^r & 0 \\ -\frac{p}{\omega_b} X_{mq} & 0 & r'_{kq1} + \frac{p}{\omega_b} X'_{kq1} & \frac{p}{\omega_b} X_q & 0 & 0 & 0 & 0 \\ -\frac{p}{\omega_b} X_{mq} & 0 & \frac{p}{\omega_b} X_{mq} & r'_{kq2} + \frac{p}{\omega_b} X'_{kq2} & 0 & 0 & 0 & 0 \\ 0 & -\frac{X_{md}}{r'_{fd}} \left(\frac{p}{\omega_b} X_{md} \right) & 0 & 0 & \frac{X_{md}}{r'_{fd}} \left(r'_{fd} + \frac{p}{\omega_b} X'_{fd} \right) & \frac{X_{md}}{r'_{fd}} \left(\frac{p}{\omega_b} X_{md} \right) & 0 & 0 \\ 0 & -\frac{p}{\omega_b} X_{md} & 0 & 0 & \frac{p}{\omega_b} X_{md} & r'_{kd} + \frac{p}{\omega_b} X'_{kd} & 0 & 0 \\ X_{mq} i_{dso}^r - X_{md} (i_{dso}^r - i_{fdo}^{r'}) & -X_{md} i_{qso}^r + X_{mq} i_{qso}^r & -X_{mq} i_{dso}^r & -X_{mq} i_{dso}^r & X_{md} i_{qso}^r & X_{md} i_{qso}^r & 2Hp & 0 \\ 0 & 0 & 0 & 0 & 0 & 0 & -\omega_b & p \end{bmatrix} \begin{bmatrix} \Delta i_{qs}^r \\ \Delta i_{ds}^r \\ \Delta i_{kq1}^{r'} \\ \Delta i_{kq2}^{r'} \\ \Delta i_{fd}^{r'} \\ \Delta i_{kd}^{r'} \\ \frac{\Delta \omega_r}{\omega_b} \\ \Delta \delta \end{bmatrix}$$

Source Voltage

$$v_{as} = \sqrt{2}v_s \cos(\theta_{ev})$$

$$v_{bs} = \sqrt{2}v_s \cos(\theta_{ev} - \frac{2\pi}{3})$$

$$v_{cs} = \sqrt{2}v_s \cos(\theta_{ev} + \frac{2\pi}{3})$$

synchronous reference frame

$$v_{qs}^e = \sqrt{2}v_s \quad v_{qso}^e = \sqrt{2}v_s \quad \Delta v_{qs}^e = 0$$

$$v_{ds}^e = 0 \quad v_{dso}^e = 0 \quad \Delta v_{ds}^e = 0$$

rotor reference frame

$$\begin{bmatrix} v_{qs}^r \\ v_{ds}^r \end{bmatrix} = \begin{bmatrix} \cos(\theta_r - \theta_{ev}) & -\sin(\theta_r - \theta_{ev}) \\ \sin(\theta_r - \theta_{ev}) & \cos(\theta_r - \theta_{ev}) \end{bmatrix} \begin{bmatrix} v_{qs}^e \\ v_{ds}^e \end{bmatrix} = \begin{bmatrix} \cos(\delta) & -\sin(\delta) \\ \sin(\delta) & \cos(\delta) \end{bmatrix} \begin{bmatrix} v_{qs}^e \\ v_{ds}^e \end{bmatrix}$$

Linearized Source Voltage Equations

$$v_{qs}^r = v_{qs}^e \cos(\delta) - v_{ds}^e \sin(\delta) = v_{qso}^r + \Delta v_{qs}^r$$

$$\Delta v_{qs}^r = \cos(\delta_o) \Delta v_{qs}^e - \sin(\delta_o) \Delta v_{ds}^e - \left[\sin(\delta_o) v_{qso}^e + \cos(\delta_o) v_{dso}^e \right] \Delta \delta$$

note: $v_{dso}^r = \sin(\delta_o) v_{qso}^e + \cos(\delta_o) v_{dso}^e$

$$\Delta v_{qs}^r = \cos(\delta_o) \Delta v_{qs}^e - \sin(\delta_o) \Delta v_{ds}^e - v_{dso}^r \Delta \delta$$

$$\begin{bmatrix} \Delta v_{qs}^r \\ \Delta v_{ds}^r \end{bmatrix} = \begin{bmatrix} \cos(\delta_o) & -\sin(\delta_o) \\ \sin(\delta_o) & \cos(\delta_o) \end{bmatrix} \begin{bmatrix} \Delta v_{qs}^e \\ \Delta v_{ds}^e \end{bmatrix} + \begin{bmatrix} -v_{dso}^r \\ v_{qso}^r \end{bmatrix} \Delta \delta$$

Transformations

transformation to rotor

$$\begin{bmatrix} \Delta f_{qs}^r \\ \Delta f_{ds}^r \end{bmatrix} = \begin{bmatrix} \cos(\delta_o) & -\sin(\delta_o) \\ \sin(\delta_o) & \cos(\delta_o) \end{bmatrix} \begin{bmatrix} \Delta f_{qs}^e \\ \Delta f_{ds}^e \end{bmatrix} + \begin{bmatrix} -f_{dso}^r \\ f_{qso}^r \end{bmatrix} \Delta \delta$$

where f can be v , i , or λ

inverse transformation

$$\begin{bmatrix} \Delta f_{qs}^e \\ \Delta f_{ds}^e \end{bmatrix} = \begin{bmatrix} \cos(\delta_o) & \sin(\delta_o) \\ -\sin(\delta_o) & \cos(\delta_o) \end{bmatrix} \begin{bmatrix} \Delta f_{qs}^r \\ \Delta f_{ds}^r \end{bmatrix} + \begin{bmatrix} f_{dso}^e \\ -f_{qso}^e \end{bmatrix} \Delta \delta$$

compressed equations

$$\Delta \mathbf{f}_{qds}^r = \mathbf{T} \Delta \mathbf{f}_{qds}^e + \mathbf{F}^r \Delta \delta$$

$$\Delta \mathbf{f}_{qds}^e = (\mathbf{T})^{-1} \Delta \mathbf{f}_{qds}^r + \mathbf{F}^e \Delta \delta$$

Equations in Functional Form

$$\begin{bmatrix} \cos \delta_o \Delta v_{qs}^e - \sin \delta_o \Delta v_{ds}^e \\ \sin \delta_o \Delta v_{qs}^e + \cos \delta_o \Delta v_{ds}^e \\ \Delta v_{kq1}^r \\ \Delta v_{kq2}^r \\ \Delta e_{xfd}^r \\ \Delta v_{kd}^r \\ \Delta T_l \\ 0 \end{bmatrix} = \begin{bmatrix} \text{First} \\ \text{seven} \\ \text{columns} \\ \text{same as} \\ \text{(8.3.19)} \\ p \end{bmatrix} \begin{bmatrix} \left(r_s + \frac{p}{\omega_b} X_q \right) i_{dso}^r + \frac{\omega_c}{\omega_b} X_d i_{qso}^r + v_{dso}^r \\ \left(-r_s - \frac{p}{\omega_b} X_d \right) i_{qso}^r + \frac{\omega_c}{\omega_b} X_q i_{dso}^r - v_{qso}^r \\ \frac{p}{\omega_b} X_{mq} i_{dso}^r \\ \frac{p}{\omega_b} X_{mq} i_{dso}^r \\ - \frac{X_{md}}{r_{fd}} \left(\frac{p}{\omega_b} X_{md} \right) i_{qso}^r \\ - \frac{p}{\omega_b} X_{md} i_{qso}^r \\ - i_{dso}^r [X_{mq} i_{dso}^r - X_{md} (i_{dso}^r - i_{fdo}^r)] \\ - i_{qso}^r (X_{md} i_{qso}^r - X_{mq} i_{qso}^r) \end{bmatrix} \begin{bmatrix} \cos \delta_o \Delta i_{qs}^e - \sin \delta_o \Delta i_{ds}^e \\ \sin \delta_o \Delta i_{qs}^e + \cos \delta_o \Delta i_{ds}^e \\ \Delta i_{kq1}^r \\ \Delta i_{kq2}^r \\ \Delta i_{fd}^r \\ \Delta i_{kd}^r \\ \frac{\Delta \omega_c}{\omega_b} \\ \Delta \delta \end{bmatrix}$$

rearrange to form

$$p\mathbf{x} = \mathbf{Ax} + \mathbf{Bu}$$

$$p\mathbf{x} = \mathbf{Ax} + \mathbf{Bu}$$

$$\mathbf{A} = (\mathbf{E})^{-1}\mathbf{F}$$

$$\mathbf{B} = (\mathbf{E})^{-1}$$

$$\mathbf{E} = \begin{bmatrix} (\mathbf{T})^{-1}\mathbf{W}_p\mathbf{T} & (\mathbf{T})^{-1}\mathbf{Y}_p \\ \mathbf{Q}_p\mathbf{T} & \mathbf{S}_p \end{bmatrix}$$

$$\mathbf{F} = -\begin{bmatrix} (\mathbf{T})^{-1}\mathbf{W}_k\mathbf{T} & (\mathbf{T})^{-1}\mathbf{Y}_k \\ \mathbf{Q}_k\mathbf{T} & \mathbf{S}_k \end{bmatrix}$$

$$x = \begin{bmatrix} \Delta i_{qs}^e \\ \Delta i_{ds}^e \\ \Delta i_{kq1}^{'r} \\ \Delta i_{kq2}^{'r} \\ \Delta i_{fd}^{'r} \\ \Delta i_{kd}^{'r} \\ \Delta \frac{\omega_r}{\omega_b} \\ \Delta \delta \end{bmatrix}$$

$$u = \begin{bmatrix} \Delta v_{qs}^e \\ \Delta v_{ds}^e \\ \Delta v_{kq1}^{'r} \\ \Delta v_{kq2}^{'r} \\ \Delta e_{xfd}^{'r} \\ \Delta v_{kd}^{'r} \\ \Delta T_I \\ 0 \end{bmatrix}$$

Eigenvalue Analysis

Find Eigenvalues from $\det(\mathbf{A} - \lambda\mathbf{I}) = 0$

Example:

Table 8.6-1 Synchronous Machine Eigenvalues for Rated Conditions

Hydro Turbine Generator	Steam Turbine Generator
$-3.58 \pm j77$	$-4.45 \pm j377$
$-1.33 \pm j8.68$	$-1.70 \pm j10.5$
-24.4	-32.2
-22.9	-11.1
-0.453	-0.349
	-0.855

60-Hz damped

$$\tau = 1/3.58 = 0.27\text{s}$$

rotor oscillations

$$T = 2\pi/8.68 = 0.72\text{s}$$

$$\tau = 1/1.33 = 0.75\text{s}$$

rotor circuit time constants

$$\text{field: } \tau = 1/0.453 = 2.215\text{s}$$

Fault Simulation




Figure 5.11-1 Dynamic performance of a hydro turbine generator during a 3-phase fault at the terminals.

Synchronous Machine Reduced-Order Equations (Chapter 8)

Neglecting stator transients:

- Provides approximate transient prediction
- Works better for larger machines
- Reduces number of states
 - Helpful in power system simulations
- Model inputs are currents
 - Good for average-value models of current-regulated power electronic converters

Neglect Stator Transients

Neglect $p\lambda_{qs}^e$ $p\lambda_{ds}^e$

In the synchronous reference frame

$$v_{qs}^e = -r_s i_{qs}^e + \frac{\omega_e}{\omega_b} \Psi_{ds}^e + \cancel{p \Psi_{qs}^e} \quad 0$$

$$v_{ds}^e = -r_s i_{ds}^e - \frac{\omega_e}{\omega_b} \Psi_{qs}^e + \cancel{p \Psi_{ds}^e} \quad 0$$

Accurate in steady-state,
approximately true in transient-state

Transform to Rotor Reference Frame

Frame-to-frame transformation: ${}^e K^r = \begin{bmatrix} \cos(\theta_r - \theta_e) & -\sin(\theta_r - \theta_e) & 0 \\ \sin(\theta_r - \theta_e) & \cos(\theta_r - \theta_e) & 0 \\ 0 & 0 & 1 \end{bmatrix}$

$${}^e K^r v_{qd0s}^e = -r_s {}^e K^r i_{qd0s}^e + \frac{\omega_e}{\omega_b} {}^e K^r \Psi_{dqs}^e \quad \Psi_{dqs}^e = \begin{bmatrix} \Psi_{ds}^e \\ -\Psi_{qs}^e \\ 0 \end{bmatrix}$$

↓

$$\frac{\omega_e}{\omega_b} [\Psi_{ds}^e \cos(\theta_r - \theta_e) + \Psi_{qs}^e \sin(\theta_r - \theta_e)] = \frac{\omega_e}{\omega_b} \Psi_{ds}^r$$

$$\frac{\omega_e}{\omega_b} [\Psi_{ds}^e \sin(\theta_r - \theta_e) - \Psi_{qs}^e \cos(\theta_r - \theta_e)] = -\frac{\omega_e}{\omega_b} \Psi_{qs}^r$$

$$v_{qd0s}^r = -r_s i_{qd0s}^r + \frac{\omega_e}{\omega_b} \Psi_{dqs}^r \quad \Psi_{dqs}^r = \begin{bmatrix} \Psi_{ds}^r \\ -\Psi_{qs}^r \\ 0 \end{bmatrix}$$

Reduced-Order Model Equations

$$v_{qs}^r = -r_s i_{qs}^r + \frac{\omega_e}{\omega_b} \psi_{ds}^r$$

$$v_{ds}^r = -r_s i_{ds}^r - \frac{\omega_e}{\omega_b} \psi_{qs}^r$$

$$v_{kq1}^r = r'_{kq1} i_{kq1}^r + \frac{p}{\omega_b} \psi_{kq1}^r$$

$$v_{kq2}^r = r'_{kq2} i_{kq2}^r + \frac{p}{\omega_b} \psi_{kq2}^r$$

$$v_{fd}^r = r'_{fd} i_{fd}^r + \frac{p}{\omega_b} \psi_{fd}^r$$

$$v_{kd}^r = r'_{kd} i_{kd}^r + \frac{p}{\omega_b} \psi_{kd}^r$$

$$\psi_{qs}^r = -X_{ls} i_{qs}^r + X_{mq} (-i_{qs}^r + i_{kq1}^r + i_{kq2}^r)$$

$$\psi_{ds}^r = -X_{ls} i_{ds}^r + X_{md} (-i_{ds}^r + i_{fd}^r + i_{kd}^r)$$

$$\psi_{kq1}^r = X'_{lkq1} i_{kq1}^r + X_{mq} (-i_{qs}^r + i_{kq1}^r + i_{kq2}^r)$$

$$\psi_{kq2}^r = X'_{lkq2} i_{kq2}^r + X_{mq} (-i_{qs}^r + i_{kq1}^r + i_{kq2}^r)$$

$$\psi_{fd}^r = X'_{lfd} i_{fd}^r + X_{md} (-i_{ds}^r + i_{fd}^r + i_{kd}^r)$$

$$\psi_{kd}^r = X'_{lkd} i_{kd}^r + X_{md} (-i_{ds}^r + i_{fd}^r + i_{kd}^r)$$

Eigenvalue Examples

Full-order model Eigenvalues

Table 8.6-1 Synchronous Machine Eigenvalues for Rated Conditions

Hydro Turbine Generator	Steam Turbine Generator
$-3.58 \pm j77-377$	$-4.45 \pm j377$
$-1.33 \pm j8.68$	$-1.70 \pm j10.5$
-24.4	-32.2
-22.9	-11.1
-0.453	-0.349
	-0.855

Reduced-order model Eigenvalues

Table 9.6-2 Synchronous Machine Eigenvalues for Rated Conditions Calculated with Stator Electric Transients Neglected

Hydro Turbine Generator	Steam Turbine Generator
$-1.33 \pm j8.68$	$-1.70 \pm j10.5$
-24.4	-32.2
-22.9	-11.1
-0.453	-0.855
	-0.350

← stator transients gone
(no $\pm j377$ term)

Fault Simulation




Figure 5.11-1 Dynamic performance of a hydro turbine generator during a 3-phase fault at the terminals.

Full-order model




Figure 9.4-1 Dynamic performance of a hydro turbine generator during a 3-phase fault at the terminals predicted with stator electric transients neglected.

Reduced-order model