




ECE 802, Electric Motor Control

Indirect Vector Control

Indirect Vector Control (Chapter 14)

- High-performance fast-response control
- Based on dynamic q - d model
- Rotor oriented (using rotor equations)

structure



Rotor Equations

induction motor model in the synchronous reference frame

$$v_{qr}'^e = r_r' i_{qr}'^e + (\omega_e - \omega_r) \lambda_{dr}'^e + p \lambda_{qr}'^e = 0 \quad (1)$$

$$v_{dr}'^e = r_r' i_{dr}'^e - (\omega_e - \omega_r) \lambda_{qr}'^e + p \lambda_{dr}'^e = 0 \quad (2)$$

$$\lambda_{qr}'^e = L_{rr}' i_{qr}'^e + L_M i_{qs}^e \quad (3)$$


$$\lambda_{dr}'^e = L_{rr}' i_{dr}'^e + L_M i_{ds}^e \quad (4)$$

$$T_e = \frac{3}{2} \frac{P}{2} (\lambda_{qr}'^e i_{dr}'^e - \lambda_{dr}'^e i_{qr}'^e) \quad (5)$$

Note: Torque equation is not as straightforward as with the PMSM

If $\lambda_{qr}'^e = 0$, torque equation is straightforward
 Design vector control so that

$$\omega_e - \omega_r = \frac{-r_r' i_{qr}'^e}{\lambda_{dr}'^e} \quad (6)$$



Note, from (1) and (6)

$$p\lambda_{qr}'^e = -r_r' i_{qr}'^e - (\omega_e - \omega_r)\lambda_{dr}'^e = 0$$

$$\text{so } \lambda_{qr}'^e = \lambda_{qr}'^e \Big|_{t=0} = 0 \quad (\text{if motor is not energized at } t = 0)$$

$$\text{then } \lambda_{qr}'^e = 0$$

From (2) with $\lambda_{qr}'^e = 0$

$$r_r' i_{dr}'^e + p \lambda_{dr}'^e = 0 \quad (7)$$

Substitute (4) into (7)

$$r_r' i_{dr}'^e + L_{rr}' p i_{dr}'^e + L_M p i_{ds}^e = 0$$

From modulation (hysteresis or sine-triangle with compensation)


$$i_{ds}^e = i_{ds}^{e*} \quad i_{qs}^e = i_{qs}^{e*}$$

Command constant d -axis current so $p i_{ds}^{e*} = 0$

$$\text{Then } p i_{dr}'^e = \frac{-r_r'}{L_{rr}'} i_{dr}'^e$$

$$\tau_r = \frac{L_{rr}'}{r_r'} \quad (\text{rotor time constant})$$

$$\text{Solution is: } i_{dr}'^e = A e^{-t/\tau_r}$$



after $t = 5 \tau_r$ $i_{dr}'^e \approx 0$
(with constant i_{ds}^{e*})

with $i_{dr}^{'e} = 0$ $p\lambda_{qr}^{'e} = 0$ $\lambda_{qr}^{'e} = 0$

$$\omega_e - \omega_r = \frac{-r'_r i_{qr}^{'e}}{\lambda_{dr}^{'e}} \quad (8)$$

$$L'_{rr} i_{qr}^{'e} + L_M i_{qs}^e = 0 \quad (9)$$

$$\lambda_{dr}^{'e} = L_M i_{ds}^e \quad (10)$$

$$T_e = -\frac{3}{2} \frac{P}{2} \lambda_{dr}^{'e} i_{qr}^{'e} \quad (11)$$

Substitute (9) into (11)

$$T_e = \frac{3}{2} \frac{P}{2} \lambda_{dr}^{'e} \frac{L_M}{L'_{rr}} i_{qs}^e \quad (12)$$

With knowledge of $\lambda_{dr}'^e$ and L_M

Specifically command $i_{ds}^{e*} = \frac{\lambda_{dr}'^{e*}}{L_M}$ $\lambda_{dr}'^{e*}$ desired or rated $\lambda_{dr}'^e$

From (10) $\lambda_{dr}'^e = L_M i_{ds}^e = L_M i_{ds}^{e*} = \lambda_{dr}'^{e*}$

$$\lambda_{dr}'^e = \lambda_{dr}'^{e*}$$

For the q -axis, specifically command, $i_{qs}^{e*} = \frac{2}{3} \frac{2}{P} \frac{L'_{rr}}{L_M} \frac{T_e^*}{\lambda_{dr}' e^*}$

From (12) $T_e = \frac{3}{2} \frac{P}{2} \lambda_{dr}' e \frac{L_M}{L'_{rr}} \left(\frac{2}{3} \frac{2}{P} \frac{L'_{rr}}{L_M} \frac{T_e^*}{\lambda_{dr}' e^*} \right)$

$$T_e = T_e^*$$

From (8) and (9)


$$\omega_e - \omega_r = \frac{r'_r}{L'_{rr}} \frac{L_M}{\lambda'_{dr}} i_{qs}^e$$

In terms of commanded current,

$$\omega_e - \omega_r = \frac{r'_r}{L'_{rr}} \frac{i_{qs}^{e*}}{i_{ds}^{e*}}$$

Vector Control Implementation Steps

Example: 5hp (3.7 kW) induction motor



- command $\lambda_{dr}'^{e*} = \sqrt{2} |\tilde{\Lambda}'_{ar}| = 0.385 \text{ V} \cdot \text{s}$
- wait $5\tau_r = 1.5 \text{ sec}$
- command step in torque

constant speed

$$\omega_{rm} = 1750 \text{ rpm} = 183.3 \text{ rad / sec}$$

hysteresis $h = 0.5 \text{ A}$

IM Steady-State Calculations

IM parameters

$$\text{RPM} := \frac{2 \cdot \pi \cdot \text{rad}}{60 \cdot \text{s}}$$

$$r_s := 0.4 \Omega$$

$$P := 4$$

$$r'_r := 0.2266 \Omega$$

$$\text{lagging} := 1$$

$$L_{ls} := 5.73 \text{ mH}$$

$$L_M := 64.4 \text{ mH}$$

$$L'_{lr} := 4.64 \text{ mH}$$

$$L_{ss} := L_{ls} + L_M$$

$$L_{ss} = 70.1 \text{ mH}$$

$$L'_{lr} := L'_{lr} + L_M$$

$$L'_{lr} = 69 \text{ mH}$$

operating conditions

$$f_e := 60 \text{ Hz}$$

$$\omega_e := 2 \cdot \pi \cdot f_e$$

$$\omega_e = 377 \frac{\text{rad}}{\text{s}}$$

$$\omega_{rm} := 1750 \text{ RPM}$$

$$\omega_{rm} = 183.3 \frac{\text{rad}}{\text{s}}$$

$$V_{LL} := 220 \text{ V}$$

$$V_s := \frac{V_{LL}}{\sqrt{3}}$$

$$V_s = 127 \text{ V}$$

synchronous speed (no-load speed)

$$\omega_{em} := \left(\frac{2}{P} \right) \cdot \omega_e$$

$$\omega_{em} = 188.5 \frac{\text{rad}}{\text{s}}$$

$$\omega_{em} = 1800 \text{ RPM}$$

slip

$$\omega_r := \frac{P}{2} \cdot \omega_{rm}$$

$$\omega_r = 366.5 \frac{\text{rad}}{\text{s}}$$

$$s := \frac{\omega_e - \omega_r}{\omega_e}$$

$$s = 0.0278$$

IM Steady-State Calculations

impedances

$$Z_s := r_s + j \cdot \omega_e \cdot L_{ls}$$

$$|Z_s| = 2.2\Omega$$

$$\arg(Z_s) = 79.5\text{deg}$$

$$Z_m := j \cdot \omega_e \cdot L_M$$

$$|Z_m| = 24.3\Omega$$

$$\arg(Z_m) = 90\text{deg}$$

$$Z'_r := \frac{r'_r}{s} + j \cdot \omega_e \cdot L'_{lr}$$

$$|Z'_r| = 8.34\Omega$$

$$\arg(Z'_r) = 12.1\text{deg}$$

$$Z_f := \frac{1}{\frac{1}{Z_m} + \frac{1}{Z'_r}}$$

$$|Z_f| = 7.43\Omega$$

$$\arg(Z_f) = 29.5\text{deg}$$

$$Z_{in} := Z_s + Z_f$$

$$|Z_{in}| = 9\Omega$$

$$\arg(Z_{in}) = 40.3\text{deg}$$

currents

$$V_{as} := V_s \cdot e^{j \cdot 0}$$

$$I_{as} := \frac{V_{as}}{Z_{in}}$$

$$|I_{as}| = 14.1\text{A}$$

$$\arg(I_{as}) = -40.3\text{deg}$$

$$I'_{ar} := -I_{as} \cdot \frac{Z_m}{Z_m + Z'_r}$$

$$|I'_{ar}| = 12.6\text{A}$$

$$\arg(I'_{ar}) = 157.1\text{deg}$$

IM Steady-State Calculations

torque and power

$$T_e := 3 \cdot \frac{P}{2} \cdot \left(|I_{ar}| \right)^2 \cdot \frac{r'_r}{s \cdot \omega_e}$$

$$T_e = 20.5 \text{ N}\cdot\text{m}$$

$$T_e := \frac{3 \cdot \left(\frac{P}{2} \right) \cdot \omega_e \cdot L_M^2 \cdot r'_r \cdot s \cdot \left(|V_{as}| \right)^2}{\left[r_s \cdot r'_r + s \cdot \omega_e^2 \cdot \left(L_M^2 - L_{ss} \cdot L'_{rr} \right) \right]^2 + \omega_e^2 \cdot \left(r'_r \cdot L_{ss} + s \cdot r_s \cdot L'_{rr} \right)^2}$$

$$T_e = 20.5 \text{ N}\cdot\text{m}$$

$$\theta := \arg(Z_{in})$$

$$\theta = 40.3 \text{ deg}$$

$$\text{pf} := \cos(\theta)$$

$$\text{pf} = 0.763 \text{ lagging}$$

$$P_{in} := 3 \cdot |V_{as}| \cdot |I_{as}| \cdot \text{pf}$$

$$P_{in} = 4.104 \text{ kW}$$

$$P_{out} := T_e \cdot \omega_{rm}$$

$$P_{out} = 3.757 \text{ kW}$$

$$P_{out} = 5 \text{ hp}$$

$$\text{eff} := \frac{P_{out}}{P_{in}}$$

$$\text{eff} = 91.6\%$$

IM Steady-State Calculations

magnetizing flux linkage

$$I_{am} := I_{as} + I_{ar}$$

$$|I_{am}| = 4.32A$$

$$\arg(I_{am}) = -100.8\text{deg}$$

$$\Lambda_m := L_M \cdot I_{am}$$

$$\boxed{|\Lambda_m| = 0.278V \cdot \text{sec}}$$

$$V_m := V_{as} - Z_s \cdot I_{as}$$

$$|V_m| = 105V$$

$$\arg(V_m) = -10.8\text{deg}$$

$$\Lambda_m := \frac{V_m}{\omega_e}$$

$$|\Lambda_m| = 0.278V \cdot \text{sec}$$

rotor flux linkage

$$\Lambda'_r := \frac{-I'_{ar} \cdot \frac{r'_r}{s}}{j \cdot \omega_e}$$

$$|\Lambda'_r| = 0.272V \cdot \text{sec}$$


$$\boxed{\sqrt{2} \cdot |\Lambda'_r| = 0.385V \cdot \text{sec}}$$

rotor time constant

$$\tau_r := \frac{L'_{rr}}{r'_r}$$


$$\tau_r = 0.3s$$

$$5 \cdot \tau_r = 1.5s$$



Vector controlled induction motor with hysteresis control

$P = 4$	$L_M = 64.43 \text{ mH}$	$\lambda_{dre}'^* = 0.385 \text{ V-sec}$	$h = 0.5 \text{ A}$
$r_s = 0.3996 \Omega$	$r_r' = 0.2266 \Omega$	$T_e^* = 20 \text{ N-m}$	
$L_{ls} = 5.73 \text{ mH}$	$L_{lr}' = 4.64 \text{ mH}$	$\omega_{rm} = 1750 \text{ RPM} = 183.3 \text{ rad/sec}$	



Vector controlled induction motor with hysteresis control

$P = 4$	$L_M = 64.43 \text{ mH}$	$\lambda_{dre}^* = 0.385 \text{ V-sec}$	$h = 0.5 \text{ A}$
$r_s = 0.3996 \Omega$	$r_r' = 0.2266 \Omega$	$T_e^* = 20 \text{ N-m}$	
$L_{ls} = 5.73 \text{ mH}$	$L_{lr}' = 4.64 \text{ mH}$	$\omega_{rm} = 1750 \text{ RPM} = 183.3 \text{ rad/sec}$	

Vector Control Terminology

Define vectors $\vec{\lambda}_{qdr}'^e = \lambda_{qr}'^e - j\lambda_{dr}'^e$ $\vec{i}_{qdr}'^e = i_{qr}'^e - ji_{dr}'^e$

Vector control ensures, $\lambda_{qr}'^e = 0$ $i_{dr}'^e = 0$

$$\vec{\lambda}_{qdr}'^e = -j\lambda_{dr}'^e \quad \vec{i}_{qr}'^e = i_{qr}'^e$$

For motor operation $T_e^* > 0$ so $i_{qs}^{e*} > 0$

$$i_{qr}'^e = \frac{-L_M}{L_{rr}} i_{qs}^{e*} \quad \text{so } i_{qr}'^e < 0$$

Synchronous reference frame vectors


Note $\left| \vec{\lambda}_{qdr}'^e \times \vec{i}_{qdr}'^e \right| = \left| \vec{\lambda}_{qdr}'^e \right| \left| \vec{i}_{qdr}'^e \right| \sin \left(\angle \vec{i}_{qdr}'^e - \angle \vec{\lambda}_{qdr}'^e \right) = \lambda_{dr}'^e i_{qr}'^e$

from before, $T_e = \frac{3}{2} \frac{P}{2} (\lambda_{qr}'^e i_{dr}'^e - \lambda_{dr}'^e i_{qr}'^e)$

with $\lambda_{qr}'^e = 0$ $i_{dr}'^e = 0$ $T_e = -\frac{3}{2} \frac{P}{2} \lambda_{dr}'^e i_{qr}'^e$

Cross-Coupling Compensation Control

Interface vector control to voltage-source modulation




Compensation Control

add $\omega_e \lambda_{qs}^e$ and $\omega_e \lambda_{ds}^e$ to v_{qs}^{e*} and v_{ds}^{e*}

command

$$v_{qs}^{e*} = \left(K_{pc} + \frac{K_{ic}}{s} \right) (i_{qs}^{e*} - i_{qs}^e) + \omega_e \lambda_{ds}^e$$

$$v_{ds}^{e*} = \left(K_{pc} + \frac{K_{ic}}{s} \right) (i_{ds}^{e*} - i_{ds}^e) - \omega_e \lambda_{qs}^e$$



Next step : Compute λ_{qs}^e and λ_{ds}^e from i_{qs}^e , i_{ds}^e

Stator Flux Linkage from Commanded Currents

Note: Vector control ensures $\lambda_{qr}'^e = 0$ $i_{dr}'^e = 0$

From machine equations:

$$\lambda_{ds}^e = L_{ls} i_{ds}^e + L_M (i_{ds}^e + i_{dr}'^e) = L_{ss} i_{ds}^e + L_M i_{dr}'^e$$

$$\lambda_{ds}^e = L_{ss} i_{ds}^{e*}$$


$$\lambda_{qr}'^e = L'_{lr} i_{qr}'^e + L_M (i_{qs}^e + i_{qr}'^e) = L'_{rr} i_{qr}'^e + L_M i_{qs}^e = 0$$

$$\rightarrow i_{qr}'^e = \frac{-L_M}{L'_{rr}} i_{qs}^e$$

$$\lambda_{qs}^e = L_{ls} i_{qs}^e + L_M (i_{qs}^e + i_{qr}'^e) = L_{ss} i_{qs}^e + L_M i_{qr}'^e = L_{ss} i_{qs}^e - \frac{L_M^2}{L'_{rr}} i_{qs}^e$$

$$\lambda_{qs}^e = \left(L_{ss} - \frac{L_M^2}{L'_{rr}} \right) i_{qs}^{e*}$$

Compensation Control Block Diagram



Practical Current Measurement Technique

τ = low-pass filter time constant (sec)

f_c = low-pass filter cut-off frequency (Hz)

set f_c lower than the switching frequency
but higher than the fundamental frequency

Determine T1 - T6 from v_{qs}^{e*}, v_{ds}^{e*}

modulation index

$$V_s^* = \frac{1}{\sqrt{2}} \sqrt{(v_{qs}^{e*})^2 + (v_{ds}^{e*})^2}$$

$$d = 2\sqrt{2} \frac{V_s^*}{v_{dc}}$$

phase shift

$$\phi_v^* = \tan^{-1} \left(\frac{-v_{ds}^{e*}}{v_{qs}^{e*}} \right)$$

$$\theta_c = \theta_e + \phi_v^*$$

duty cycles

$$d_a = d \cos(\theta_c) - \frac{d}{6} \cos(3\theta_c)$$

$$d_b = d \cos\left(\theta_c - \frac{2\pi}{3}\right) - \frac{d}{6} \cos(3\theta_c)$$


$$d_c = d \cos\left(\theta_c + \frac{2\pi}{3}\right) - \frac{d}{6} \cos(3\theta_c)$$

compare to a triangle waveform to obtain T1 - T6

Example from before: 5hp (3.7 kW) motor


constant speed with cross-coupling compensation control

- command $\lambda_{dr}'^{e*} = \sqrt{2} |\tilde{\Lambda}'_{ar}| = 0.385 \text{ V} \cdot \text{s}$
- wait $5\tau_r = 1.5 \text{ sec}$
- command step in torque



Vector controlled induction motor with sine-triangle modulation

$P = 4$	$L_M = 64.43 \text{ mH}$	$\lambda_{dre}^* = 0.385 \text{ V-sec}$
$r_s = 0.3996 \Omega$	$r_r' = 0.2266 \Omega$	$T_e^* = 20 \text{ N-m}$
$L_{ls} = 5.73 \text{ mH}$	$L_{lr}' = 4.64 \text{ mH}$	$\omega_{rm} = 1750 \text{ RPM} = 183.3 \text{ rad/sec}$
$K_{pc} = 50 \text{ V/A}$	$K_{ic} = 50 \text{ V/A-sec}$	



Vector controlled induction motor with sine-triangle modulation

$$P = 4$$

$$L_M = 64.43 \text{ mH}$$

$$\lambda_{dre}^* = 0.385 \text{ V-sec}$$

$$r_s = 0.3996 \Omega$$

$$r_r' = 0.2266 \Omega$$

$$T_e^* = 20 \text{ N-m}$$


$$L_{ls} = 5.73 \text{ mH}$$

$$L_{lr}' = 4.64 \text{ mH}$$

$$\omega_{rm} = 1750 \text{ RPM} = 183.3 \text{ rad/sec}$$


$$K_{pc} = 50 \text{ V/A}$$

$$K_{ic} = 50 \text{ V/A-sec}$$



Vector controlled induction motor with sine-triangle modulation

$P = 4$	$L_M = 64.43 \text{ mH}$	$\lambda_{dre}^* = 0.385 \text{ V-sec}$
$r_s = 0.3996 \Omega$	$r_r' = 0.2266 \Omega$	$T_e^* = 20 \text{ N-m}$
$L_{ls} = 5.73 \text{ mH}$	$L_{lr}' = 4.64 \text{ mH}$	$\omega_{rm} = 1750 \text{ RPM} = 183.3 \text{ rad/sec}$
$K_{pc} = 50 \text{ V/A}$	$K_{ic} = 5000 \text{ V/A-sec}$	



Vector controlled induction motor with sine-triangle modulation

$$P = 4$$

$$L_M = 64.43 \text{ mH}$$

$$\lambda_{dre}^* = 0.385 \text{ V-sec}$$

$$r_s = 0.3996 \Omega$$

$$r_r' = 0.2266 \Omega$$

$$T_e^* = 20 \text{ N-m}$$

$$L_{ls} = 5.73 \text{ mH}$$

$$L_{lr}' = 4.64 \text{ mH}$$

$$\omega_{rm} = 1750 \text{ RPM} = 183.3 \text{ rad/sec}$$

$$K_{pc} = 50 \text{ V/A}$$

$$K_{ic} = 5000 \text{ V/A-sec}$$

Indirect Vector Control

Based on rotor equations formulated in the synchronous reference frame

Based on controlling the flux and current to be at 90 degrees. The d -axis current sets the flux much like the field of a dc machine. The q -axis current sets the torque much like the armature of a dc machine.


Implementation is straightforward if the machine parameters are known. The vector control can be followed by a current regulated control or a voltage-source control with cross-coupling compensation.

Speed and Position Control

mechanical systems

- Regulator applications - keep output constant despite disturbances (inertia helps)
- Servo applications - rapidly change system output (inertia hinders)

system control




Speed Control Example

Motor from before 5hp (3.7 kW)


$$J = 0.15 \text{ kg}\cdot\text{m}^2$$

- ramp speed command from zero to rated
- step load torque from zero to rated
- ramp speed from rated to zero while rated load torque is applied



Vector controlled induction motor with sine-triangle modulation and speed control

$P = 4$	$L_M = 64.43 \text{ mH}$	$\lambda_{dre}^* = 0.385 \text{ V-sec}$
$r_s = 0.3996 \Omega$	$r_r' = 0.2266 \Omega$	$\omega_{rm} = 0 \text{ to } 1750 \text{ RPM (183.3 rad/sec)}$
$L_{ls} = 5.73 \text{ mH}$	$L_{lr}' = 4.64 \text{ mH}$	$T_L = 0 \text{ to } 20 \text{ N-m}$
$K_{pc} = 50 \text{ V/A}$	$K_{ic} = 50 \text{ V/A-sec}$	$K_p = 10 \text{ N-m-sec}$ $K_i = 5 \text{ N-m}$



Vector controlled induction motor with sine-triangle modulation and speed control

$$P = 4$$

$$r_s = 0.3996 \, \Omega$$

$$L_{ls} = 5.73 \, \text{mH}$$

$$K_{pc} = 50 \, \text{V/A}$$

$$L_M = 64.43 \, \text{mH}$$

$$r_r' = 0.2266 \, \Omega$$

$$L_{lr}' = 4.64 \, \text{mH}$$

$$K_{ic} = 50 \, \text{V/A-sec}$$

$$\lambda_{dre}'^* = 0.385 \, \text{V-sec}$$

$$\omega_{rm} = 0 \text{ to } 1750 \, \text{RPM} \, (183.3 \, \text{rad/sec})$$

$$T_L = 0 \text{ to } 20 \, \text{N-m}$$


$$K_p = 10 \, \text{N-m-sec}$$

$$K_i = 5 \, \text{N-m}$$

Position Control Example


Motor from before 5hp (3.7 kW)

- change position from zero to 90 degrees
- step torque from zero to rated



Vector controlled induction motor with sine-triangle modulation and position control

$P = 4$	$L_M = 64.43 \text{ mH}$	$\lambda_{dre}^* = 0.385 \text{ V-sec}$	
$r_s = 0.3996 \Omega$	$r_r' = 0.2266 \Omega$	$\omega_{rm} = 0 \text{ to } 1750 \text{ RPM (183.3 rad/sec)}$	
$L_{ls} = 5.73 \text{ mH}$	$L_{lr}' = 4.64 \text{ mH}$	$T_L = 0 \text{ to } 20 \text{ N-m}$	
$K_{pc} = 50 \text{ V/A}$	$K_{ic} = 50 \text{ V/A-sec}$	$K_p = 10 \text{ N-m-sec}$	$K_i = 5 \text{ N-m}$
		$K_{pt} = 50 \text{ sec}$	$K_{it} = 20$



Vector controlled induction motor with sine-triangle modulation and position control

$P = 4$	$L_M = 64.43 \text{ mH}$	$\lambda_{dre}^{\prime*} = 0.385 \text{ V-sec}$	
$r_s = 0.3996 \Omega$	$r_r' = 0.2266 \Omega$	$\omega_{rm} = 0 \text{ to } 1750 \text{ RPM (183.3 rad/sec)}$	
$L_{ls} = 5.73 \text{ mH}$	$L_{lr}' = 4.64 \text{ mH}$	$T_L = 0 \text{ to } 20 \text{ N-m}$	
$K_{pc} = 50 \text{ V/A}$	$K_{ic} = 50 \text{ V/A-sec}$	$K_p = 10 \text{ N-m-sec}$	$K_i = 5 \text{ N-m}$
		$K_{pt} = 50 \text{ sec}$	$K_{it} = 20$

Speed and Position Control Examples

Traditional PI controllers to regulated speed and position

The drive was implemented with a vector controlled induction machine using voltage-source modulation

Speed and position are commanded to move along a ramp and parabolic curve respectively to avoid commanding a step change in speed which realistically cannot be achieved