





ECE 802, Electric Motor Control

Reference Frame Theory

Reference Frame Theory (Chapter 3)



Introduced by R.H. Park in 1929 to model synchronous machines

Three-Phase Transformation to the Arbitrary Reference Frame

$$f_{qd0s} = K_s f_{abcs}$$

$$f_{qd0s} = \begin{bmatrix} f_{qs} \\ f_{ds} \\ f_{0s} \end{bmatrix} \quad f_{abcs} = \begin{bmatrix} f_{as} \\ f_{bs} \\ f_{cs} \end{bmatrix}$$

f = voltage, current, or flux linkage

q = q -axis (quadrature axis)

d = d -axis (direct axis)

0 = zero sequence

a = a -phase

b = b -phase

c = c -phase

The Reference Frame Transformation

$$K_s = \frac{2}{3} \begin{bmatrix} \cos(\theta) & \cos\left(\theta - \frac{2\pi}{3}\right) & \cos\left(\theta + \frac{2\pi}{3}\right) \\ \sin(\theta) & \sin\left(\theta - \frac{2\pi}{3}\right) & \sin\left(\theta + \frac{2\pi}{3}\right) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix}$$

$$\theta = \int_0^t \omega(\varsigma) d\varsigma + \theta(0)$$

ω = reference frame speed (rad/sec)

θ = reference frame position (rad)

The Inverse Transformation

$$f_{abcs} = K_s^{-1} f_{qd0s}$$


$$K_s^{-1} = \begin{bmatrix} \cos(\theta) & \sin(\theta) & 1 \\ \cos\left(\theta - \frac{2\pi}{3}\right) & \sin\left(\theta - \frac{2\pi}{3}\right) & 1 \\ \cos\left(\theta + \frac{2\pi}{3}\right) & \sin\left(\theta + \frac{2\pi}{3}\right) & 1 \end{bmatrix}$$

Example: Three-Phase Set of Voltages

$$v_{as} = \sqrt{2} V_s \cos(\theta_e + \phi_v)$$

$$v_{bs} = \sqrt{2} V_s \cos\left(\theta_e + \phi_v - \frac{2\pi}{3}\right)$$

$$v_{cs} = \sqrt{2} V_s \cos\left(\theta_e + \phi_v + \frac{2\pi}{3}\right)$$



$$\theta_e = \omega_e t$$

$$\omega_e = 2\pi f$$

f - electric frequency (Hz)

ω_e - electric radian frequency (rad/sec)

θ_e - electrical position (rad)

V_s - rms Voltage (V)

ϕ_v - phase shift (rad)

Transform to the Arbitrary Reference Frame

$$v_{qd0s} = K_s v_{abcs}$$

$$\begin{bmatrix} v_{qs} \\ v_{ds} \\ v_{0s} \end{bmatrix} = \frac{2}{3} \begin{bmatrix} \cos(\theta) & \cos\left(\theta - \frac{2\pi}{3}\right) & \cos\left(\theta + \frac{2\pi}{3}\right) \\ \sin(\theta) & \sin\left(\theta - \frac{2\pi}{3}\right) & \sin\left(\theta + \frac{2\pi}{3}\right) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix} \begin{bmatrix} \sqrt{2} V_s \cos(\theta_e + \phi_v) \\ \sqrt{2} V_s \cos\left(\theta_e + \phi_v - \frac{2\pi}{3}\right) \\ \sqrt{2} V_s \cos\left(\theta_e + \phi_v + \frac{2\pi}{3}\right) \end{bmatrix}$$

Voltages in Arbitrary Reference Frame

q-axis voltage

$$v_{qs} = \frac{2}{3} \sqrt{2} V_s \left[\cos(\theta) \cos(\theta_e + \phi_v) + \cos\left(\theta - \frac{2\pi}{3}\right) \cos\left(\theta_e + \phi_v - \frac{2\pi}{3}\right) + \cos\left(\theta + \frac{2\pi}{3}\right) \cos\left(\theta_e + \phi_v + \frac{2\pi}{3}\right) \right]$$

using the identity,

$$\cos(x) \cos(y) + \cos\left(x - \frac{2\pi}{3}\right) \cos\left(y - \frac{2\pi}{3}\right) + \cos\left(x + \frac{2\pi}{3}\right) \cos\left(y + \frac{2\pi}{3}\right) = \frac{3}{2} \cos(x - y)$$

$$\boxed{v_{qs} = \sqrt{2} V_s \cos(\theta - \theta_e - \phi_v)}$$

d-axis voltage

$$v_{ds} = \frac{2}{3} \sqrt{2} V_s \left[\sin(\theta) \cos(\theta_e + \phi_v) + \sin\left(\theta - \frac{2\pi}{3}\right) \cos\left(\theta_e + \phi_v - \frac{2\pi}{3}\right) + \sin\left(\theta + \frac{2\pi}{3}\right) \cos\left(\theta_e + \phi_v + \frac{2\pi}{3}\right) \right]$$

using the identity,

$$\sin(x) \cos(y) + \sin\left(x - \frac{2\pi}{3}\right) \cos\left(y - \frac{2\pi}{3}\right) + \sin\left(x + \frac{2\pi}{3}\right) \cos\left(y + \frac{2\pi}{3}\right) = \frac{3}{2} \sin(x - y)$$

$$\boxed{v_{ds} = \sqrt{2} V_s \sin(\theta - \theta_e - \phi_v)}$$

zero sequence voltage

$$\boxed{v_{0s} = \frac{1}{3} \sqrt{2} V_s \left[\cos(\theta_e + \phi_v) + \cos\left(\theta_e + \phi_v - \frac{2\pi}{3}\right) + \cos\left(\theta_e + \phi_v + \frac{2\pi}{3}\right) \right] = 0}$$

Numerical Example


208 V, 3-phase, $f = 60$ Hz (208 V line-to-line rms)

$$V_s = \frac{208 \text{ V}}{\sqrt{3}} = 120 \text{ V} \quad \phi_v = 0$$

1. Stationary reference frame $\theta = 0$

$$v_{qs}^s = \sqrt{2}V_s \cos(\theta_e)$$


$$v_{ds}^s = -\sqrt{2}V_s \sin(\theta_e)$$




2. Synchronous reference frame $\theta = \theta_e$

$$v_{qs}^e = \sqrt{2}V_s \cos(\phi_v) = \sqrt{2}V_s$$

$$v_{ds}^e = -\sqrt{2}V_s \sin(\phi_v) = 0$$




Axis Sketch with $\theta=0$




$$v_{qs}^s = \sqrt{2} V_s \cos(\theta_e)$$

$$v_{ds}^s = -\sqrt{2} V_s \sin(\theta_e)$$




Axis Sketch with $\theta = \theta_e$




$$v_{qs}^e = \sqrt{2} V_s \cos(\phi_v) = 170 \text{ V}$$

$$v_{ds}^e = -\sqrt{2} V_s \sin(\phi_v) = 0$$




Axis Sketch with $\theta=\theta_e$ and $\phi_v=30^\circ$



$$v_{qs}^e = \sqrt{2} V_s \cos(\phi_v) = 147 \text{ V}$$

$$v_{ds}^e = -\sqrt{2} V_s \sin(\phi_v) = -85 \text{ V}$$



Commonly Used Reference Frames

Arbitrary	$\omega = \omega$	f_{qs}, f_{ds}, f_{0s}	K_s
Stationary	$\omega = 0$	$f_{qs}^s, f_{ds}^s, f_{0s}$	K_s^s
Synchronous	$\omega = \omega_e$	$f_{qs}^e, f_{ds}^e, f_{0s}$	K_s^e
Rotor	$\omega = \omega_r$	$f_{qs}^r, f_{ds}^r, f_{0s}$	K_s^r

compact notation

$$v_{qd0s} = K_s v_{abcs}$$

$$v_{qd0s}^e = K_s^e v_{abcs}$$

Notes: In all reference frames $f_{0s} = \frac{1}{3}(f_{as} + f_{bs} + f_{cs})$

The reference frame speed defines one reference frame. There are an infinite number since $\theta(0)$ can be set to any value.

Frame-to-Frame Transformation

$$f_{qd0s}^x = K_s^x f_{abcs}$$

$${}^x K^y = \begin{bmatrix} \cos(\theta_y - \theta_x) & \sin(\theta_y - \theta_x) & 0 \\ \sin(\theta_y - \theta_x) & \cos(\theta_y - \theta_x) & 0 \\ 0 & 0 & 1 \end{bmatrix}$$

Real Power in the q - d Reference Frame

$$P_{in} = v_{as} i_{as} + v_{bs} i_{bs} + v_{cs} i_{cs} = \begin{bmatrix} v_{as} & v_{bs} & v_{cs} \end{bmatrix} \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix} = v_{abcs}^T i_{abcs}$$

$$P_{in} = \frac{3}{2} (v_{qs} i_{qs} + v_{ds} i_{ds}) + 3v_{0s} i_{0s}$$


Reference Frame Transformation

Developed by R.H. Park in 1929 for analysis of synchronous machines.

Allows treatment of balanced three-phase ac systems as two-phase dc systems.

- This leads to application of classical control theory
- Also simplifies control equations of some systems

Transforming Circuit Elements: R-L Example



voltage equations

$$v_{as} = Ri_{as} + p\lambda_{as}$$

$$v_{bs} = Ri_{bs} + p\lambda_{bs}$$

$$v_{cs} = Ri_{cs} + p\lambda_{cs}$$

note: $p = \frac{d}{dt}$

flux linkage equations

$$\lambda_{as} = Li_{as}$$

$$\lambda_{bs} = Li_{bs}$$

$$\lambda_{cs} = Li_{cs}$$



Transform Flux Linkage Equations

1. Compress equations

$$\lambda_{abcs} = Li_{abcs}$$

2. Transform equations

3. Expand equations

$$\lambda_{qs} = Li_{qs}$$

$$\lambda_{ds} = Li_{ds}$$

$$\lambda_{0s} = Li_{0s}$$

Transform Voltage Equations

1. Compress equations

$$v_{abcs} = Ri_{abcs} + p\lambda_{abcs}$$

2. Transform equations

$$p\{K_s^{-1}\} = \omega \begin{bmatrix} -\sin(\theta) & \cos(\theta) & 0 \\ -\sin\left(\theta - \frac{2\pi}{3}\right) & \cos\left(\theta - \frac{2\pi}{3}\right) & 0 \\ -\sin\left(\theta + \frac{2\pi}{3}\right) & \cos\left(\theta + \frac{2\pi}{3}\right) & 0 \end{bmatrix}$$

$$K_s p\{K_s^{-1}\} = \begin{bmatrix} 0 & \omega & 0 \\ -\omega & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix}$$

$$v_{qd0s} = Ri_{qd0s} + p\lambda_{qd0s} + \omega\lambda_{dqs}$$

$$\lambda_{dqs} = \begin{bmatrix} \lambda_{ds} \\ -\lambda_{qs} \\ 0 \end{bmatrix}$$

3. Expand equations


$$v_{qs} = Ri_{qs} + p\lambda_{qs} + \omega\lambda_{ds}$$

$$v_{ds} = Ri_{ds} + p\lambda_{ds} - \omega\lambda_{qs}$$

$$v_{0s} = Ri_{0s} + p\lambda_{0s}$$

Equivalent Circuit


q -axis



$$v_{qs} = Ri_{qs} + p\lambda_{qs} + \omega\lambda_{ds}$$

$$\lambda_{qs} = Li_{qs}$$


d -axis



$$v_{ds} = Ri_{ds} + p\lambda_{ds} - \omega\lambda_{qs}$$

$$\lambda_{ds} = Li_{ds}$$

zero sequence




$$v_{0s} = Ri_{0s} + p\lambda_{0s}$$

$$\lambda_{0s} = Li_{0s}$$

R-L Example from Book


Stationary Reference Frame



matches Figure 3.10-1


R-L Example from Book

Synchronous Reference Frame




matches Figure 3.10-2

R-L Example from Book Varying Reference Frame



matches Figure 3.10-3

Coupled Inductors



voltage equations

$$v_{abcs} = Ri_{abcs} + p\lambda_{abcs}$$

$$v_{qd0s} = Ri_{qd0s} + p\lambda_{qd0s} + \omega\lambda_{dqs}$$

$$\lambda_{dqs} = \begin{bmatrix} \lambda_{ds} \\ -\lambda_{qs} \\ 0 \end{bmatrix}$$

Coupled Inductors

flux linkage equations

$$\begin{bmatrix} \lambda_{as} \\ \lambda_{bs} \\ \lambda_{cs} \end{bmatrix} = \begin{bmatrix} L_{ls} + L_{ms} & -\frac{1}{2}L_{ms} & -\frac{1}{2}L_{ms} \\ -\frac{1}{2}L_{ms} & L_{ls} + L_{ms} & -\frac{1}{2}L_{ms} \\ -\frac{1}{2}L_{ms} & -\frac{1}{2}L_{ms} & L_{ls} + L_{ms} \end{bmatrix} \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix}$$

$$K_s \mathbf{L}_s K_s^{-1} = \begin{bmatrix} L_{ls} + \frac{3}{2} L_{ms} & 0 & 0 \\ 0 & L_{ls} + \frac{3}{2} L_{ms} & 0 \\ 0 & 0 & L_{ls} \end{bmatrix}$$

expanded form

$$\lambda_{qs} = \left(L_{ls} + \frac{3}{2} L_{ms} \right) i_{qs}$$

$$\lambda_{ds} = \left(L_{ls} + \frac{3}{2} L_{ms} \right) i_{ds}$$

$$\lambda_{0s} = L_{ls} i_{0s}$$

Transformation of Circuit Elements

Balanced three-phase ac circuits transformed to two-phase dc circuits (neglecting the zero sequence and assuming analysis in the synchronous reference frame)

Flux linkage equations for inductive circuits were used for generality to other circuits; including electric machines

Coupling terms between the q - and d -axes result from the transformation. These will later be viewed as back-emf terms when observing electric machinery in the synchronous reference frame.

Balanced Steady-State Calculations

$$\theta_e = \int_0^t \omega_e(\varsigma) d\varsigma + \theta_e(0) \quad \text{define } \phi_v = \theta_e(0)$$

$$= \omega_e t + \phi_v$$

$$\theta = \int_0^t \omega(\varsigma) d\varsigma + \theta(0)$$

$$= \omega t + \theta(0)$$

Balanced Steady-State Voltages

$$v_{as} = \sqrt{2}V_s \cos(\omega_e t + \phi_v)$$

$$v_{bs} = \sqrt{2}V_s \cos\left(\omega_e t + \phi_v - \frac{2\pi}{3}\right)$$

$$v_{cs} = \sqrt{2}V_s \cos\left(\omega_e t + \phi_v + \frac{2\pi}{3}\right)$$

$$\tilde{V}_{as} = V_s e^{j\phi_v} \longrightarrow \tilde{V}_{as} = V_s \angle \phi_v$$

$$\tilde{V}_{bs} = \tilde{V}_s e^{-j\frac{2\pi}{3} + j\phi_v}$$

$$\tilde{V}_{cs} = \tilde{V}_s e^{j\frac{2\pi}{3} + j\phi_v}$$

Synchronous Reference Frame q - d Voltages

Synchronous: $\omega = \omega_e$ and $\theta(0) = 0$

$$V_{qs}^e = \sqrt{2}V_s \cos(\phi_v)$$

$$V_{ds}^e = -\sqrt{2}V_s \sin(\phi_v)$$

note:
$$\sqrt{2}V_s = \sqrt{(V_{qs}^e)^2 + (V_{ds}^e)^2}$$

$$\phi_v = \tan^{-1}\left(\frac{-V_{ds}^e}{V_{qs}^e}\right)$$

R-L Circuit Example

$$R := 1 \cdot \Omega \quad L := 10 \text{ mH} \quad f := 60 \text{ Hz} \quad V_s := 120 \text{ V} \quad \phi_v := 30 \text{ deg}$$

load impedance

$$\omega_e := 2 \cdot \pi \cdot f$$


$$Z := R + j \cdot \omega_e \cdot L$$

solution in a-b-c

$$V_{as} := V_s \cdot e^{j \cdot \phi_v}$$

$$I_{as} := \frac{V_{as}}{Z}$$

Steady-State Calculation ($\omega = \omega_e$)



solution in q-d

$$V_{qse} := \sqrt{2} \cdot V_s \cdot \cos(\phi_V)$$

$$V_{dse} := -\sqrt{2} \cdot V_s \cdot \sin(\phi_V)$$

steady-state equations

$$V_{qs}^e = R I_{qs}^e + \omega_e L I_{ds}^e$$

$$V_{ds}^e = R I_{ds}^e - \omega_e L I_{qs}^e$$

steady-state equations in matrix form

$$\begin{bmatrix} V_{qs}^e \\ V_{ds}^e \end{bmatrix} = \begin{bmatrix} R & \omega_e L \\ -\omega_e L & R \end{bmatrix} \begin{bmatrix} I_{qs}^e \\ I_{ds}^e \end{bmatrix}$$

solve for currents


$$\begin{bmatrix} I_{qs}^e \\ I_{ds}^e \end{bmatrix} = \frac{1}{R^2 + \omega_e^2 L^2} \begin{bmatrix} R & -\omega_e L \\ \omega_e L & R \end{bmatrix} \begin{bmatrix} V_{qs}^e \\ V_{ds}^e \end{bmatrix}$$

$$\begin{pmatrix} I_{qse} \\ I_{dse} \end{pmatrix} := \begin{pmatrix} R & \omega_e \cdot L \\ -\omega_e \cdot L & R \end{pmatrix}^{-1} \cdot \begin{pmatrix} V_{qse} \\ V_{dse} \end{pmatrix}$$

$$I_s := \frac{1}{\sqrt{2}} \cdot \sqrt{I_{qse}^2 + I_{dse}^2}$$

$$\phi_i := \text{atan} \left(\frac{-I_{dse}}{I_{qse}} \right)$$

Voltage and Current Vectors




Steady-State q - d Calculations

In the synchronous reference frame, the q - d circuits are supplied from dc and the corresponding dc solution is steady-state (inductors treated as short-circuit, capacitors treated as open-circuit)


Can be used to analyze steady-state operation of electric machines

Equations can be linearized about the dc operating point for application of control theory


Active Filter Example



Active Filter Control



PSCAD Transformation Block




abc to dq0:

$$\begin{bmatrix} d \\ q \\ 0 \end{bmatrix} = \frac{2}{3} \cdot \begin{bmatrix} \cos(\theta) & \cos\left(\theta - \frac{2\pi}{3}\right) & \cos\left(\theta + \frac{2\pi}{3}\right) \\ \sin(\theta) & \sin\left(\theta - \frac{2\pi}{3}\right) & \sin\left(\theta + \frac{2\pi}{3}\right) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix} \cdot \begin{bmatrix} a \\ b \\ c \end{bmatrix}$$



dq0 to abc:

$$\begin{bmatrix} a \\ b \\ c \end{bmatrix} = \begin{bmatrix} \cos(\theta) & \sin(\theta) & 1 \\ \cos\left(\theta - \frac{2\pi}{3}\right) & \sin\left(\theta - \frac{2\pi}{3}\right) & 1 \\ \cos\left(\theta + \frac{2\pi}{3}\right) & \sin\left(\theta + \frac{2\pi}{3}\right) & 1 \end{bmatrix} \cdot \begin{bmatrix} d \\ q \\ 0 \end{bmatrix}$$



- q - and d -axis swapped as compared to the notation in Krause's book
- double-click to set reference frame angle, which may also be a variable

Active Filter Waveforms




Active Filter Example

Common in higher power applications where the main rectifier contains significant harmonics


Demonstrates an effective control method using the synchronous reference frame

Passive Filter Example

transform, then filter



filter, then transform



Is there a difference?

The Low-Pass Filter (LPF)

$$x \rightarrow \boxed{\frac{G}{1 + sT}} \rightarrow y$$

$G = 1 \quad T = \tau$

transfer function

$$\frac{y}{x} = \frac{1}{\tau s + 1}$$

time constant $\tau = \frac{1}{\omega_c}$

cut-off frequency $\omega_c = 2\pi f_c$

LPF gain

$$\left| \frac{y}{x} \right| = \frac{1}{\sqrt{\tau^2 \omega^2 + 1}} = \frac{1}{\sqrt{\left(\frac{f}{f_c} \right)^2 + 1}}$$

LPF phase delay

$$\angle y - \angle x = -\tan^{-1}(\tau \omega) = -\tan^{-1}\left(\frac{f}{f_c}\right)$$

Transform, Then Filter

filter output \tilde{i}_{qd0r}^e

$$\frac{\tilde{i}_{qd0r}^e}{i_{qd0r}^e} = \frac{1}{\tau s + 1}$$

$$\tilde{i}_{qd0r}^e + \tau p \tilde{i}_{qd0r}^e = i_{qd0r}^e$$

steady-state

$$\tilde{I}_{qd0r}^e = I_{qd0r}^e$$

Filter, Then Transform

$$\frac{\tilde{i}_{abcr}}{i_{abcr}} = \frac{1}{\tau s + 1}$$

$$\tilde{i}_{abcr} + \tau p \tilde{i}_{abcr} = i_{abcr}$$

$$K_s^e \tilde{i}_{abcr} + K_s^e \tau p \tilde{i}_{abcr} = K_s^e i_{abcr}$$



$$\tilde{i}_{qd0r}^e + \tau K_s^e p \left\{ \left(K_s^e \right)^{-1} \tilde{i}_{qd0r}^e \right\} = i_{qd0r}^e$$

$$\tilde{i}_{qd0r}^e + \tau K_s^e \left(K_s^e \right)^{-1} p \tilde{i}_{qd0r}^e + \tau K_s^e p \left\{ \left(K_s^e \right)^{-1} \right\} \tilde{i}_{qd0r}^e = i_{qd0r}^e$$

$$\tilde{i}_{qd0r}^e + \tau p \tilde{i}_{qd0r}^e + \omega_e \tau \tilde{i}_{dqr}^e = i_{qd0r}^e$$

$$\tilde{i}_{dqr}^e = \begin{bmatrix} \tilde{i}_{dr}^e \\ -\tilde{i}_{qr}^e \\ 0 \end{bmatrix}$$

Filter, Then Transform (Steady-State)

steady-state

$$\tilde{I}_{qd0r}^e + \omega_e \tau \tilde{I}_{dqr}^e = I_{qd0r}^e$$

expand equations

$$\tilde{I}_{qr}^e + \omega_e \tau \tilde{I}_{dr}^e = I_{qr}^e$$

$$\tilde{I}_{dr}^e - \omega_e \tau \tilde{I}_{qr}^e = I_{dr}^e$$

in matrix form

$$\begin{bmatrix} 1 & \omega_e \tau \\ -\omega_e \tau & 1 \end{bmatrix} \begin{bmatrix} \tilde{I}_{qr}^e \\ \tilde{I}_{dr}^e \end{bmatrix} = \begin{bmatrix} I_{qr}^e \\ I_{dr}^e \end{bmatrix}$$

$$\begin{bmatrix} \tilde{I}_{qr}^e \\ \tilde{I}_{dr}^e \end{bmatrix} = \begin{bmatrix} 1 & \omega_e \tau \\ -\omega_e \tau & 1 \end{bmatrix}^{-1} \begin{bmatrix} I_{qr}^e \\ I_{dr}^e \end{bmatrix} = \frac{\begin{bmatrix} 1 & -\omega_e \tau \\ \omega_e \tau & 1 \end{bmatrix}}{1 + \omega_e^2 \tau^2} \begin{bmatrix} I_{qr}^e \\ I_{dr}^e \end{bmatrix}$$

$$\tilde{I}_{dqr}^e = \begin{bmatrix} \tilde{I}_{dr}^e \\ -\tilde{I}_{qr}^e \\ 0 \end{bmatrix}$$

Note:

$$\omega_e \tau = \frac{f}{f_c}$$

Passive Filter Example

$$f := 60 \cdot \text{Hz}$$

$$\omega_e := 2 \cdot \pi \cdot f$$

$$\tau := 10 \cdot \text{ms}$$

$$\omega_c := \frac{1}{\tau}$$



$$f_c := \frac{\omega_c}{2 \cdot \pi}$$

transform, then filter (from PSCAD)


filter, then transform

$$\begin{pmatrix} I_{qsef} \\ I_{dsef} \end{pmatrix} := \begin{pmatrix} 1 & \omega_e \cdot \tau \\ -\omega_e \cdot \tau & 1 \end{pmatrix}^{-1} \cdot \begin{pmatrix} I_{qse} \\ I_{dse} \end{pmatrix}$$

PSCAD Simulation



PSCAD Waveforms




Passive Filter Example

Illustrates the low-pass filter (LPF)

Shows difference between placing a passive filter before and after a transformation to the synchronous reference frame

For accurate steady-state numbers, the LPF must be placed after the transformation to the synchronous reference frame


Phase-Locked Loop (PLL) Example




The electrical angle can be observed by using the stationary reference frame voltages

$$\theta_e = \tan^{-1} \left(\frac{-v_{ds}^s}{v_{qs}^s} \right)$$

PLL Simulation



PLL Simulation Waveforms



PLL Example

PLL obtains electrical angle from processing the measured voltages (without a PI control loop)

Using this method, filtering of the line voltages may be required. The PLL angle can be adjusted to compensate for filter delay.