




ECE 891, Electric Motor Control

Direct Torque Control

Induction Motor Drive Controls



G.S. Buja and M.P. Kazmierkowski, "Direct Torque Control of PWM Inverter-Fed AC Motors - A Survey," *IEEE Transactions on Industrial Electronics*, volume 51, number 4, pages 744-757, August 2004.


Flux and Torque Observer

stationary reference frame ($\omega = 0$)

$$v_{qs}^s = r_s i_{qs}^s + p \lambda_{qs}^s$$

$$v_{ds}^s = r_s i_{ds}^s + p \lambda_{ds}^s$$

$$T_e = \frac{3}{2} \frac{P}{2} (\lambda_{ds}^s i_{qs}^s - \lambda_{qs}^s i_{ds}^s)$$




Transfer Function as an Integrator

$$T_1(s) := \frac{1}{s}$$

$$\tau := 10$$

$$T_2(s, \tau) := \frac{\tau}{\tau \cdot s + 1}$$

$$|T_2(j \cdot 0, \tau)| = 10$$




$$T_1(s) := \frac{1}{s}$$


$$\tau := 100$$

$$T_2(s, \tau) := \frac{\tau}{\tau \cdot s + 1}$$

$$|T_2(j \cdot 0, \tau)| = 100$$



Stator Flux Reference Frame



Motor Equations in the Stator Flux Linkage Reference Frame

flux reference frame $\theta = \phi_\lambda + \frac{\pi}{2}$ $\lambda_{qs}^\lambda = 0$ $\lambda_{ds}^\lambda = \lambda_s$

$$v_{qs}^\lambda = r_s i_{qs}^\lambda + \omega_e \lambda_{ds}^\lambda + p \lambda_{qs}^\lambda$$

$$v_{ds}^\lambda = r_s i_{ds}^\lambda - \omega_e \lambda_{qs}^\lambda + p \lambda_{ds}^\lambda$$

$$T_e = \frac{3}{2} \frac{P}{2} (\lambda_{ds}^\lambda i_{qs}^\lambda - \lambda_{qs}^\lambda i_{ds}^\lambda)$$

neglecting r_s terms

$$v_{tan} = v_{qs}^\lambda \approx \omega_e \lambda_s + p \lambda_{qs}^\lambda$$

$$v_{rad} = v_{ds}^\lambda \approx p \lambda_{ds}^\lambda$$

radial voltage used to control flux

tangential voltage used to control torque angle

IM Steady-State Example

IM parameters

$$r_s := 0.4 \Omega$$

$$P := 4$$

$$r_r' := 0.2266 \Omega$$

$$\text{RPM} := \frac{2 \cdot \pi \cdot \text{rad}}{60 \text{ sec}}$$

$$\text{lagging} := 1$$

$$L_{ls} := 5.73 \text{ mH}$$

$$L_M := 64.43 \text{ mH}$$

$$L_{lr}' := 4.64 \text{ mH}$$

operating conditions

$$f_e := 60 \text{ Hz}$$

$$\omega_e := 2 \cdot \pi \cdot f_e$$

$$\omega_e = 377 \frac{\text{rad}}{\text{sec}}$$

$$\omega_{rm} := 1750 \text{ RPM}$$

$$\omega_{rm} = 183.3 \frac{\text{rad}}{\text{sec}}$$

$$v_s := \frac{220 \text{ V}}{\sqrt{3}}$$

$$v_s = 127 \text{ V}$$

synchronous speed (no-load speed)

$$\omega_{em} := \left(\frac{2}{P} \right) \cdot \omega_e$$

$$\omega_{em} = 188.5 \frac{\text{rad}}{\text{sec}}$$

$$\omega_{em} = 1800 \text{ RPM}$$

slip

$$\omega_r := \frac{P}{2} \cdot \omega_{rm}$$

$$\omega_r = 366.5 \frac{\text{rad}}{\text{sec}}$$

$$sl := \frac{\omega_e - \omega_r}{\omega_e}$$

$$sl = 2.78\%$$

impedances

$$Z_s := r_s + j \cdot \omega_e \cdot L_{ls}$$

$$Z_m := j \cdot \omega_e \cdot L_M$$

$$Z_r := \frac{r'_r}{s} + j \cdot \omega_e \cdot L'_{lr}$$

$$Z_f := \frac{1}{\frac{1}{Z_m} + \frac{1}{Z_r}}$$

$$Z_{in} := Z_s + Z_f$$

$$|Z_s| = 2.2\Omega$$

$$\arg(Z_s) = 79.5\text{deg}$$

$$|Z_m| = 24.3\Omega$$

$$\arg(Z_m) = 90\text{deg}$$

$$|Z_r| = 8.34\Omega$$

$$\arg(Z_r) = 12.1\text{deg}$$

$$|Z_f| = 7.43\Omega$$

$$\arg(Z_f) = 29.5\text{deg}$$

$$|Z_{in}| = 9.00\Omega$$

$$\arg(Z_{in}) = 40.3\text{deg}$$

currents

$$V_{as} := v_s \cdot e^{j \cdot 0}$$

$$I_{as} := \frac{V_{as}}{Z_{in}}$$

$$i_s := |I_{as}|$$

$$I_{ar} := -I_{as} \cdot \frac{Z_m}{Z_m + Z_r}$$

$$|I_{as}| = 14.1\text{A}$$

$$\arg(I_{as}) = -40.3\text{deg}$$

$$|I_{ar}| = 12.6\text{A}$$

$$\arg(I_{ar}) = 157\text{deg}$$

torque and power

$$L_{ss} := L_{ls} + L_M$$

$$L_{ss} = 70.2\text{mH}$$

$$L'_{rr} := L'_{lr} + L_M$$

$$L'_{rr} = 69.1\text{mH}$$

$$T_e := 3 \cdot \frac{P}{2} \cdot \left(|I_{ar}| \right)^2 \cdot \frac{r'_r}{sl \cdot \omega_e}$$

$$T_e = 20.5\text{N}\cdot\text{m}$$

$$T_e := \frac{3 \cdot \left(\frac{P}{2} \right) \cdot \omega_e \cdot L_M^2 \cdot r'_r \cdot sl \cdot \left(|V_{as}| \right)^2}{\left[r_s \cdot r'_r + sl \cdot \omega_e^2 \cdot \left(L_M^2 - L_{ss} \cdot L'_{rr} \right) \right]^2 + \omega_e^2 \cdot \left(r'_r \cdot L_{ss} + sl \cdot r_s \cdot L'_{rr} \right)^2}$$

$$T_e = 20.5\text{N}\cdot\text{m}$$

$$\theta_z := \arg(Z_{in})$$

$$\theta_z = 40.3\text{deg}$$

$$\text{pf} := \cos(\theta_z)$$

$$\text{pf} = 0.763\text{lagging}$$

$$P_{in} := 3 \cdot |V_{as}| \cdot |I_{as}| \cdot \text{pf}$$

$$P_{in} = 4.104\text{kW}$$

$$P_{out} := T_e \cdot \omega_{rm}$$

$$P_{out} = 3.757\text{kW}$$

$$\text{eff} := \frac{P_{out}}{P_{in}}$$

$$P_{out} = 5.04\text{hp}$$

$$\text{eff} = 91.6\%$$

synchronous reference frame with $\theta = \theta_e$

$$\theta := \theta_e$$

$$V_{qse} := \sqrt{2} \cdot v_s \cdot \cos(\theta - \theta_e)$$

$$V_{dse} := \sqrt{2} \cdot v_s \cdot \sin(\theta - \theta_e)$$

$$I_{qse} := \sqrt{2} \cdot i_s \cdot \cos(\theta - \theta_e + \theta_z)$$

$$I_{dse} := \sqrt{2} \cdot i_s \cdot \sin(\theta - \theta_e + \theta_z)$$

$$\lambda_{qse} := - \left(\frac{V_{dse} - r_s \cdot I_{dse}}{\omega_e} \right)$$

$$\lambda_{dse} := \frac{V_{qse} - r_s \cdot I_{qse}}{\omega_e}$$

$$\lambda_s := \sqrt{\lambda_{qse}^2 + \lambda_{dse}^2}$$

$$\phi_{\lambda e} := \text{atan} \left(\frac{-\lambda_{dse}}{\lambda_{qse}} \right)$$

$$I'_{\text{qre}} := \frac{\lambda_{\text{qse}} - L_{\text{ss}} \cdot I_{\text{qse}}}{L_{\text{M}}}$$

$$I'_{\text{dre}} := \frac{\lambda_{\text{dse}} - L_{\text{ss}} \cdot I_{\text{dse}}}{L_{\text{M}}}$$

$$\lambda'_{\text{qre}} := L'_{\text{rr}} \cdot I'_{\text{qre}} + L_{\text{M}} \cdot I_{\text{qse}}$$

$$\lambda'_{\text{dre}} := L'_{\text{rr}} \cdot I'_{\text{dre}} + L_{\text{M}} \cdot I_{\text{dse}}$$


$$\lambda_{\text{r}} := \sqrt{\lambda_{\text{qre}}^2 + \lambda_{\text{dre}}^2}$$

$$\lambda_{\text{qdse}} := \begin{pmatrix} \lambda_{\text{qse}} \\ -\lambda_{\text{dse}} \end{pmatrix}$$

$$j\lambda'_{\text{qdre}} := \begin{pmatrix} \lambda'_{\text{dre}} \\ \lambda'_{\text{qre}} \end{pmatrix}$$

$$T_{\text{e}} := \frac{3}{2} \cdot \left(\frac{P}{2} \right) \cdot \left(\frac{L_{\text{M}}}{L_{\text{ss}} \cdot L'_{\text{rr}} - L_{\text{M}}^2} \right) \cdot (\lambda_{\text{qdse}} \cdot j\lambda'_{\text{qdre}})$$

Synchronous Reference Frame Vectors



synchronous reference frame with $\theta = \theta_e + \phi_{\lambda e} + \pi/2$

$$\theta := \theta_e + \phi_{\lambda e} + \frac{\pi}{2}$$

$$V_{qs\lambda} := \sqrt{2} \cdot v_s \cdot \cos(\theta - \theta_e)$$

$$V_{ds\lambda} := \sqrt{2} \cdot v_s \cdot \sin(\theta - \theta_e)$$

$$I_{qs\lambda} := \sqrt{2} \cdot i_s \cdot \cos(\theta - \theta_e + \theta_z)$$

$$I_{ds\lambda} := \sqrt{2} \cdot i_s \cdot \sin(\theta - \theta_e + \theta_z)$$

$$\lambda_{qs\lambda} := - \left(\frac{V_{ds\lambda} - r_s \cdot I_{ds\lambda}}{\omega_e} \right)$$

$$\lambda_{ds\lambda} := \frac{V_{qs\lambda} - r_s \cdot I_{qs\lambda}}{\omega_e}$$

$$I'_{qr\lambda} := \frac{\lambda_{qs}\lambda - L_{ss} \cdot I_{qs}\lambda}{L_M}$$

$$I'_{dr\lambda} := \frac{\lambda_{ds}\lambda - L_{ss} \cdot I_{ds}\lambda}{L_M}$$

$$\lambda'_{qr\lambda} := L'_{rr} \cdot I'_{qr\lambda} + L_M \cdot I_{qs}\lambda$$

$$\lambda'_{dr\lambda} := L'_{rr} \cdot I'_{dr\lambda} + L_M \cdot I_{ds}\lambda$$

$$\lambda_{qds}\lambda := \begin{pmatrix} \lambda_{qs}\lambda \\ -\lambda_{ds}\lambda \end{pmatrix}$$

$$j\lambda'_{qdr\lambda} := \begin{pmatrix} \lambda'_{dr\lambda} \\ \lambda'_{qr\lambda} \end{pmatrix}$$

$$T_e := \frac{3}{2} \cdot \left(\frac{P}{2} \right) \cdot \left(\frac{L_M}{L_{ss} \cdot L'_{rr} - L_M^2} \right) \cdot (\lambda_{qds}\lambda \cdot j\lambda'_{qdr\lambda})$$

Direct Torque Control

Flux observer determines magnitude and angle of stator flux linkages

Reference frame can be oriented so that the stator flux is entirely in the d -axis

Radial voltage (d -axis voltage) can be controlled to regulate the flux magnitude

Tangential voltage (q -axis voltage) can be controlled to regulate the torque

Table Lookup Implementation

Inverter switching based on *direct* control of flux and torque

Inverter Voltage Vectors


$$\begin{bmatrix} v_{ag} \\ v_{bg} \\ v_{cg} \end{bmatrix} = \begin{bmatrix} T_1 \\ T_2 \\ T_3 \end{bmatrix} v_{dc} \quad \begin{bmatrix} v_{as} \\ v_{bs} \\ v_{cs} \end{bmatrix} = \frac{1}{3} \begin{bmatrix} 2 & -1 & -1 \\ -1 & 2 & -1 \\ -1 & -1 & 2 \end{bmatrix} \begin{bmatrix} v_{ag} \\ v_{bg} \\ v_{cg} \end{bmatrix}$$

Using the stationary reference
frame transformation K_s^s

$$v_{qs}^s = v_{as} \quad v_{ds}^s = \frac{v_{cs} - v_{bs}}{\sqrt{3}}$$

| T_1 | T_2 | T_3 | v_{qs}^s | v_{ds}^s |
|-------|-------|-------|--------------|--------------------|
| 0 | 0 | 0 | 0 | 0 |
| 0 | 0 | 1 | $-v_{dc}/3$ | $v_{dc}/\sqrt{3}$ |
| 0 | 1 | 0 | $-v_{dc}/3$ | $-v_{dc}/\sqrt{3}$ |
| 0 | 1 | 1 | $-2v_{dc}/3$ | 0 |
| 1 | 0 | 0 | $2v_{dc}/3$ | 0 |
| 1 | 0 | 1 | $v_{dc}/3$ | $v_{dc}/\sqrt{3}$ |
| 1 | 1 | 0 | $v_{dc}/3$ | $-v_{dc}/\sqrt{3}$ |
| 1 | 1 | 1 | 0 | 0 |


Voltage Vector Space



Switching Rules

switching based on *direct* control of flux and torque

switching rules for $\alpha = 1$



permutate outputs (T_1, T_2, T_3) based on α


Other methods use different switching rules which make use of the 000 and 111 states to improve torque ripple

Lookup Table


| | $T1^*$ | $T2^*$ | $T3^*$ |
|--------------|--------------|--------------|--------------|
| $\alpha = 1$ | ϕ | τ | $\bar{\tau}$ |
| $\alpha = 2$ | $\bar{\tau}$ | τ | $\bar{\phi}$ |
| $\alpha = 3$ | $\bar{\tau}$ | ϕ | τ |
| $\alpha = 4$ | $\bar{\phi}$ | $\bar{\tau}$ | τ |
| $\alpha = 5$ | τ | $\bar{\tau}$ | ϕ |
| $\alpha = 6$ | τ | $\bar{\phi}$ | $\bar{\tau}$ |

DTC Implementation with Lookup Table

Comparator / latch circuit



Hysteresis comparator





DTC Lookup Table IM Simulation

control settings


$$K_p = 20 \text{ N} \cdot \text{m} \cdot \text{s}$$

$$K_i = 30 \text{ N} \cdot \text{m}$$

$$\lambda_s^* = 0.35 \text{ V} \cdot \text{s}$$



Flux Linkage Vector Plot



Lookup Table DTC

Stator flux angle identifies the sector location of the flux linkage


Inverter switching is obtained from a table based on sector angle so that the transistor switching controls radial and tangential voltage

Implementation can be carried out with a comparator/latch circuit or a hysteresis comparator

Direct Torque Control - Space Vector Modulation

Also called DTC-SVM or stator-oriented vector control

Control Diagram



command flux at rated steady-state value, or use field weakening (lower commanded flux at higher speeds)

DTC-SVM Induction Motor Simulation

control settings

$$K_p = 20 \text{ N} \cdot \text{m} \cdot \text{s}$$

$$K_i = 30 \text{ N} \cdot \text{m}$$

$$\lambda_s^* = 0.35 \text{ V} \cdot \text{s}$$


$$K_{p,v\text{tan}} = 1.7 \text{ A}^{-1} \cdot \text{s}^{-1}$$

$$K_{i,v\text{tan}} = 200 \text{ A}^{-1} \cdot \text{s}^{-2}$$


$$K_{p,v\text{rad}} = 500 \text{ s}^{-1}$$

$$K_{i,v\text{rad}} = 20 \text{ s}^{-2}$$


v_{rad} limited to $\pm 10\text{V}$



Radial and Tangential Voltage



Flux Linkage Vector Plot



DTC-SVM

PI controls are used to turn commanded torque and flux into commanded tangential and radial voltages

With the commanded voltages and flux angle, standard sine-triangle modulation or space-vector modulation (SVM) can be applied to switch the inverter

Brushless Dc Drives

rotor reference frame ($\theta = \theta_r$)

$$\lambda_{qs}^r = L_s i_{qs}^r$$

$$\lambda_{ds}^r = L_s i_{ds}^r + \lambda'_m$$

$$v_{qs}^r = r_s i_{qs}^r + \omega_r \lambda_{ds}^r + p \lambda_{qs}^r$$

$$v_{ds}^r = r_s i_{ds}^r - \omega_r \lambda_{qs}^r + p \lambda_{ds}^r$$


flux reference frame ($\theta = \phi_\lambda$)

$$\lambda_{qs}^\lambda = 0$$

$$\lambda_{ds}^\lambda = \lambda_s$$

$$v_{qs}^\lambda = r_s i_{qs}^\lambda + \omega_r \lambda_s + p \lambda_{qs}^\lambda = v_{tan}$$

$$v_{ds}^\lambda = r_s i_{ds}^\lambda + p \lambda_{ds}^\lambda = v_{rad}$$



ignoring r_s , v_{rad} sets $p\lambda_{ds}^\lambda$ determining the change in flux λ_s
and v_{tan} sets $p\lambda_{qs}^\lambda$ determining torque (angle between λ_s and λ'_m)

Brushless Dc Drive System

- Lookup table method used
- Flux / torque estimator and switching rules are generalized concepts (apply to IM and PMSM)
- Note: no need for position encoder

Machine equations


$$i_{qs}^{r*} = \frac{2}{3} \frac{2}{P} \frac{T_e^*}{\lambda'_m}$$

$$i_{ds}^{r*} = 0$$

$$\lambda_{qs}^{r*} = L_s i_{qs}^{r*}$$

$$\lambda_{ds}^{r*} = L_s i_{ds}^{r*} + \lambda'_m$$

$$\lambda_s^* = \sqrt{(\lambda_{qs}^{r*})^2 + (\lambda_{ds}^{r*})^2}$$



Torque Response

$$P := 4$$

$$r_s := 2.9 \cdot \Omega$$


$$L_s := 11.35 \cdot \text{mH}$$

$$\lambda'_m := 0.156 \cdot \text{V} \cdot \text{s}$$

$$\omega_{\text{rm}} := 314.2 \cdot \frac{\text{rad}}{\text{s}}$$

$$T_{\text{e_star_1}} := 0.99 \cdot \text{N} \cdot \text{m}$$

$$T_{\text{e_star_2}} := 2.79 \cdot \text{N} \cdot \text{m}$$



L. Zhong, M.F. Rahman, W.Y. Hu, and K.W. Lim, "Analysis of direct torque control in permanent magnet synchronous motor drives," *IEEE Transactions on Power Electronics*, volume 12, number 3, pages 528-536, May 1997.






Fig. 9. The block diagram of a PMSM drive with DTC.



$$T_{sw} = 100 \mu s$$



$$T_{sw} = 10 \mu s$$

Y. Hu, G Tian, Y. Gu, Z. You, L.X. Tang, and M.F. Rahman, "In-depth research on direct torque control of permanent magnet synchronous motor," *Proceedings of the IEEE Industrial Electronics Society Conference*, volume 2, pages 1060-1065, November 2002.





Fig.1. The block diagram of a PMSM drive with DTC



Ch1: torque reference
Ch2: torque response 1div=4N.m
torque response (-5N.m~+5N.m)
Fig. 4. The experimental results