




ECE 802, Electric Motor Control

Induction Machines

# Symmetrical Induction Machines (Chapter 6)



voltage equations

$$v_{abcs} = r_s i_{abcs} + p \lambda_{abcs}$$

$$v_{abcr} = r_r i_{abcr} + p \lambda_{abcr}$$

typically wye connected windings

# Flux Linkage Equations

$$\begin{bmatrix} \lambda_{abcs} \\ \lambda_{abcr} \end{bmatrix} = \begin{bmatrix} \mathbf{L}_s & \mathbf{L}_{sr} \\ \mathbf{L}_{rs} & \mathbf{L}_r \end{bmatrix} \begin{bmatrix} i_{abcs} \\ i_{abcr} \end{bmatrix}$$

$$\mathbf{L}_s = \begin{bmatrix} L_{ls} + L_{ms} & -\frac{1}{2}L_{ms} & -\frac{1}{2}L_{ms} \\ -\frac{1}{2}L_{ms} & L_{ls} + L_{ms} & -\frac{1}{2}L_{ms} \\ -\frac{1}{2}L_{ms} & -\frac{1}{2}L_{ms} & L_{ls} + L_{ms} \end{bmatrix}$$

$$L_{ls} = \frac{N_s^2}{\mathfrak{R}_{ls}}$$

$$L_{ms} = \frac{N_s^2}{\mathfrak{R}_m}$$

# Rotor Inductances

$$\mathbf{L}_r = \begin{bmatrix} L_{lr} + L_{mr} & -\frac{1}{2}L_{mr} & -\frac{1}{2}L_{mr} \\ -\frac{1}{2}L_{mr} & L_{lr} + L_{mr} & -\frac{1}{2}L_{mr} \\ -\frac{1}{2}L_{mr} & -\frac{1}{2}L_{mr} & L_{lr} + L_{mr} \end{bmatrix}$$



$$L_{lr} = \frac{N_r^2}{\mathfrak{R}_{lr}}$$

$$L_{mr} = \frac{N_r^2}{\mathfrak{R}_m}$$



# Stator-to-Rotor Inductances

$$\mathbf{L}_{sr} = \begin{bmatrix} L_{asar} & L_{asbr} & L_{ascr} \\ L_{bsar} & L_{bsbr} & L_{bscr} \\ L_{csar} & L_{csbr} & L_{cscr} \end{bmatrix}$$

$L_{asar}$  - component of  $\lambda_{as}$  due to  $i_{ar}$



$L_{asbr}$  - component of  $\lambda_{as}$  due to  $i_{br}$



$$\mathbf{L}_{sr} = L_{sr} \begin{bmatrix} \cos(\theta_r) & \cos\left(\theta_r + \frac{2\pi}{3}\right) & \cos\left(\theta_r - \frac{2\pi}{3}\right) \\ \cos\left(\theta_r - \frac{2\pi}{3}\right) & \cos(\theta_r) & \cos\left(\theta_r + \frac{2\pi}{3}\right) \\ \cos\left(\theta_r + \frac{2\pi}{3}\right) & \cos\left(\theta_r - \frac{2\pi}{3}\right) & \cos(\theta_r) \end{bmatrix}$$

$$L_{sr} = \frac{N_s N_r}{\Re_m}$$

$$\mathbf{L}_{rs} = (\mathbf{L}_{sr})^T$$

# Refer Rotor Quantities to Stator

Put all magnetizing inductances in terms of  $L_{ms}$  (Steinmetz model)

$$\begin{bmatrix} \lambda_{abcs} \\ \frac{N_s}{N_r} \lambda_{abcr} \end{bmatrix} = \begin{bmatrix} \mathbf{L}_s & \frac{N_s}{N_r} \mathbf{L}_{sr} \\ \frac{N_s}{N_r} (\mathbf{L}_{sr})^T & \left( \frac{N_s}{N_r} \right)^2 \mathbf{L}_r \end{bmatrix} \begin{bmatrix} i_{abcs} \\ \frac{N_r}{N_s} i_{abcr} \end{bmatrix}$$

define  $\lambda'_{abcr} = \frac{N_s}{N_r} \lambda_{abcr}$   $i'_{abcr} = \frac{N_r}{N_s} i_{abcr}$   $\mathbf{L}'_{sr} = \frac{N_s}{N_r} \mathbf{L}_{sr}$   $\mathbf{L}'_r = \left( \frac{N_s}{N_r} \right)^2 \mathbf{L}_r$

$$\begin{bmatrix} \lambda_{abcs} \\ \lambda'_{abcr} \end{bmatrix} = \begin{bmatrix} \mathbf{L}_s & \mathbf{L}'_{sr} \\ (\mathbf{L}'_{sr})^T & \mathbf{L}'_r \end{bmatrix} \begin{bmatrix} i_{abcs} \\ i'_{abcr} \end{bmatrix}$$

$$\mathbf{L}'_{sr} = L_{ms} \begin{bmatrix} \cos(\theta_r) & \cos\left(\theta_r + \frac{2\pi}{3}\right) & \cos\left(\theta_r - \frac{2\pi}{3}\right) \\ \cos\left(\theta_r - \frac{2\pi}{3}\right) & \cos(\theta_r) & \cos\left(\theta_r + \frac{2\pi}{3}\right) \\ \cos\left(\theta_r + \frac{2\pi}{3}\right) & \cos\left(\theta_r - \frac{2\pi}{3}\right) & \cos(\theta_r) \end{bmatrix}$$



$$\mathbf{L}'_r = \begin{bmatrix} \left(\frac{N_s}{N_r}\right)^2 L_{lr} + L_{ms} & -\frac{1}{2} L_{ms} & -\frac{1}{2} L_{ms} \\ -\frac{1}{2} L_{ms} & \left(\frac{N_s}{N_r}\right)^2 L_{lr} + L_{ms} & -\frac{1}{2} L_{ms} \\ -\frac{1}{2} L_{ms} & -\frac{1}{2} L_{ms} & \left(\frac{N_s}{N_r}\right)^2 L_{lr} + L_{ms} \end{bmatrix}$$

define  $L'_{lr} = \left(\frac{N_s}{N_r}\right)^2 L_{lr}$

# Refer Voltage Equations

Stator

$$v_{abcs} = r_s i_{abcs} + p \lambda_{abcs}$$

Rotor

$$\frac{N_s}{N_r} v_{abcr} = \frac{N_s}{N_r} r_r i_{abcr} + p \frac{N_s}{N_r} \lambda_{abcr}$$

$$\frac{N_s}{N_r} v_{abcr} = \left( \frac{N_s}{N_r} \right)^2 r_r i'_{abcr} + p \lambda'_{abcr}$$

define  $v'_{abcr} = \frac{N_s}{N_r} v_{abcr} \quad r'_r = \left( \frac{N_s}{N_r} \right)^2 r_r$

$$v'_{abcr} = r'_r i'_{abcr} + p \lambda'_{abcr}$$

# Transform to the Arbitrary Reference Frame

stator variables, use  $\theta \longrightarrow K_s$   
rotor variables, use  $\beta \longrightarrow K_r$

# Transform Voltage Equations

Stator

$$v_{qd0s} = r_s i_{qd0s} + \omega \lambda_{dqs} + p \lambda_{qd0s} \quad \lambda_{dqs} = \begin{bmatrix} \lambda_{ds} \\ -\lambda_{qs} \\ 0 \end{bmatrix}$$

Rotor

$$v'_{qd0r} = r'_r i'_{qd0r} + (\omega - \omega_r) \lambda'_{dqr} + p \lambda'_{qd0r} \quad \lambda_{dqr} = \begin{bmatrix} \lambda'_{dr} \\ -\lambda'_{qr} \\ 0 \end{bmatrix}$$

# Transform Flux Linkages

Stator  $\lambda_{abcs} = \mathbf{L}_s \mathbf{i}_{abcs} + \mathbf{L}'_{sr} \mathbf{i}'_{abcr}$

$$\lambda_{qd0s} = K_s \mathbf{L}_s (K_s)^{-1} i_{qd0s} + K_s \mathbf{L}'_{sr} (K_r)^{-1} i'_{qd0r}$$

Rotor  $\lambda'_{abcr} = (\mathbf{L}'_{sr})^T i_{abcs} + \mathbf{L}'_r i'_{abcr}$

$$\lambda'_{qd0r} = K_r (\mathbf{L}'_{sr})^T (K_s)^{-1} i_{qd0s} + K_r \mathbf{L}'_r (K_r)^{-1} i'_{qd0r}$$

$$\begin{bmatrix} \lambda_{qdos} \\ \lambda'_{qdor} \end{bmatrix} = \begin{bmatrix} K_s \mathbf{L}_s (K_s)^{-1} & K_s \mathbf{L}'_{sr} (K_r)^{-1} \\ K_r (\mathbf{L}'_{sr})^T (K_s)^{-1} & K_r \mathbf{L}'_r (K_r)^{-1} \end{bmatrix} \begin{bmatrix} i_{qdos} \\ i'_{qdor} \end{bmatrix}$$

$$K_s \mathbf{L}_s (K_s)^{-1} = \begin{bmatrix} L_{ls} + L_M & 0 & 0 \\ 0 & L_{ls} + L_M & 0 \\ 0 & 0 & L_{ls} \end{bmatrix} \quad L_M = \frac{3}{2} L_{ms}$$

$$K_r \mathbf{L}_r' (K_r)^{-1} = \begin{bmatrix} L'_{lr} + L_M & 0 & 0 \\ 0 & L'_{lr} + L_M & 0 \\ 0 & 0 & L'_{lr} \end{bmatrix}$$

$$K_s \mathbf{L}'_{sr} (K_r)^{-1} = K_r (\mathbf{L}'_{sr})^T (K_s)^{-1} = \begin{bmatrix} L_M & 0 & 0 \\ 0 & L_M & 0 \\ 0 & 0 & 0 \end{bmatrix}$$

# IM $q$ - $d$ Model Equations

$$v_{qs} = r_s i_{qs} + \omega \lambda_{ds} + p \lambda_{qs}$$

$$v_{ds} = r_s i_{ds} - \omega \lambda_{qs} + p \lambda_{ds}$$

$$v_{0s} = r_s i_{0s} + p \lambda_{0s}$$

$$v'_{qr} = r'_r i'_{qr} + (\omega - \omega_r) \lambda'_{dr} + p \lambda'_{qr}$$

$$v'_{dr} = r'_r i'_{dr} - (\omega - \omega_r) \lambda'_{qr} + p \lambda'_{dr}$$

$$v'_{0r} = r'_r i'_{0r} + p \lambda'_{0r}$$

$$\lambda_{qs} = L_{ls} i_{qs} + L_M (i_{qs} + i'_{qr})$$

$$\lambda_{ds} = L_{ls} i_{ds} + L_M (i_{ds} + i'_{dr})$$





$$\lambda_{0s} = L_{ls} i_{0s}$$

$$\lambda'_{qr} = L'_{lr} i'_{qr} + L_M (i_{qs} + i'_{qr})$$

$$\lambda'_{dr} = L'_{lr} i'_{dr} + L_M (i_{ds} + i'_{dr})$$

$$\lambda'_{0r} = L'_{lr} i'_{0r}$$

# IM $q$ - $d$ Equivalent Circuit





# Torque Expressions

with  $\omega = 0$

$$T_e = \frac{3}{2} \frac{P}{2} \frac{1}{\omega_r} (\omega_r \lambda'_{qr} i'_{dr} - \omega_r \lambda'_{dr} i'_{qr})$$

$$T_e = \frac{3}{2} \frac{P}{2} (\lambda'_{qr} i'_{dr} - \lambda'_{dr} i'_{qr})$$

with  $\omega = \omega_r$

$$T_e = \frac{3}{2} \frac{P}{2} \frac{1}{\omega_r} (\omega_r \lambda_{ds} i_{qs} - \omega_r \lambda_{qs} i_{ds})$$

$$T_e = \frac{3}{2} \frac{P}{2} (\lambda_{ds} i_{qs} - \lambda_{qs} i_{ds})$$

# More Torque Expressions

in terms of currents

$$\lambda_{qs} = (L_{ls} + L_M) i_{qs} + L_M i'_{qr}$$

$$\lambda_{ds} = (L_{ls} + L_M) i_{ds} + L_M i'_{dr}$$

$$T_e = \frac{3}{2} \frac{P}{2} \left[ (L_{ls} + L_M) i_{ds} i_{qs} + L_M i_{qs} i'_{dr} - (L_{ls} + L_M) i_{qs} i_{ds} - L_M i_{ds} i'_{qr} \right]$$

$$T_e = \frac{3}{2} \frac{P}{2} L_M (i_{qs} i'_{dr} - i_{ds} i'_{qr})$$

in terms of flux linkages

$$T_e = \frac{3}{2} \frac{P}{2} \left( \frac{L_M}{L_{ss} L'_{rr} - L_M^2} \right) (\lambda_{qs} \lambda'_{dr} - \lambda_{ds} \lambda'_{qr})$$

$$L_{ss} = L_{ls} + L_M$$

$$L'_{rr} = L'_{lr} + L_M$$

# Torque in $a$ - $b$ - $c$ Variables

$$T_e = -\frac{P}{2} L_{ms} \left\{ \begin{aligned} & \left[ \begin{aligned} & i_{as} \left( i'_{ar} - \frac{1}{2} i'_{br} - \frac{1}{2} i'_{cr} \right) + \\ & i_{bs} \left( i'_{br} - \frac{1}{2} i'_{ar} - \frac{1}{2} i'_{cr} \right) + \\ & i_{cs} \left( i'_{cr} - \frac{1}{2} i'_{ar} - \frac{1}{2} i'_{br} \right) \end{aligned} \right] \sin(\theta_r) + \\ & \frac{\sqrt{3}}{2} [i_{as}(i'_{br} - i'_{cr}) + i_{bs}(i'_{cr} - i'_{ar}) + i_{cs}(i'_{ar} - i'_{br})] \cos(\theta_r) \end{aligned} \right\}$$

## Torque in $q$ - $d$ variables

$$T_e = \frac{3}{2} \frac{P}{2} (\lambda'_{qr} i'_{dr} - \lambda'_{dr} i'_{qr})$$

$$T_e = \frac{3}{2} \frac{P}{2} L_M (i_{qs} i'_{dr} - i_{ds} i'_{qr})$$

$$T_e = \frac{3}{2} \frac{P}{2} (\lambda_{ds} i_{qs} - \lambda_{qs} i_{ds})$$

$$T_e = \frac{3}{2} \frac{P}{2} \left( \frac{L_M}{L_{ss} L'_{rr} - L_M^2} \right) (\lambda_{qs} \lambda'_{dr} - \lambda_{ds} \lambda'_{qr})$$

# Steady-State Calculations ( $q$ - $d$ Model)

## IM parameters

$$r_s := 0.4 \Omega$$

$$P := 4$$

$$r'_r := 0.2266 \Omega$$

$$\text{RPM} := \frac{2 \cdot \pi \cdot \text{rad}}{60 \text{ s}}$$

$$\text{lagging} := 1$$

$$L_{ls} := 5.73 \text{ mH}$$

$$L_M := 64.4 \text{ mH}$$

$$L'_{lr} := 4.64 \text{ mH}$$

$$L_{ss} := L_{ls} + L_M$$

$$L_{ss} = 70.1 \text{ mH}$$

$$L'_{lr} := L'_{lr} + L_M$$

$$L'_{lr} = 69 \text{ mH}$$

## operating conditions

$$f_e := 60 \text{ Hz}$$

$$\omega_e := 2 \cdot \pi \cdot f_e$$

$$\omega_e = 377 \frac{\text{rad}}{\text{s}}$$

$$\omega_{rm} := 1750 \text{ RPM}$$

$$\omega_{rm} = 183.3 \frac{\text{rad}}{\text{s}}$$

$$V_{LL} := 220 \text{ V}$$

$$V_s := \frac{V_{LL}}{\sqrt{3}}$$

$$V_s = 127 \text{ V}$$

## synchronous speed (no-load speed)

$$\omega_{em} := \left( \frac{2}{P} \right) \cdot \omega_e$$

$$\omega_{em} = 188.5 \frac{\text{rad}}{\text{s}}$$

$$\omega_{em} = 1800 \text{ RPM}$$

## slip

$$\omega_r := \frac{P}{2} \cdot \omega_{rm}$$

$$\omega_r = 366.5 \frac{\text{rad}}{\text{s}}$$

$$s := \frac{\omega_e - \omega_r}{\omega_e}$$

$$s = 0.0278$$

# Steady-State Calculations ( $q$ - $d$ Model)

**steady-state calculations (synchronous reference frame)**

$$V_{qs\_e} := \sqrt{2} \cdot V_s \quad V_{ds\_e} := 0 \cdot V \quad V'_{qr\_e} := 0 \cdot V \quad V'_{dr\_e} := 0 \cdot V$$

$$\begin{pmatrix} I_{qs\_e} \\ I_{ds\_e} \\ I'_{qr\_e} \\ I'_{dr\_e} \end{pmatrix} := \begin{bmatrix} r_s & \omega_e \cdot L_{ss} & 0 & \omega_e \cdot L_M \\ -\omega_e \cdot L_{ss} & r_s & -\omega_e \cdot L_M & 0 \\ 0 & (\omega_e - \omega_r) \cdot L_M & r'_r & (\omega_e - \omega_r) \cdot L'_{rr} \\ -(\omega_e - \omega_r) \cdot L_M & 0 & -(\omega_e - \omega_r) \cdot L'_{rr} & r'_r \end{bmatrix}^{-1} \cdot \begin{pmatrix} V_{qs\_e} \\ V_{ds\_e} \\ V'_{qr\_e} \\ V'_{dr\_e} \end{pmatrix}$$

# Steady-State Calculations ( $q$ - $d$ Model)

## current and torque

$$I_s := \frac{1}{\sqrt{2}} \cdot \sqrt{I_{qs\_e}^2 + I_{ds\_e}^2}$$

$$\lambda_{qs\_e} := L_{ss} \cdot I_{qs\_e} + L_M \cdot I'_{qr\_e}$$

$$\lambda_{ds\_e} := L_{ss} \cdot I_{ds\_e} + L_M \cdot I'_{dr\_e}$$

$$T_e := \frac{3}{2} \cdot \frac{P}{2} \cdot (\lambda_{ds\_e} \cdot I_{qs\_e} - \lambda_{qs\_e} \cdot I_{ds\_e})$$

# Steady-State Calculations ( $q$ - $d$ Model)

## magnetizing and rotor flux linkages

$$\lambda_{qM\_e} := L_M \cdot (I_{qs\_e} + I'_{qr\_e})$$

$$\lambda_{dM\_e} := L_M \cdot (I_{ds\_e} + I'_{dr\_e})$$

$$\Lambda_M := \frac{1}{\sqrt{2}} \cdot \sqrt{\lambda_{qM\_e}^2 + \lambda_{dM\_e}^2}$$

$$\lambda'_{qr\_e} := L'_{rr} \cdot I'_{qr\_e} + L_M \cdot I_{qs\_e}$$

$$\lambda'_{dr\_e} := L'_{rr} \cdot I'_{dr\_e} + L_M \cdot I_{ds\_e}$$

$$\lambda'_r := \frac{1}{\sqrt{2}} \cdot \sqrt{\lambda'_{qr\_e}^2 + \lambda'_{dr\_e}^2}$$

# Induction Machine $q$ - $d$ Model

Rotor referred to stator


Formulated in the arbitrary reference frame (could later be set to synchronous, stationary, rotor)

Steady-state variables are constant in the synchronous reference frame



Torque can be expressed in terms of stator quantities, rotor quantities, currents, or flux linkages



# Induction Machine Simulation



# Predefined IM Models





PSCAD

## Matlab Simulink SimPowerSystems

- Notation and model mostly matches the book
- Constant speed and free rotor modes
- Per unit parameters (SI or pu in Simulink)

# SimPowerSystems IM Model

## Electrical System



$$V_{qs} = R_s i_{qs} + \frac{d}{dt} \varphi_{qs} + \omega \varphi_{ds}$$

$$V_{ds} = R_s i_{ds} + \frac{d}{dt} \varphi_{ds} - \omega \varphi_{qs}$$

$$V'_{qr} = R'_r i'_{qr} + \frac{d}{dt} \varphi'_{qr} + (\omega - \omega_r) \varphi'_{dr}$$

$$V'_{dr} = R'_r i'_{dr} + \frac{d}{dt} \varphi'_{dr} - (\omega - \omega_r) \varphi'_{qr}$$

$$T_e = 1.5 p (\varphi_{ds} i_{qs} - \varphi_{qs} i_{ds})$$

where

$$\varphi_{qs} = L_s i_{qs} + L_m i'_{qr}$$

$$\varphi_{ds} = L_s i_{ds} + L_m i'_{dr}$$


$$\varphi'_{qr} = L'_r i'_{qr} + L_m i_{qs}$$

$$\varphi'_{dr} = L'_r i'_{dr} + L_m i_{ds}$$

$$L_s = L_{ls} + L_m$$

$$L'_r = L'_{lr} + L_m$$

# PSCAD IM Model



A, B, C, N - stator electrical terminals

a b c - rotor electrical terminals

S = 1 - constant speed mode

S = 0 - mechanical equations

W - speed when S = 1

initial speed when S = 0

expressed in per unit as  $\omega_r / \omega_e$

TL - load torque when S = 0

# IM Per-Unit Example

## Induction machine ratings/parameters

$$\omega_b := 2 \cdot \pi \cdot 60 \text{ Hz}$$

$$P_B := 10 \text{ hp}$$

$$V_B := \frac{220 \text{ V}}{\sqrt{3}}$$

$$P := 6$$

$$r_{s\_pu} := 0.0453$$

$$X_{ls\_pu} := 0.0775$$

$$X_{M\_pu} := 2.042$$

$$r'_{r\_pu} := 0.0222$$

$$X'_{lr\_pu} := 0.0322$$

$$H := 0.5 \text{ s}$$

## per unit quantities

$$I_B := \frac{P_B}{3 \cdot V_B}$$

$$Z_B := \frac{V_B}{I_B}$$

$$T_B := \frac{P_B}{\left(\frac{2}{P}\right) \cdot \omega_b}$$

$$\omega_b = 377 \frac{\text{rad}}{\text{s}}$$

$$P_B = 7.457 \text{ kW}$$

$$V_B = 127 \text{ V}$$

$$2 \cdot H = 1 \text{ s}$$

$$I_B = 19.57 \text{ A}$$

$$Z_B = 6.491 \Omega$$

$$T_B = 59.3 \text{ N} \cdot \text{m}$$

# Induction Machine SI Quantities

## machine parameters

$$r_s := r_{s\_pu} \cdot Z_B$$

$$r_s = 0.294\Omega$$

$$L_{ls} := \frac{X_{ls\_pu} \cdot Z_B}{\omega_b}$$

$$L_{ls} = 1.33\text{mH}$$

$$L_M := \frac{X_{M\_pu} \cdot Z_B}{\omega_b}$$

$$L_M = 35.16\text{mH}$$

$$r'_r := r'_{r\_pu} \cdot Z_B$$

$$r'_r = 0.144\Omega$$

$$L'_{lr} := \frac{X'_{lr\_pu} \cdot Z_B}{\omega_b}$$

$$L'_{lr} = 0.55\text{mH}$$

$$J := 2 \cdot H \cdot \frac{T_B}{\left(\frac{2}{P}\right) \cdot \omega_b}$$

$$J = 0.472\text{kgm}^2$$

# SimPowerSystems Inputs

Block Parameters: Asynchronous Machine SI Units

Asynchronous Machine (mask) (link)

Implements a three-phase asynchronous machine (wound rotor, squirrel cage or double squirrel cage) modeled in a selectable dq reference frame (rotor, stator, or synchronous). Stator and rotor windings are connected in wye to an internal neutral point.

Configuration Parameters Advanced

Preset model: No

Mechanical input: Torque  $T_m$

Rotor type: Squirrel-cage

Reference frame: Rotor

Mask units: SI

OK Cancel Help Apply

Block Parameters: Asynchronous Machine SI Units

Asynchronous Machine (mask) (link)

Implements a three-phase asynchronous machine (wound rotor, squirrel cage or double squirrel cage) modeled in a selectable dq reference frame (rotor, stator, or synchronous). Stator and rotor windings are connected in wye to an internal neutral point.

Configuration Parameters Advanced

Nominal power, voltage (line-line), and frequency [  $P_n(VA)$ ,  $V_n(V_{rms})$ ,  $f_n(Hz)$  ]:

[ 10\*746, 220, 60 ]

Stator resistance and inductance [  $R_s(ohm)$   $L_s(H)$  ]:

[ 0.294 1.33e-3 ]

Rotor resistance and inductance [  $R_r(ohm)$   $L_r(H)$  ]:

[ 0.144 0.55e-3 ]

Mutual inductance  $L_m$  (H):

35.16e-3

Inertia, friction factor, pole pairs [  $J(kg.m^2)$   $F(N.m.s)$   $p()$  ]:

[ 0.472 0 3 ]

Initial conditions

[ 1 0 0 0 0 0 0 ]

☐ Simulate saturation

Saturation Parameters [  $i_1, i_2, \dots$  (Arms) ;  $v_1, v_2, \dots$  ( $V_{rmsLL}$ ) ]

1, 302.9841135, 428.7778367 ; 230, 322, 414, 460, 506, 552, 598, 644, 690 ]

OK Cancel Help Apply

# PSCAD Model Inputs

Global Substitutions [IM]

$\omega_b = 376.99$  [rad/s]  
 $PB = 7457$  [VA]  
 $VLL = 220$  [V]  
 $TB = 59.3$  [J]  
 $VB = 127$  [V]  
 $IB = 19.57$  [A]

OK Cancel

[wound\_rotor] Wound Rotor Induction Machine

Stator and rotor resistances

Stator Resistance	0.0453 [pu]
Wound rotor resistance	0.0222 [pu]
First squirrel cage resistance	0.298 [pu]
Second squirrel cage resistance	0.018 [pu]

[wound\_rotor] Wound Rotor Induction Machine

General data

Motor Name	
Rated Power	\$(PB)
Rated Voltage (L-L)	\$(VLL)
Base Angular Frequency	\$(\omega_b)
Stator / Rotor Turns Ratio	1
Angular Moment of Inertia (J=2H)	1 [s]
Mechanical Damping	0.00005 [pu]
Graphics Display	3 phase view


[wound\_rotor] Wound Rotor Induction Machine

Stator and rotor inductances


Magnetizing inductance	2.042 [pu]
Stator leakage inductance	0.0775 [pu]
Wound rotor leakage inductance	0.0322 [pu]
First cage leakage inductance	0.05 [pu]
Second cage leakage inductance	0.05 [pu]
Third cage leakage inductance	0.05 [pu]
Mutual inductance : Wound rotor - 1st Cage	0.02 [pu]
Mutual inductance : Wound rotor - 2nd Cage	0.02 [pu]
Mutual inductance : Wound rotor - 3rd Cage	0.02 [pu]
Mutual inductance : 1st - 2nd Cages	0.02 [pu]
Mutual inductance : 1st - 3rd Cages	0.02 [pu]
Mutual inductance : 2nd - 3rd Cages	0.02 [pu]



# Stationary Reference Frame (Book Figure 6.11-2)




Simulink




PSCAD

# Synchronous Reference Frame (Book Figure 6.11-4)




Simulink




PSCAD

# Rotor Reference Frame (Book Figure 6.11-3)



Simulink



PSCAD

# Induction Machine Simulation

Transient and steady-state performance prediction

Flux linkages or currents can be state variables

Simulink and PSCAD models are based on the standard  $q$ - $d$  machine model with some additional features such as saturation

Simulink: parameters in SI units (or per-unit) using the same  $q$ - $d$  model as in the book.

PSCAD: parameters entered in per-unit. Internal output variables in per-unit.

# IM Steady-State Calculations

Could use  $q$ - $d$  equations or  $a$ - $b$ - $c$  equations

Instantaneous voltages

$$v_{as} = \sqrt{2}V_s \cos(\theta_e)$$

$$v_{bs} = \sqrt{2}V_s \cos\left(\theta_e - \frac{2\pi}{3}\right)$$

$$v_{cs} = \sqrt{2}V_s \cos\left(\theta_e + \frac{2\pi}{3}\right)$$

$$\theta_e = \omega_e t \quad \omega_e = 2\pi f$$

voltage phasors

$$\tilde{V}_{as} = V_s \angle 0$$


$$\tilde{V}_{bs} = V_s \angle -120^\circ$$

$$\tilde{V}_{cs} = V_s \angle 120^\circ$$

constant  $\omega_{rm}$        $\omega_r = \frac{P}{2} \omega_{rm}$

define slip  $s = \frac{\omega_e - \omega_r}{\omega_e}$

# Per-Phase Steady-State Circuit



squirrel cage  $\tilde{V}'_{ar} = 0$

# Steady-State (Average) Torque

$$P_{out} = 3r'_r \left( \frac{1-s}{s} \right) |\tilde{I}'_{ar}|^2$$

$$P_{out} = T_e \omega_{rm}$$

$$\omega_{rm} = \frac{2}{P} \omega_r = \frac{2}{P} (1-s) \omega_e$$

$$T_e = \frac{P}{2} \frac{1}{(1-s) \omega_e} P_{out}$$

$$T_e = 3 \frac{P}{2} \frac{r'_r}{s \omega_e} |\tilde{I}'_{ar}|^2$$

# Torque in Terms of Voltage

input impedance  $Z_{in} = Z_s + (Z_m \parallel Z'_r)$

$$Z_s = r_s + j\omega_e L_{ls} \quad Z'_r = \frac{r'_r}{s} + j\omega_e L'_{lr} \quad Z_m = j\omega_e L_M$$

currents

$$\tilde{I}_{as} = \frac{\tilde{V}_{as}}{Z_{in}} \quad \tilde{I}'_{ar} = -\left(\frac{Z_m}{Z_m + Z'_r}\right)\tilde{I}_{as} = -\left(\frac{Z_m}{Z_m + Z'_r}\right)\frac{\tilde{V}_{as}}{Z_{in}}$$

torque

$$T_e = \frac{3\frac{P}{2}\omega_e L_M^2 r'_r s |\tilde{V}_{as}|^2}{\left[r_s r'_r + s\omega_e^2 (L_M^2 - L_{ss} L'_{rr})\right]^2 + \omega_e^2 (r'_r L_{ss} + s r_s L'_{rr})^2}$$

$$L_{ss} = L_{ls} + L_M$$

$$L'_{rr} = L'_{lr} + L_M$$



# Steady-State Calculations (Per-Phase Model)

## IM parameters

$$r_s := 0.4 \Omega$$

$$P := 4$$

$$r'_r := 0.2266 \Omega$$

$$\text{RPM} := \frac{2 \cdot \pi \cdot \text{rad}}{60 \cdot \text{s}}$$

$$\text{lagging} := 1$$

$$L_{ls} := 5.73 \text{ mH}$$

$$L_M := 64.4 \text{ mH}$$

$$L'_{lr} := 4.64 \text{ mH}$$

$$L_{ss} := L_{ls} + L_M$$

$$L_{ss} = 70.1 \text{ mH}$$

$$L'_{lr} := L'_{lr} + L_M$$

$$L'_{lr} = 69 \text{ mH}$$

## operating conditions

$$f_e := 60 \text{ Hz}$$

$$\omega_e := 2 \cdot \pi \cdot f_e$$

$$\omega_e = 377 \frac{\text{rad}}{\text{s}}$$

$$\omega_{rm} := 1750 \text{ RPM}$$

$$\omega_{rm} = 183.3 \frac{\text{rad}}{\text{s}}$$

$$V_{LL} := 220 \text{ V}$$

$$V_s := \frac{V_{LL}}{\sqrt{3}}$$

$$V_s = 127 \text{ V}$$

## synchronous speed (no-load speed)

$$\omega_{em} := \left( \frac{2}{P} \right) \cdot \omega_e$$

$$\omega_{em} = 188.5 \frac{\text{rad}}{\text{s}}$$

$$\omega_{em} = 1800 \text{ RPM}$$

## slip

$$\omega_r := \frac{P}{2} \cdot \omega_{rm}$$

$$\omega_r = 366.5 \frac{\text{rad}}{\text{s}}$$

$$s := \frac{\omega_e - \omega_r}{\omega_e}$$

$$s = 0.0278$$

# Steady-State Calculations (Per-Phase Model)

## impedances

$$Z_s := r_s + j \cdot \omega_e \cdot L_{ls}$$

$$Z_m := j \cdot \omega_e \cdot L_M$$

$$Z'_r := \frac{r'_r}{s} + j \cdot \omega_e \cdot L'_{lr}$$

$$Z_f := \frac{1}{\frac{1}{Z_m} + \frac{1}{Z'_r}}$$

$$Z_{in} := Z_s + Z_f$$

## currents

$$V_{as} := V_s \cdot e^{j \cdot 0}$$

$$I_{as} := \frac{V_{as}}{Z_{in}}$$

$$I'_{ar} := -I_{as} \cdot \frac{Z_m}{Z_m + Z'_r}$$

# Steady-State Calculations (Per-Phase Model)

## torque and power

$$T_e := 3 \cdot \frac{P}{2} \cdot (|I_{ar}|)^2 \cdot \frac{r'_r}{s \cdot \omega_e}$$

$$T_e := \frac{3 \cdot \left(\frac{P}{2}\right) \cdot \omega_e \cdot L_M^2 \cdot r'_r \cdot s \cdot (|V_{as}|)^2}{\left[r_s \cdot r'_r + s \cdot \omega_e^2 \cdot (L_M^2 - L_{ss} \cdot L'_{rr})\right]^2 + \omega_e^2 \cdot (r'_r \cdot L_{ss} + s \cdot r_s \cdot L'_{rr})^2}$$

$$\theta := \arg(Z_{in})$$

$$pf := \cos(\theta)$$

$$P_{in} := 3 \cdot |V_{as}| \cdot |I_{as}| \cdot pf$$

$$P_{out} := T_e \cdot \omega_{rm}$$

$$eff := \frac{P_{out}}{P_{in}}$$

# Steady-State Calculations (Per-Phase Model)

rotor flux linkage

$$\Lambda'_r := \frac{-I'_{ar} \frac{r'_r}{s}}{j \cdot \omega_e}$$


# IM Steady-State Model

Straightforward and quick calculation of steady-state operation

Model provides insight into motor operation

Can be used to predict peak torque, stall torque, and starting current

# Simplified IM Steady-State Model



$$T_e = 3 \frac{P}{2} \frac{r'_r}{s \omega_e} |\tilde{I}'_{ar}|^2$$

$$|\tilde{I}'_{ar}|^2 = \frac{|\tilde{V}_{as}|^2 s^2}{r_r'^2}$$

$$T_e = 3 \frac{P}{2} \frac{s |\tilde{V}_{as}|^2}{r'_r \omega_e} = 3 \frac{P}{2} \left( \frac{|\tilde{V}_{as}|}{\omega_e} \right)^2 \frac{\omega_e - \omega_r}{r'_r}$$

Note: model suggest

- Torque proportional to slip
- Torque inversely proportional to rotor resistance
- Torque proportional to stator voltage squared

# Calculations Using the Simplified Model

**Table 4.10-1 Induction Machine Parameters**

Machine Rating			$T_B$	$I_{B(abc)}$	$r_s$	$X_{ls}$	$X_M$	$X'_{lr}$	$r'_r$	$J$
hp	Volts	rpm	(N · m)	(amps)	(ohms)	(ohms)	(ohms)	(ohms)	(ohms)	(kg · m <sup>2</sup> )
3	220	1710	11.9	5.8	0.435	0.754	26.13	0.754	0.816	0.089
50	460	1705	198	46.8	0.087	0.302	13.08	0.302	0.228	1.662
500	2300	1773	$1.98 \times 10^3$	93.6	0.262	1.206	54.02	1.206	0.187	11.06
2250	2300	1786	$8.9 \times 10^3$	421.2	0.029	0.226	13.04	0.226	0.022	63.87

## Note

- Inertia is proportional to power rating
- Rotor resistance is small for large machines

### 3 horsepower machine

$$f_e := 60 \text{ Hz}$$

$$V_{as} := \frac{220 \text{ V}}{\sqrt{3}}$$

$$\omega_e := 2 \cdot \pi \cdot f_e$$

$$P := 4$$

$$r_s := 0.435 \Omega$$

$$L_{ls} := \frac{0.754 \Omega}{\omega_e}$$

$$L_M := \frac{26.13 \Omega}{\omega_e}$$

$$L'_{lr} := \frac{0.754 \Omega}{\omega_e}$$

$$r'_r := 0.816 \Omega$$

$$L_{ss} := L_{ls} + L_M$$

$$L'_{rr} := L'_{lr} + L_M$$

$$\omega_{rm} := 1710 \text{ RPM}$$

$$\omega_r := \frac{P}{2} \cdot \omega_{rm}$$

$$s_{rated} := \frac{\omega_e - \omega_r}{\omega_e}$$

$$V_{as} = 127 \text{ V}$$

$$\omega_e = 377 \frac{\text{rad}}{\text{s}}$$

$$L_{ls} = 2 \text{ mH}$$

$$L_M = 69.3 \text{ mH}$$

$$L'_{lr} = 2 \text{ mH}$$

$$L_{ss} = 71.3 \text{ mH}$$

$$L'_{rr} = 71.3 \text{ mH}$$

$$\omega_{rm} = 179 \frac{\text{rad}}{\text{s}}$$

$$\omega_r = 358 \frac{\text{rad}}{\text{s}}$$

$$s_{rated} = 0.05$$





## torque equations and plots

$$T_e(s) := \frac{3 \cdot \frac{P}{2} \cdot \omega_e \cdot L_M^2 \cdot r'_r \cdot s \cdot (|V_{as}|)^2}{\left[ r_s \cdot r'_r + s \cdot \omega_e^2 \cdot (L_M^2 - L_{ss} \cdot L'_{rr}) \right]^2 + \omega_e^2 \cdot (r'_r \cdot L_{ss} + s \cdot r_s \cdot L'_{rr})^2}$$

$$T_{e\_approx}(s) := 3 \cdot \frac{P}{2} \cdot \frac{s \cdot (|V_{as}|)^2}{r'_r \cdot \omega_e}$$

$$s := 0.0001 \ 0.001 \ 1$$



## 2250 horsepower machine

$$f_e := 60 \text{ Hz}$$

$$V_{as} := \frac{2250 \text{ V}}{\sqrt{3}}$$

$$\omega_e := 2 \cdot \pi \cdot f_e$$

$$P := 4$$

$$r_s := 0.029 \Omega$$

$$L_{ls} := \frac{0.226 \Omega}{\omega_e}$$

$$L_M := \frac{13.04 \Omega}{\omega_e}$$

$$L'_{lr} := \frac{0.226 \Omega}{\omega_e}$$

$$r'_r := 0.022 \Omega$$

$$L_{ss} := L_{ls} + L_M$$

$$L'_{rr} := L'_{lr} + L_M$$

$$\omega_{rm} := 1786 \text{ RPM}$$

$$\omega_r := \frac{P}{2} \cdot \omega_{rm}$$

$$s_{rated} := \frac{\omega_e - \omega_r}{\omega_e}$$

$$V_{as} = 1299 \text{ V}$$

$$\omega_e = 377 \frac{\text{rad}}{\text{s}}$$

$$L_{ls} = 0.599 \text{ mH}$$

$$L_M = 34.6 \text{ mH}$$

$$L'_{lr} = 0.599 \text{ mH}$$

$$L_{ss} = 35.2 \text{ mH}$$

$$L'_{rr} = 35.2 \text{ mH}$$

$$\omega_{rm} = 187 \frac{\text{rad}}{\text{s}}$$

$$\omega_r = 374 \frac{\text{rad}}{\text{s}}$$



$$s_{rated} = 0.0078$$

## torque equations and plots

$$T_e(s) := \frac{3 \cdot \frac{P}{2} \cdot \omega_e \cdot L_M^2 \cdot r'_r \cdot s \cdot (|V_{as}|)^2}{\left[ r_s \cdot r'_r + s \cdot \omega_e^2 \cdot (L_M^2 - L_{ss} \cdot L'_{rr}) \right]^2 + \omega_e^2 \cdot (r'_r \cdot L_{ss} + s \cdot r_s \cdot L'_{rr})^2}$$

$$T_{e\_approx}(s) := 3 \cdot \frac{P}{2} \cdot \frac{s \cdot (|V_{as}|)^2}{r'_r \cdot \omega_e}$$

$$s := 0.0001 : 0.001 : 1$$



# Induction Machine Simplified Model

Simple determination of steady-state operation

Accurate in normal operation close to no-load speed