


Overview

[Estimate](#)
[TMC2208-2209](#)
[Speed calculation](#)
[Calibration instruction feeder](#)


Sheet 1: Estimate

	Name	Description	quantity	price, USD	delivery	Total, USD	ссылка на товар
	Cable channel 7 * 7mm	1 meter	1	5.9	0	5.9	http://ali.pub/53z26k
	Fitting	PC4-01	1	0.5	0.67	1.17	http://ali.pub/53z2jl
	Switch	KCD-2	1	0.5	0	0.5	http://ali.pub/53z2pl
	Round hygrometer	the black	1	2.03	0.49	2.52	http://ali.pub/53z2tb
	Magnet 20 * 10 * 3		2	1.7	1	4.4	http://ali.pub/53z33t
	Fan 6010 24V	60x60x10	2	1.71	0	3.42	http://ali.pub/53z39g
	Fan 4010 24V	40x40x10	1	1	0	1	http://ali.pub/5b3tg4
	BIGTREETECH TMC2209 V1.2		1	10.38	0	10.38	http://ali.pub/53z3or
	Insulation for the table	310*310	1	2.51	1.31	3.82	http://ali.pub/53z40h
	Wire braid		1	3	0	3	http://ali.pub/53z49f
	Baldwin sticky		2	0.50	0.86	2.02	http://ali.pub/53z4xx
	LED strip SMD 5050	IP65 Waterproof + 24V	1	7.6	0	7.6	http://ali.pub/53z52g
	Bear Nozzles	0.4 mm	2	2	0	4	http://ali.pub/55aa2i
	Screws m3 * 12	50 pcs				0	
	Screws m3 * 16	10 pieces				0	
	Screws m3 * 16	10 pieces				0	
	Heat chamber bearings	8x2x7 mm 608ZZ	10	1	3	4	http://ali.pub/5b3ykc








optional,
optional



optional,
optional



Estimate for ChuchaTV heads							
	E3d V6 BMG Hoend SET	set N3 for 24v Right	1	44	0	44	http://ali.pub/57c7c7
	Turbine SNAIL 4020	24V	1	1.2	0	1.2	http://ali.pub/57624g
	Biunital NI V6 THERMOBARRIER		1	8	0	8	http://ali.pub/59x0mg



Sheet 2: TMC2208-2209

Vref - Driver voltage	Vref	
Irms - Constant current on motors.	Irms	
Imax - Peak current on motors	Imax	

$Vref = (Irms * 2.5) / 1.77$	Vref	0
$Irms = (Vref * 1.77) / 2.5$	Irms	0
$Imax = Irms * 1.41$	Imax	0
$Irms = Imax / 1.41$	Irms	0

enter values
enter values
enter values

Sheet 3: Speed calculation

in English

Parameters	known	necessary to find out	formula	what values to set		
Initial speed (Jerk) V0, mm / s		0.00	$V0=V\cdot a\cdot t$	V	a	t
Final speed (printing speed) V, mm / s		0.00	$V=V0+a\cdot t$	V0	a	t
Acceleration (ACCELERATION) a, mm / s²		#DIV/0!	$a=(V-V0)/2S$	V	S	V0
Time t, s		#DIV/0!	$t=(V-V0)/a$	V	a	V0
Travel S, mm		#DIV/0!	$S=(V^2-V0^2)/2a$	V	a	V0

Jerk enter values	
ACCELERATION enter values	
d- JUNCTION DEVIATION RESULT	#DIV/0!

$$d = 0.4 \cdot \frac{Jerk^2}{Accel_{printing}}$$

Sheet 4: Calibration instruction feeder

M302 P1; Disabling the temperature protection of the extruder
G21 E0; Resetting the extruder position
G1 E280 F800; Extrude 280mm plastic

To start setting up the steps, we need to free the filament from the printer. To do this, it is necessary to heat the nozzle to the operating temperature (the easiest way to do this is by starting the preheating of the extruder on the printer); then squeeze the filament a little (3-5 mm) towards the table, and then roll it back ~8 cm. After this operation, you can safely pull out the filament with your hands without fear of damaging anything.

1. Take the ptfz tube out of the feeder fitting. To do this, press on the black ring on the fitting evenly and as far as possible until it stops, in this position the fitting releases the tube and it is pulled out without applying force.

2. Slightly rewind the plastic back onto the reel, an even (not rolled) filament should come out of the feeder. Cut it off exactly along the edge of the fitting.

3. We go to the kuru, connect to the printer via WiFi, go to the monitor tab and send the following lines in turn to the Send g-code window

M302 P1; Disabling the temperature protection of the extruder
G21 E0; Resetting the extruder position
G1 E280 F800; Extrude 280mm plastic

It is better to choose the length of the extruded plastic based on the size of the ruler you have, extrude 10% less.

4. Cut off the extended plastic in the same way along the edge of the fitting. We measure the length of the cut piece - for example 265 mm.

5. Calculate the correct number of motor steps per mm. To do this, we take the current value of the steps (IN THE FIRMWARE by default 400), multiply by the length that was requested to extrude (in example 280) and divide by the result obtained (in example 265):

$$400 * 280/265 = 422.64$$

6. Take the robin_nano35_cfg.txt file from the firmware, find the parameter: DEFAULT_E0_STEPS_PER_UNIT in it and replace its value with the value obtained in the previous step. Save, put the file in the root of the sd card and restart the printer.

7. It is recommended to repeat the procedure from step 3.

8. Putting back the printer.

- Find out the current number of steps per mm, (command M503)

We multiply by the received coefficient.

- Introduces into the firmware, or quickly into memory: M502 E ***

Don't forget to save the M500.