

# 690 Project 3: Motor Control

Luke Weaver

February 7, 2018



### **Abstract**

The purpose of this project is to configure a DC Motor controlled by a PWM signal. The motor has a built in encoder; the encoder gets information from the motor such as velocity, direction, and position. Upon running the program, UART will display two options; option 1 will ask the user for a velocity between -100 to 100 inclusive. A value of 100 indicating full speed clockwise, -100 full speed counter clockwise, and 0 to a stop. Choosing option 1 will also report the direction and velocity to the ReportData facility. Option 2 will turn the motor axle to a specified position; after selecting option 2 UART will ask for a degree between -180 and 180 inclusive to rotate the motor.

# Contents

<b>List of Figures</b>	<b>1</b>
<b>1 Principles of Operation</b>	<b>2</b>
<b>2 Data Structure Descriptions</b>	<b>3</b>
<b>3 Function Descriptions</b>	<b>4</b>
3.1 Task_PWM(void)	4
3.2 extern void PWMClockSet(uint32_t ui32Base, uint32_t ui32Config)	4
3.3 void PWMGenConfigure(uint32_t ui32Base, uint32_t ui32Gen, uint32_t ui32Config)	4
3.4 void PWMGenPeriodSet(uint32_t ui32Base, uint32_t ui32Gen, uint32_t ui32Period)	4
3.5 void PWMPulseWidthSet(uint32_t ui32Base, uint32_t ui32PWMOut, uint32_t ui32Width)	4
3.6 void PWMGenEnable(uint32_t ui32Base, uint32_t ui32Gen)	4
3.7 void PWMOutputState(uint32_t ui32Base, uint32_t ui32PWMOutBits, bool bEnable)	4
3.8 void QEIConfigure(uint32_t ui32Base, uint32_t ui32Config, uint32_t ui32MaxPosition)	4
3.9 void QEIEnable(uint32_t ui32Base)	4
3.10 void QEIVelocityEnable(uint32_t ui32Base)	4
3.11 void QEIVelocityConfigure(uint32_t ui32Base, uint32_t ui32PreDiv, uint32_t ui32Period)	4
3.12 uint32_t QEIPositionGet(uint32_t ui32Base)	4
3.13 Main_Sharp1_Test.c(void)	5
3.14 PsuedoCode	5
<b>4 Parameters</b>	<b>6</b>
4.1 char mode[1]	6
4.2 char UserInput[3]	6
4.3 uint32_t currentMultiplier	6
4.4 uint32_t servoPW	6
4.5 uint32_t servoPeriod	6
4.6 uint32_t servoPosition	6
4.7 uint32_t qeipos	6
<b>5 Testing</b>	<b>7</b>
<b>6 Lessons Learned and Revision History</b>	<b>8</b>
<b>7 Program Listing</b>	<b>9</b>
7.1 Main_NoSharp1_Test.c	9
7.2 Task_PWM.c	11

## List of Figures

1	Top-Level Block Diagram . . . . .	2
2	UART output task 1 . . . . .	7
3	UART output task 2 and 3 . . . . .	8

## List of Tables

none

# 1 Principles of Operation

The Motor is powered by an external power supply and has an input channel which is configured to port G pin 1; this pin can be found on the Tiva LaunchPad's GPIO pin header. The decoder has two input channels connected to the Tiva board. The motors channels are connected to Port L Pin 1 and 2. These gpio pins can be found on the BoosterPack1 header. Listing the pin configuration is crucial in order to recreate the lab. In order to rotate the motor I used PWM functions that can be found in the PWM header file. By creating a PWM signal I was able to rotate the motor at various speeds. The next step was to gather data from the motor via the encoder. After enabling the aforementioned pins I was able to configure the quadratic encoder interface and gather information such as velocity and position. Once I knew the position of the motor, I was able to write a program to rotate the motor from -180 to 180 degrees. A top-level block diagram of the design is shown below:




Figure 1: Top-Level Block Diagram

`Task_PWM`, is instantiated within the main using a function `xTaskCreate()`. This is part of the FreeRTOS language and is used to add a task to a list of tasks running; this is used for memory allocation. Upon creation of the PWM task, the PWM is initialized and the task asks the user which mode they want to enter. Mode 1 will run task 1 of the project and Mode 2 implements Task 2 and 3. If the user selects 1, the program will

prompt the user to set a direction and velocity of the motor ranging from -100 to 100 and if the user selects 2 the program will prompt the user to set a position of the motor ranging from -180 to 180.

## **2 Data Structure Descriptions**

No major data structures were used.

## 3 Function Descriptions

### 3.1 Task\_PWM(void)

The PWM task controls all order of operation. Task\_PWM initializes and implements the motor and decoder.

### 3.2 extern void PWMClockSet(uint32\_t ui32Base, uint32\_t ui32Config)

Sets the PWM clock configuration.

### 3.3 void PWMGenConfigure(uint32\_t ui32Base, uint32\_t ui32Gen, uint32\_t ui32Config)

This function configures a PWM generator to be used.

### 3.4 void PWMGenPeriodSet(uint32\_t ui32Base, uint32\_t ui32Gen, uint32\_t ui32Period)

Sets the period of a PWM generator.

### 3.5 void PWMPulseWidthSet(uint32\_t ui32Base, uint32\_t ui32PWMOut, uint32\_t ui32Width)

This function sets the pulse width for the specified PWM output.

### 3.6 void PWMGenEnable(uint32\_t ui32Base, uint32\_t ui32Gen)

This function enables PWM generator 2.

### 3.7 void PWMOutputState(uint32\_t ui32Base, uint32\_t ui32PWMOutBits, bool bEnable)

This function enables or disables PWM outputs.

### 3.8 void QEIConfigure(uint32\_t ui32Base, uint32\_t ui32Config, uint32\_t ui32MaxPosition)

Configures the quadrature encoder.

### 3.9 void QEIEnable(uint32\_t ui32Base)

Enables the quadrature encoder.

### 3.10 void QEIVelocityEnable(uint32\_t ui32Base)

Enables the velocity capture.

### 3.11 void QEIVelocityConfigure(uint32\_t ui32Base, uint32\_t ui32PreDiv, uint32\_t ui32Period)

Configures the velocity capture.

### 3.12 uint32\_t QEIPositionGet(uint32\_t ui32Base)

Gets the current encoder position.



### 3.13 Main\_Sharp1\_Test.c(void)

Instantiates Task\_PWM and starts the FreeRTOS Task Scheduler.

### 3.14 PsuedoCode

Project 3 Psuedo Code

```
//function call in main
//xtaskcreate(Task_PWM())

//function inside Task_PWM.c
extern void Task_PWM( void )
{
    PWM_Initialization();
    enable peripherals(Port L and G)
    configure pwm and qei
    uint userinput
    public float pulsewidth;
    pulsewidthset( user input);
    if(position of motor == desired position)
    {
        stop rotating();
    }
    uart (qeipositionget)
    uart (qeivelocityget)
}
```

## 4 Parameters

### 4.1 `char mode[1]`

This parameter captures user input via UART; mode determines which mode the user wishes to enter.

### 4.2 `char UserInput[3]`

This parameter captures user input via UART;

userInput is to be used to set the desired velocity or position.

### 4.3 `uint32_t currentMultiplier`

This integer converts the userInput character array to an integer.

### 4.4 `uint32_t servoPW`

This value is used to set the pulse width for the motor.

### 4.5 `uint32_t servoPeriod`

This value is used to set the period for the motor.

### 4.6 `uint32_t servoPosition`

This value stores the desired position of the motor.

### 4.7 `uint32_t qeipos`


This value gets the current position of the motor.

## 5 Testing

First, I would test my PWM code on a servo since they were more widely available and required less set-up. I used a servo that could rotate freely without constraints to emulate a motor as closely as possible. Once I was able to enter proper velocity input through UART I felt confident enough to hook up the motor. At first I thought I set up the motor incorrectly but I later learned that some of the motor controllers were not functioning properly. Once I properly set up the motor the next step was to gather information from the encoder. I had to set up channels A and B to port L pin 1 and 2 respectively. I learned that these pins are not interchangeable; as Port L pin 1 is expecting input from channel A and vice versa for Port L pin 2.


I spent a majority of my time testing part 3 of the project (rotating motor a certain degree from origin). There seems to be residual rotation after the motor finishes rotating. The way I got around this was to add leniency, a  $\pm 2$  tics of uncertainty so that even if the motor rotated a little too much, it would still register as a degree. This translates to a  $\pm .64$  degree uncertainty.

After experimenting with setting various velocities and positions I was able to accurately set and retrieve the information from the QEI. Figure 2 tests task 1's output. The parameters fed into the Que are: time-stamp, task name, velocity, and position. Figure 3 tests task 1's output. The parameters fed into the Que are: time-stamp, task name, and position.



```
COM12 - PuTTY
FreeRTOS Starting!
Press 1 to set velocity OR press 2 to set position.1
Set speed (-100 - 100) : 20
user input: 20
current Pulse Width Value: 3000
Set speed (-100 - 100) : { 00004804, 01, 4, 1, 679, 0 },
-20
user input: -20
current Pulse Width Value: 2626
Set speed (-100 - 100) : { 00008468, 01, 4, -1, 718, 0 },
0
user input: 0
current Pulse Width Value: 2813
Set speed (-100 - 100) : { 00010276, 01, 0, 1, 192, 0 },
100
user input: 100
current Pulse Width Value: 3750
Set speed (-100 - 100) : { 00016820, 01, 26, 1, 170, 0 },
0
user input: 0
current Pulse Width Value: 2813
Set speed (-100 - 100) : { 00017823, 01, 7, 1, 136, 0 },
```

Figure 2: UART output task 1



```
COM12 - PuTTY
FreeRTOS Starting!
Press 1 to set velocity OR press 2 to set position.2
Set position in degrees (-180 - 180): 45
Current Position: 560
Desired Position: 700
New Current Position: 698
Set position in degrees (-180 - 180): { 00003880, 02, 698, 0, 0, 0 },
90
Current Position: 723
Desired Position: 840
New Current Position: 838
Set position in degrees (-180 - 180): { 00005752, 02, 838, 0, 0, 0 },
-90
Current Position: 857
Desired Position: 280
New Current Position: 282
Set position in degrees (-180 - 180): { 00011671, 02, 282, 0, 0, 0 },
-180
Current Position: 266
Desired Position: 0
New Current Position: 2
Set position in degrees (-180 - 180): { 00025140, 02, 2, 0, 0, 0 },
█
```

Figure 3: UART output task 2 and 3

## 6 Lessons Learned and Revision History

Luckily this project uses components from project 2. I utilized the PWM knowledge I learned from project 2 to drive the motor. With Doctor Minden's help I was able to locate the correct pins to use on the Tiva for channel A and B on the QEI. I thoroughly enjoyed this project and wish we had time to do a fourth project. The new concepts used in this project include PWM motor control, and UART input. I have greater knowledge on motor control and plan on using the knowledge gained in my senior design project.

## 7 Program Listing

### 7.1 Main\_NoSharp1\_Test.c

```
/*--Main_Sharp1_Test.c
 *
 * Author: Luke Weaver
 * Organization: KU/EECS/EECS 690
 * Date: October 30, 2017 (B60313)
 *
 * Description: Starts RTOS Scheduler and Creates tasks: Task_PWM
 *
 *
 *
 */

/*
 * main.c
 */

#include "inc/hw_ints.h"
#include "inc/hw_memmap.h"
#include "inc/hw_types.h"
#include "inc/hw_uart.h"

#include <stddef.h>
#include <stdbool.h>
#include <stdint.h>
#include <stdarg.h>

#include "driverlib/sysctl.h"
#include "driverlib/pin_map.h"
#include "driverlib/gpio.h"

#include "Drivers/Processor_Initialization.h"
#include "Drivers/UARTStdio_Initialization.h"
#include "Drivers/uartstdio.h"

#include "FreeRTOS.h"
#include "task.h"

#include <stdio.h>

extern void Task_PWM( void *pvParameters );
//extern void Task_MotorPosition( void *pvParameters );
extern void Task_Blink_LED_PortN_1( void *pvParameters );
extern void Task_ReportTime( void *pvParameters );
extern void Task_ReportData( void *pvParameters );

//extern void Task_I2C7_Handler( void *pvParameters );

int main( void ) {
```

```

Processor_Initialization();
UARTStdio_Initialization();
//
// Create a task to blink LED
//
xTaskCreate( Task_Blink_LED_PortN_1, "Task_Blink_LED_PortN_1", 128, NULL, 1, NULL );
UARTprintf( "FreeRTOS Starting!\n" );

//
// Create a task to report data.
//
xTaskCreate( Task_ReportData, "ReportData", 512, NULL, 1, NULL );


xTaskCreate( Task_PWM, "PWM", 512, NULL, 1, NULL );
//xTaskCreate( Task_MotorPosition, "PWM", 512, NULL, 1, NULL );


//
// Create a task to report SysTickCount
//
//xTaskCreate( Task_ReportTime, "ReportTime", 512, NULL, 1, NULL );

//
// Create a task to initialize I2C7_Handler.
//
//xTaskCreate( Task_I2C7_Handler, "I2C7_Handler", 1024, NULL, 2, NULL );


//
// Start FreeRTOS Task Scheduler
//
vTaskStartScheduler();

while ( 1 ) {

}

}

```

## 7.2 Task\_PWM.c

```
/*--Task_PWM.c
 *
 * Author: Luke Weaver
 * Organization: KU/EECS/EECS 690
 * Date: November 28, 2017
 *
 * Description: Controls motor functions
 *
 *
 *
 */

#include <stddef.h>
#include <stdbool.h>
#include <stdint.h>
#include <stdarg.h>

#include "inc/hw_types.h"
#include "inc/hw_gpio.h"
#include "inc/hw_memmap.h"
#include "inc/hw_uart.h"
#include "inc/hw_timer.h"

#include "driverlib/gpio.h"
#include "driverlib/pin_map.h"
#include "driverlib/pwm.h"
#include "driverlib/timer.h"
#include "driverlib/sysctl.h"
#include "driverlib/uart.h"
#include "utils/uartstdio.h"
#include "driverlib/qei.c"
#include "FreeRTOS.h"
#include "task.h"
#include "Tasks/Task_ReportData.h"

char userInput[3];
int32_t currentMultiplier;
uint32_t servoPW;
uint32_t servoPeriod;
int32_t servoPosition;
int32_t qeipos;
char mode[1];

extern void Task_PWM( void *pvParameters ) {

    ReportData_Item      QeiInfo;

    servoPeriod = 120000000/3200;
```

```

servoPW = 2813;
SysCtlPeripheralEnable(SYSCTL_PERIPH_PWM0);
SysCtlPeripheralEnable(SYSCTL_PERIPH_QEIO);
SysCtlPeripheralEnable(SYSCTL_PERIPH_GPIOG); //port G
SysCtlPeripheralEnable(SYSCTL_PERIPH_GPIO_L); //port L

GPIOPinConfigure(GPIO_PG1_MOPWM5); //pg p1
GPIOPinConfigure(GPIO_PL1_PHA0); //pg L1
GPIOPinConfigure(GPIO_PL2_PHB0); //pg L2

GPIOPinTypeQEIO(GPIO_PORTL_BASE, GPIO_PIN_1);
GPIOPinTypeQEIO(GPIO_PORTL_BASE, GPIO_PIN_2);
//pwm
GPIOPinTypePWM(GPIO_PORTG_BASE, GPIO_PIN_1);
PWMClockSet(PWM0_BASE, PWM_SYSCLK_DIV_64);
PWMGenConfigure(PWM0_BASE, PWM_GEN_2, (PWM_GEN_MODE_DOWN | PWM_GEN_MODE_NO_SYNC));
PWMGenPeriodSet(PWM0_BASE, PWM_GEN_2, servoPeriod);
PWMPulseWidthSet(PWM0_BASE, PWM_OUT_5, (servoPW));
PWMGenEnable(PWM0_BASE, PWM_GEN_2);
PWMOutputState(PWM0_BASE, (PWM_OUT_5_BIT), true);

//qeio
QEIOConfigure(QEIO_BASE, (QEIO_CONFIG_CAPTURE_A_B | QEIO_CONFIG_RESET_IDX | QEIO_CONFIG_QUADRATURE | QEIO_CONFIG_VELOCITY));
QEIOEnable(QEIO_BASE);
QEIOVelocityEnable(QEIO_BASE);
QEIOVelocityConfigure(QEIO_BASE, QEIO_VELDIV_1, 1120000);
QEIOPositionSet(QEIO_BASE, 560); //set baseline
/*
* servoPeriod = 40704; //16 least significant bits 1001111100000000. 20ms
servoPW = 43392; //54464 cw, 43392 ccw
SysCtlPeripheralEnable(SYSCTL_PERIPH_TIMER3);
SysCtlPeripheralEnable(SYSCTL_PERIPH_GPIOA);

GPIOPinConfigure(GPIO_PA7_T3CCP1); //Sets up pin to use alternative function. The General Purpose
GPIOPinTypeTimer(GPIO_PORTA_BASE, GPIO_PIN_7); //Sets as a timer pin.

TimerConfigure(TIMER3_BASE, TIMER_CFG_SPLIT_PAIR | TIMER_CFG_B_PWM); //Specifies mode as PWM.
TimerMatchSet(TIMER3_BASE, TIMER_B, servoPW); //Initialized Pulse Width value
TimerPrescaleMatchSet(TIMER3_BASE, TIMER_B, 3); //counter clock wise, 2 clockwise
TimerPrescaleSet(TIMER3_BASE, TIMER_B, 36); //8 most significant bits 100100, extends of 16-bit timer
TimerLoadSet(TIMER3_BASE, TIMER_B, servoPeriod); //Set period
TimerEnable(TIMER3_BASE, TIMER_B); //enables timer
*/
UARTprintf("Press 1 to set velocity OR press 2 to set position.");
UARTgets(mode, 2);
while (1) {
    if (mode[0] == '1')
    {
        UARTprintf("Set speed (-100 - 100) : ");
        //alternate between high and low pulse widths
        userInput[0] = NULL;
        userInput[1] = NULL;
        userInput[2] = NULL;
        userInput[3] = NULL;
    }
}

```



```

//set pulse width
//TimerMatchSet(TIMER3_BASE, TIMER_B, servoPW);
vTaskDelay( ( 5000 * configTICK_RATE_HZ ) / 10000 );
UARTgets(userInput,5);
currentMultiplier = atoi(userInput);
if(currentMultiplier>-101 && currentMultiplier<101)
{
//1875 - 3750
servoPW = 2813 + (937*currentMultiplier)/100;
}
else
{
UARTprintf("%d is not a valid input. Please choose a value between -100 and 100 inclusi
}
PWMPulseWidthSet(PWM0_BASE, PWM_OUT_5, (servoPW));

UARTprintf("user input: %d \n",currentMultiplier);
UARTprintf("current Pulse Width Value: %d \n",servoPW);

vTaskDelay( ( 5000 * configTICK_RATE_HZ ) / 10000 );

QeiInfo.TimeStamp = xPortSysTickCount;
QeiInfo.ReportName = 1;
QeiInfo.ReportValue_0 = QEIVelocityGet(QEIO_BASE);
QeiInfo.ReportValue_1 = QEIDirectionGet(QEIO_BASE);
QeiInfo.ReportValue_2 = QEIPositionGet(QEIO_BASE);
QeiInfo.ReportValue_3 = 0;
xQueueSend( ReportData_Queue, &QeiInfo, 0 );

//UARTprintf("Position: %d \n",QEIPositionGet(QEIO_BASE));
//UARTprintf("Velocity: %d \n",QEIVelocityGet(QEIO_BASE));
//UARTprintf("Direction: %d \n",QEIDirectionGet(QEIO_BASE));
currentMultiplier = 0;
}

else if(mode[0] == '2')
{
//get user input
qeipos = QEIPositionGet(QEIO_BASE);
UARTprintf("Set position in degrees (-180 - 180): ");
userInput[0] = NULL;
userInput[1] = NULL;
userInput[2] = NULL;
userInput[3] = NULL;
vTaskDelay( ( 5000 * configTICK_RATE_HZ ) / 10000 );
UARTgets(userInput,5);
currentMultiplier = atoi(userInput);
if(currentMultiplier>-181 && currentMultiplier<181){

servoPosition = 560+ (currentMultiplier*560)/180; //destination
}
}

```

```

else{
    UARTprintf("%d is not a valid input. Please choose a value between -180 and 180 inclusi
    servoPosition = 560;
}

vTaskDelay( ( 5000 * configTICK_RATE_HZ ) / 10000 );

//Determine which direction to go

if(qeipos - servoPosition > 0) //ccw
{
    PWMPulseWidthSet(PWM0_BASE, PWM_OUT_5, (2700));
}
else if(qeipos - servoPosition == 0)
{
    PWMPulseWidthSet(PWM0_BASE, PWM_OUT_5, (2813)); //zero
}
else
{
    PWMPulseWidthSet(PWM0_BASE, PWM_OUT_5, (2950)); //cw
}
UARTprintf("Current Position: %d \n",QEIPositionGet(QEIO_BASE));
UARTprintf("Desired Position: %d \n",servoPosition);
while(abs((qeipos - servoPosition)) > 2)
{

    qeipos = QEIPositionGet(QEIO_BASE);
    vTaskDelay( configTICK_RATE_HZ / 1000 );
}
UARTprintf("New Current Position: %d \n",QEIPositionGet(QEIO_BASE));
PWMPulseWidthSet(PWM0_BASE, PWM_OUT_5, (2813));

//report data
QeiInfo.TimeStamp = xPortSysTickCount;
QeiInfo.ReportName = 2; //1 is velocity, 2 is position
QeiInfo.ReportValue_0 = QEIPositionGet(QEIO_BASE);
QeiInfo.ReportValue_1 = 0;
QeiInfo.ReportValue_2 = 0;
QeiInfo.ReportValue_3 = 0;
xQueueSend( ReportData_Queue, &QeiInfo, 0 );
currentMultiplier = 0;
servoPosition = 560;
}

else
{
    UARTprintf("Enter a valid option 1 or 2.");
    UARTgets(mode,2);
}
}
}

```

