



## Electrical Machines

# DC machines :-# DC Motor :-


i/p = electrical DC  
o/p = mechanical



★ 2 main parts  $\rightarrow$  stator (static part)  
 $\rightarrow$  rotor (rotating part)

{ min. number of pole in any machine = 2 }





Purpose of stator core is to provide path for flow of flux.

Core  $\rightarrow$  cast iron

winding  $\rightarrow$  core

for big machines, core is laminated (0.4-0.6)mm of laminate core size

# winding for DC machines  $\rightarrow$  ① field winding

② Armature winding  $\rightarrow$  a) ~~loop~~ winding  
b) wave winding

in ~~loop~~ winding

Number of core parallel path = No. of pole for Armature.

in wave winding

fixed parallel path & No of parallel path = 2

# Commutator  $\rightarrow$  when a dc machine used as a motor then it works as a Inverter or Convert AC  $\rightarrow$  DC

for a motor  $\rightarrow$  works as Inverter

for a generator  $\rightarrow$  " " Commutator ~~is not~~

the function of Commutator is to rectify the AC supply in the Armature to DC supply


No of commutator segment = No of coil turns

flaming LHR  $\rightarrow$

for DC machines

flaming RHR  $\rightarrow$


for DC generators




## # Field winding excitation!

- ① separately excited dc machine
- ② self excited

- DC series m/c
- DC shunt m/c
- DC compound m/c




DC Series m/c



DC Shunt m/c

excitation depend on armature current & if  $R$  of  $F, FF$  is large current less so larger cross section area here.


larger turns, cross section area is lesser



Residual flux

\* self excited DC machine starts with residual flux.





DC Compound M/c (2 types)


① Cumulative Compound M/c

② Differentially Compound M/c

\* If the flux of the 2 field windings adds to each other such that the resultant flux increases then the compound M/c is Cumulatively compound M/c.

\* If the flux of 2 field windings oppose to each other such that the resultant flux decreases then the compound M/c is Differentially compound M/c.

Working Principle :-



for motor ( $i_a$  incoming) (left hand rule)  
here rotate in clockwise dirn

for generator ( $i_a$  outgoing) (right hand rule)  
we apply mechanical rotation

① Flts always exist in pair

② Constant flux induced in ~~the~~ machine

③ in current carrying conductor

~~the~~ Constant E.M

Torque will develop  
if this rotor or  
armature ckt  
will rotate.


Fleming left hand rule  
give dirn of rotation

(Let clockwise  
so cross thumb dot)



# Electrical Machine

## DC Machines



# Parts of DC Machines →


- ① Stator
- ② Rotor
- ③ Commutator
- ④ Brush

- ⑤ Armature Core
- ⑥ Armature winding
  - ① Lapwinding
  - ② wave binding

① Stator :- It is stationary part of DC machine. It provide accomodation for poles.


★ The poles can be permanent ~~iron~~ or binding both (field winding)

★ It provide magnetic path as @  
 $R_{air} \gg R_{iron}$ . [R=reluctance]



## ② Rotary :-

Rotary is on shaft





## ③ Commutator → only present in DC machine

(not present in AC)

★ It converts AC to DC and DC to AC so it is called mechanical Rectifier or Inverter

★ It is made up of hard drawn copper



## ④ Brush → made of carbon (for less heating) because it provides self lubrication to reduce friction.



⑤ Armature core:- the slots on stator & rotor is Armature core  
★ slots for winding

★ The winding on armature core = Armature winding


★ core provide low reluctance path for flux.

Note:- ★ field winding has very low current

★ Armature winding has  $v$

⑥ Armature winding:- on the basis of connection to commutator they are of 2 types

① Lap winding



for Lap winding

$$A = P$$

$A$  = no. of parallel paths through armature


$P$  = total Number of poles

finishing end of adjacent  
coil 1 is connected to  
started end of coil 2

i.e. finishing & starting end  
of adjacent coils are  
connected respectively

★ lap winding is used when the  
current capacity of machine is  
high whereas voltage capacity is low

## 2 wave binding -




the starting and end of ~~coil~~ Coil 2 is number of segments away from starting of first coil.

- ★ here there are only 2 parallel paths hence  $A=2$
- ★ this type of winding is only used when machine require low capacity of current & high voltage,




## # field winding Excitations:

### ① separate Excitation -




### ② Self Excitation -

#### ① Series excitation -




#### ② Shunt Excitation - (also known as voltage operated field)

Voltage of Armature = voltage of shunt field winding



② Compound excitation :- how 2 field windings are present



2 field flux are produced in this excitation

- (i) if direction of both field are opposite  $\Rightarrow$  resultant flux  $\downarrow$ es
- (ii) " " " is same  $\Rightarrow$  resultant flux  $\uparrow$ es

here if flux  $\uparrow \Rightarrow$  Cumulative Compound DC machine  
" "  $\downarrow \Rightarrow$  Differentially " " "