

CT & PT

- ① CT = Current Transformer (used to measure ^{high} current)
② PT = Potential Transformer (" " ^{high} voltage)

③ CT & PT is always used in AC

④ Current ratio in CT = $1000/5$
PT = $1000/1$

⑤ CT & PT are installed in grid in substation.

CT

Current Transformer - ① It is an instrument transformer used for measurement of high current.

② Rating: $500/5$, $500/1$, $1000/5$, $1000/1$ mostly used


③ Step up transformer is used for CT. ($I_1 N_1 = I_2 N_2$)

④ Why we use CT? if we go on design a Ammeter to measure that (1000A) large current the size & cost of (A) will very large & expensive

so use  we use CT.

⑤ Calibrated Ammeter are used to measure current using CT.

⑥ 3 ϕ AC



Let $\frac{N_1}{N_2} = \frac{5}{1000}$

then

$$\frac{I_1}{I_2} = \frac{1000 \text{ A}}{5 \text{ A}}$$

↓
this rating is rated on CT

★ Calibration → $200 \times \text{Reading}$

★ why switch is used?

Ans) Ammeter behave as short circuit. So To remove ammeter the switch should ON otherwise CT will blast.

⑦ CT is designed upto I for shortckt Load ($\text{max}^m I$ passed)
as CT depend on Load (current varies per load)

CT will measure 0 if Load = 0

⑧ CT is series to load.



Pen down


~~Basic of PT~~

PT

- ① It is a Instrument Transformer used to measure ^{high} voltage
- ② Rating - 1000/5, 500/1, 500/5, 1000/1 (ratio of turns or voltage)
- as $\left(\frac{V_1}{V_2} = \frac{N_1}{N_2} \right)$

③ step down Transformer is used.

④ Connected in parallel to load.



As the internal resistance of $V = \infty$ so terminal pot. can be measured by proper calibration.

~~why not use~~


* pot. transformer terminals can be left open no harm (C & D)

* As the voltage in transformation line remains constant so PT works good even fluctuations in load



Pen down


CT & PT in a Circuit



Phasor for CT

$$\text{let } \phi = \phi_0 \sin \omega t$$


$$E_2 = -\frac{d\phi}{dt} = -\phi_0 \omega \cos \omega t = E_0 \sin(\omega t - \pi/2)$$



$$I_1 = I_0 + I_2'$$

phapor for PT

$$V_2' = -enV_s$$



Errors in CT & PT

① Ratio error

② Phase angle error

CT error -

① Ratio error:

$$\frac{N_1}{N_2} \neq \frac{I_2}{I_1} \quad \text{due to magnetizing \& core loss Component}$$

(K_n) (R_n)

$$\% \text{ Ratio error} = \frac{\text{Nominal ratio} - \text{actual ratio}}{\text{actual ratio}} \times 100$$

$$= \frac{K_n - R_n}{R_n} \times 100$$

$$\text{② Phase angle error} = \frac{\frac{N_1}{N_2} - \frac{I_2}{I_1}}{\frac{I_2}{I_1}} \times 100$$

I_2 & I_1 has phase shift of 180° but not actually found due to magnetizing & core loss
& phase angle is $\neq 180^\circ$

$$\text{phase angle error } (\theta) = \frac{180}{\pi} \left[\frac{I_m \cos \delta + I_c \sin \delta}{n I_s} \right]$$

$$\theta = \frac{I_m \cos \delta - I_c \sin \delta}{n I_s} \text{ in radians}$$

in degrees

② PT - error -

$$\textcircled{1} \quad \frac{N_1}{N_2} = \frac{V_1}{V_2}$$

(K_n) (R_n)

$$\% \text{ ratio error} = \frac{K_n - R_n}{R_n} \times 100$$

$$= \frac{\frac{N_1}{N_2} - \frac{V_1}{V_2}}{\frac{V_1}{V_2}} \times 100$$

② Phase angle error -
should

V_p & V_{s1} not has any phase diff

but due to mag & core loss

loss comes as phase angle in PT

$$\theta = \frac{I_a}{n} (X_p \cos \Delta - R_p \sin \Delta) + I_e X_p - I_m R_p$$

nV_s

(in radians)