

## STM32 CNC 6 Axis Card

### Features



- ❖ Adopt STM32 32 bits high-speed processor, Arm-cortex-m.
- ❖ Compatible with Fluidnc, Candle, Bcnc, CNC3D COMMANDER...

(GRBL only 1.1f is available)

- ❖ Support XYZABC six stepper drivers.
- ❖ Support Homing, software/hardware endstop, Z probe.
- ❖ Support 3pin laser. Adjustable voltage PWM output.
- ❖ Support 12V-24V DC

Auto-cut off power when voltage exceeding 30V.

Automatically select external power supply as the main control input power,  
and prevent reverse power transmission, protect USB port.



PROBE	Z-probe
X-LIM	X limit, On
Y-LIM	Y limit, On
Z-LIM	Z limit, On
GND	XYZ axis limit com, Z-probe
PWM-ADJ	PWM voltage adjustment
COM	PUL-,EAN-,DIR- of stepper drivers
X-PUL	X-PUL+
X-ENA	X-ENA+
X-DIR	X-DIR+
PWM3.3	Output 3.3v PWM

## Install STM32 USB Driver




# Software

Candle,CNC3dCommander and Bcnc.

上位机软件.rar 2022/11/2 星期... WinRAR 压缩文件 110,909 KB

## 1.Candle

Unzip candle and open [candle.exe](#)



设置

?

X

连接

发送者

机器信息

控制

用户命令

高度地图

解析器

可视化工具

工具模型

控制台

面板

颜色

字体

连接

端口: COM6 波特率: 115200

发送者

☐ 忽略错误响应

☒ 从所选行发送前自动设置分析器状态

机器信息

状态查询周期: 250 单位: 毫米

快速速度: 0 加速度: 10

主轴最小转速: 0 最大: 100

最小激光功率: 9 最大: 100

控制

对刀命令:

G90G21G38.2Z-50F100; G92Z1.6; G0Z10;

安全位置命令:

命令 1; 命令 2; ...

☒ “还原原点”将工具移入: 平面

用户命令

按钮 1:

命令 1; 命令 2; ...

设为默认值

确认

取消

状态

工作坐标:

0.000 0.000 0.000

机器坐标:

0.000 0.000 0.000

状态:

空闲




## 2. BCNC

Plug control board to PC via USB cable, and enter bcnc.exe



Click CAM, select language.



Enable 6 axis display, then reboot software.




Click file, select COM and open it.




### 3.CNC3d Commander

Open CNC3dcommander as below



Connect control board and reflash.



Parameters configuration

You can use PC software such as GRBLaser to config the parameters by sending commands, here is the list:

COMMANDS	PARAMETERS	DESCRIPTION
\$0	10	Sets time length per step. Minimum 3usec.
\$1	5	Sets a short hold delay when stopping to let dynamics settle before disabling steppers. Value 255 keeps motors enabled with no delay.
\$2	0	Inverts the step signal. Set axis bit to invert (00000ZYX). The details can refer to <a href="#">XYZ-TABLE</a>
\$3	1	Inverts the direction signal. Set axis bit to invert (00000ZYX). The details can refer to <a href="#">XYZ-TABLE</a>
\$4	0	Inverts the stepper driver enable pin signal.
\$5	1	Inverts the all of the limit input pins.
\$6	0	Inverts the probe input pin signal.
\$10	1	Alters data included in status reports.
\$11	0.01	Sets how fast Gbl travels through consecutive motions. Lower value slows it down.
\$12	0.002	Sets the G2 and G3 arc tracing accuracy based on radial error. Beware: A very small value may effect performance.
\$13	0	Enables inch units when returning any position and rate value that is not a settings value.
\$20	0	Enables soft limits checks within machine travel and sets alarm when exceeded. Requires homing.
\$21	0	Enables hard limits. Immediately halts motion and throws an alarm when switch is triggered.
\$22	0	Enables homing cycle. Requires limit switches on all axes.
\$23	0	Homing searches for a switch in the positive direction. Set axis bit (00000ZYX) to search in negative direction. The details can refer to <a href="#">XYZ-TABLE</a>
\$24	300	Feed rate to slowly engage limit switch to determine its location accurately.
\$25	1000	Seek rate to quickly find the limit switch before the slower locating phase.
\$26	250	Sets a short delay between phases of homing cycle to let a switch debounce.
\$27	1	Retract distance after triggering switch to disengage it. Homing will fail if switch isn't cleared.
\$28	1000	Modify the output frequency of the spindle, the input range is 0-100000
\$30	1000	Maximum spindle speed. Sets PWM to 100% duty cycle.
\$31	0	Minimum spindle speed. Sets PWM to 0.4% or lowest duty cycle.
\$32	1	Enables laser mode. Consecutive G1/2/3 commands will not halt when spindle speed is changed.
\$100	80	X-axis travel resolution in steps per millimeter.
\$101	80	Y-axis travel resolution in steps per millimeter.
\$102	80	Z-axis travel resolution in steps per millimeter.
\$110	6000	X-axis maximum rate. Used as G0 rapid rate.
\$111	6000	Y-axis maximum rate. Used as G0 rapid rate.
\$112	6000	Z-axis maximum rate. Used as G0 rapid rate.
\$120	500	X-axis acceleration. Used for motion planning to not exceed motor torque and lose steps.
\$121	500	Y-axis acceleration. Used for motion planning to not exceed motor torque and lose steps.
\$122	500	Z-axis acceleration. Used for motion planning to not exceed motor torque and lose steps.
\$130	285	Maximum X-axis travel distance from homing switch. Determines valid machine space for soft-limits and homing search distances.
\$131	272	Maximum Y-axis travel distance from homing switch. Determines valid machine space for soft-limits and homing search distances.
\$132	80	Maximum Z-axis travel distance from homing switch. Determines valid machine space for soft-limits and homing search distances.

XYZ TABLE

☰ README.md

Directions	Parameters
X+ Y+ Z+	0
X- Y+ Z+	1
X+ Y- Z+	2
X- Y- Z+	3
X+ Y+ Z-	4
X- Y+ Z-	5
X+ Y- Z-	6
X- Y- Z-	7